### 7.0 Buildability Constraints – Junction 12 to 15



### Traffic Management - Conclusions

- Worst case scenario to highlight the extensive work and planning to design the traffic management
- Extensive/detailed TM modelling is recommended at specific locations on the network. Consideration given to hardshoulder running, narrow lanes, progressive closures etc.









# 7.0 Buildability Constraints – Junction 12 to 15 (Contd) Scotland Tran Serv

### **Constraints Summary**

- · Departures will be necessary regardless of the type of systems we use
- Departures will be required for working widths at some locations
- Departures required for setback at some locations
- Highmasts will not be relocated between 12 and 15 therefore barrier design will need to accommodate the high masts
- Barrier design will need to accommodate the gantry legs
- Diversion/protection work may be necessary before barrier replacement can take place
- Traffic Management Significant and extensive delay will be encountered by travellers during the works. TM to be planned and managed, extensive modelling to take place.










#### 8.0 Possible Solutions



### **Design Requirements**


- Safety barrier MUST be provided where the central reserve is less than 10m.
- Traffic flows >=25,000 vehicles per day a rigid concrete barrier with minimum H1
  containment must be provided in England. In Scotland the use of concrete barriers
  is not mandatory.
- System will have a minimum containment of H1.
- At gantries very high containment H4a should be provided
- · WW1 required to minimise the number of departures from standard





### **Design Requirements**



- The Vehicle Intrusions (VI) needs to be taken account of as changes the available working width.
- Example Hill and Smith "Hi Flex" product claims to be an H2 WW1 product, however the vehicle intrusion on the product is VI3 which ultimately makes the products working width the equivalent of WW3.









 Two main types of barrier on the market, concrete or steel.


- Jct 12 15 Requirements WW1,
   VI1, H4a containment
- Is this type of system available?



### **Steel Products**

- H1 Containment WW2, VI3 1 product sourced
- H2 Containment WW2, VI2 2 products sourced
- H4a Containment WW5, VI5 (1 safety barrier sourced, all rest are classified as parapet)
- Limited products available









#### **Concrete Products**

- H1 Containment Concrete products are generally H2. H1 products larger working widths.
- 'H2 Containment WW1, VI1
- H4a Containment WW6, VI7
- · Limited products available
- Some products are precast, some in-situ

### Concrete V's Steel



Consideration	Steel	Concrete
Maintenance Regime	Ongoing throughout life of barrier.	Manufacturer's claim the barrier is maintenance free, however the drainage and debris maintenance can be more difficult.
Serviceable Life	20 years	50 years
Construction Time	Longer construction period on site than concrete for same length of barrier.	Shorter construction period on site than concrete for same length of barrier.
Flexibility	Can accommodate obstacles/street furniture	Not as easy to accommodate obstacles
Other	Can be used on bridge decks	May not be able to be used on bridge decks



### Summary

- No products on the market for the required working width/vehicle intrusion –
   Departure from Standards
- No very high containment barrier available with adequate working width/vehicle intrusion – Departure from standards
- Concrete is likely to be difficult to accommodate within a constrained central reserve and if concrete barrier was progressed this would likely need to be combined with sections of steel barrier. On this basis implement steel barrier solution......THOUGHTS?









### 9.0 Construction Costs - Jct 12 to 15



Item	Cost	
Preliminaries		
Traffic Management		
Site Clearance		
Safety Fence		
Drainage	(1 - Vis.	
Earthworks		
Pavements	164	ETF.
Utility Diversions/Protection	and the second section of the section of the section of the second section of the secti	
40% Contingencies		
<u>Total</u>		

- Costs assume one phase
- Unlikely to be possible due to construction period
- If broken down into different zones costs would increase

#### **10.0 Forward Planning**

### November 2014 to March 2015

### Investigations


- Detailed Drainage Survey (CCTV)
- Trial Holes
- Additional Information from Mobile Surveys
- Environmental Surveys

### Preliminary Design Tasks

- Priority Matrix
- Validation of TM Model
- Utility C2 Notices and Liaison
- TS Containment levels discussions
- TM Preliminary Design
- Preliminary Barrier Design

Investigation/Preliminary Design Cost Estimate

### **10.0 Forward Planning**




- Detailed Design Estimate
   to end of Dec 2015 for construction Summer 2016
- Length of section to be constructed is unknown.
- Investigation/Design (including Modelling) will have a significant impact on the construction phasing

### 11.0 Conclusions



- Barrier needs replaced as non-standard, life expired and non-proprietary and therefore cannot be defined or guaranteed.
- Condition surveys, push pull testing and accident data have been utilised to establish a priority system for the maintenance sequence
- Identified constraints that will need to be incorporated into design process including departures from standard
- Extensive traffic management planning and modelling
- Next Steps Preliminary/Detailed design of Junctions 12 to 15.



#### STSV Incident Report **General Details Incident Details** 00025049 Incident Cat RTC STSW Incident Type MINOR 28/12/2014 20:30:16 O/I Ref 0 Defect Ref SW14850598 Incident Description RTC/ Barrler Damage Contacts Contact Phone Contact Mobile Contact Email Traffic Scotland Traffic Scotland **Location Details** Route Junction Marker Post M8 M8 - Junction 14 W/B SW14850598 Location Description 260997 Northing 665887 Link/Section Vehicle Response Time Called Time Allocated Time Arrived Time Departed 29/12/2014 00:00:00 29/12/2014 00:00:00 29/12/2014 00:25:00 29/12/2014 01:25:00 28/12/2014 20:45:00 28/12/2014 20:30:00 28/12/2014 20:30:00 29/12/2014 02:05:00 28/12/2014 20:40:00 28/12/2014 20:40:00 28/12/2014 22:00:00 29/12/2014 02:05:00 28/12/2014 22:40:00 28/12/2014 22:40:00 29/12/2014 00:15:00 29/12/2014 01:50:00 False Vehicles Involved Vehicle Colour Driver Foreign Slight Injuries Serious Fatal Injuries Registration Vehicle Injuries False 0

Incident ID

Contract

Issued

Status

Weather

Police Inc No

Other Cause

Organisation

Region

Easting

**ISURef** 

PAPA 1

PAPA 2

TM Crew

Nightshift

No Trace

Make/Model

Damage

Single Sided Box Beam (OBB)

20 mtr central reservation open box barrier/ 7 posts

ĺ	Action Date	Actions Taken
	28/12/2014 20:33:00	From camera lane 4 closed
	28/12/2014 20:36:00	email sent to transport emergencies in box.
	28/12/2014 20:51:00	From police require lanes 3/4 closed on the e/b and w/b carriageway trapped in the vehicle.
	28/12/2014 20:51:00	From requires IPV vehicle and TM foreman.
	28/12/2014 20:51:00	NCC called SWDO
	28/12/2014 20:51:00	updated email sent to Transport emergencies.
	28/12/2014 20:51:00	From eta for TM Crew 20 minutes.
	28/12/2014 20:51:00	Papa 2 updated .
	28/12/2014 21:13:00	From police require lanes 3 and 4 closed in both directions state crash investigation are attending
	28/12/2014 21:13:00	police called for eta for TM NCC called Papa 2 eta 20 minutes.
	28/12/2014 21:13:00	From Traffic scotland lane 4 of 4 closed on the e/b carriageway.
	28/12/2014 22:05:00	updated email sent to transport emergencies inbox.
	28/12/2014 22:23:00	From currently putting on the TM he has assess the barrier state that it either going to need varioguard or lane closure to be left on.
	28/12/2014 22:23:00	NCC called Duty Officer has been supplied by the will contain the will be
	28/12/2014 22:32:00	SWDE updated.
	28/12/2014 22:32:00	From Papa 2 police are requesting to attend to discuss barrier damage.
	28/12/2014 22:32:00	NCC spoke to he will attend .
	28/12/2014 22:45:00	Traffic Scotland updated -
	28/12/2014 22:45:00	From Papa 2 crash investigation team at locus.
	28/12/2014 23:53:00	From Papa 2 police are looking for still saw to cut a bit of the barrier to take away as evidence.
	28/12/2014 23:53:00	From Papa 2 doesnt have a still saw on vehicle ,
	28/12/2014 23:53:00	From Papa 1 to attend with still saw.
	28/12/2014 23:53:00	
	29/12/2014 00:15:00	NCC called police scotland for update no details have been received from hospital as yet of injuries.
	29/12/2014 00:19:00	SWDO on site.
		advised they will hard cone where barrier has been it and also hard cone the e/b verge.
	29/12/2014 00:42:00	Damage as follows 20mtr central reservation open box barrier and 7 posts.
	29/12/2014 00:42:00	Traffic Scotland updated.
	29/12/2014 01:23:00	registration number.
	29/12/2014 01:23:00	NCC sending patrol driver to locus to spot grit closure.
	29/12/2014 01:23:00	From Control of side lane closure w/b will remain in place arrangement will be made tomorrow for barrier repair.
	29/12/2014 01:23:00	
	29/12/2014 01:23:00	email sent to Transport emergencies inbox
	29/12/2014 01:23:00	email sent to