Statement of I Maintenance	ntent (S	OI) F	orm: Stru	ctur	al			
1. Scheme Name	A83 Cairndow	/ (HD28)						
2. Scheme ID	16/NW/0104/0)24	4. Sol Revision	1.0			TRANSPORT	
3. Scheme Manager Ref	16NW010400	7	5. Work Year	20	16/17		SCOTLAND	
SCHEME LOCATION				value!				
6. Road	A83	7. Loca	tion description	A83 C	Cairndow, dow	hill S2	M section.	
8. Network referencing	Link/Section		Start Chainage	En	d Chainage	Leng	th(m)	
(from IRIS)	16520/05		1220	187	72	652	200 THE THE STATE OF THE STATE	
				Schen	ne Length(m)	652		
SCHEME DETAILS								
9. Traffic flow		AAI	OT/AADF	W	% HGV	10.	Year of count	
a, maint now	AADF		5837		7		2015	
CONDITION ASSESS 11. Construction Detail and Recorded Maintenance	IRIS construct of approximate dressing applie	ely 270m ed to bot	m. This material da h CL1 & CR1 in 20	tes bacl 01 the la	k to 1988, with ast recorded tr	a 10mı əatmen	s material to a dept m thick surface	
			highlighted as a roo				t.	
12. IRIS / Visual Survey Justification for Scheme	recommendati have occurred is proposed to accidents at th wheel tracks, v water ponding at this site. IRI backed up by	on for tre at this lo provide iis locatio with an o in the op S record HD28 Inv	Unit. Secondary site eatment to improve pocation and received an improved level con. A visual inspect pen texture through pen matrix could be a found this section	es withing the skid of the skid reference of	n this location I resistance. A media coverage esistance and large areas e suspected duting to the repe SCRIM below e are areas of	tions inthe have re numbe e. Treat address of fatige rainage beated a vinabl	to skid resistance aceived a rof recent accidents are the recent accidents are the number of the cracking in the issue combined with accidents recorded throughout, which is edeflections within	
Justification for	recommendati have occurred is proposed to accidents at the wheel tracks, water ponding at this site. IRI backed up by I the scheme, the Scheme exten	on for tre at this lo provide is locatio with an o in the or S record HD28 Inv nese can	Unit. Secondary site eatment to improve pocation and received an improved level on. A visual inspect pen texture through pen matrix could be a found this section vestigations and VC	es within the skid docal not skid reion four out. The contribute to have S. Therweral cu	n this location I resistance. A media coverage esistance and and large areas e suspected duting to the repe SCRIM below e are areas of liverts found at a appropria	tions inthe tions into the tions in the tion	to skid resistance accived a rof recent accidents then the recent accidents the number of the cracking in the issue combined with accidents recorded throughout, which is edeflections within ocations.	
Justification for	recommendati have occurred is proposed to accidents at the wheel tracks, water ponding at this site. IRI backed up by I the scheme, the Scheme exten	on for tre at this lo provide is locatio with an o in the or S record HD28 Inv nese can	Unit. Secondary site eatment to improve cation and received an improved level con. A visual inspect pen texture through the matrix could be so found this section westigations and VC be attributed by second as the wider area in RMMS.	es within the skid docal not skid reion four out. The contribute to have S. Therweral cu	n this location I resistance. A media coveragesistance and and large areas e suspected duting to the rege SCRIM belower are areas of alverts found at recent accider	tions inthe tions into the tions in the tion	to skid resistance accived a rof recent accidents then the strain of the number of the cracking in the issue combined will accidents recorded throughout, which is e deflections within ocations.	
Justification for Scheme 13. IRIS Report Detail,	recommendati have occurred is proposed to accidents at th wheel tracks, v water ponding at this site. IRI backed up by I the scheme, th Scheme exten sites identified No. of C/wa	on for tre at this lo provide is locatio with an o in the op S record HD28 Inv nese can ts have t	Unit. Secondary site eatment to improve cation and received an improved level con. A visual inspect pen texture through the matrix could be so found this section vestigations and VC be attributed by second the wider area in RMMS.	es withing the skid docal not skid referenced to the skid referenced ref	n this location I resistance. A media coveragesistance and and large areas e suspected duting to the rege SCRIM belower are areas of alverts found at recent accider	tions inthe have refunded and restand and	to skid resistance accived a rof recent accidents are this location at this location at the number of the cracking in the issue combined with accidents recorded throughout, which is e deflections within ocations.	
Justification for Scheme	recommendati have occurred is proposed to accidents at th wheel tracks, v water ponding at this site. IRI backed up by I the scheme, the Scheme exten sites identified	on for tre at this lo provide is locatio with an o in the op S record HD28 Inv nese can ts have t	Unit. Secondary site eatment to improve cation and received an improved level con. A visual inspect pen texture through the matrix could be so found this section westigations and VC be attributed by second as the wider area in RMMS.	es withing the skid docal not skid referenced to the skid referenced ref	n this location I resistance. A media coverage esistance and and large areas e suspected duting to the rege SCRIM below e are areas of alverts found at a mean as appropriate recent accider t Data Last 3 full	tions inthe have refunded and restand and	to skid resistance accived a rof recent accidents are this location at this location at the number of the cracking in the issue combined with accidents recorded throughout, which is e deflections within ocations.	
Scheme 13. IRIS Report Detail, Routine Maintenance	recommendati have occurred is proposed to accidents at th wheel tracks, v water ponding at this site. IRI backed up by I the scheme, th Scheme exten sites identified No. of C/wa	on for treat this lost this location for the provide his location with an original in the open of the provided HD28 Invalues o	Unit. Secondary site eatment to improve coation and received an improved level com. A visual inspection texture through the matrix could be sound this section estigations and VC be attributed by second the wider area in RMMS. Current inancial year	es within the skid docal not skid referenced to the skid referenced to the skid referenced to have S. There weral cutaire seem volving S. Defec	n this location I resistance. A media coverage esistance and and large areas e suspected duting to the rege SCRIM below e are areas of alverts found at a mean as appropriate recent accider t Data Last 3 full	tions inthe have referenced to the hard restricted to the hard restr	to skid resistance accived a rof recent accidents are this location is the number of the cracking in the issue combined with accidents recorded throughout, which is e deflections within ocations. pturing the HD28	

	IRIS	Accident Data			
No. of Injury Accidents	Current financial year	Last 3 full financial years			
	2016/17	2015/16	2014/15	2013/14	
Total No. of Injury Accidents	1	0	2	0	
Wet Only	0	n =	0	-	
Skid Only	0	9.5	1	-	
Wet Skid	1	» -	1	-	

There is 1 CAT1 defect noted, dating back to Feb 2014. The defect notes a drainage issue with water encroaching the carriageway. There are 16 CAT2 defects recorded. There are 5 recorded as cracking and stripping/fretting, with 2 further areas of surface cracking. Worn slow markings and centre lines are recorded as well as road studs missing/ damaged.

There are three recorded accidents within the last three years. Two of these occurred in wet conditions. There have been a number of non-injury accidents in recent weeks and months on this section of carriageway which have been highlighted prompting a response issued from BEAR Scotland to the local media.

There are two HD28 sites which were highlighted at Preliminary Investigation stage. Both sites underwent a Secondary Investigation receiving recommendation for Treatment to Improve the skid resistance. This recommendation has been reviewed and approved prior to the visual survey taking place. Details of the HD28 sites Investigated can be seen below in bold, as well as wider HD28 sites which have been incorporated into the scheme.

Item	HD28 Priority	Rank	Road	Section Code	XSP	Start(m)	End(m)	SurveyDate	SCRIMSIteCategory	SCRIMDIFF	Accident	WetAcc
1128032	2	0010	A83	16520/05	CL1	1240	1330	22/09/2015	Single <500m (S2M)	-0.23	0.00	0.00
1128059	2	0377	A83	16520/05	CR1	1240	1330	22/09/2015	Single <500m (S2M)	-0.16	0.00	0.00
1128033	2	2214	A83	16520/05	CL1	1330	1370	22/09/2015	Gradient 5-10% (G1L)	-0.10	0.00	0.00
1128060	4	0163	A83	16520/05	CR1	1330	1370	22/09/2015	Gradient 5-10% (G1L)	-0.09	0.00	0.00
1128061	2	0246	A83	16520/05	CR1	1370	1440	22/09/2015	Single <500m (S2M)	-0,17	0.00	0.00
1128034	2	1001	AB3	16520/05	CL1	1370	1440	22/09/2015	Single <500m (S2M)	-0.13	0,00	0.00
1128035	2	1358	A83	16520/05	CL1	1440	1540	22/09/2015	Gradient 5-10% (G1L)	-0.12	0.00	0,00
1128062	2	1732	A83	16520/05	CR1	1440	1540	22/09/2015	Gradient 5-10% (G1L)	-0.11	0,00	0.00
1128036	2	1359	A83	16520/05	CL1	1540	1600	22/09/2015	Gradient 5-10% (G1L)	-0,12	0.00	0.00
1128063	4	1460	A83	16520/05	CR1	1540	1600	22/09/2015	Gradient 5-10% (G1L)	-0.07	0.00	0.00
1128064	2	0539	A83	16520/05	CR1	1600	1700	22/09/2015	Single <500m (S2M)	-0.15	0.00	0.00
1128037	2	0245	A83	16520/05	CL1	1600	1700	22/09/2015	Single <500m (S2M)	-0,17	0.00	0.00
1128065	1	0031	A83	16520/05	CR1	1700	1760	22/09/2015	Single <500m (S2M)	-0.16	2.00	1.00
1128038		0027	A83	16520/05	CL1	1700	1760	22/09/2015	Single <500m (S2M)	-0.23	2.00	1.00
1128039	4	1459	A83	16520/05	CLI	1760	1860	22/09/2015	Gradient 5-10% (G1L)	-0.07	0.00	0.00
1128066	4	0164	A83	16520/05	CR1	1760	1860	22/09/2015	Gradient 5-10% (G1L)	-0.09	0.00	0.00
1128040		2215	A83	16520/05	CL1	1860	1960	22/09/2015	Gradient 5-10% (G1L)	-0.10	0.00	0.00
1128067	-	4937	A83	16520/05	CR1	1860	1960	22/09/2015	Gradient 5-10% (G1L)	-0.03	0.00	0.00

FURTHER INVESTIGATION

14. Scope, intended purpose and cost of any proposed further investigation and design works Coring Investigation is taking place to find the construction layers of the pavement and determine which areas may require deeper Inlay patches. An investigation into SCRIM history has been carried out which determined that retexturing could not provide the desired result.

Estimated Investigation Cost

POTENTIAL TREATMENT

15. Potential Treatment Options

An Inlay treatment is the proposed treatment at this location. This will provide the desired improvements in skid resistance at the HD28 accident sites highlighted, as well as enhanced durability to the pavement and improved safety for the road user. The existing drainage will be investigated during detailed design stage. Extending the safety barrier will also be considered, to take into account recent accidents.

16. Potential
Sustainability
Treatment Options


Retexturing is a low waste treatment which has been considered. This has been ruled out based on an investigation into SCRIM History which found that retexturing is unlikely to provide the required improvements in terms of residual grip and texture.

17. Approval to undertake the further	Operating Company Representative name	Signature	Date	
investigation works as outlined above NB. If no further			16/11/2016	
NB. If no further investigation is required then please complete and submit the full form SOI(sa) Transport Scotland Representative name		Signature	Date	
SUMMARY OF MAIN	TENANCE NEED	The second secon		
	If coring was undertaken did correct?	cores confirm IRIS Construction records are	NA	
	If "No" has a Corrective M	SD been submitted	NA	
18. Summary of	Have the scheme extents cha	nged following investigation	NA	
findings from further investigation works	If "Yes" has Section 8 abo	ve been amended	NA	
(if applicable)	If "Yes" has Scheme Mana	ager – Section details been updated	NA	
	Coring Investigation is progra	mmed to take place at the time of writing, as di tt. The findings will be uploaded to scheme ma	scussed inager as soon	
mechanism(s) and probable cause(s)	HD28 Secondary sites identifi	nce of below zero is recorded over the full sche		
	recommendation to improve the through the scheme.	ne skid resistance. There are also a number of	potholes foun	
20. Justification for Works	recommendation to improve the through the scheme. The scheme was identified as performance across the network both of which underwent Secondarian to improve skid resistance. The areas of the company, namely departments. There have bee local media attention. The scheme also areas of cracking/ crapond. As well as the recent acres.	a result of HD28 Investigations into skid resist ork. There are two HD28 sites located within so andary Investigation receiving recommendation be problems at this location have also been ide to the Routine Maintenance and Strategic Road in a number of recent accidents at this location have as SCRIM difference below zero through by the carriageway edge which could allocated to the work of the could allocated the strategic Road and the strategic Road in the st	potholes found ance cheme extents, as for treatment ntified by other Safety resulting in aghout. There	
Works	recommendation to improve the through the scheme. The scheme was identified as performance across the network both of which underwent Secondary to improve skid resistance. The areas of the company, namely departments. There have bee local media attention. The scheme are also areas of cracking/ crapond. As well as the recent activities within the previous three years.	a result of HD28 Investigations into skid resist ork. There are two HD28 sites located within so andary Investigation receiving recommendation be problems at this location have also been ide to the Routine Maintenance and Strategic Road in a number of recent accidents at this location have as SCRIM difference below zero through by the carriageway edge which could allocated to the work of the could allocated the strategic Road and the strategic Road in the st	ance cheme extents, is for treatment on tified by other Safety resulting in lighout. There we water to	
20. Justification for Works PROPOSED OPTIONS 21. Sustainability Options Considered	recommendation to improve the through the scheme. The scheme was identified as performance across the network both of which underwent Secondary to improve skid resistance. The areas of the company, namely departments. There have bee local media attention. The scheme also areas of cracking/ crappond. As well as the recent act within the previous three years. Waste is to be minimised on a methods.	ne skid resistance. There are also a number of a result of HD28 Investigations into skid resist ork. There are two HD28 sites located within so ondary Investigation receiving recommendation be problems at this location have also been ide to the Routine Maintenance and Strategic Road in a number of recent accidents at this location teme has a SCRIM difference below zero through by the carriageway edge which could allocated by the carriageway edge which could allocated be seen that all planings are to be recycled using State and all planings are to be recycled using State and all planings are to be recycled using State and all planings are to be recycled using State and all planings are to be recycled using State and all planings are to be recycled using State and all planings are to be recycled using State and all planings are to be recycled using State and all planings are to be recycled using State and all planings are to be recycled using State and S	potholes foundance cheme extents, as for treatmen ntified by other Safety resulting in Ighout. There we water to noted in IRIS	
Works PROPOSED OPTIONS 21. Sustainability	recommendation to improve the through the scheme. The scheme was identified as performance across the network both of which underwent Secondary to improve skid resistance. The areas of the company, namely departments. There have bee local media attention. The scheme also areas of cracking/ crappond. As well as the recent act within the previous three years. Waste is to be minimised on smethods. The Do Something Option involutional area of 100m length patches, pending the findings identified issues, preventing further scheme.	ne skid resistance. There are also a number of a result of HD28 Investigations into skid resist ork. There are two HD28 sites located within so ondary Investigation receiving recommendation be problems at this location have also been ide of the Routine Maintenance and Strategic Road in a number of recent accidents at this location heme has a SCRIM difference below zero through a scidents, two wet skid accidents have also been section and all planings are to be recycled using Scille and all planings are to be recycled usin	potholes foundance cheme extents, is for treatmentified by other Safety resulting in Ighout. There we water to in noted in IRIS EPA approved 50mm Inlay, cover an 100mm Inlay dress the	
Works PROPOSED OPTIONS 21. Sustainability Options Considered 22. Do Something	recommendation to improve the through the scheme. The scheme was identified as performance across the network both of which underwent Secondary to improve skid resistance. The areas of the company, namely departments. There have been local media attention. The scheme are also areas of cracking/ crappond. As well as the recent act within the previous three years. Waste is to be minimised on smethods. The Do Something Option involutional area of 100m length patches, pending the findings identified issues, preventing further the interest of the safety of the Do Minimum Option involutional out reactive maintenant.	ne skid resistance. There are also a number of a result of HD28 Investigations into skid resist ork. There are two HD28 sites located within so ondary Investigation receiving recommendation be problems at this location have also been ide of the Routine Maintenance and Strategic Road in a number of recent accidents at this location heme has a SCRIM difference below zero through a single by the carriageway edge which could allocated be seen to be recycled using Scholers, two wet skid accidents have also been seen and all planings are to be recycled using Scholers treating the full scheme extents, using a with 68PSV. An allowance has been made to a per lane which has been set aside for deeper of Investigation works. This option will best adout the road user.	potholes foun ance cheme extents is for treatmen ntified by other Safety resulting in Ighout. There we water to n noted in IRIS EPA approved 50mm Inlay, cover an 100mm Inlay dress the improvements aree years,	


	Option Title		Discounted WLC (£)		Discounted (orks Cost(£)	Commer	nts	
	Do Something			50mm Inlay, with 100m length per lane allowance for deeper 100mm Inlay patching.				
25. Whole Life Costing Results	Do Minimum					Reactive patching for three years, followed by Do Something treatment. Patching of HD28 secondary sites in year 1.		
	Add other option and more lines required).							
PROPOSED WORKS								
26. Proposed Works	The proposed we money, and be	vorks a st addr	are to use the Do ess the cause of	Somet recent	hing option. This accidents at this	will provi location.	de the best value for	
					Weighting		Un-weighted Score	
	Safety				0.3	4.50	8	
27. Preliminary Value Management Score	Journey Time Reliability				0.2	2.20		
	Environmental Sustainability				0.1		2.0	
							VfM Indicator	
	Value for Money				0.4		0.22	
	Importance Ranking			Rank 3 - Hybrid Scheme				
28. Disability Discrimination Act	We confirm that barriers to accessibility have been considered and the DDA proforma has been signed off for this scheme by both the Operating Company and Transport Scotland ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐					⊠ Tick to confirm		
(DDA)	Enter any reason why box was not ticked or any other relevant information.							
29. Network Operations	Network Operation Equipment affected? No							
Equipment	If Yes, Enter Details of Network Operations Equipment and works required.							
	Year Activites					Estimated Cost		
	2016/2017	A Committee of the Comm	stigation			£		
30. Proposed Works	2016/2017	Desi	\$100 m			£		
Cost Estimates	2016/2017 2016/2017		truction ronmental			£		
	2016/2017	XXX	ommentar			£		
	2010/2017				TOTA	AL £		
sale from a price is	M	andato	ory:	Other attachments (list):				
	Visual Condition S	urvey	☑ Tick to confirm	Core L	.ogs	□ Ti	ck to confirm	
31. Attached information	Scheme Photograp	ohs	☑ Tick to confirm	As stated in Sect. 18, co scheme manager followi Investigation works.		core logs wing con	will be uploaded to apletion of	
	IRIS Data Graphs		☑ Tick to confirm					
	WLC/VfM report	CONT.	☑ Tick to confirm					

33. Statement of Intent Agreement: Type and Extent of Pavement and Non- Pavement	Operating Company Representative name Signature		Date	
			22/11/2016	
	Transport Scotland Representative name	Signature	Date	
Treatments			2/12/16	
SOI DOCUMENT HIS	TORY			
Revision number	Date Issued	Comments		
	22/11/2016	Updated sect.25&27 from prev.		

Resurfacing



Street Works Report



16:13

07:00

07:00

Width

0.00

Works Details

Works Ref:

XQ001-NW164317

LAREF: Address: 2190437

A83T SOUTH OF CAIRNDOW FROM A815 JUNCTIO

CAIRNDOW

Town: County: CAIRNDOW ARGYLL AND BUTE

Works Type:

ROAD RESTRICTION

Engineering Difficulty

Project:

Promoter:

Transport Scotland - NW Unit Op Company / TRO North West Transport Scotland - NW Unit Op Company / TRO North West

Notifiable Authority: NSG Ref:

10/10760

Carriageway Reinst.:

Traffic Management:

Location:

Description:

Cairndow

Carriageway Resurfacing

Easting: CARRIAGEWAY TYPE 2 - 2.5 TO 10 MS

CONVOY WORKING

218141.49 Northing:

Footway Reinst.:

Works Technique.:

Works Recorded Date: 28/11/2016

Proposed start date: 16/12/2016

Estimated end date: 21/12/2016

710229.82

Postcode

Actual start date: 16/12/2016

Latest Notice Type: WORKS CLOSED

MACHINE

Username

Depth

STD

STD

Length

0.00

Status: WORKS CLOSED

Sites

1

Site Surface Location

Site status PROPOSED SITE

> Length: Width:

Site Location

0.00

0.00

Cairndow

Depth Code:

Easting: Northing:

Surface Type:

Dimensions:

Interim Reinstatement Date:

Permanent Reinstatement Date:

Made date/time

9:23

13:52

9:42

Tel No.

29/11/2016

29/11/2016

07/12/2016

Comments

AR001

No.

OD

SS001

Type

COMMENT OR INFORMATION

Trunk Road, no input. Route is Maintained by the Scottish Executive.

COMMENT OR INFORMATION

CUSTOMER HAS ACCESS TO SSE WEBSITE TO OBTAIN CABLE RECORDS

COMMENT OR INFORMATION

AR001 Trunk Road, no input. Route is Maintained by the Scottish Executive.

Contact type **ORIGINATOR**

CONTRACTOR

Contacts

Contact name

Address **BEARSCOTLAND**

BEAR Scotland Ltd

NW Roadspace

INVERALMOND ROAD INVERALMOND INDUSTRIAL ESTATE

PERTH

PH1 3TW

BEARSCOTLAND

INVERALMOND ROAD

INVERALMOND INDUSTRIAL ESTATE

PERTH PH1 3TW

APPLICANT

BEARSCOTLAND

INVERALMOND ROAD

INVERALMOND INDUSTRIAL ESTATE

PERTH PH1 3TW

History

Date/Time 28/11/2016

29/11/2016

7:57

Event Type

16:13 WORKS RECORDED

WORKS STATUS CHANGED

Details

POTENTIAL WORKS: 12/03/2017 - 13/03/2017 POTENTIAL WORKS to PROPOSED WORKS

Username



Qualification Ref

29/11/2016	7:57	THREE MONTHS	PROPOSED WORKS: 12/03/2017 13/03/2017	
29/11/2016	7:59	SEVEN DAY	PROPOSED WORKS: 12/12/2016 - 13/12/2016	建 区 图图 65.
29/11/2016	8:17	VIEW NOTICE ASSESSMENT	SW100	
29/11/2016	8:17	NOTICE ASSESSMENT	SW100-Plans Required	
29/11/2016	9:22	VIEW NOTICE ASSESSMENT	AR001	
29/11/2016	9:23	COMMENT OR INFORMATION	AR001-Trunk Road, no input. Route is Maintained by	
29/11/2016	9:23	NOTICE ASSESSMENT	AR001-Plans Required	
29/11/2016	10:07	VIEW NOTICE ASSESSMENT	SG002	337 Det.
29/11/2016	10:07	NOTICE ASSESSMENT	SG002-Plans Required	
29/11/2016	13:49	VIEW NOTICE ASSESSMENT	SS001	
29/11/2016	13:52	COMMENT OR INFORMATION	SS001-CUSTOMER HAS ACCESS TO SSE WEBSITE	
29/11/2016	13:52	NOTICE ASSESSMENT	SS001-Plans Required	
30/11/2016	11:40	COMMENT ASSESSMENT	XQ001	
	11:40	COMMENT ASSESSMENT	XQ001	A PRINCIPAL S
05/12/2016		WORKS DETAILS CHANGED	PROPOSED WORKS: 13/12/2016 - 16/12/2016	
05/12/2016		SEVEN DAY	PROPOSED WORKS: 13/12/2016 - 16/12/2016	
05/12/2016		NOTICE ASSESSMENT	SW100-High Interest	
05/12/2016		NOTICE ASSESSMENT	SG002-High Interest	
07/12/2016	9:41	VIEW NOTICE ASSESSMENT	AR001	
07/12/2016	9:42	COMMENT OR INFORMATION	AR001-Trunk Road, no input. Route is Maintained by	
07/12/2016	9:48	NOTICE ASSESSMENT	AR001-High Interest	
07/12/2016		COMMENT ASSESSMENT	XQ001	
09/12/2016		WORKS DETAILS CHANGED	PROPOSED WORKS: 15/12/2016 - 20/12/2016	
		SEVEN DAY	PROPOSED WORKS: 15/12/2016 - 20/12/2016 PROPOSED WORKS: 15/12/2016 - 20/12/2016	
09/12/2016				
12/12/2016	7:39	NOTICE ASSESSMENT	SW100-High Interest	
12/12/2016	9:05	NOTICE ASSESSMENT	SG001-High Interest	
12/12/2016	9:19	VIEW NOTICE ASSESSMENT	AR001	
12/12/2016	9:19	NOTICE ASSESSMENT	AR001-High Interest	
15/12/2016		WORKS DETAILS CHANGED	PROPOSED WORKS: 16/12/2016 - 21/12/2016	
15/12/2016		SEVEN DAY	PROPOSED WORKS: 16/12/2016 - 21/12/2016	
15/12/2016	10:54		XQ001-NW164525 Same Street - Dates Overlap	型 等 加入交流
15/12/2016		VIEW NOTICE ASSESSMENT	XQ001	
15/12/2016		MAP RESOLVED	USER	
15/12/2016		NOTICE ASSESSMENT	SW100-High Interest	
15/12/2016	12:53	NOTICE ASSESSMENT	AR001-High Interest	
16/12/2016	8:53	WORKS STATUS CHANGED	PROPOSED WORKS to IN PROGRESS	
16/12/2016	8:53	ACTUAL START	IN PROGRESS: 16/12/2016 - 21/12/2016	
16/12/2016	8:56	NOTICE ASSESSMENT	SW100-Low Interest	Branch Branch
16/12/2016	13:49	NOTICE ASSESSMENT	SG002-Low Interest	
20/12/2016	8:14	NOTICE ASSESSMENT	AR001-Low Interest	
22/12/2016	8:45	WORKS STATUS CHANGED	IN PROGRESS to WORKS CLOSED	
22/12/2016	8:45	WORKS CLOSED	WORKS CLOSED: 16/12/2016 - 21/12/2016	
22/12/2016	9:17	NOTICE ASSESSMENT	SW100-Low Interest	
22/12/2016	11:48	NOTICE ASSESSMENT	SG002-Low Interest	
22/12/2016	14:20	NOTICE ASSESSMENT	AR001-Low Interest	
12/01/2017	14:43	NOTICE ASSESSMENT	TL001-Plans Required	
16/02/2017	14:32	NOTICE ASSESSMENT	SP008-Plans Required	
07/04/2017	10:59	NOTICE ASSESSMENT	SS001-Low Interest	
29/06/2017	8:52	NOTICE ASSESSMENT	SS002-Plans Required	The Annual Control of the Control of
Designa	tions		A CONTRACTOR OF THE PARTY OF TH	
Type			Validity Start date	End date
	IGINEE	RING DIFFICULTY	EVERYDAY	
		the A815 Junction	Teroperation HDS/NIGUESE	
Δ83 70 (273 Cul	vert		

EVERYDAY

A83 70 C73 Culvert

A83 70 C77 Culvert


SPECIAL ENGINEERING DIFFICULTY

2km North of the A815 Junction

SPECIAL ENGINEERING DIFFICULTY 500m West of the A815 Junction A83 70 C59 Culvert

EVERYDAY

Street Works Report



13:29

09:30 09:30

Works Details

Works Ref:

BT015-AMBO-WS0PYP64-P2

LAREF:

Town:

2084004

A83T SOUTH OF CAIRNDOW FROM A815 JUNCTIO Address:

CAIRNDOW

County:

CAIRNDOW ARGYLL AND BUTE

Works Type:

MINOR WITHOUT EXCAVATION

Engineering Difficulty

CAIRNDOW Project:

Promoter:

Location:

Sites

Description:

Dimensions:

Openreach / BT SAFE DIG

Notifiable Authority: NSG Ref: 10/10760

Transport Scotland - NW Unit Op Company / TRO North West

Easting:

Carriageway Reinst.:

Traffic Management:

Site Surface Location

CARRIAGEWAY TYPE 2 - 2.5 TO 10 MS

PORTABLE TRAFFIC LIGHTS (TTLS)

Approx 485m South of Junc with Cairndow Village A83T South of Cairndon from A815 Junc to North Junc with

WORKING IN A CARRIAGEWAY MANHOLE, TRAFFIC LIGHT APPLICATION FORM WILL BE

Site status

SITE CLOSED NOX

Length:

Site Location

0.00

PROVIDED BY A-PLANT LUX. NO EXCAVATIONS PLANNED.

Approx 485m South of June with Cairne

Depth Code:

Northing:

218236.50 Northing:

Footway Reinst.:

Works Technique.:

Permanent Reinstatement Date:

Made date/time

Width:

0.00 Easting:

Surface Type:

Type

Interim Reinstatement Date:

NW161513

No.

Comments

OD

XQ001

COMMENT OR INFORMATION

02/05/2016 11:38

Contacts Contact type Contact name ORIGINATOR

Address **EDMONTON TE** STERLING WAY

> LONDON N18 1QP Site Office

TRAFFIC SIGNAL SIA-Plant Lux Ltd

6 South Wardpark Court Wardpark South

Cumbernauld Glasgow G67 3EH

Tel No.

Works Recorded Date: 28/04/2016

Proposed start date: 11/05/2016

Estimated end date: 11/05/2016

710874.20

Postcode

PA26 8BA

Actual start date: 11/05/2016

Latest Notice Type: WORKS CLOSED

Status: WORKS CLOSED NOX

NO EXCAVATION

Depth

NOEXC

NOEXC

Length

0.00

Width

0.00

Qualification Ref

Username


History

Date/Time		Event Type	Details
28/04/2016	13:29	WORKS RECORDED	PROPOSED WORKS: 11/05/2016 - 11/05/2016
28/04/2016	13:29	NON-NOTIFIABLE ACTIVITY	PROPOSED WORKS: 11/05/2016 - 11/05/2016
02/05/2016	11:38	COMMENT OR INFORMATION	XQ001-NW161513
09/05/2016	7:34	VIEW COMMENT ASSESSMENT	BT015
09/05/2016	7:36	COMMENT ASSESSMENT	BT015
11/05/2016	9:08	WORKS STATUS CHANGED	PROPOSED WORKS to IN PROGRESS
11/05/2016	9:08	ACTUAL START	IN PROGRESS: 11/05/2016 - 11/05/2016
12/05/2016	9:06	WORKS STATUS CHANGED	IN PROGRESS to WORKS CLOSED NOX
12/05/2016	9:06	WORKS CLOSED	WORKS CLOSED NOX: 11/05/2016 - 11/05/2016



Designations		en gerkend.	
Type	Validity	Start date	End date
SPECIAL ENGINEERING DIFFICULTY	EVERYDAY		
1600m North of the A815 Junction			
A83 70 C73 Culvert			
SPECIAL ENGINEERING DIFFICULTY	EVERYDAY		
2km North of the A815 Junction			
A83 70 C77 Culvert			
SPECIAL ENGINEERING DIFFICULTY	EVERYDAY		
500m West of the A815 Junction			
A83 70 C59 Culvert			

Street Works Report



13:41

Works Details

Works Ref:

BT021-1161066/2

LAREF:

2120243

Address: A83T SOUTH OF CAIRNDOW FROM A815 JUNCTIO

CAIRNDOW

Town:

CAIRNDOW

County: Works Type:

STANDARD

ARGYLL AND BUTE **Engineering Difficulty**

Project:

IBN5HKHJ

Promoter:

Notifiable Authority: NSG Ref:

10/10760

Carriageway Reinst .:

Traffic Management:

Location: Description:

Openreach / BT KNN (BDUK) Transport Scotland - NW Unit Op Company / TRO North West

219106.55 Northing:

CARRIAGEWAY TYPE 2 - 2,5 TO 10 MS

STOP/GO BOARDS TRAFFIC CONTROL

Easting:

(CAIRNDOWE ARROCHAR) ON A83T FROM A815 JUNCTION TO

709904,42 Footway Reinst.:

Postcode

Works Recorded Date: 06/07/2016

Proposed start date: 22/07/2016

Estimated end date: 02/08/2016

Actual start date: 22/07/2016

Latest Notice Type: REGISTRATION

MACHINE

Status: WORKS CLOSED

COMPLETE NON EXCAVATION OVERBLOW

Sites

Site Surface Location 1 VERGE

Site status SITE PERMANENT

Site Location

(CAIRNDOWE ARROCHAR) ON A83T

STD STD

Depth

1.00

Length

Width 0.50

Dimensions:

Length: Width:

GRASS

1.00 0.50

Easting: Northing:

Depth Code:

Surface Type: Interim Reinstatement Date:

Permanent Reinstatement Date:

Works Technique.:

02/08/2016

Comments

No.

OD 1 XQ001 Processed under NW162373

Type

COMMENT OR INFORMATION

COMMENT OR INFORMATION

Made date/time 11/07/2016 13:27

21/07/2016

15/07/2016 9:11

13:45

Username

AR001

Trunk Road, no input, Route is Maintained by the Scottish Executive. COMMENT OR INFORMATION

XQ001

No objection to an early start of 22/7/16

ORIGINATOR

Contacts Contact type

Contact name

Conal keeney

Karen McFarlane

Address

45-47 Hawbank Road

Tel No. 07896 841623

Qualification Ref

Username

CONTRACTOR

KN DL

45-47 Hawbank Road

East Kilbride

East Kilbride G74 5EX

07712324966

01355 200500

History

APPLICANT

Date/Time Event Type 06/07/2016 13:41 WORKS RECORDED 06/07/2016 13:41 **SEVEN DAY**

06/07/2016 13:41 MAP CONFLICT 06/07/2016 13:47 VIEW NOTICE ASSESSMENT

13:48 06/07/2016 NOTICE ASSESSMENT 15:21 NOTICE ASSESSMENT 06/07/2016 06/07/2016 17:38 NOTICE ASSESSMENT

07/07/2016 8:13 NOTICE ASSESSMENT 11/07/2016 13:27 COMMENT OR INFORMATION Details

PROPOSED WORKS: 15/07/2016 - 29/07/2016 PROPOSED WORKS: 15/07/2016 - 29/07/2016

BT021-1161066/1 Within 100m AR001

AR001-High Interest SW100-High Interest

SP008-High Interest SG002-High Interest

XQ001-Processed under NW162373

11/07/2016		VIEW COMMENT ASSESSMENT	BT021	
11/07/2016		COMMENT ASSESSMENT	BT021	A STATE OF
12/07/2016	9:08	VIEW NOTICE ASSESSMENT	XQ001	
12/07/2016	9:09	MAP RESOLVED	USER TAGGING	
12/07/2016	9:09	NOTICE ASSESSMENT	XQ001-High Interest	
12/07/2016	9:14	NOTICE ASSESSMENT	TL001-High Interest	
14/07/2016		WORKS DETAILS CHANGED	PROPOSED WORKS: 25/07/2016 - 05/08/2016	
14/07/2016	14:52	SEVEN DAY	PROPOSED WORKS: 25/07/2016 - 05/08/2016	一种工程
14/07/2016		MAP CONFLICT	BT021-1161066/1 Within 100m	
14/07/2016	14:52	MAP CONFLICT	BT022-S000000011385 Same Street - Dates Overlap	353153
14/07/2016	15:57	NOTICE ASSESSMENT	SW100-High Interest	
15/07/2016	7:40	VIEW NOTICE ASSESSMENT	XQ001	
15/07/2016	7:40	MAP RESOLVED	USER	
15/07/2016	7:40	NOTICE ASSESSMENT	XQ001-High Interest	
15/07/2016	8:33	NOTICE ASSESSMENT	SG002-High Interest	
15/07/2016	9:10	VIEW NOTICE ASSESSMENT	AR001	
15/07/2016	9:11	COMMENT OR INFORMATION	AR001-Trunk Road, no input. Route is Maintained by	
15/07/2016	9:12	NOTICE ASSESSMENT	AR001-High Interest	No.
15/07/2016	10:55	COMMENT ASSESSMENT	BT021	
15/07/2016	16:39	COMMENT ASSESSMENT	XQ001	
15/07/2016	16:44	NOTICE ASSESSMENT	SP008-High Interest	
19/07/2016	8:31	NOTICE ASSESSMENT	TL001-High Interest	
21/07/2016	13:45	COMMENT OR INFORMATION	XQ001-No objection to an early start of 22/7/16	2000年,66
22/07/2016	13:24	WORKS DETAILS CHANGED	PROPOSED WORKS: 22/07/2016 - 03/08/2016	
22/07/2016	13:24	SEVEN DAY	PROPOSED WORKS: 22/07/2016 - 03/08/2016	
22/07/2016	13:24	MAP CONFLICT	BT021-1161066/1 Within 100m	
22/07/2016	13:24	MAP CONFLICT	BT022-S000000011385 Same Street - Dates Overlap	
22/07/2016	13:24	WORKS STATUS CHANGED	PROPOSED WORKS to IN PROGRESS	No. 3 Stay
22/07/2016	13:24	ACTUAL START	IN PROGRESS: 22/07/2016 - 03/08/2016	
22/07/2016	14:36	VIEW COMMENT ASSESSMENT	BT021	
22/07/2016	14:36	COMMENT ASSESSMENT	BT021	
25/07/2016	15:08	MAP RESOLVED	USER TAGGING	
25/07/2016	15:08		XQ001-Low Interest	2000年1月1日
26/07/2016	10:12	WORKS DETAILS CHANGED	IN PROGRESS: 22/07/2016 - 03/08/2016	数百马克斯
26/07/2016	10:12	ERROR CORRECTION	IN PROGRESS: 22/07/2016 - 03/08/2016	
27/07/2016	8:04	NOTICE ASSESSMENT	XQ001-High Interest	和中国企业
27/07/2016	10:01		AR001-High Interest	
02/08/2016	8:59	WORKS STATUS CHANGED	IN PROGRESS to WORKS CLOSED	
02/08/2016	8:59	WORKS CLOSED	WORKS CLOSED: 22/07/2016 - 02/08/2016	
02/08/2016	9:03	SITE DETAILS CHANGED	A CONTRACTOR OF THE CONTRACTOR	B. C. Africa
02/08/2016	9:03	REGISTRATION	WORKS CLOSED: 22/07/2016 - 02/08/2016	作品。"温度
02/08/2016	9:33	NOTICE ASSESSMENT	XQ001-Low Interest	
production to the contract of	NO PROPERTY OF	CONTROL CONTROL CONTROL CONTROL OF CONTROL CON		
Designa	uuone			

Type	Validity	Start date	End date
SPECIAL ENGINEERING DIFFICULTY	EVERYDAY		
1600m North of the A815 Junction			
A83 70 C73 Culvert			
SPECIAL ENGINEERING DIFFICULTY	EVERYDAY		
2km North of the A815 Junction			
A83 70 C77 Culvert	EVEDVDAV		
SPECIAL ENGINEERING DIFFICULTY	EVERYDAY		
500m West of the A815 Junction			
A83 70 C59 Culvert			