

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 24/03/2018 and 24/06/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A82',)
(Section Code is 10863/00) Or

(Section Code is 10864/00) Or

(Section Code is 10864/70)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
10863/00 : S BALLACHULISH RBT TO KINLOCHLEVEN JUNC B863									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 27 March 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 03 April 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 10 April 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 17 April 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 24 April 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 01 May 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 08 May 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 15 May 2018									
NW34347682-235787798	240m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	12/06/2018	Completed Defects	15/05/2018	BALLACHULISH
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 22 May 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 29 May 2018									
NW34353796-235815655	656m	656m	FOOTWAY	Slab rocking (SROK)	3RD PTY	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLACHULISH BRIDGE
NW34353796-235815656	653m	653m	FOOTWAY	Missing (MISS)	3RD PTY	26/06/2018	Awaiting CCMS Temp Date	01/01/9999	BALLACHULISH BRIDGE
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 05 June 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 12 June 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 15 June 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 18 June 2018									
NW34364646-235858200	964m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	19/06/2018	Completed Defects	18/06/2018	BALLACHULISH BRIDGE
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 22 June 2018									
No defects recorded									
10864/00 : KINLOCHLEVEN JUNC B863 TO CUILCHENNA HOUSE									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 27 March 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 03 April 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 10 April 2018									
NWG23-335455-235618940	2,357m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/04/2018	Completed Defects	10/04/2018	ONICH HOTEL
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 17 April 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG23-337466-235641489	1,827m	0m	GULLY	Blockage (BLOK)	CAT 1	15/05/2018	Completed Defects	26/04/2018	BUS STOP ONICH HALL
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 24 April 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 01 May 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 08 May 2018									
NW34344787-235705755	103m	0m	GULLY	Rocking under load (IRLD)	CAT 1	05/06/2018	Completed Defects	04/06/2018	NORTH BALLACHULISH
NW34344787-235705754	3,416m	0m	GULLY	Difference in level with road (IDLV)	CAT 1	05/06/2018	Completed Defects	04/06/2018	PRIOR TO STRATHLINNHE COTTAGES ONICH
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 15 May 2018									
NW34347682-235787795	3,482m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	12/06/2018	Completed Defects	06/06/2018	ONICH
NW34347682-235787796	3,417m	0m	GULLY	Rocking under load (IRLD)	CAT 1	12/06/2018	Completed Defects	05/06/2018	STRATHLINNHE
NW34347682-235787797	3,203m	0m	MANHOLE	Rocking under load (IRLD)	3RD PTY	12/06/2018	Awaiting CCMS Temp Date	01/01/9999	HIGHLAND CROFT ACCESS ONICH
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 22 May 2018									
NW35350725-235803796	108m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/05/2018	Completed Defects	22/05/2018	NORD OF BALLACHULISH
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 29 May 2018									
NW34353796-235815657	810m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/05/2018	Completed Defects	29/05/2018	ONICH FILLING STATION
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 05 June 2018									
NW34357164-235820072	3,009m	0m	MANHOLE	Rocking under load (IRLD)	3RD PTY	03/07/2018	Awaiting CCMS Temp Date	01/01/9999	OUTSIDE ONICH TEAROOM
NW34357164-235820073	2,966m	0m	MANHOLE	Rocking under load (IRLD)	3RD PTY	03/07/2018	Awaiting CCMS Temp Date	01/01/9999	ONICH
NW34357164-235820074	1,816m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/06/2018	Completed Defects	05/06/2018	ONICH
NW34357164-235820107	116m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	NORTH BALLACHULISH
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 12 June 2018									
NW34360527-235844247	3,548m	0m	GULLY	Rocking under load (IRLD)	CAT 1	10/07/2018	Completed Defects	28/06/2018	GOLLANFIELD, ONICH
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 15 June 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 18 June 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 22 June 2018									
NW34364839-235858171	3,705m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	23/06/2018	Completed Defects	22/06/2018	ONICH
NW34364839-235858172	1,815m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	20/07/2018	Completed Defects	06/07/2018	PRIOR TO LODGES ON THE LOCH ONICH
10864/70 : CUILCHENNA HO TO A861 CORRAN FERRY JUNCTION									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 27 March 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 03 April 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG23-332647-235614524	228m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/04/2018	Completed Defects	03/04/2018	ONICH
NWG23-332647-235614525	190m	0m	FOOTWAY	Other (OTHR)	CAT 1	01/05/2018	Completed Defects	24/04/2018	ONICH
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 10 April 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 17 April 2018									
NWG23-337466-235641488	599m	0m	GULLY	Blockage (BLOK)	CAT 1	15/05/2018	Completed Defects	26/04/2018	ONICH
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 24 April 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 01 May 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 08 May 2018									
NW34344787-235705752	1,750m	0m	GULLY	Broken (BROK)	CAT 1	05/06/2018	Completed Defects	04/06/2018	CORRAN FRY
NW34344787-235705753	1,882m	0m	GULLY	Broken (BROK)	CAT 1	05/06/2018	Completed Defects	04/06/2018	CORRAN FERRY
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 15 May 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 22 May 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 29 May 2018									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 05 June 2018									
NW34357164-235820071	1,748m	0m	GULLY	Broken (BROK)	CAT 1	03/07/2018	Completed Defects	28/06/2018	CORRAN FERRY
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 12 June 2018									
NW34360527-235844210	1,796m	0m	GULLY	Cracked or broken (IBCK)	CAT 1	10/07/2018	Completed Defects	28/06/2018	CORRAN FERRY
NW34360527-235844248	1,755m	0m	GULLY	Cracked or broken (IBCK)	CAT 1	10/07/2018	Completed Defects	28/06/2018	CORRAN FERRY
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 15 June 2018									
NW34364838-235858168	1,752m	0m	GULLY	Other (OTHR)	CAT 1	13/07/2018	Completed Defects	15/06/2018	CORRAN FERRY
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 18 June 2018									
NW34364646-235858201	1,751m	0m	GULLY	Other (OTHR)	CAT 1	16/07/2018	Completed Defects	18/06/2018	CORRAN FERRY
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 22 June 2018									
NW34364839-235858169	1,118m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 1	20/07/2018	Completed Defects	16/07/2018	BUNREE
NW34364839-235858170	1,011m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	20/07/2018	Completed Defects	11/07/2018	PRIOR TO BUNREE