

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/10/2017 and 01/12/2017, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'DIPPLE,FACTORY ENTRANCE TO A719 JUNCTION'), Or

(Section is 'A719 JCT TO STH END TURNBERRY CLIMBING LANE'),

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|--|---------|--------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|--|
| 11622/59 : DIPPLE,FACTORY ENTRANCE TO A719 JUNCTION | | | | | | | | | |
| Safety Inspection of A77 Ayr South V1 on 05 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A77 Ayr South V1 on 12 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A77 Ayr South V1 on 19 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A77 Ayr South V1 on 26 October 2017 | | | | | | | | | |
| SW82315666-235445930 | 305m | 306m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 23/11/2017 | Completed Defects | 13/11/2017 | A77 NB CW, 150M STH OF DIPPLE FACTORY, OPPOSITE LAYBY |
| Safety Inspection of A77 Ayr South V1 on 02 November 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A77 Ayr South V1 on 09 November 2017 | | | | | | | | | |
| SW82316119-235470414 | 2,396m | 2,406m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 07/12/2017 | Completed Defects | 05/12/2017 | A77 ON CL, 100M STH OF TURNBURY STH GATEWAY |
| Safety Inspection of A77 Ayr South V1 on 16 November 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A77 Ayr South V1 on 23 November 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A77 Ayr South V1 on 30 November 2017 | | | | | | | | | |
| SW82316486-235485394 | 301m | 302m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 28/12/2017 | Completed Defects | 16/12/2017 | A77 NB CW, 300M NTH OF DIPPLE FACTORY OPPOSITE LAYBY, NTH OF GIRVAN |
| SW82316486-235485395 | 318m | 320m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 28/12/2017 | Completed Defects | 16/12/2017 | A77 NB CW, 350M NTH OF DIPPLE FACTORY, OPPOSITE LAYBY, NTH OF GIRVAN |
| 11626/04 : A719 JCT TO STH END TURNBERRY CLIMBING LANE | | | | | | | | | |
| Safety Inspection of A77 Ayr South V1 on 05 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A77 Ayr South V1 on 12 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A77 Ayr South V1 on 19 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A77 Ayr South V1 on 26 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A77 Ayr South V1 on 02 November 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A77 Ayr South V1 on 09 November 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A77 Ayr South V1 on 16 November 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A77 Ayr South V1 on 23 November 2017 | | | | | | | | | |
| SW82316384-235479135 | 54m | 55m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 21/12/2017 | Completed Defects | 06/12/2017 | A77 NB CW, 40M NTH OF MAIDENS JCT, TURNBURY |
| Safety Inspection of A77 Ayr South V1 on 30 November 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |

