

Highways  
Operational Control Room Statistics - 08 December 2017  
All Contracts

Incident	Contract	Issued	Arrived	Closed	Response Time	Duration on Site	Source	Responder	Category	Type	Description	Route	Direction	Junction	Co-ordinates	Link Section	Location
<a href="#">230575</a>	ASE	08/12/2017 08:00	08:00	09:00	00:00	01:00	SE2	SE2 (TRISS)	Minor	Breakdown	SE2 attended a BDV.	M8	Eastbound	2 - 1	315081, 671634	11302/27	Hard shoulder
<a href="#">230596</a>	ASE	08/12/2017 11:15	11:15	11:45	00:00	00:30	SE2	SE2 (TRISS)	Minor	Breakdown	SE2 attended a BDV.	M8	Eastbound	3a - 3	301862, 669306	11311/20	Hard shoulder
<a href="#">230598</a>	ASE	08/12/2017 13:25	13:25	14:40	00:00	01:15	SE2	SE2 (TRISS)	Minor	Breakdown	BDV attended by SE2.	M8	Eastbound	2 - 3	309487, 671284	11310/14	Hard shoulder
<a href="#">230608</a>	ASE						Amey OCR	SE2 (TRISS)	Major	Road Traffic Collision	HGV on its side reported by Traffic Scotland	M8	Eastbound	3 - 2	310990, 671168	11310/08	Lanes 1 and 2 prior to junction 2