

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 17/11/2017 and 20/01/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'JUNCTION DRUMELLAN TO SMITHSTON BRIDGE',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
11632/05 : JUNCTION DRUMELLAN TO SMITHSTON BRIDGE									
Safety Inspection of A77 Ayr South V1 on 23 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 30 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 07 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 14 December 2017									
SW82316869-235496149	1,102m	1,103m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/01/2018	Completed Defects	09/01/2018	A77 NB CW, 200M STH OF DALRYMPLE JCT, STH OF SMITHSTON BRIDGE
SW82316869-235496150	1,331m	1,332m	GULLY	Blockage (BLOK)	CAT 1	11/01/2018	Completed Defects	18/12/2017	A77 NB CW, AT DALRYMPLE JCT, STH OF SMITHSTON BRIDGE
Safety Inspection of A77 Ayr South V1 on 21 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 28 December 2017									
SW82317141-235513280	590m	591m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/01/2018	Completed Defects	05/03/2018	A77 NB CW, APPROX 1 MILE NTH MAYBOLE NTH
Safety Inspection of A77 Ayr South V1 on 04 January 2018									
SW82317326-235513687	1,220m	1,221m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	22/01/2018	nb cw north of neth culzean farm at one mile reduce speed now sign
SW82317326-235513688	642m	644m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	10/02/2018	100meters north of myrehill farm sb cw
SW82317326-235513686	1,905m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	09/02/2018	AT JUNCTION WITH HIGH SMITHSTONE FARM AND JUST SOUTH OF FARM ENTRANCE S\B C\
SW82317326-235513689	585m	587m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	04/01/2018	15meters north of myrehill farm nb cw near centre line
Safety Inspection of A77 Ayr South V1 on 11 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 18 January 2018									
SW82317666-235521329	583m	584m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	09/02/2018	A77 SB CW, 200M STH OF LAYBY AT DRUMELLAN, NTH OF MAYBOLE
SW82317666-235521331	458m	459m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	05/03/2018	A77 NB CW, 300M STH OF LAYBY AT DRUMELLAN FARM, NTH OF MAYBOLE

