Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 16/12/2017 and 16/03/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST: EAST LODGE TO SYMINGTON SB',) Or

(Section is 'AGAINST: SYMINGTON SB TO DUTCH HOUSE RBT',) Or

(Section is 'WITH: DUTCH HOUSE ROUNDABOUT TO SYMINGTON NB',) Or

(Section is 'WITH: SYMINGTON NB TO EAST LODGE',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
11650/08 : WITH: DUTCH H	OUSE RO	DUNDA	BOUT TO SYMING	STON NB					
Safety Inspection of A76 & A77 No defects recorded	Ayr North	V1 on 19	December 2017						
Safety Patrol of A77 Ayr North SW82317041-235510681	Safety Pate 2,657m		22 December 2017 CARRIAGEWAY	Pothole (POTH)	CAT 1	19/01/2018	Completed Defects	31/01/2018	A77 NB CW, CL, AT SYMINGTON NB OFFSLIP
Safety Inspection of A76 & A77 No defects recorded	Ayr North	V1 on 26	December 2017						
Safety Patrol of A77 Ayr North SW82317163-235513437	Safety Patr 204m		29 December 2017 FENCES_AND_BA RRIERS	Accident damage (ACCD)	CAT 1	26/01/2018	Completed Defects	02/02/2018	A77 CENTER RESERVE, 120M NTH OF DUTCH HOUSE RBT, CENTER RESERVE
Safety Inspection of A76 & A77 No defects recorded	Ayr North	V1 on 02	January 2018	(1.002)					<u></u>
Safety Patrol of A77 Ayr North No defects recorded	Safety Pat	rol V1 on	05 January 2018						
Safety Inspection of A76 & A77 No defects recorded	Ayr North	V1 on 09	January 2018						
Safety Patrol of A77 Ayr North No defects recorded	•		·						
Safety Inspection of A76 & A77 No defects recorded	Ayr North	V1 on 16	January 2018						
Safety Patrol of A77 Ayr North No defects recorded	-		•						
Safety Inspection of A76 & A77 No defects recorded			·						
Safety Patrol of A77 Ayr North No defects recorded Safety Inspection of A76 & A77	-		•						
SW82318102-235532001	288m		CARRIAGEWAY	Pothole (POTH)	CAT 1	27/02/2018	Completed Defects	14/02/2018	A77 NB CW, 300M NTH OF DUTCHHOUSE RBT
SW82318102-235531999	184m	284m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/02/2018	Completed Defects	14/02/2018	A77 NB CW, LANE 1, 200M N OF DUTCHHOUSE RBT
SW82318102-235532000	242m	245m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/02/2018	Completed Defects	14/02/2018	A77 NB CW, LANE 1 250M NT OF DUTCHHOUSE RBT
Safety Patrol of A77 Ayr North No defects recorded									
Safety Inspection of A76 & A77 SW82318894-235534931	Ayr North 1,499m		February 2018 CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	07/02/2018	A77 NB CW, LANE 1, 400M ST OF HANSEL VILLAGE
SW82318894-235534932	1,760m	1,780m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	07/02/2018	A77 NB CW, LANE 1, 200M ST OF HANSEL VILLAGE
Safety Patrol of A77 Ayr North No defects recorded	Safety Pat	rol V1 on	09 February 2018						

Safety Inspection of A76 & A77 SW82319390-235542963	' Ayr North ' 98m		February 2018 CARRIAGEWAY	Pothole (POTH)	CAT 1	13/03/2018	Completed Defects	14/02/2018	A77 NB CW, LANE 1, 100M NTH DUTCH HOUSE RBT, TO 300M
Safety Patrol of A77 Ayr North No defects recorded	Safety Patr	rol V1 on	16 February 2018						
Safety Inspection of A76 & A77 SW82321390-235546234	' Ayr North ' 1,491m		February 2018 CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2018	Completed Defects	20/02/2018	A77 N/B LANE 1 NORH OF AVERAGE SPEED CAMERAS SOUTH OF HANSEL
SW82321390-235546235	1,751m	1,752m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2018	Completed Defects	21/02/2018	A77N/B LANE1 AT FARM JCT SOUTH OF HANSEL VILAGE
Safety Patrol of A77 Ayr North SW82322248-235548888	Safety Patr 1,495m		23 February 2018 CARRIAGEWAY	Pothole (POTH)	CAT 1	23/03/2018	Completed Defects	23/02/2018	A77 N/B LANE 1 30M NORTH OF AVERAGE SPEED CAMERA SOUTH OF HANSEL VILLAGE
Safety Inspection of A76 & A77 No defects recorded	Ayr North	V1 on 27	February 2018						OCCUPATION NAME OF THE OCCUPATION OF THE OCCUPAT
Safety Patrol of A77 Ayr North No defects recorded	Safety Patr	rol V1 on	02 March 2018						
Safety Inspection of A76 & A77									
SW82325502-235553021	198m	199m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	06/03/2018	A77 NB CW LANE 1, 190M NTH OF DUTCH HOUSE RBT
SW82325502-235553024	339m	340m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	06/03/2018	A77 NB CW, LANE 1, 290M NTH OF DUTCH HOUSE RBT
SW82325502-235553025	1,708m	1,709m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	07/03/2018	A77 NB CW, LANE 1, 250M STH OF HANSEL VILLAGE
SW82325502-235553022	253m	254m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	06/03/2018	A77 NB CW, LANE 1, 253M NTH OF DUTCH HOUSE RBT
SW82325502-235553023	304m	305m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	06/03/2018	A77 NB CW, LANE 1 280M NTH OF DUTCHHOUSE RBT
Safety Patrol of A77 Ayr North SW82326369-235553165	Safety Patr 1,803m		09 March 2018 CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	09/03/2018	A77 NB CW, LANE 1, AT WEXFORD FARM, 400M STH OF HANSEL VILLAGE OB
Safety Inspection of A76 & A77 No defects recorded	Ayr North	V1 on 13	March 2018						0.7% 11.022 11.23.02 02
Safety Patrol of A77 Ayr North No defects recorded	Safety Patr	rol V1 on	16 March 2018						
11650/40 : WITH: SYMINGT	ON NB T	O EAS	ΓLODGE						
Safety Inspection of A76 & A77 No defects recorded	Ayr North	V1 on 19	December 2017						
Safety Patrol of A77 Ayr North SW82317041-235510682	Safety Patr 493m		22 December 2017 CARRIAGEWAY	Pothole (POTH)	CAT 1	19/01/2018	Completed Defects	09/01/2018	A77 NB CW, LANE 1, 200M NTH OF SYMINGTON OB
SW82317041-235510683	1,142m	1,145m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/01/2018	Completed Defects	08/01/2018	A77 NB CW, LANE 2, 150M NTH OF HALFWAY HOUSE
Safety Inspection of A76 & A77 No defects recorded	Ayr North	V1 on 26	December 2017						
Safety Patrol of A77 Ayr North									
SW82317163-235513438	1,258m	1,260m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/01/2018	Completed Defects	06/03/2018	A77 NB CW, ON CL, AT END OF BUS STOP OPPOSITE BALBIRS STH OF BOG END TOLL
Safety Inspection of A76 & A77 No defects recorded			•						
Safety Patrol of A77 Ayr North SW82317357-235513858	Safety Patr 290m		05 January 2018 CARRIAGEWAY	Pothole (POTH)	CAT 1	02/02/2018	Completed Defects	13/01/2018	A77 N/B LANE 1 10M NORTH OF END OF ONSLIP FROM
				,					

SW82317357-235513860									
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	464m	466m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/02/2018	Completed Defects	31/01/2018	SYMINGTON A77 N/B LANE 1 AND LANE2 60M NORTH OF COTAGES NORTH OF ON SLIP FROM SYMINGTON
SW82317357-235513857	238m	239m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/02/2018	Completed Defects	31/01/2018	A7 N/B ON CENTRE LINE 50M NORTH OF SYMINGTON OVERBRIDGE
Safety Inspection of A76 & A77 SW82317440-235515662	Ayr North V 720m		January 2018 CARRIAGEWAY	Pothole (POTH)	CAT 1	06/02/2018	Completed Defects	31/01/2018	A77 NB CW, LANE 2, OUTSIDE HALFWAY HOUSE
SW82317440-235515649	1,196m	1,197m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/01/2018	Completed Defects	31/01/2018	A77 NB CW LANE 1, 150M NTH OF HALFWAY HOUSE NTH OF SYMINGTON
SW82317440-235515650	1,343m	1,345m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/02/2018	Completed Defects	31/01/2018	A77 NB CW, LANE 1, 350M NT OF HALFWAY HOUSE, NTH OF SYMINGTON
Safety Patrol of A77 Ayr North No defects recorded	Safety Patro	ol V1 on	12 January 2018						
Safety Inspection of A76 & A77			January 2018 CARRIAGEWAY	Pothole (POTH)	CAT 1	13/02/2018	Completed Defects	09/02/2018	LANE 1 AT ADS PRIOR TO BOGEND N\B OPPOSITE WHITELEES COTTAGES
SW82317632-235520465	1,008m	1,018m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	13/02/2018	Completed Defects	31/01/2018	LANE 2 AT THE SLIP ROAD TO OLD HALFWAY HOUSE BETWEEN SYMINGTON AND BOGENDTOLL
Safety Patrol of A77 Ayr North No defects recorded Safety Inspection of A76 & A77			•						
No defects recorded Safety Patrol of A77 Ayr North			•						
No defects recorded Safety Inspection of A76 & A77			•						
No defects recorded Safety Patrol of A77 Ayr North No defects recorded			·						
Safety Inspection of A76 & A77 SW82318894-235534934	740m		CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	07/02/2018	A77 NB CW, 600M NTH OF SYMINGTON ONSLIP
Safety Patrol of A77 Ayr North 8 SW82319109-235534717	Safety Patro 417m		09 February 2018 CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, LANE 1, 410M NT OF SYMINGTON NB ONSLIP
SW82319109-235534719	712m	722m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, ON CL, 720M NT OF SYMINGTON NB ONSLIP
SW82319109-235534718	661m	665m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, 660M NTH OF SYMINGTON NB ONSLIP
SW82319109-235534720	1,071m	1,073m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, LANE 2, OPPOSITE HALFWAY HOUSE NTH OF SYMINGTON OB
SW82319109-235534721	1,737m	1,757m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, 150M STH OF BOGEND TOLL TO BOGEND TOLL
Safety Inspection of A76 & A77 No defects recorded	Ayr North V	/1 on 13	February 2018						TOLL
Safety Patrol of A77 Ayr North No defects recorded Safety Inspection of A76 & A77	_		-						
			2010						
No defects recorded Safety Patrol of A77 Ayr North No defects recorded	Safety Patro	ol V1 on	23 February 2018						

No defects recorded Safety Patrol of A77 Ayr North	Safety Pa	trol V1 on	02 March 2018						
No defects recorded Safety Inspection of A76 & A7	7 Ayr North	n V1 on 06	March 2018						
No defects recorded									
Safety Patrol of A77 Ayr North SW82326369-235553171	n Safety Pa 850m		09 March 2018 CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, 250M STH OF HALFWAY HOUSE
SW82326369-235553173	942m	943m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, 150M STH OF HALFWAY HOUSE
SW82326369-235553177	1,656m	1,657m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, OPPOSITE SPICE ROUTE
SW82326369-235553174	998m	999m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, 100M STH OF HALFWAY HOUSE
SW82326369-235553170	800m	801m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, 300M STH OF HALFWAY HOUSE
SW82326369-235553175	1,636m	1,637m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, LANE 1, OPPOSITE SPICE ROUTE
SW82326369-235553176	1,652m	1,653m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, OPPOSITE SPICE ROUTE
SW82326369-235553172	904m	905m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, 200M STH OF HALFWAY HOUSE
Safety Inspection of A76 & A7 No defects recorded Safety Patrol of A77 Ayr North	-								
SW82328364-235586130	489m		CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW, 600M STH OF HALFWAY HOUSE ON CL
SW82328364-235586132	613m	614m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW LANE 1, 500M STH OF HALFWAY HOUSE
SW82328364-235586133	678m	679m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW LANE 2, 450M STH OF HALFWAY HOUSE
SW82328364-235586134	752m	753m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW, ON CL, 400M STH OF HALFWAY HOUSE
SW82328364-235586131	552m	553m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW ON CL, 550M STH OF HALFWAY HOUSE
11650/41 : AGAINST: EAS	T LODGE	TO SYN	MINGTON SB						
Safety Inspection of A76 & A7	7 Ayr North	v1 on 19	December 2017						
SW82316989-235510270	2,457m	2,458m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/01/2018	Completed Defects	31/01/2018	A77N/B ON CENTRE LINE OPPOSITE FIRST COTAGES 150M NORTH OF SYMINGTON N/B ON SLIP
Safety Patrol of A77 Ayr North No defects recorded	•								
Safety Inspection of A76 & A7 No defects recorded Safety Patrol of A77 Ayr North	•								
SW82317163-235513439	582m		CARRIAGEWAY	Pothole (POTH)	CAT 1	26/01/2018	Completed Defects	09/02/2018	A77 NB CL, 100M NTH OF BOG END TOLL NB ON SLIP
SW82317163-235513440	348m	350m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/01/2018	Completed Defects	09/02/2018	A77 NB CW, ON CL, 200M NTH OF BOG END TOLL NB ONSLIP
Safety Inspection of A76 & A7	7 Ayr North	v1 on 02	January 2018						
Safety Patrol of A77 Ayr North SW82317357-235513859	Safety Pa 2,457m		05 January 2018 <i>CARRIAGEWAY</i>	Pothole	CAT 1	02/02/2018	Completed	31/01/2018	A77 N/B LANE1 AND

	(POTH)			Defects		CENTRELINE 40M NORTH OF COTAGESNORTH OFSYMINGTON ON SLIP
Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018						or origination on our
No defects recorded Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018 No defects recorded						
Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018						
SW82317632-235520464 2,456m 2,457m CARRIAGEWAY	Pothole (POTH)	CAT 1	13/02/2018	Completed Defects	31/01/2018	LANE 1 200meters north of the symington nb on slip at cottages
Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018 No defects recorded						
Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018 No defects recorded						
Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018						
SW82317812-235529552 878m 880m CARRIAGEWAY	Pothole (POTH)	CAT 1	23/02/2018	Completed Defects	09/02/2018	A77 NB CW, AT BOG END TOLL NB ON SLIP
Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018 No defects recorded						
Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018 No defects recorded						
Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018						
SW82318894-235534933 2,590m 2,590m CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	07/02/2018	A77 NB CW, LANE 1, 100M NTH OF SYMINGTON ONSLIP
Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018	- 4 4	a	00/00/00/0		00/00/00/0	
SW82319109-235534716 2,447m 2,450m CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, ON CL, 300M NTH OF SYMINGTON NB ONSLIP
Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018 No defects recorded						
Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018 No defects recorded						
Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018						
No defects recorded Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018 No defects recorded						
Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018						
No defects recorded						
Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018 No defects recorded Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018						
SW82325502-235553035 2,463m 2,863m CARRIAGEWAY	Pothole	CAT 1	03/04/2018	Completed	07/03/2018	A77 NB CW, ON CL, 500M NTH
	(POTH)			Defects		OF SYMINGTON ONSLIP, TO 200M STH HALFWAY HOUSE
Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018 No defects recorded						
Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018 No defects recorded						
Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018 No defects recorded						
11650/09 : AGAINST: SYMINGTON SB TO DUTCH HOUSE R	ВТ					
Safety Inspection of A76 & A77 Ayr North V1 on 19 December 2017						
No defects recorded Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 December 2017 No defects recorded						
Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017						
SW82317095-235513358 545m 555m CARRIAGEWAY	Pothole (POTH)	CAT 1	23/01/2018	Completed Defects	01/02/2018	A77 NB CW, ON CL, OPPOSITE HANSEL VILLAGE
Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017 No defects recorded						
Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018						
SW82317274-235513678 511m 514m CARRIAGEWAY	Pothole (POTH)	CAT 1	30/01/2018	Completed Defects	02/02/2018	A7 S/B ON CENTRE LINE OPPOSITE JCT HANSEL

									VILLAGE
Safety Patrol of A77 Ayr North No defects recorded	-	•							
Safety Inspection of A76 & A77	-								
SW82317440-235515661	643m	644m CARRIAGEW		Pothole (POTH)	CAT 1	06/02/2018	Completed Defects	01/02/2018	A77 SB CW, LANE 2, OUTSIDE HANSEL VILLAGE
Safety Patrol of A77 Ayr North No defects recorded	•	•							
Safety Inspection of A76 & A77 SW82317632-235520463		v1 on 16 January 2018 2,365m CARRIAGEW	VAY	Pothole (POTH)	CAT 1	13/02/2018	Completed Defects	31/01/2018	300 M NORTH OF DUTCHHOUSE RBT LANE 1
Safety Patrol of A77 Ayr North No defects recorded	-	-							
Safety Inspection of A76 & A77 No defects recorded	Ayr North \	v i on 23 January 2018	D						
Safety Patrol of A77 Ayr North	Safety Patr	ol V1 on 26 January 2	018						
No defects recorded Safety Inspection of A76 & A77	-	-							
No defects recorded			_						
Safety Patrol of A77 Ayr North No defects recorded	Safety Patr	ol V1 on 02 February	2018						
Safety Inspection of A76 & A77 No defects recorded	7 Ayr North \	V1 on 06 February 201	18						
Safety Patrol of A77 Ayr North No defects recorded	Safety Patr	ol V1 on 09 February	2018						
Safety Inspection of A76 & A77	7 Ayr North \	V1 on 13 February 201	18						
SW82319390-235542962	2,103m	2,104m CARRIAGEW		Pothole (POTH)	CAT 1	13/03/2018	Completed Defects	13/02/2018	A77 SB CW LANE 1, 500M NTH OF DUTCH HOUSE RBT
Safety Patrol of A77 Ayr North No defects recorded	Safety Patr	ol V1 on 16 February	2018						
Safety Inspection of A76 & A77	7 Ayr North \	/1 on 20 February 201	18						
No defects recorded									
Safety Patrol of A77 Ayr North No defects recorded	Safety Patr	ol V1 on 23 February	2018						
Safety Inspection of A76 & A77 No defects recorded	7 Ayr North \	V1 on 27 February 201	18						
Safety Patrol of A77 Ayr North No defects recorded	Safety Patr	ol V1 on 02 March 201	18						
Safety Inspection of A76 & A77 No defects recorded	7 Ayr North \	V1 on 06 March 2018							
Safety Patrol of A77 Ayr North No defects recorded	Safety Patr	ol V1 on 09 March 201	18						
Safety Inspection of A76 & A77	7 Ayr North \	V1 on 13 March 2018							
SW82327521-235576666	608m	610m CARRIAGEW		Pothole (POTH)	CAT 1	10/04/2018	Completed Defects	14/03/2018	A77 SB CW, AT HANSEL VILLAGE

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018 No defects recorded