

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/08/2015 and 27/07/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section Code is 16520/05)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
16520/05 : JUNCTION A815 TO UC29 CAIRNDOW NORTH									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 05 August 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 12 August 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 19 August 2015									
No defects recorded									
NWG11127394-1334929	1,529m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	23/09/2015	Completed Defects	26/08/2015	TOP OF CAIRNDOW HILL, N/B VERGE
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 02 September 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 09 September 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 16 September 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 23 September 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 30 September 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 07 October 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 14 October 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 21 October 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 28 October 2015									
No defects recorded									
NWG11131071-1481914	1,794m	0m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	02/12/2015	Completed Defects	24/11/2015	TOP OF CAIRNDOW HILL, S/B VERGE
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 11 November 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 18 November 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 25 November 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 09 December 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 16 December 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 23 December 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 30 December 2015									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 06 January 2016									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 13 January 2016									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 20 January 2016									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 27 January 2016									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 03 February 2016									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 10 February 2016									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 17 February 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 24 February 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 02 March 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 09 March 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 16 March 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 23 March 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 30 March 2016									
NWG21142575-1783773	1,772m	0m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	27/04/2016	Completed Defects	20/04/2016	CAIRNDOW HILL
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 06 April 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 13 April 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 20 April 2016									
<i>No defects recorded</i>									
Detailed Inspection TEMPLATE of A83 A814 JCT TO ACCESS TO DUNDERARVE CASTLE on 26 April 2016									
NWG11142438-121	1,726m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CAIRNDOW HILL.
NWG11142438-125	2,155m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	@ CAIRNDOW WEST JUNCTION.
NWG11142438-125	2,155m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	@ CAIRNDOW WEST JUNCTION.
NWG11142438-116	491m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	19/05/2016	JUST WEST OF DUNOON A815 JUNCTION.
NWG11142438-117	1,044m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	TOP OF CAIRNDOW HILL.
NWG11142438-119	1,523m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CAIRNDOW HILL.
NWG11142438-123	1,576m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CAIRNDOW HILL.
NWG11142438-122	1,467m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CAIRNDOW HILL.
NWG11142438-124	1,726m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CAIRNDOW HILL.
NWG11142438-118	1,105m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	TOP OF CAIRNDOW HILL.
NWG11142438-120	1,494m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CAIRNDOW HILL.
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 27 April 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 04 May 2016									
NWG11150603-1898056	738m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/05/2016	Completed Defects	04/05/2016	JUST EAST OF CAIRNDOW EAST JCT, W/B C/WAY

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 11 May 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 18 May 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 25 May 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 01 June 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 08 June 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 15 June 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 22 June 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 29 June 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 06 July 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 13 July 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 20 July 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 27 July 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 03 August 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 10 August 2016									
NWG21177972-2110641	32m	0m	BOLLARDS	Missing (MISS)	CAT 1	07/09/2016	Completed Defects	02/09/2016	A815 DUNOON JCT W/B
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 17 August 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 24 August 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 31 August 2016									
NWG21181709-2158755	1,774m	0m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 1	01/09/2016	Completed Defects	31/08/2016	CAIRNDOW HILL S/B C/WAY
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 07 September 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 14 September 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 21 September 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 28 September 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 05 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 12 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 19 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 26 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 02 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 09 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 16 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 23 November 2016									
NWG5211642-2353273	1,185m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/11/2016	Completed Defects	23/11/2016	CAIRNDOW HILL WB CWAY

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG5211642-2353274	1,095m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/11/2016	Awaiting CCMS Permanent Date	23/11/2016	CAIRNDOW HILL WB CWAY
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 30 November 2016									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 07 December 2016									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 14 December 2016									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 21 December 2016									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 28 December 2016									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 04 January 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 11 January 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 18 January 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 25 January 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 01 February 2017									
NWG5240364-235048818	1,393m	0m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	01/03/2017	Completed Defects	01/03/2017	JUST EAST OF CAIRNDOW WEST JCT, W/B VERGE
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 08 February 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 15 February 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 22 February 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 01 March 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 08 March 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 15 March 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 22 March 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 29 March 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 05 April 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 12 April 2017									
NWG21259617-235078628	753m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/04/2017	Completed Defects	12/04/2017	JUST EAST OF CAIRNDOW JCT, W/B C/WAY
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 19 April 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 26 April 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 03 May 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 10 May 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 17 May 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 24 May 2017									
NWG7274922-235161801	1,714m	0m	DITCH	Collapsed bank (CLBK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CAIRNDOW HILL, E/B VERGE
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 31 May 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 07 June 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 14 June 2017									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 19 July 2017									
NWG11282452-235268508	0m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	OPP DUNOON A815 JCT
NWG11282452-235268507	1m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	OPP DUNOON A815 JCT WB
NWG11282452-235268506	1m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	OPP DUNOON A815 JCT WB
NWG11282452-235268509	4m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	OPP DUNOON A815 JCT
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 09 August 2017									
NW31283113-235299520	9m	0m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	06/09/2017	Completed Defects	09/08/2017	JUST INSIDE DUNOON JCT
NW31283113-235299521	0m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/09/2017	Completed Defects	06/09/2017	OPP A815 DUNOON JCT WB
NW31283113-235299523	4m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/08/2017	Completed Defects	09/08/2017	OPP A815 DUNOON JCT EB
NW31283113-235299522	2m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/08/2017	Completed Defects	09/08/2017	OPP A815 DUNOON JCT WB
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 22 November 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 13 December 2017									
NW122316783-235496080	3m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	10/01/2018	Completed Defects	10/01/2018	@ DUNOON A815 JUNCTION, FILTER LANE.
NW122316783-235496078	1m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	10/01/2018	Completed Defects	10/01/2018	@ DUNOON A815 JUNCTION, W/B C/WAY.
NW122316783-235496079	2m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	10/01/2018	Completed Defects	10/01/2018	@ DUNOON A815 JUNCTION, W/B C/WAY.
NW122316783-235496081	5m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	10/01/2018	Completed Defects	10/01/2018	@ DUNOON A815 JUNCTION, E/B C/WAY.
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 24 January 2018									
NW122317733-235528543	760m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/01/2018	Completed Defects	24/01/2018	TOP OF CAIRNDOW HILL, W/B C/WAY.
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 09 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 15 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 22 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 02 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 08 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 15 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 22 March 2018									
NW122328663-235597562	764m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	09/04/2018	NEAR CAIRNDOW EAST JUNCTION, W/B C/WAY.
NW122328663-235597563	770m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/03/2018	Completed Defects	22/03/2018	NEAR CAIRNDOW EAST JUNCTION, W/B C/WAY.
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 29 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 05 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet (Awaiting Return)									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 19 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 26 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 03 May 2018									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 10 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 17 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 24 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 31 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 07 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 14 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 21 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 28 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 05 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 12 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 19 July 2018									
<i>No defects recorded</i>									
Detailed Inspection TEMPLATE of A83 A814 JCT TO ACCESS TO DUNDERARVE CASTLE on 29 June 2018									
NWG11328944-417	2,138m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (W/B C/WAY)
NWG11328944-424	1,944m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (W/B C/WAY)
NWG11328944-420	2,041m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (E/B C/WAY)
NWG11328944-421	2,023m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (W/B C/WAY)
NWG11328944-411	598m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (E/B C/WAY)
NWG11328944-413	574m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (E/B C/WAY)
NWG11328944-428	1,889m	0m	GRIP	Detritus / Refuse (DETR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (W/B VERGE)
NWG11328944-430	2,163m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (W/B C/WAY)
NWG11328944-415	1,279m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (E/B VERGE)
NWG11328944-426	1,876m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (W/B C/WAY)
NWG11328944-419	2,075m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (W/B C/WAY)
NWG11328944-422	1,996m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (CENTRE LINE)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11328944-418	2,111m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (W/B C/WAY)
NWG11328944-423	1,976m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (W/B C/WAY)
NWG11328944-425	1,908m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (W/B C/WAY)
NWG11328944-410	81m	0m	GRIP	Detritus / Refuse (DETR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (E/B VERGE)
NWG11328944-412	649m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (E/B C/WAY)
NWG11328944-414	1,229m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (W/B VERGE)
NWG11328944-427	1,698m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (W/B VERGE)
NWG11328944-429	1,799m	0m	GRIP	Detritus / Refuse (DETR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A83 BETWEEN DUNOON A815 JCT & CAIRNDOW JCT. (E/B VERGE)

Safety Inspection of A82 A85 A83 Safety Balloch - Dalmally Inv - Tarbet on 26 July 2018
No defects recorded