

Document: 4GNW-F261	Form Statement of Intent	 
Issue: 3		
Related to: 4GNW-P93 Doc. Owner: Planned Maintenance Manager		

Page No. 1 of 21

4th Generation Term Contract for Management and Maintenance of the Scottish Trunk Road Network

North West Unit


Statement of Intent for: *A83 Cairndow (HD28)*
 Scheme Identification: *IRIS Ref 16NW0104007*
 SOI Version: *Version 1.0*

Contents


Section 1:	Statement of Intent/Scheme Approval
Section 2:	Predicted Treatment Type
Section 3-6:	IRIS output
Section 7-8:	Photographs
Section 9-10:	Additional Visual Information/RMMS output




A83 Cairndow (HD28)
Scheme Extents - Predicted Micro Scheme




A83 Cairndow (HD28)
IRIS Structural Summary Data




A83 Cairndow (HD28)
IRIS Functional Summary Data



A83 Cairndow (HD28)
IRIS Functional Summary Data




A83 Cairndow (HD28)
IRIS Safety Summary Data



[illegible]

[illegible]

A83 Cairndow (HD28)
Photograph location Plan



A83 Cairndow (HD28)
Site Photographs



Photo 1: A83 Cairndow (HD28). Section 16520/05 CH1220. Photo detailing rulling/ pothole forming in the nearside wheel tracks CL1 at the start of scheme extents.



Photo 2: A83 Cairndow (HD28). Section 16520/05 CH1255. Photo detailing cracking by nearside carriageway edge CL1.



Photo 3: A83 Cairndow (HD28). Section 16520/05 CH1350. Photo detailing open texture of the surface course, nearside wheel tracks CR1. This is prominent throughout the scheme surface area.



Photo 4: A83 Cairndow (HD28). Section 16520/05 CH1370. Photo detailing polishing to the surface, open texture also in evidence.



Photo 5: A83 Cairndow (HD28). Section 16520/05 CH1370. Photo detailing localised depression and cracking CR1.



Photo 6: A83 Cairndow (HD28). Section 16520/05 CH1400. Photo detailing edge cracking CL1.