

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/09/2018 and 11/11/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST: SLIP OFF TO A8 TO ENTRY SLIP M8 EB',) Or

(Section is 'AGAINST: SLIP WEST FERRY - SLIP TO ERSK BRIDGE',) Or

(Section is 'AGAINST: SLIP TO M898 TO CRAIGTON INT UPASS',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

13719/95 : AGAINST: SLIP OFF TO A8 TO ENTRY SLIP M8 EB

Safety Patrol of M8 A898 M898 on 01 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 04 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 08 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 11 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 15 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 18 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 22 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 25 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 29 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 02 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 06 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 08 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 13 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 16 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 20 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 23 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 27 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 20 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 03 November 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 06 November 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 10 November 2018

No defects recorded

13719/49 : AGAINST: SLIP WEST FERRY - SLIP TO ERSK BRIDGE

Safety Patrol of M8 A898 M898 on 01 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 04 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 08 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 11 September 2018

SW77-406219-236054640	420m	420m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/09/2018	Completed Defects	11/09/2018	M8 EB 300M AFTER JCT 31
SW77-406219-236054642	557m	560m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/09/2018	Completed Defects	11/09/2018	M8 EB 500M AFTER JCT 31

Safety Patrol of M8 A898 M898 on 15 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 18 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 22 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 25 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 29 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 02 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 06 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 08 October 2018

SW77-419273-236112430	551m	551m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/10/2018	Completed Defects	09/10/2018	M8 EB 500M AFTER JCT 31
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	-------------------------

Safety Patrol of M8 A898 M898 on 13 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 16 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 20 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 23 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 27 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 20 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 03 November 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 06 November 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 10 November 2018

No defects recorded

13719/03 : AGAINST: SLIP TO M898 TO CRAIGTON INT UPASS

Safety Patrol of M8 A898 M898 on 01 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 04 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 08 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 11 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 15 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 18 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 22 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 25 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 29 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 02 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 06 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 08 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 13 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 16 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 20 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 23 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 27 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 20 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 03 November 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 06 November 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 10 November 2018

No defects recorded

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/09/2018 and 11/11/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: UNDER CRAIGTON INTER TO SLIP FROM M898',) Or

(Section is 'WITH: SLIP FROM M898 - WEST FERRY INTERCHANGE',) Or

(Section is 'WITH: SLIP OFF M8 TO SLIP ROAD ENTRY WB',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

13719/00 : WITH: UNDER CRAIGTON INTER TO SLIP FROM M898

Safety Patrol of M8 A898 M898 on 01 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 04 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 08 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 11 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 15 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 18 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 22 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 25 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 29 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 02 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 06 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 08 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 13 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 16 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 20 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 23 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 27 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 20 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 03 November 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 06 November 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 10 November 2018

No defects recorded

13719/06 : WITH: SLIP FROM M898 - WEST FERRY INTERCHANGE

Safety Patrol of M8 A898 M898 on 01 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 04 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 08 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 11 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 15 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 18 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 22 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 25 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 29 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 02 October 2018

SW77-416035-236080618	1,908m	1,908m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/10/2018	Completed Defects	02/10/2018	M8 WB JCT 30-31
SW77-416035-236080619	4,203m	4,203m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/10/2018	Completed Defects	02/10/2018	M8 WB 600M PRIOR JCT 31

Safety Patrol of M8 A898 M898 on 06 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 08 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 13 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 16 October 2018

SW77-422507-236141662	614m	615m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	17/10/2018	Completed Defects	16/10/2018	M8 W/B 70M AFTER SOS BOX 949W
SW77-422507-236141664	2,264m	2,265m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	17/10/2018	Completed Defects	16/10/2018	M8 W/B 300M AFTER SOS BOX 957W
SW77-422507-236141663	2,064m	2,065m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	17/10/2018	Completed Defects	16/10/2018	M8 W/B 30M AFTER SOS BOX 957W

Safety Patrol of M8 A898 M898 on 20 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 20 October 2018

SW77-426024-236178938	478m	480m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/10/2018	Completed Defects	20/10/2018	M8 WB JCT 30 AT O/BRIGE
SW77-426024-236178939	478m	480m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/10/2018	Completed Defects	20/10/2018	M8 WB JCT 30 PRIOR TELEBOX 949
SW77-426024-236178945	478m	480m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	31/10/2018	Completed Defects	30/10/2018	M8 WB JCT 30
SW77-426024-236178944	478m	480m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	31/10/2018	Completed Defects	30/10/2018	M8 WB JCT 30

Safety Inspection of M8 A898 M898 on 23 October 2018

SW77-425730-236166827	409m	411m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/10/2018	Completed Defects	23/10/2018	M8 WB JCT 30 OBRIDGE
SW77-425730-236166829	483m	485m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/10/2018	Completed Defects	23/10/2018	M8 WB JCT 30 @ TELE BOX 949
SW77-425730-236166828	443m	443m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/10/2018	Completed Defects	23/10/2018	M8 WB JCT 30

Safety Patrol of M8 A898 M898 on 27 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 03 November 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 06 November 2018

SW77-426402-236214922	471m	473m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/11/2018	Completed Defects	06/11/2018	M8 WB JCT 30 AT TELEBOX 949
SW77-426402-236214919	461m	462m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/11/2018	Completed	06/11/2018	M8 WB JCT 30 AT O/BRIDGE

							(POTV)	Defects		
SW77-426402-236214918	454m	456m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/11/2018	Completed Defects	06/11/2018	M8 WB JCT 30 AT OBRIDGE	
SW77-426402-236214920	461m	462m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/11/2018	Completed Defects	06/11/2018	M8 WB JCT 30	
SW77-426402-236214921	467m	468m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/11/2018	Completed Defects	06/11/2018	M8 WB JCT 30 AT TELEBOX	

Safety Patrol of M8 A898 M898 on 10 November 2018

No defects recorded

13719/91 : WITH: SLIP OFF M8 TO SLIP ROAD ENTRY WB

Safety Patrol of M8 A898 M898 on 01 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 04 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 08 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 11 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 15 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 18 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 22 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 25 September 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 29 September 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 02 October 2018

SW77-416035-236080620	319m	321m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/10/2018	Completed Defects	02/10/2018	M8 WB JCT 31 TELE BOX 989W
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	----------------------------

SW77-416035-236080621	408m	408m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/10/2018	Completed Defects	02/10/2018	M8 WB JCT 31
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--------------

Safety Patrol of M8 A898 M898 on 06 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 08 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 13 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 16 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 20 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 23 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 27 October 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 20 October 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 03 November 2018

No defects recorded

Safety Inspection of M8 A898 M898 on 06 November 2018

No defects recorded

Safety Patrol of M8 A898 M898 on 10 November 2018

No defects recorded

STSV Incident Report

General Details

Incident ID	00070658
Contract	STSW
Issued	13/09/2018 08:00:51
Status	O
BeCogent Ref:	
Weather	
Other Cause	

Incident Details

Incident Cat	DEB
Incident Type	Carriageway
O/I Ref	18SW04881
Defect Ref	D-SW18236060292
Police Inc. No:	
Incident Description	
Debris	

Organisation	Contacts	Contact Phone	Contact Mobile	Contact Email
Scotland Transerv	Tango 2			

Location Details

Region	Route	Junction	Marker Post
	M8		
Location Description	MOI-SW1875229 M8 W/B J30 - 31 L1 D-SW18236060292		
Easting	242800	Northing	672333
Link/Section	13719/06		

Vehicle Response

ISURef	Time Called	Time Allocated	Time Arrived	Time Departed
TANGO 2	13/09/2018 08:00:00	13/09/2018 08:00:00	13/09/2018 08:00:00	13/09/2018 08:05:00

No Trace	False
----------	-------

Vehicles Involved

Make/Model	Vehicle Registration	Colour	Driver	Foreign Vehicle	Slight Injuries	Serious Injuries	Fatal Injuries

Damage

Action Date Actions Taken

13/09/2018 08:01:00 Cone uplifted

STSV Incident Report

General Details		Incident Details	
Incident ID	00070716	Incident Cat	DEB
Contract	STSW	Incident Type	Central Reservation
Issued	14/09/2018 15:33:20	O/I Ref	
Status	O	Defect Ref	
BeCogent Ref:		Police Inc. No:	2345
Weather	Raining no high winds	Incident Description	
Other Cause		Debris	

Organisation	Contacts	Contact Phone	Contact Mobile	Contact Email
Traffic Scotland	Traffic Scotland			

Location Details				
Region	Route	Junction	Marker Post	
	M8			
Location Description	M8 e/bJ30			
Easting		Northing	Link/Section	

Vehicle Response				
ISURef	Time Called	Time Allocated	Time Arrived	Time Departed
TANGO 2	14/09/2018 15:30:00	14/09/2018 15:30:00	14/09/2018 16:00:00	14/09/2018 16:00:00

No Trace	False
----------	-------

Vehicles Involved							
Make/Model	Vehicle Registration	Colour	Driver	Foreign Vehicle	Slight Injuries	Serious Injuries	Fatal Injuries

Damage

Action Date	Actions Taken
14/09/2018 15:33:00	Traffic Scotland reports a concrete block in L1 of M8
14/09/2018 15:33:00	T1 despatched.
14/09/2018 16:26:00	No trace.

STSV Incident Report

General Details		Incident Details	
Incident ID	00070793	Incident Cat	DA
Contract	STSW	Incident Type	Deer
Issued	17/09/2018 13:00:13	O/I Ref	18SW05010
Status	O	Defect Ref	D-SW18236079919
BeCogent Ref:		Police Inc. No:	
Weather		Incident Description	
Other Cause		Dead deer on lane 2	

Organisation	Contacts	Contact Phone	Contact Mobile	Contact Email
Scotland Transerv	Tango 2			

Location Details				
Region	Route	Junction	Marker Post	
	M8			
Location Description	MOI-SW1875410 M8 E/B Jct 30-29 D-SW18236079919			
Easting	245751	Northing	666906	Link/Section 13717/50

Vehicle Response				
ISURef	Time Called	Time Allocated	Time Arrived	Time Departed
TANGO 2	17/09/2018 13:00:00	17/09/2018 13:00:00	17/09/2018 13:00:00	17/09/2018 13:05:00

No Trace	False
----------	-------

Vehicles Involved							
Make/Model	Vehicle Registration	Colour	Driver	Foreign Vehicle	Slight Injuries	Serious Injuries	Fatal Injuries

Damage

Action Date	Actions Taken
17/09/2018 13:07:00	Deer removed

STSV Incident Report

General Details	
Incident ID	00070841
Contract	STSW
Issued	18/09/2018 16:20:27
Status	O
BeCogent Ref:	
Weather	
Other Cause	

Incident Details	
Incident Cat	DEB
Incident Type	Hard Shoulder
O/I Ref	18SW05066
Defect Ref	D-SW18236080616
Police Inc. No:	
Incident Description	
Debris - Plastic	

Organisation	Contacts	Contact Phone	Contact Mobile	Contact Email
Scotland Transerv	Tango 2			

Location Details				
Region	Route	Junction	Marker Post	
	M8			
Location Description: MOI-SW1875467 - M8 W/B J30 - 31, D-SW18236080616				
Easting	243188	Northing	672069	Link/Section: 13719/06

Vehicle Response				
ISURef	Time Called	Time Allocated	Time Arrived	Time Departed
TANGO 2	18/09/2018 16:20:00	18/09/2018 16:20:00	18/09/2018 16:20:00	18/09/2018 16:25:00
No Trace	False			

Vehicles Involved							
Make/Model	Vehicle Registration	Colour	Driver	Foreign Vehicle	Slight Injuries	Serious Injuries	Fatal Injuries

Damage

Action Date	Actions Taken
18/09/2018 16:22:00	From T2 - Debris removed

STSV Incident Report

General Details	
Incident ID	00071012
Contract	STSW
Issued	21/09/2018 12:50:37
Status	O
BeCogent Ref:	
Weather	
Other Cause	

Incident Details	
Incident Cat	DEB
Incident Type	Hard Shoulder
O/I Ref	18SW05240
Defect Ref	D-SW18236086659
Police Inc. No:	
Incident Description	
Debris - HGV Mud guard.	

Organisation	Contacts	Contact Phone	Contact Mobile	Contact Email
Scotland Transerv	Tango 2			

Location Details				
Region	Route	Junction	Marker Post	
	M8			
Location Description: MOI-SW1875659 M8 - Junction 30 E/B D-SW18236086659				
Easting	244965	Northing	669033	Link/Section: 13717/50

Vehicle Response				
ISURef	Time Called	Time Allocated	Time Arrived	Time Departed
TANGO 2	21/09/2018 12:50:00	21/09/2018 12:50:00	21/09/2018 12:50:00	21/09/2018 12:55:00
No Trace	False			

Vehicles Involved							
Make/Model	Vehicle Registration	Colour	Driver	Foreign Vehicle	Slight Injuries	Serious Injuries	Fatal Injuries

Damage

Action Date	Actions Taken
21/09/2018 12:54:00	Debris removed .

STSV Issue Report

Outside Contract Area	Depot Name	Damage	Vehicles	DCP
False		False	False	

Issue Ref	Issue Date	Issue Type	Sub Type	Status
00071217	28/09/2018 17:14:14	Customer	Complaint	Open
Status Description			Closed	Closure Date
Open			True	28/09/2018 18:34:00

Call Type	Organisation	Organisation Type	Contact Name
Online	BCogent	Transport Scotland, Traffic Scotland, PAG, BeCogent	Bcogent

Contact Address	Contact Options
	Phone: Mobile: e-mail:

Reason	Issue Description
Complaint	Customer informed bcogent of a cone out of place in roadworks

Location Description
M8 w/b J30

Road Name	Direction	Chainage	Link/Section	Easting	Northing	M/Post
M8	WB					

Section Name	Length	Speed Limit

Action Date	Contact Actions	Username
28/09/2018 17:14:00	<p>Road Defect</p> <p>Incident Information ID : 106562 Incident Date : Fri Sep 28 17:14:00 BST 2018 Issue Type : DEBRIS / ANIMALS Classification: EMERGENCY Issue Status : NEW Cust Callback : true Operator : TRANSERV Notes : Cone from roadworks has been knocked out into the middle of the road, cars having to divert.</p> <p>Agent Name : tpuk\garden.11</p> <p>Contact Information Title : ██████████ First Name : ██████████ Middle Initial : ██████████ Last Name : ██████████ Address 1 : ██████████ Address 2 : ██████████ Address 3 : ██████████ Postcode : ██████████ Telephone : ██████████ Email :</p> <p>Location Information Easting : 0 Northing : 0 Road Name : M8 (J8 to J31) Carriageway : WESTBOUND Location Notes : M8 roadworks at the Erskine bridge</p> <p>First Created : 28/09/2018 17:14</p>	██████████
28/09/2018 17:14:00	Contacted traffic management at M8 Roadworks.	██████████

STSV Incident Report

General Details	
Incident ID	00071421
Contract	STSW
Issued	05/10/2018 08:26:40
Status	O
BeCogent Ref:	
Weather	Fine no high winds
Other Cause	

Incident Details	
Incident Cat	DEB
Incident Type	Hard Shoulder
O/I Ref	18SW05583
Defect Ref	D-SW18236111989
Police Inc. No:	
Incident Description	
Tyre debris	

Organisation	Contacts	Contact Phone	Contact Mobile	Contact Email
Scotland Transerv	Tango 2			

Location Details				
Region	Route	Junction	Marker Post	
	M8			
Location Description	MOI-SW1876500, M8 J31 e/b, D-SW18236111989			
Easting	240739	Northing	672992	Link/Section 13719/49

Vehicle Response

ISURef	Time Called	Time Allocated	Time Arrived	Time Departed
TANGO 2	05/10/2018 08:25:00	05/10/2018 08:25:00	05/10/2018 08:25:00	05/10/2018 08:30:00

No Trace	False
----------	-------

Vehicles Involved

Make/Model	Vehicle Registration	Colour	Driver	Foreign Vehicle	Slight Injuries	Serious Injuries	Fatal Injuries

Damage

Action Date Actions Taken

05/10/2018 08:30:00 Debris uplifted.

STSV Incident Report

General Details	
Incident ID	00071511
Contract	STSW
Issued	08/10/2018 10:52:07
Status	O
BeCogent Ref:	
Weather	
Other Cause	

Incident Details	
Incident Cat	DEB
Incident Type	Carriageway
O/I Ref	18SW05614
Defect Ref	D-SW18236113155
Police Inc. No:	
Incident Description	
Debris - Wood	

Organisation	Contacts	Contact Phone	Contact Mobile	Contact Email
Scotland Transerv	Tango 1			

Location Details			
Region	Route	Junction	Marker Post
	M8		
Location Description: MOI-SW 1876634 Jc 30, D-SW18236113155			
Easting	244859	Northing	669813
Link/Section	13717/04		

Vehicle Response				
ISURef	Time Called	Time Allocated	Time Arrived	Time Departed
TANGO 1	08/10/2018 10:50:00	08/10/2018 10:50:00	08/10/2018 11:05:00	08/10/2018 11:10:00

No Trace	False
----------	-------

Vehicles Involved							
Make/Model	Vehicle Registration	Colour	Driver	Foreign Vehicle	Slight Injuries	Serious Injuries	Fatal Injuries

Damage

Action Date	Actions Taken
08/10/2018 11:10:00	Wood debris uplifted from L2

STSV Incident Report

General Details	
Incident ID	00071637
Contract	STSW
Issued	11/10/2018 10:25:56
Status	O
BeCogent Ref:	
Weather	
Other Cause	

Incident Details	
Incident Cat	DEB
Incident Type	Hard Shoulder
O/I Ref	18SW05740
Defect Ref	D-SW18236135530
Police Inc. No:	
Incident Description	
Debris - plastic	

Organisation	Contacts	Contact Phone	Contact Mobile	Contact Email
Scotland Transerv	Tango 2			

Location Details				
Region	Route	Junction	Marker Post	
	M8			
Location Description	MOI-SW1876863 M8 - Junction 31 - 30 E/B D-SW18236135530			
Easting	241181	Northing	672936	Link/Section 13719/49

Vehicle Response				
ISURef	Time Called	Time Allocated	Time Arrived	Time Departed
TANGO 2	11/10/2018 10:25:00	11/10/2018 10:25:00	11/10/2018 10:25:00	11/10/2018 10:30:00
No Trace	False			

Vehicles Involved							
Make/Model	Vehicle Registration	Colour	Driver	Foreign Vehicle	Slight Injuries	Serious Injuries	Fatal Injuries

Damage

Action Date	Actions Taken
11/10/2018 11:28:00	debris removed from the hard shoulder

STSV Incident Report

General Details	
Incident ID	00071706
Contract	STSW
Issued	12/10/2018 17:35:30
Status	O
BeCogent Ref:	
Weather	
Other Cause	

Incident Details	
Incident Cat	DEB
Incident Type	Carriageway
O/I Ref	18SW05804
Defect Ref	D-SW18236142953
Police Inc. No:	3024
Incident Description	
Debris - HGV Mud guard	

Organisation	Contacts	Contact Phone	Contact Mobile	Contact Email
Traffic Scotland	Traffic Scotland			

Location Details				
Region	Route	Junction	Marker Post	
	M8			
Location Description	MOI-SW1876967 - M8 E J30, D-SW18236142953			
Easting	244717	Northing	670385	Link/Section 13719/03

Vehicle Response				
ISURef	Time Called	Time Allocated	Time Arrived	Time Departed
TANGO 2	12/10/2018 17:35:00	12/10/2018 17:35:00	12/10/2018 17:55:00	12/10/2018 18:00:00

No Trace	False
----------	-------

Vehicles Involved							
Make/Model	Vehicle Registration	Colour	Driver	Foreign Vehicle	Slight Injuries	Serious Injuries	Fatal Injuries

Damage

Action Date	Actions Taken
12/10/2018 17:35:00	T2 attends
12/10/2018 18:00:00	From T2 - debris removed

STSV Incident Report

General Details	
Incident ID	00071753
Contract	STSW
Issued	14/10/2018 17:50:22
Status	O
BeCogent Ref:	
Weather	
Other Cause	

Incident Details	
Incident Cat	LA
Incident Type	Swan
O/I Ref	
Defect Ref	
Police Inc. No:	3053
Incident Description	
Swan on road	

Organisation	Contacts	Contact Phone	Contact Mobile	Contact Email
Traffic Scotland	Traffic Scotland			

Location Details				
Region	Route	Junction	Marker Post	
	M8			
Location Description	M8 W/B Jct 30			
Easting	244798	Northing	670078	Link/Section 13717/95

Vehicle Response				
ISURef	Time Called	Time Allocated	Time Arrived	Time Departed
TANGO 2	14/10/2018 17:50:00	14/10/2018 17:50:00	14/10/2018 18:05:00	14/10/2018 18:10:00

No Trace	False
----------	-------

Vehicles Involved							
Make/Model	Vehicle Registration	Colour	Driver	Foreign Vehicle	Slight Injuries	Serious Injuries	Fatal Injuries

Damage

Action Date	Actions Taken
14/10/2018 18:03:00	Tango 2 advise the swan is on the hard shoulder and they will close lane 1 before attempting to catch it - Traffic Scotland aware.
14/10/2018 18:10:00	Swan has left the locus.

STSV Incident Report

General Details	
Incident ID	00072126
Contract	STSW
Issued	27/10/2018 10:25:48
Status	O
BeCogent Ref:	
Weather	
Other Cause	

Incident Details	
Incident Cat	DEB
Incident Type	Hard Shoulder
O/I Ref	18SW06149
Defect Ref	D-SW18236182064
Police Inc. No:	
Incident Description	
Debris - Metal	

Organisation	Contacts	Contact Phone	Contact Mobile	Contact Email
Scotland Transerv	Tango 2			

Location Details				
Region	Route	Junction	Marker Post	
	M8			
Location Description MOI-SW1877689 - M8 E J31 - 30, D-SW18236182064				
Easting	243686	Northing	671752	Link/Section 13719/49

Vehicle Response				
ISURef	Time Called	Time Allocated	Time Arrived	Time Departed
TANGO 2	27/10/2018 10:25:00	27/10/2018 10:25:00	27/10/2018 10:25:00	27/10/2018 10:30:00

No Trace	False
----------	-------

Vehicles Involved							
Make/Model	Vehicle Registration	Colour	Driver	Foreign Vehicle	Slight Injuries	Serious Injuries	Fatal Injuries

Damage

Action Date	Actions Taken
27/10/2018 10:30:00	From T2 - Debris removed