

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/02/2018 and 05/02/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST: Slip entry from A726 to exit slip to M8',) Or

(Section is 'AGAINST: CRAIGTON INT TO M8 EB',) Or

(Section is 'AGAINST:Off slip to A726 to on slip from A726',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>18501/86 : AGAINST:Off slip to A726 to on slip from A726</b>									
<b>Safety Patrol of M8 A898 M898 on 03 February 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M8 A898 M898 on 06 February 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M8 A898 M898 on 10 February 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M8 A898 M898 on 13 February 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M8 A898 M898 on 17 February 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M8 A898 M898 on 20 February 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M8 A898 M898 on 24 February 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M8 A898 M898 on 27 February 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M8 A898 M898 on 03 March 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M8 A898 M898 on 06 March 2018</b>									
SW77-325507-235553026	149m	149m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	21/03/2018	M898 SB BETWEEN A726 OFF TO ON
<b>Safety Patrol of M8 A898 M898 on 10 March 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M8 A898 M898 on 13 March 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M8 A898 M898 on 17 March 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M8 A898 M898 on 20 March 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M8 A898 M898 on 24 March 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M8 A898 M898 on 27 March 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M8 A898 M898 on 31 March 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M8 A898 M898 on 03 April 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M8 A898 M898 on 07 April 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M8 A898 M898 on 10 April 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M8 A898 M898 on 14 April 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M8 A898 M898 on 17 April 2018</b>									
SW77-338298-235613795	151m	153m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/04/2018	Completed Defects	17/04/2018	M898 SB BETWEEN OFF SLIP + ON SLIP, LANE 1
<b>Safety Patrol of M8 A898 M898 on 21 April 2018</b>									
<i>No defects recorded</i>									

<b>Safety Inspection of M8 A898 M898 on 24 April 2018</b>									
SW77-340426-235667087	223m	225m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/04/2018	Completed Defects	25/04/2018	M898 SB ADJACENT TO A726 ON SLIP

**Safety Patrol of M8 A898 M898 on 28 April 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 01 May 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 05 May 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 08 May 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 12 May 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 15 May 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 19 May 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 22 May 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 26 May 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 29 May 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 01 June 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 05 June 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 09 June 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 12 June 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 19 June 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 23 June 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 26 June 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 30 June 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 03 July 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 07 July 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 10 July 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 14 July 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 17 July 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 21 July 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 24 July 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 28 July 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 31 July 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 04 August 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 07 August 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 11 August 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 14 August 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 18 August 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 21 August 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 25 August 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 28 August 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 01 September 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 04 September 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 08 September 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 11 September 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 15 September 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 18 September 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 22 September 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 25 September 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 29 September 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 02 October 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 06 October 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 08 October 2018**

SW77-419273-236112441	131m	132m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/10/2018	Completed Defects	10/10/2018	M898 SB 20M PAST 70MPH SIGN
SW77-419273-236112442	130m	131m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/10/2018	Completed Defects	10/10/2018	M898 SB 30M AFTER 70MPH SIGN
SW77-419273-236112443	148m	149m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/10/2018	Completed Defects	10/10/2018	M898 SB 40M AFTER 70MPH SIGN

**Safety Patrol of M8 A898 M898 on 13 October 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 16 October 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 20 October 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 23 October 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 27 October 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 20 October 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 03 November 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 06 November 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 10 November 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 13 November 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 17 November 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 20 November 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 24 November 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 27 November 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 01 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 04 December 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 08 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 11 December 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 15 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 18 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 20 December 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 22 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 27 December 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 29 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 03 January 2019**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 05 January 2019**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 08 January 2019**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 12 January 2019**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 15 January 2019**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 19 January 2019**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 22 January 2019**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 26 January 2019**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 29 January 2019**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 02 February 2019**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 05 February 2019**

*No defects recorded*

**18501/38 : AGAINST: Slip entry from A726 to exit slip to M8**

**Safety Patrol of M8 A898 M898 on 03 February 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 06 February 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 10 February 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 13 February 2018**

SW77-319445-235542927	521m	531m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/02/2018	Completed Defects	14/02/2018	M898 SB ENTRY TO M8, 300Y MARKER
-----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	-------------------------------------

**Safety Patrol of M8 A898 M898 on 17 February 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 20 February 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 24 February 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 27 February 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 03 March 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 06 March 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 10 March 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 13 March 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 17 March 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 20 March 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 24 March 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 27 March 2018**

SW77-331498-235608708	482m	490m	CARRIAGEWAY	Pothole (POTH)	CAT 1	28/03/2018	Completed Defects	28/03/2018	M898 SB AT THE 300Y COUNTDOWN MARKER
-----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	---

**Safety Patrol of M8 A898 M898 on 31 March 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 03 April 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 07 April 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 10 April 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 14 April 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 17 April 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 21 April 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 24 April 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 28 April 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 01 May 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 05 May 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 08 May 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 12 May 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 15 May 2018**

SW77-348946-235794916	519m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/05/2018	Completed Defects	15/05/2018	M898 S/B AT 300 COUNTDOWN MARKER
-----------------------	------	----	-------------	--------------------------	-------	------------	----------------------	------------	-------------------------------------

No defects recorded  
**Safety Patrol of M8 A898 M898 on 19 May 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 22 May 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 26 May 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 29 May 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 01 June 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 05 June 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 09 June 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 12 June 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 19 June 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 23 June 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 26 June 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 30 June 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 03 July 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 07 July 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 10 July 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 14 July 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 17 July 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 21 July 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 24 July 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 28 July 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 31 July 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 04 August 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 07 August 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 11 August 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 14 August 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 18 August 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 21 August 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 25 August 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 28 August 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 01 September 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 04 September 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 08 September 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 11 September 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 15 September 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 18 September 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 22 September 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 25 September 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 29 September 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 02 October 2018**

No defects recorded  
**Safety Patrol of M8 A898 M898 on 06 October 2018**

No defects recorded  
**Safety Inspection of M8 A898 M898 on 08 October 2018**

SW77-419273-236112446	514m	514m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/10/2018	Completed Defects	10/10/2018	M898 SB AT 300M COUNTDOWN
SW77-419273-236112444	364m	365m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/10/2018	Completed Defects	10/10/2018	M898 SB AT LAYBY
SW77-419273-236112445	476m	478m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/10/2018	Completed Defects	10/10/2018	M898 SB 400M PRIOR M8
SW77-419273-236112447	525m	525m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/10/2018	Completed Defects	10/10/2018	M898 SB 300M PRIOR M8

**Safety Patrol of M8 A898 M898 on 13 October 2018**

No defects recorded

**Safety Inspection of M8 A898 M898 on 16 October 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 20 October 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 23 October 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 27 October 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 20 October 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 03 November 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 06 November 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 10 November 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 13 November 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 17 November 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 20 November 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 24 November 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 27 November 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 01 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 04 December 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 08 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 11 December 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 15 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 18 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 20 December 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 22 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 27 December 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 29 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 03 January 2019**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 05 January 2019**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 08 January 2019**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 12 January 2019**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 15 January 2019**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 19 January 2019**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 22 January 2019**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 26 January 2019**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 29 January 2019**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 02 February 2019**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 05 February 2019**

*No defects recorded*

**13717/94 : AGAINST: CRAIGTON INT TO M8 EB**

**Safety Patrol of M8 A898 M898 on 03 February 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 06 February 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 10 February 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 13 February 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 17 February 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 20 February 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 24 February 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 27 February 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 03 March 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 06 March 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 10 March 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 13 March 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 17 March 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 20 March 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 24 March 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 27 March 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 31 March 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 03 April 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 07 April 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 10 April 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 14 April 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 17 April 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 21 April 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 24 April 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 28 April 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 01 May 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 05 May 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 08 May 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 12 May 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 15 May 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 19 May 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 22 May 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 26 May 2018**



*No defects recorded*

**Safety Inspection of M8 A898 M898 on 29 May 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 01 June 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 05 June 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 09 June 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 12 June 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 19 June 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 23 June 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 26 June 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 30 June 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 03 July 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 07 July 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 10 July 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 14 July 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 17 July 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 21 July 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 24 July 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 28 July 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 31 July 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 04 August 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 07 August 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 11 August 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 14 August 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 18 August 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 21 August 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 25 August 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 28 August 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 01 September 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 04 September 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 08 September 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 11 September 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 15 September 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 18 September 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 22 September 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 25 September 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 29 September 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 02 October 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 06 October 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 08 October 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 13 October 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 16 October 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 20 October 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 23 October 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 27 October 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 20 October 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 03 November 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 06 November 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 10 November 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 13 November 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 17 November 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 20 November 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 24 November 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 27 November 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 01 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 04 December 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 08 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 11 December 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 15 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 18 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 20 December 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 22 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 27 December 2018**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 29 December 2018**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 03 January 2019**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 05 January 2019**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 08 January 2019**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 12 January 2019**

*No defects recorded*

**Safety Inspection of M8 A898 M898 on 15 January 2019**

*No defects recorded*

**Safety Patrol of M8 A898 M898 on 19 January 2019**

*No defects recorded*  
**Safety Inspection of M8 A898 M898 on 22 January 2019**  
*No defects recorded*  
**Safety Patrol of M8 A898 M898 on 26 January 2019**  
*No defects recorded*  
**Safety Inspection of M8 A898 M898 on 29 January 2019**  
*No defects recorded*  
**Safety Patrol of M8 A898 M898 on 02 February 2019**  
*No defects recorded*  
**Safety Inspection of M8 A898 M898 on 05 February 2019**  
*No defects recorded*