

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/06/2017 and 19/12/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'LENDALFOOT BRIDGE TO ARDMILLAN CASTLE')

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
11617/05 : LENDALFOOT BRIDGE TO ARDMILLAN CASTLE									
Safety Inspection of A77 Ayr South V1 on 01 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 08 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 15 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 22 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 29 June 2017									
SW82281701-235240864	2,245m	2,248m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/07/2017	Completed Defects	20/07/2017	A77 NB CW 20M NTH OF LAYBY, STH OF TRAFFIC LIGHTS STRAIDS PASS
SW82281701-235240865	3,041m	3,042m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/07/2017	Completed Defects	20/07/2017	A7 NB CW 400M NTH OF TRAFFIC LIGHTS AT STRAIDS PASS, AT SIGN POLE
SW82281701-235240863	2,220m	2,223m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A77 NB CW 10M NTH OF LAYBY, STH OF TRAFFIC LIGHTS AT STRAIDS PASS
SW82281701-235240867	2,987m	2,988m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/07/2017	Completed Defects	20/07/2017	A77 NB CW 360M NTH OF STRAIDS PASS TRAFFIC LIGHTS
SW82281701-235240866	2,969m	2,972m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/07/2017	Completed Defects	20/07/2017	A77 NB CW 350M NTH OF STRAIDS PASS TRAFFIC LIGHTS
Safety Inspection of A77 Ayr South V1 on 06 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 13 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 20 July 2017									
SW82282561-235276818	1,699m	1,700m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/08/2017	Completed Defects	03/08/2017	A77 NB CW, APPROX 1000M STH OF TRAFFIC LIGHTS AT STRAIDS PASS
SW82282561-235276817	1,929m	1,932m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/08/2017	Completed Defects	03/08/2017	A77 NB CW, APPROX 800M STH OF TRAFFIC LIGHTS AT STRAIDS PASS
Safety Inspection of A77 Ayr South V1 on 27 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 03 August 2017									
SW82283011-235291972	5,618m	5,619m	CARRIAGEWAY	Pothole (POTH)	CAT 1	31/08/2017	Completed Defects	28/08/2017	A77 NB CW 400 M NORTH OF ARDWELL FARM SOUTH OF GIRVAN
SW82283011-235291973	5,548m	5,550m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	31/08/2017	Completed Defects	28/08/2017	350 M NORTH OF ARDWELL FARM SOUTH OF GRVAN
SW82283011-235291975	3,981m	3,984m	CARRIAGEWAY	Patch - difference in level (PDLV)	CAT 1	31/08/2017	Completed Defects	21/08/2017	A77 S/B CW 50 M NORTH 9F KENNEDYS PASS
SW82283011-235291974	5,511m	5,514m	CARRIAGEWAY	Patch - difference in level (PDLV)	CAT 2	01/01/9999	Completed Defects	23/11/2018	300 M NORTH OF ARDWELL FARM SOUTH OF GIRVAN
Safety Inspection of A77 Ayr South V1 on 10 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 17 August 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
SW82283681-235322192	3,948m	3,948m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/09/2017	Completed Defects	21/08/2017	30M PAST LAYBY PARKING STRHSIDE OF KEENEDYS PASS ON RP1
Safety Inspection of A77 Ayr South V1 on 24 August 2017									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 31 August 2017									
SW82283940-235361597	3,009m	3,011m	CARRIAGEWAY	Pothole (POTH)	CAT 1	28/09/2017	Completed Defects	06/10/2017	A77 CL, 300M NTH OF TRAFFIC LIGHTS AT STRAIDS PASS, STH OF GIRVAN
SW82283940-235361596	3,133m	3,135m	CARRIAGEWAY	Pothole (POTH)	CAT 1	28/09/2017	Completed Defects	06/10/2017	A77 CL, 400M NTH OF STRAIDS PASS, STH OF GIRVAN
Safety Inspection of A77 Ayr South V1 on 07 September 2017									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 14 September 2017									
SW82302427-235377791	1,688m	1,689m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/10/2017	Completed Defects	10/10/2017	A77 NB CW, 2000M NTH OF LENDALFOOT AT START OF THE STRAIDS PASS BENDS
Safety Inspection of A77 Ayr South V1 on 21 September 2017									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 28 September 2017									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 05 October 2017									
SW82315213-235425911	5,122m	5,123m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/11/2017	Completed Defects	31/10/2017	A77 NB CW, OUTSIDE ARDWELL FARM, STH OF GIRVAN
Safety Inspection of A77 Ayr South V1 on 12 October 2017									
SW82315366-235428683	200m	201m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/11/2017	Completed Defects	07/11/2017	A77 SB CW, AT 100M COUNTDOWN MARKER LENDALFOOT NTH GATEWAY
Safety Inspection of A77 Ayr South V1 on 19 October 2017									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 26 October 2017									
SW82315666-235445929	5,157m	5,160m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/11/2017	Completed Defects	22/11/2017	A77 NB CW, 50M STH OF ARDWELL FARM, STH OF GIRVAN
Safety Inspection of A77 Ayr South V1 on 02 November 2017									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 09 November 2017									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 16 November 2017									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 23 November 2017									
SW82316384-235479132	5,865m	5,866m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/12/2017	Completed Defects	10/01/2018	A77 NB CW, 500M STH OF ARDMILLAN CARAVAN PARK ENTRANCE STH OF GIRVAN
SW82316384-235479130	1,610m	1,611m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/12/2017	Completed Defects	09/01/2018	A77 SB CW, 100M STH OF STRAIDS PASS AFTER BENDS
SW82316384-235479131	4,190m	4,195m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/12/2017	Completed Defects	09/01/2018	A77 SB CW, 300M NTH OF LAYBY NTH OF KENNEDYS PASS
Safety Inspection of A77 Ayr South V1 on 30 November 2017									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 07 December 2017									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 14 December 2017									
SW82316869-235496145	1,702m	1,703m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/01/2018	Completed Defects	10/01/2018	A77 SB CW, AT END OF STRAIDS PASS BENDS, NTH OF LENDALFOOT
SW82316869-235496146	2,130m	2,131m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/01/2018	Completed Defects	09/01/2018	A77 NB CW, 50M STH OF LAYBY, STRAIDS PASS, FIRST LAYBY HEADING NTH ON NB CW
Safety Inspection of A77 Ayr South V1 on 21 December 2017									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A77 Ayr South V1 on 28 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 04 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 11 January 2018									
SW82317471-235518222	1,851m	1,853m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	09/02/2018	A77 NB AND SB CW, 200M NTH OF END OF STRAIDS PASS BENDS
SW82317471-235518220	1,754m	1,760m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	09/02/2018	A77 NB CW, 150M NTH OF STH END OF STRAIDS PASS BENDS
SW82317471-235518221	1,788m	1,789m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	09/02/2018	A77 ON CL, 200M NTH OF END OF STRAIDS PASS BENDS
SW82317471-235518219	1,624m	1,625m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	09/02/2018	A77 NB CW, AT STH END OF STRAIDS PASS BENDS
Safety Inspection of A77 Ayr South V1 on 18 January 2018									
SW82317666-235521317	3,097m	3,100m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	09/02/2018	A77 NB CW AND SB CW, STRAIDS PASS STH OF GIRVAN
SW82317666-235521318	5,186m	5,188m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	08/02/2018	A77 SB CW, OUTSIDE ARDWELL FARM, STH OF GIRVAN
Safety Inspection of A77 Ayr South V1 on 25 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 01 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 08 February 2018									
SW82319037-235539790	1,843m	1,845m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 BOTH CW, 220M STH OF NB LAYBY STRAIDS PASS
SW82319037-235539788	1,938m	1,939m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 NB CW, 150M STH OF NB LAYBY, STRAIDS PASS
SW82319037-235539787	2,020m	2,021m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 SB CW, 120M STH OF NB LAYBY STRAIDS PASS
SW82319037-235539789	1,883m	1,884m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 NB CW, 200M STH OF NB LAYBY STRAIDS PASS
SW82319037-235539782	2,897m	2,910m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	08/02/2018	A77 BOTH CW, STRAIDS PASS, STH GIRVAN
SW82319037-235539792	1,788m	1,744m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 BOTH CW, CLUSTER OF POTHOLES OVER 100M STRETCH, 11 HOLES, 250M STH OF NB LAYBY STRAIDS PASS
SW82319037-235539781	2,948m	2,950m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	08/02/2018	A77 SB CW, STRAIDS PASS
SW82319037-235539791	1,798m	1,799m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 SB CW, 230M STH OF NB LAYBY, STRAIDS PASS
SW82319037-235539783	2,291m	2,295m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 SB CW, 100M NTH OF LAYBY AT STRAIDS PASS ON HILL
SW82319037-235539785	2,156m	2,157m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 STRAIDS PASS, STH OF NB LAYBY
SW82319037-235539784	2,238m	2,240m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 NB CW, AT NB LAYBY, STRAIDS PASS
SW82319037-235539786	2,096m	2,097m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 STH OF NB LAYBY STRAIDS PASS, 100M
Safety Inspection of A77 Ayr South V1 on 15 February 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
SW82319984-235544954	1,643m	1,645m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	16/02/2018	A77 SB CW, AT STH END OF STRAIDS PASS
SW82319984-235544955	4,737m	4,738m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	16/02/2018	A77 NB CW, 400M STH OF ARDWELL FARM, STH OF GIRVAN
SW82319984-235544953	1,581m	1,582m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	16/02/2018	A77 NB CW, AT STH END OF STRAIDS PASS
Safety Inspection of A77 Ayr South V1 on 22 February 2018									
SW82321955-235548231	1,795m	1,796m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	AT pedestrian 200yds sign in straid pass sth of girvan sb cw
SW82321955-235548233	1,659m	1,660m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	NB CW AT SOUTHSIDE OF STRAID PASS SOUTH OF GIRVAN
SW82321955-235548234	1,652m	1,653m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	POTHOLE
SW82321955-235548228	1,942m	1,944m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	A77 STRAID PASS
SW82321955-235548230	1,899m	1,900m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	A77 STRAID PASS STH OF GIRVAN
SW82321955-235548229	0m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	A77 STRAID PASS STH OF GIRVAN
SW82321955-235548227	2,040m	2,041m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	A77 STRAID PASS
SW82321955-235548232	1,730m	1,731m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	NB CW SOUTHSIDE OF STRAID PASS
Safety Inspection of A77 Ayr South V1 on 01 March 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 08 March 2018									
SW82326075-235554325	313m	314m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, 250M NTH OF LENDALFOOT NTH GATEWAY
SW82326075-235554326	2,587m	2,588m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, 500M NTH OF LAYBY BETWEEN STRAIDS PASS AND KENNEDYS PASS, AT OLD LANDSLIP
SW82326075-235554324	275m	276m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, 200M NTH OF LENDALFOOT NTH GATEWAY
Safety Inspection of A77 Ayr South V1 on 15 March 2018									
SW82328086-235590027	4,701m	4,702m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 SB CW, 300M STH OF ARDWELL FARM
SW82328086-235590026	1,646m	1,650m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	25/03/2018	A77 BOTH CW, MULTIPLE HOLES FROM STH START OF STRAIDS PASS TO 100M NTH OF LAYBY
Safety Inspection of A77 Ayr South V1 on 22 March 2018									
SW82330474-235608109	2,062m	2,063m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 NB CW, 50M STH OF NB LAYBY STRAIDS PASS
SW82330474-235608111	2,238m	2,239m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 ON CL, 30M NTH OF NB LAYBY, STRAIDS PASS
SW82330474-235608107	1,892m	1,893m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 NB CW, 170M NTH OF STRAIDS PASS BENDS START
SW82330474-235608106	1,833m	1,834m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 NB CW, 150M NTH OF STRAIDS PASS STAR

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
SW82330474-235608110	2,224m	2,225m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 NB CW, 20M NTH OF NB LAYBY, STRAIDS PASS
SW82330474-235608108	1,888m	1,889m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 NB CW, 175M NTH OF START OF STRAIDS PASS BENDS
SW82330474-235608105	1,609m	1,610m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 SB CW, START OF STRAIDS PASS BENDS
SW82330474-235608112	2,242m	2,243m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 SB CW, 50M TH OF NB LAYBY, STRAIDS PASS
Safety Inspection of A77 Ayr South V1 on 29 March 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 05 April 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 12 April 2018									
SW82336916-235633869	5,559m	5,600m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/05/2018	Completed Defects	12/04/2018	A77 NB CW, 200M NTH OF ARDWELL FARM, STH OF GIRVAN
Safety Inspection of A77 Ayr South V1 on 19 April 2018									
SW82338893-235633870	5,162m	5,162m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/04/2018	Completed Defects	19/04/2018	M77 N/B/ AT ARDWELL FARM N/S/W/T
SW82338893-235633869	5,162m	5,162m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/04/2018	Completed Defects	19/04/2018	A77 S/B @ ARDWELL FARM O/S/W/T AND N/S/W/T
Safety Inspection of A77 Ayr South V1 on 26 April 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 03 May 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 10 May 2018									
SW82346930-235712684	4,625m	4,626m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/06/2018	Completed Defects	10/05/2018	A77 NB CW 300 SOUTH OF ARDWELL FARM
SW82346930-235712685	4,589m	4,590m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/06/2018	Completed Defects	10/05/2018	A77 SB CW 400 M SOUTH OF ARDWELL FARM
Safety Inspection of A77 Ayr South V1 on 17 May 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 24 May 2018									
SW82352984-235812705	5,159m	5,160m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/06/2018	Completed Defects	24/05/2018	A77 NB CW OPPOSITE ARDWELL FARM
Safety Inspection of A77 Ayr South V1 on 31 May 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 07 June 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 14 June 2018									
SW80-363687-235858067	3,457m	2,458m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/07/2018	Completed Defects	15/06/2018	A77 CL 299 M SOUTH OF BIG ROCK
SW80-363687-235858066	3,471m	3,472m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/07/2018	Completed Defects	15/06/2018	A77 CL 300M SOUTH OF BIG ROCK
SW80-363687-235858068	5,201m	5,202m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/07/2018	Completed Defects	19/07/2018	A77 SB CW 25M NORTH OF ARDWELL FARM
Safety Inspection of A77 Ayr South V1 on 21 June 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 28 June 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 05 July 2018									
SW82374127-235892358	313m	314m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/08/2018	Completed Defects	01/08/2018	A77 NB CW 250M PRIOR TO LENDALFOOT NORTH GATEWAY
Safety Inspection of A77 Ayr South V1 on 12 July 2018									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A77 Ayr South V1 on 19 July 2018									
SW82380667-235914377	5,576m	5,577m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/08/2018	Completed Defects	19/07/2018	A77 NB CW 250M AFTER ARDWELL FARM
Safety Inspection of A77 Ayr South V1 on 26 July 2018									
SW82383889-235917503	3,594m	3,595m	GULLY	Blockage (BLOK)	CAT 1	23/08/2018	Completed Defects	03/08/2018	A77 SB CW KENEDYS PASS
SW82383889-235917502	4,970m	4,971m	GULLY	Blockage (BLOK)	CAT 1	23/08/2018	Completed Defects	03/08/2018	A77 SB CW 100M AFTER ARDWELL FARM
Safety Inspection of A77 Ayr South V1 on 02 August 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 09 August 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 16 August 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 23 August 2018									
SW80-397303-235954868	2,129m	2,130m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/08/2018	Completed Defects	23/08/2018	A77 N/B C/W 500M FROM START OF STRAID PASS NORTH OF LENDAL FOOT
Safety Inspection of A77 Ayr South V1 on 30 August 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 06 September 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 13 September 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 20 September 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 27 September 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 04 October 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 11 October 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 18 October 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 25 October 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 01 November 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 08 November 2018									
SW82426441-236211988	4,191m	4,192m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	09/11/2018	Completed Defects	08/11/2018	A77 SB CW 100M PRIOR TO KENNEDYS PASS
Safety Inspection of A77 Ayr South V1 on 15 November 2018									
SW82426587-236223177	2,048m	2,049m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/12/2018	Completed Defects	15/11/2018	A77 SB CW AT STRAID PASS 600m NORTH OF LAYBY NORTH OF LENDALFOOT
SW82426587-236223175	1,871m	1,872m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/12/2018	Completed Defects	15/11/2018	A77 SB CW AT STRAID PASS 500M NORTH OF LAYBY NORTH OF LENDALFOOT
SW82426587-236223174	3,846m	3,846m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A78 SB CW LAYBY AT KENNEDYS PASS
SW82426587-236223176	1,859m	1,860m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/12/2018	Completed Defects	15/11/2018	A77 SB CW AT STRAID PASS 550M NORTH OF LAYBY NORTH OF LENDALFOOT
Safety Inspection of A77 Ayr South V1 on 22 November 2018									
SW82426764-236231621	186m	187m	TRAFFIC_SIGNS	Missing (MISS)	CAT 1	20/12/2018	Completed Defects	27/11/2018	A77 SB CW 200M NORTH OF LENDALFOOT
SW82426764-236231623	239m	240m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/11/2018	Completed Defects	22/11/2018	A77 NB CW 200M NORTH OF LENDALFOOT
Safety Inspection of A77 Ayr South V1 on 29 November 2018									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A77 Ayr South V1 on 06 December 2018									
SW80-427220-236234311	4,651m	4,652m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/01/2019	Completed Defects	06/12/2018	A77 SB CW 150M SOUTH OF ARDWELL FARM
SW80-427220-236234310	1,948m	1,949m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/01/2019	Completed Defects	06/12/2018	A77 NB CW AT STRAID PASS
Safety Inspection of A77 Ayr South V1 on 13 December 2018									
SW82427366-236262607	190m	191m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/01/2019	Completed Defects	13/12/2018	A77 SB CW, LENDALFOOT NTH GATEWAY
SW82427366-236262608	2,027m	2,028m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/01/2019	Completed Defects	13/12/2018	A77 ON CL, STRAIDS PASS, 50M STH OF LAYBY
Safety Inspection of A77 Ayr South V1 on 20 December 2018									
SW82427527-236264605	4,148m	4,149m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/01/2019	Completed Defects	12/01/2019	A77 SB CW 150M PRIOR TO KENNEDYS PASS AT SPEED CAMERA
Safety Inspection of A77 Ayr South V1 on 27 December 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 03 January 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 10 January 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 17 January 2019									
SW82428228-236270546	4,898m	4,899m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/01/2019	Completed Defects	17/01/2019	A77 SB CW 150M SOUTH OF ARDWELL FARM
Safety Inspection of A77 Ayr South V1 on 24 January 2019									
SW82428351-236284321	47m	48m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2019	Completed Defects	06/02/2019	A77 NB CW, 80M STH OF LENDALFOOT NTH GATEWAY
Safety Inspection of A77 Ayr South V1 on 31 January 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 07 February 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 14 February 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 21 February 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 28 February 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 07 March 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 14 March 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 21 March 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 28 March 2019									
SW82459990-236492548	1,030m	1,031m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/03/2019	Completed Defects	28/03/2019	A77 S/B OPP LAY BY PRIOR TO LENDAL FOOT
Safety Inspection of A77 Ayr South V1 on 04 April 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 11 April 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 18 April 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 25 April 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 02 May 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 09 May 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 16 May 2019									
SW82509321-236673881	2,377m	2,378m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	17/05/2019	Completed Defects	16/05/2019	A77 N/B STRAID PASS

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
SW82509321-236673882	5,105m	5,106m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	17/05/2019	Completed Defects	16/05/2019	A77 SB AT ARDWELL FARM
Safety Inspection of A77 Ayr South V1 on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 30 May 2019									
SW82515651-236805612	2,092m	2,093m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	31/05/2019	Completed Defects	30/05/2019	A77 N/B CARRIAGEWAY STRADEPASS NORTH OF LENDALFOOT
Safety Inspection of A77 Ayr South V1 on 06 June 2019									
SW82520636-236809551	1,908m	1,909m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/06/2019	Completed Defects	06/06/2019	A77 N/B C/W 500M AFTER START OF STRAEPASS NORTH OF GLENDALEFOOT
Safety Inspection of A77 Ayr South V1 on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 27 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 04 July 2019									
SW82530842-236896673	1,028m	1,028m	CARRIAGEWAY	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A77 S/B C/W NORTH OF LENDAL FOOT OPPOSITE SECOND LAYBY PRIOR TO LENDALFOOT
SW82530842-236896674	977m	977m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/07/2019	Completed Defects	04/07/2019	A77 S/B C/W NORTH OF LENDALFOOT 100M SOUTH OF SECOND LAYBY PRIOR TO LENDALFOOT
Safety Inspection of A77 Ayr South V1 on 11 July 2019									
SW82531044-236901969	5,226m	5,226m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/07/2019	Completed Defects	11/07/2019	A77 N/B C/W OPPOSITE ARDWELL FARM
Safety Inspection of A77 Ayr South V1 on 18 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 25 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 01 August 2019									
SW82531834-236920439	1,707m	1,707m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/08/2019	Completed Defects	01/08/2019	Straid pass falling rock barrier fence
Safety Inspection of A77 Ayr South V1 on 08 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 15 August 2019									
SW82532471-236938884	3,485m	3,485m	CARRIAGEWAY	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	a77 s/b kennedys pass north of lendalfoot
SW82532471-236938885	3,572m	3,572m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	a77 at kennndys pass north of lendalfoot
Safety Inspection of A77 Ayr South V1 on 22 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 29 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 05 September 2019									
SW82533688-237011445	1,929m	1,929m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/09/2019	Completed Defects	05/09/2019	a77 n/b c/w north of lendalfoot south of kennydys pass
SW82533688-237011446	2,042m	2,042m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/09/2019	Completed Defects	05/09/2019	a77 n/b c/w north of lendalfoot south of kennydys pass
Safety Inspection of A77 Ayr South V1 on 12 September 2019									
SW82533957-237014347	4,131m	4,131m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/09/2019	Completed Defects	12/09/2019	a77 s/b c/w north of kendys pass approx 50m north oflayby

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
SW82533957-237014346	4,147m	4,147m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/09/2019	Completed Defects	12/09/2019	a77 s/b c/w north of kendys pass approx 50m north of layby
SW82533957-237014345	1,877m	1,877m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/09/2019	Completed Defects	12/09/2019	a77 n/b c/w strade pass north of lendafoot
Safety Inspection of A77 Ayr South V1 on 19 September 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 26 September 2019									
SW82534540-237029724	4,997m	4,997m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 1	24/10/2019	Completed Defects	09/10/2019	a77 s/b approx 10m south of ardwell farm south of girvan
Safety Inspection of A77 Ayr South V1 on 03 October 2019									
SW82534855-237038990	2,044m	2,044m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/10/2019	Completed Defects	04/10/2019	A77 n/b north of ballantrae approx 200m south of layby at strade pass
Safety Inspection of A77 Ayr South V1 on 10 October 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 17 October 2019									
SW82535356-237061945	0m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/10/2019	Completed Defects	17/10/2019	a77 s/b approx 50m north of average speed camera, kennys pass
SW82535356-237061944	4,099m	4,009m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/10/2019	Completed Defects	17/10/2019	a77 s/b approx 50m north of average speed camera, kennys pass
SW82535356-237061943	4,179m	4,179m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/10/2019	Completed Defects	17/10/2019	a77 s/b approx 50m north of average speed camera, kennys pass
SW82535356-237061942	3,882m	3,884m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		a77 s/b c/w at layby, kennys pass
Safety Inspection of A77 Ayr South V1 on 24 October 2019									
SW82535747-237064390	1,878m	1,878m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/10/2019	Completed Defects	24/10/2019	a77 n/b c/w located on strade pass north of lendafoot
SW82535747-237064383	3,872m	3,872m	CARRIAGEWAY	Trench RI - difference in level (TDLV)	CAT 1	21/11/2019	Completed Defects	24/11/2019	a77 s/b located at layby prior to kennys pass, north of lendafoot
SW82535747-237064384	2,186m	2,186m	GULLY	Cracked or broken (IBCK)	CAT 1	25/10/2019	Completed Defects	24/10/2019	a77 s/b c/w prior to strade pass
Safety Inspection of A77 Ayr South V1 on 31 October 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 07 November 2019									
SW82536440-237124867	1,965m	1,965m	SHRUB	Overhanging/overgrown (OVER)	CAT 2		Cat 2 Awaiting Action		a77 kennys pass
SW82536440-237124868	3,291m	3,291m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/11/2019	Completed Defects	08/11/2019	a77 s/b c/w on anti-skid kennys pass
SW82536440-237124871	5,162m	5,162m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/11/2019	Completed Defects	08/11/2019	a77 s/b c/w at bend north of entrance to ardwell farm south girvan
SW82536440-237124869	5,244m	5,244m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/11/2019	Completed Defects	08/11/2019	a77 s/b c/w at bend north of entrance to ardwell farm south girvan
SW82536440-237124870	5,162m	5,162m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/11/2019	Completed Defects	08/11/2019	a77 s/b c/w at bend north of entrance to ardwell farm south girvan
Safety Inspection of A77 Ayr South V1 on 14 November 2019									
SW82536631-237123007	2,247m	2,247m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/11/2019	Completed Defects	14/11/2019	a77 n/b c/w at kennys pass south of girvan
SW82536631-237123006	1,177m	1,177m	CARRIAGEWAY	Other (OTHR)	CAT 1	15/11/2019	Completed Defects	14/11/2019	
Safety Inspection of A77 Ayr South V1 on 21 November 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
SW82536860-237164112	5,087m	5,087m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/11/2019	Completed Defects	21/11/2019	a77 s/b just past ardwell farm, south of girvan
SW82536860-237164111	3,879m	3,879m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/11/2019	Completed Defects	21/11/2019	a77 edge line of layby at kennydys pass, south of girvan
Safety Inspection of A77 Ayr South V1 on 28 November 2019									
SW82537039-237167270	4,568m	4,568m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/11/2019	Completed Defects	29/11/2019	pothole on c/w approx 350m south of ardwell farm south of girvan
SW82537039-237167261	18m	60m	CARRIAGEWAY	Detritus / Refuse (DETR)	3RD PTY	29/11/2019	Awaiting CCMS Permanent Date	01/01/9999	a77 n/b edgeline from bridge deck to lental foot north gateway
Safety Inspection of A77 Ayr South V1 on 05 December 2019									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 12 December 2019									
SW82537518-237211170	1,814m	1,814m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/12/2019	Completed Defects	13/12/2019	a77 strade pase north of lentalfoot
SW82537518-237211173	4,143m	4,143m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/12/2019	Completed Defects	12/12/2019	a77 s/b c/w at average speed cameras kennysys pass
SW82537518-237211174	4,143m	4,143m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/12/2019	Completed Defects	12/12/2019	a77 s/b c/w at average speed cameras kennysys pass
SW82537518-237211168	2,043m	2,043m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/12/2019	Completed Defects	13/12/2019	a77 strade pase north of lentalfoot
SW82537518-237211175	4,136m	4,136m	GULLY	Other (OTHR)	CAT 1	13/12/2019	Completed Defects	12/12/2019	a77 s/b c/w at average speed cameras kennysys pass
SW82537518-237211169	1,926m	1,926m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/12/2019	Completed Defects	13/12/2019	a77 strade pase north of lentalfoot
SW82537518-237211176	5,281m	5,281m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/12/2019	Completed Defects	12/12/2019	a77 opposite entrance to ardwell farm, south of girvan
SW82537518-237211171	4,150m	4,150m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/12/2019	Completed Defects	12/12/2019	a77 s/b c/w at average speed cameras kennysys pass
SW82537518-237211172	4,150m	4,150m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/12/2019	Completed Defects	12/12/2019	a77 s/b c/w at average speed cameras kennysys pass
Safety Inspection of A77 Ayr South V1 on 19 December 2019									
No defects recorded									