

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 02/03/2020 and 01/06/2020, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A96',)
 (Section Code is 17675/00) Or
 (Section Code is 17675/13)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
17675/00 : JUNCTION A95 CRAIGELLACHIE TO JCT B9017 NEWMILL									
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 March 2020 <i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 March 2020 <i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 March 2020 <i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 March 2020 <i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 April 2020 <i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 April 2020 <i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 April 2020 <i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 April 2020 <i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 April 2020 <i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 07 May 2020 <i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 14 May 2020									
NE131578675-237561550	250m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/05/2020	Completed Defects	14/05/2020	SB BEFORE KEITH
Safety Inspection of A95.A96 SAFETY INSPECTION on 21 May 2020 <i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 28 May 2020 <i>No defects recorded</i>									

17675/13 : JUNCTION B9017 NEWMILL TO JUNCTION B9016 BUCKIE

Safety Inspection of A95.A96 SAFETY INSPECTION on 05 March 2020
No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 12 March 2020
No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 19 March 2020
No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 26 March 2020
No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 02 April 2020
No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 09 April 2020
No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 16 April 2020
No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 23 April 2020
No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 30 April 2020
No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 07 May 2020
No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 14 May 2020
No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 21 May 2020
No defects recorded


Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

Safety Inspection of A95.A96 SAFETY INSPECTION on 28 May 2020


No defects recorded

 - worn High Friction Surfacing

Visual Condition Survey



Visual Condition Survey



- Ch 622m - AV marker post
- Ch 623m - GAS marker post
- Ch 624-629m - entrance CL1
- Ch 643-669m - Junction CR1
- Ch 929m - Start of 1x5's and solid white
- Ch991m - Start of 6x3's
- Ch 1026-1073m - Little Forge Farm Entrance CR1
- Ch 1038-1044m - Arrow
- Ch 1055m- End of HFS
- Ch 1146m - End of 6x3's, start of centre hatching
- Ch 1158-1175m - entrance CR1
- Ch 1166-1175m - entrance CL1

Key	Cracking	Patch/utility reinstatement	Crazing	Fretting	Fatting	Core	
	Constr. joint	Open joint	Rutting	Pothole	Gully	Node	Photo