

## Defect Listing (with Ch and Instruction Time)

Defect Reference	Item Category	Item Detail	Defect Category	Road	Section	Comments	Status	Perm Repair Date	Chainage	Instruction Time	Defect Source
SW79-427891-236270211	Carriageways	Cracking around ironwork (CKIR)	THIRD PARTY	A701	13112/79	CRACKING AROUND IRON WORK	Awaiting CCMS Temp Date	Unrepaired	Chainage: 1179m	03/01/2019 10:28:00	Ross Moreland (SW)
SW79-427891-236270212	Flooding	Flooding (FLOD)	THIRD PARTY	A701	13112/79	SUSPECTED BURST WATER PIPE	Awaiting CCMS Temp Date	Unrepaired	Chainage: 315m	03/01/2019 10:52:00	Ross Moreland (SW)
SW79-532226-236926950	Covers, Gratings and Frames	Rocking under load (IRLD)	THIRD PARTY	A701	13112/79	BT MANHOLE ROCKING UNDER LOAD	Awaiting CCMS Temp Date	Unrepaired	Chainage: 1184m	08/08/2019 12:17:00	Ross Moreland (SW)