

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/02/2021 and 28/02/2021, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'ROAD TO KELBURN GLEN TO PIER ROAD JUNCTION','JCT FIRPARK PLANTATION TO RD TO KELBURN GLEN','A760 JCT DALRY RD TO JCT FIRPARK PLANTATION'.)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

## 14020/05 : A760 JCT DALRY RD TO JCT FIRPARK PLANTATION

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 02 February 2021  
*No defects recorded*

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 05 February 2021  
*No defects recorded*

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 11 February 2021  
*No defects recorded*

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 12 February 2021  
*No defects recorded*

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 16 February 2021  
*No defects recorded*

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 19 February 2021  
*No defects recorded*

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 23 February 2021  
*No defects recorded*

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 26 February 2021  
*No defects recorded*

## 14020/50 : JCT FIRPARK PLANTATION TO RD TO KELBURN GLEN

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 02 February 2021  
*No defects recorded*

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 05 February 2021  
*No defects recorded*

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 11 February 2021  
*No defects recorded*

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 12 February 2021  
*No defects recorded*

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 16 February 2021  
*No defects recorded*

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 19 February 2021  
*No defects recorded*

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 23 February 2021  
*No defects recorded*

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 26 February 2021  
*No defects recorded*

## 14025/05 : ROAD TO KELBURN GLEN TO PIER ROAD JUNCTION

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 02 February 2021  
*No defects recorded*

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 05 February 2021  
*No defects recorded*

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 11 February 2021  
*No defects recorded*

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 12 February 2021  
*No defects recorded*

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 16 February 2021  
*No defects recorded*

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 19 February 2021  
*No defects recorded*

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 23 February 2021  
*No defects recorded*

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 26 February 2021  
*No defects recorded*



# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/07/2021 and 31/07/2021, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'ROAD TO KELBURN GLEN TO PIER ROAD JUNCTION','JCT FIRPARK PLANTATION TO RD TO KELBURN GLEN','A760 JCT DALRY RD TO JCT FIRPARK PLANTATION'.)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>14020/05 : A760 JCT DALRY RD TO JCT FIRPARK PLANTATION</b>									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 02 July 2021 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 06 July 2021 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 09 July 2021 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 13 July 2021 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 16 July 2021 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 20 July 2021 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 23 July 2021 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 27 July 2021 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 30 July 2021 <i>No defects recorded</i>									
<b>14020/50 : JCT FIRPARK PLANTATION TO RD TO KELBURN GLEN</b>									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 02 July 2021 <i>No defects recorded</i>									
NSW75679638-238204999	200m	200m	TRAFFIC_SIGNS	Physical condition of fittings (COFT)	CAT 2		Cat 2 Awaiting Action		A78 N/B VERGE SOUTH OF LARGS
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 09 July 2021 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 13 July 2021 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 16 July 2021 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 20 July 2021 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 23 July 2021 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 27 July 2021 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 30 July 2021 <i>No defects recorded</i>									
<b>14025/05 : ROAD TO KELBURN GLEN TO PIER ROAD JUNCTION</b>									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 02 July 2021 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 06 July 2021 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 09 July 2021 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 13 July 2021 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 16 July 2021 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 20 July 2021 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 23 July 2021 <i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

*No defects recorded*

**Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 27 July 2021**

*No defects recorded*

**Safety Patrol of NSW A78\_A76 Ayr Summer Safety Patrol Route on 30 July 2021**

*No defects recorded*

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/02/2021 and 28/02/2021, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'ACCESS TO SERVICE ROAD TO NELSON STREET JUNCTION','LODGE AT QUTER EST. TO ACCESS TO SERVICE RD',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

## 14015/05 : LODGE AT QUTER EST. TO ACCESS TO SERVICE RD

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 02 February 2021

No defects recorded

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 05 February 2021

No defects recorded

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 11 February 2021

No defects recorded

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 12 February 2021

No defects recorded

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 16 February 2021

No defects recorded

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 19 February 2021

No defects recorded

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 23 February 2021

No defects recorded

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 26 February 2021

No defects recorded

## 14015/18 : ACCESS TO SERVICE ROAD TO NELSON STREET JUNCTION

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 02 February 2021

No defects recorded

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 05 February 2021

No defects recorded

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 11 February 2021

No defects recorded

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 12 February 2021

No defects recorded

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 16 February 2021

No defects recorded

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 19 February 2021

No defects recorded

Safety Inspection of NSW A78\_A76 Ayr Safety Inspection Route on 23 February 2021

No defects recorded

Safety Patrol of NSW A78\_A76 Ayr Winter Safety Patrol Route on 26 February 2021

No defects recorded

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/07/2021 and 31/07/2021, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'ACCESS TO SERVICE ROAD TO NELSON STREET JUNCTION','LODGE AT QUTER EST. TO ACCESS TO SERVICE RD',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>14015/05 : LODGE AT QUTER EST. TO ACCESS TO SERVICE RD</b>									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 02 July 2021									
No defects recorded									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 06 July 2021									
No defects recorded									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 09 July 2021									
No defects recorded									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 13 July 2021									
No defects recorded									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 16 July 2021									
No defects recorded									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 20 July 2021									
No defects recorded									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 23 July 2021									
No defects recorded									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 27 July 2021									
No defects recorded									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 30 July 2021									
No defects recorded									
<b>14015/18 : ACCESS TO SERVICE ROAD TO NELSON STREET JUNCTION</b>									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 02 July 2021									
No defects recorded									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 06 July 2021									
No defects recorded									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 09 July 2021									
NSW75681599-238205617	177m	177m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2		Cat 2 Awaiting Action		A78 N/B VERGE 100 M PRIOR TO LARGS NORTH GATEWAY
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 13 July 2021									
No defects recorded									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 16 July 2021									
No defects recorded									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 20 July 2021									
No defects recorded									
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 23 July 2021									
No defects recorded									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 27 July 2021									
NSW75693088-238238780	1,052m	1,052m	FOOTWAY	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		
Safety Patrol of NSW A78_A76 Ayr Summer Safety Patrol Route on 30 July 2021									
No defects recorded									