

Inspection Defect Summary Report



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
12160/82 : STRATHMARTINE ROAD ROUNDABOUT									
Detailed Inspection TEMPLATE of A90 DUNDEE FILE 1 MAR on 03 March 2021									
NE14-614006-219	26m	0m	FOOTWAY	Slab profile - uneven/trips (SLPF)	CAT 2		Cat 2 Awaiting Action		@ STRATHMARTINE RBT N/B
NE14-614006-216	6m	0m	MANHOLE	Smooth surface (SMTH)	CAT 2		Cat 2 Awaiting Action		@ STRATHMARTINE RBT N/B
NE14-614006-218	27m	0m	CARRIAGEWAY	Detritus / Refuse (DETR)	CAT 2		Cat 2 Awaiting Action		@ STRATHMARTINE RBT N/B
NE14-614006-217	21m	0m	VERGE	Litter Grade D (LITD)	CAT 2		Cat 2 Awaiting Action		@ STRATHMARTINE RBT N/B
NE7-614006-76	76m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		@ STRATHMARTINE RD RBT RBT SB
NE7-614006-77	96m	0m	CARRIAGEWAY	Detritus / Refuse (DETR)	CAT 2		Cat 2 Awaiting Action		@ STRATHMARTINE RD RBT SB
NE7-614006-75	65m	0m	CARRIAGEWAY	Detritus / Refuse (DETR)	CAT 2		Cat 2 Awaiting Action		@ STRATHMARTINE RD RBT SB
NE7-614006-187	64m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2		Cat 2 Awaiting Action		@ BOTTOM OF RAMP - STRATH MARTINE RD O/BRIDGE
Reactive Defect Recorded 06/07/2021 08:55:40									
D-NE21238205585	0m	0m	MANHOLE	Difference in component levels (ICLV)	3RD PTY		Third Party Defects		Kingsway foot bridge at the junction of Kingsway/ Strathmartine Rd at the Bank outside 367/369 Kingsway
Safety Inspection of A90 SAFETY INSPECTION on 08 November 2021									
NE7-753361-238453262	59m	0m	FOOTWAY	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		STAIRS @ STRATHMARTINE RD O/BRIDGE SB

Reactive Defect Recorded 14/01/2022 12:48:44



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
D-NE22238545944	0m	0m	LIGHTING_POINT	Lamp failure (LAMP)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A90 Dundee Strathmartine Road Rab, On Strathmartine Road Rab after A90 E/B app
Detailed Inspection TEMPLATE of A90 DUNDEE FILE 1 MAR on 02 March 2022									
NW126-811824-230	69m	0m	LIGHTING_POINT	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		@ STRAMARTINE RD RBT SB
NW126-811824-177	19m	0m	KERB	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		@ S/MARTINE RD RBT NB
NW126-811824-178	9m	0m	CARRIAGEWAY	Detritus / Refuse (DETR)	CAT 2		Cat 2 Awaiting Action		@ S/MARTINE RD RBT NB
NW126-811824-231	84m	0m	CARRIAGEWAY	Detritus / Refuse (DETR)	CAT 2		Cat 2 Awaiting Action		@ STRAMARTINE RD RBT SB
NW126-811824-232	89m	0m	CARRIAGEWAY	Detritus / Refuse (DETR)	CAT 2		Cat 2 Awaiting Action		@ STRAMARTINE RD RBT SB
NW126-811824-228	46m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		@ S/MARTINE RD RBT SB
NW126-811824-229	67m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2		Cat 2 Awaiting Action		@ STRAMARTINE RD RBT SB
NW126-811824-233	22m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2		Cat 2 Awaiting Action		@ STRAMARTINE RD RBT NB

Inspection Defect Summary Report



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
12170/00 : WITH: STRATHMARTINE RD RBT TO OLD GLAMIS RD RBT									
Detailed Inspection TEMPLATE of A90 DUNDEE FILE 1 MAR on 03 March 2021									
NE14-614006-242	501m	0m	CABINET	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-258	784m	0m	FOOTWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-254	815m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-244	546m	0m	KERB	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-224	117m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B
NE14-614006-237	446m	0m	MANHOLE	Difference in level with road (IDLV)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B
NE14-614006-226	122m	0m	MANHOLE	Difference in level with road (IDLV)	CAT 2		Cat 2 Awaiting Action		ON ACCESS RD N/B
NE14-614006-225	130m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B
NE14-614006-227	140m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B
NE14-614006-236	387m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B
NE14-614006-239	472m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE14-614006-246	604m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-250	730m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-256	801m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-229	205m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B
NE14-614006-233	296m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B
NE14-614006-235	345m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B
NE14-614006-252	767m	0m	GULLY	Blockage (BLOK)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-253	797m	0m	GULLY	Blockage (BLOK)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-251	748m	0m	KERB	Vertical projection (EVPJ)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-247	627m	0m	KERB	Horizontal projection (EHPJ)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-230	233m	0m	KERB	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B
NE14-614006-234	321m	0m	KERB	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B
NE14-614006-240	484m	0m	Drainage Ancillary Items	Silted (SILT)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-249	689m	0m	CARRIAGEWAY	Detritus / Refuse (DETR)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-245	554m	0m	CENTRAL_RESERVE	Litter Grade C (LITC)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE14-614006-248	638m	0m	CENTRAL_RESERVE	Litter Grade C (LITC)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-243	499m	0m	VERGE	Litter Grade D (LITD)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-255	812m	0m	VERGE	Litter Grade D (LITD)	CAT 2		Cat 2 Awaiting Action		@ OLD GLAMIS RD RBT N/B
NE14-614006-231	229m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B ON ACCESS RD
NE14-614006-223	101m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		ON ACCESS RD N/B
NE14-614006-228	149m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B
NE14-614006-241	495m	0m	LIGHTING_POINT	Physical condition of fittings (COFT)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-257	798m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2		Cat 2 Awaiting Action		APPROACHING OLD GLAMIS RD RBT N/B
NE14-614006-220	4m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2		Cat 2 Awaiting Action		@ STRATHMARTINE RBT N/B
NE14-614006-222	11m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B
NE14-614006-221	11m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B
NE14-614006-238	441m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B
NE14-614006-232	278m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2		Cat 2 Awaiting Action		AFTER STRATHMARTINE RBT N/B

Safety Inspection of A90 SAFETY INSPECTION on 18 March 2021



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE14-624530-238031488	101m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 2		Cat 2 Awaiting Action		OUTSIDE 351 KINGSWAY NB - AFTER STRATHMARTINE RD RBT
Safety Patrol of A90 SAFETY PATROL on 15 July 2021									
NE14-683556-238215616	481m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 1	12/08/2021	Completed Defects	24/07/2021	@ FOSTER RD JCT KINGSWAY NB ON FOOTWY
Reactive Defect Recorded 26/08/2021 11:50:00									
WFE-NE21238315539	50m	50m	MANHOLE	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	?
Safety Patrol of A90 SAFETY PATROL on 26 August 2021									
NE122-710148-238305106	796m	0m	TRAFFIC_SIGNS	Other (OTHR)	CAT 1	23/09/2021	Completed Defects	10/09/2021	STRATMOARTINE RBT N/B
Safety Inspection of A90 SAFETY INSPECTION on 04 October 2021									
NE122-733600-238407965	611m	0m	CHANNEL	Other (OTHR)	CAT 1	01/11/2021	Completed Defects	16/11/2021	JUST BEFORE OLD GLAIS RBT N/B
NE122-733600-238407963	267m	0m	CHANNEL	Damaged (DAMG)	CAT 1	01/11/2021	Completed Defects	16/11/2021	NORTH OF STRATHMARTINE RBT N/B
NE122-733600-238407964	285m	0m	CARRIAGEWAY	Debris in traffic Lane (DBTL)	CAT 1	05/10/2021	Completed Defects	04/10/2021	NORTH OF STRATHMARTINE RBT N/B
NE122-733600-238407966	575m	0m	CHANNEL	Damaged (DAMG)	CAT 1	01/11/2021	Completed Defects	16/11/2021	JUST BEFORE OLD GLAMIS RBT N/B
Safety Inspection of A90 SAFETY INSPECTION on 08 November 2021									
NE7-753361-238453261	0m	0m	FOOTWAY	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		STAIRS @ STRATHMARTINE O/BRIDGE NB
Night Safety Inspection 28 day - Signs and lighting of ELEC NE R13A on 02 February 2022									
NE137-799160-238548738	0m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	03/02/2022	Completed Defects	02/02/2022	670 (30)/(40) signs at Foster Road on LHS
Detailed Inspection TEMPLATE of A90 DUNDEE FILE 1 MAR on 02 March 2022									
NW126-811824-187	254m	0m	CABINET	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		AFTER S/MARTINE RD RBT NB
NW126-811824-190	379m	0m	FOOTWAY	Bituminous surfacing - potholes (BPOT)	CAT 2		Cat 2 Awaiting Action		AFTER S/MARTINE RD RBT NB

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW126-811824-188	312m	0m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2		Cat 2 Awaiting Action		AFTER S/MARTINE RD RBT NB
NW126-811824-189	348m	0m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2		Cat 2 Awaiting Action		AFTER S/MARTINE RD RBT NB
NW126-811824-181	26m	0m	MANHOLE	Cracked or broken (IBCK)	CAT 2		Cat 2 Awaiting Action		FOOTWAY AFTER S/MARTINE RD RBT NB
NW126-811824-200	790m	0m	CARRIAGEWAY	Detritus / Refuse (DETR)	CAT 2		Cat 2 Awaiting Action		APPR OLD GLAMIS RD RBT NB
NW126-811824-201	788m	0m	VERGE	Litter Grade C (LITC)	CAT 2		Cat 2 Awaiting Action		APPR OLD GLAMIS RD RBT NB
NW126-811824-199	760m	0m	VERGE	Litter Grade C (LITC)	CAT 2		Cat 2 Awaiting Action		APPR OLD GLAMIS RD RBT NB
NW126-811824-195	609m	0m	VERGE	Litter Grade C (LITC)	CAT 2		Cat 2 Awaiting Action		
NW126-811824-196	693m	0m	VERGE	Litter Grade C (LITC)	CAT 2		Cat 2 Awaiting Action		APPR OLD GLAMIS RD RBT NB
NW126-811824-194	524m	0m	VERGE	Litter Grade D (LITD)	CAT 2		Cat 2 Awaiting Action		APPR OLD GLAMIS RD RBT NB
NW126-811824-184	140m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		AFTER S/MARTINE RD RBT NB
NW126-811824-185	196m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		AFTER S/MARTINE RD RBT NB
NW126-811824-186	229m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		AFTER S/MARTINE RD RBT NB
NW126-811824-197	726m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR OLD GLAMIS RD RBT NB

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW126-811824-193	501m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR OLD GLAMIS RD RBT NB
NW126-811824-183	125m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2		Cat 2 Awaiting Action		AFTER S/MARTINE RD RBT NB
NW126-811824-198	727m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2		Cat 2 Awaiting Action		APPR OLD GLAMIS RD RBT NB
NW126-811824-179	13m	0m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 2		Cat 2 Awaiting Action		AFTER S/MARTINE RD RBT NB
NW126-811824-180	27m	0m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 2		Cat 2 Awaiting Action		AFTER S/MARTINE RD RBT NB
NW126-811824-182	51m	0m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 2		Cat 2 Awaiting Action		AFTER S/MARTINE RD RBT NB
NW126-811824-191	390m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2		Cat 2 Awaiting Action		AFTER S/MARTINE RD RBT NB
NW126-811824-192	460m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2		Cat 2 Awaiting Action		APPR OLD GLAMIS RD RBT NB
Safety Patrol of A90 SAFETY PATROL on 10 March 2022									
NE7-819140-238601223	37m	0m	MANHOLE	Cracked or broken (IBCK)	3RD PTY	07/04/2022	Completed Defects	10/03/2022	ON FOOTWAY - JUST AFTER STRATHMARTNE RD RBT NB
Night Safety Inspection 14 day - Signs and lighting of ELEC NE R13A on 16 March 2022									
NE137-821283-238601577	185m	185m	TRAFFIC_SIGNS	No electricity supply (NOSP)	CAT 1	17/03/2022	Completed Defects	26/05/2022	670 (30)/(40) signs at Clive Road on RHS
NE137-821283-238601576	0m	0m	TRAFFIC_SIGNS	No electricity supply (NOSP)	CAT 1	17/03/2022	Completed Defects	26/05/2022	670 (30)/(40) signs at Foster Road on LHS
Safety Inspection of A90 SAFETY INSPECTION on 28 March 2022									
NE7-828628-238614198	6m	0m	CARRIAGEWAY	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		STRATHMARTINE RD O/BRIDGE NB
Safety Patrol of A90 SAFETY PATROL on 31 March 2022									
NE7-829831-238619891	62m	0m	GULLY	Cracked or broken (IBCK)	CAT 1	28/04/2022	Completed Defects	26/04/2022	JUST AFTER STRATHMARTINE RD RBT NB

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 SAFETY INSPECTION on 08 August 2022									
NE7-910005-238889733	757m	0m	FOOTWAY	Overgrown by vegetation (OVGV)	CAT 2		Cat 2 Awaiting Action		JUST BEFORE OLD GLAMIS RD RBT NB