

Inspection Defect Summary Report



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
10940/55 : SP DEREST SIGN CROMDALE TO U269 HAUGHS CROMDALE RD									
Safety Inspection of A95.A96 SAFETY INSPECTION on 08 October 2020									
NE131606018-237872338	1,623m	0m	TRAFFIC_SIGNS	Legibility distance (direct) failure (LEGF)	CAT 1	05/11/2020	Completed Defects	23/10/2020	SB BEFORE DALLACHAPEL
NE131606018-237872339	302m	0m	TRAFFIC_SIGNS	Legibility distance (direct) failure (LEGF)	CAT 1	05/11/2020	Completed Defects	23/10/2020	SB BEFORE CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 15 October 2020									
NE131606207-237893605	2,197m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/10/2020	Completed Defects	15/10/2020	NB AFTER CROMDALE
NE131606207-237893606	3,666m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/10/2020	Completed Defects	15/10/2020	NB BEFORE DALVEY
NE131606207-237893607	3,657m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/10/2020	Completed Defects	15/10/2020	NB BEFORE DALVEY
Reactive Defect Recorded 20/10/2020 12:55:00									
WFE-NE20237905061	1,466m	1,466m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	?
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 November 2020									
NE131608043-237939947	1,375m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	27/11/2020	Completed Defects	26/11/2020	NB AFTER CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 03 December 2020									
NE131608275-237940941	4,239m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/12/2020	Completed Defects	03/12/2020	SB AFTER DALVEY FARM
Reactive Defect Recorded 07/12/2020 12:41:57									
D-NE20237969939	0m	0m	CARRIAGEWAY	Flooding (FLOD)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A95 1/2 mile north of Cromdale @ Dallachapple

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A95.A96 SAFETY INSPECTION on 10 December 2020									
NE131608526-237968347	1,908m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/01/2021	Completed Defects	23/12/2020	SB BEFORE CROMDALE
NE131608526-237968348	1,910m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/01/2021	Completed Defects	23/12/2020	SB BEFORE CROMDALE
NE131608526-237968349	1,900m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/01/2021	Completed Defects	23/12/2020	SB BEFORE CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 17 December 2020									
NE131608751-237977980	4,240m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/01/2021	Completed Defects	23/12/2020	SB AFTER DALVEY FARM
NE131608751-237977982	654m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/01/9999	Cat 2 Awaiting Action	23/12/2020	SB AT DALACHAPLE
NE131608751-237977981	1,653m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/12/2020	Completed Defects	17/12/2020	NB AFTER CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 January 2021									
NE131609344-237993843	2,455m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/01/2021	Completed Defects	06/01/2021	NB BEFORE DALVEY FARM
Weekly Patrol of A95.A96 SAFETY INSPECTION on 14 January 2021									
NE131609712-237995301	402m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	3RD PTY	11/02/2021	Awaiting CCMS Permanent Date	01/01/9999	SB BEFORE CROMDALE
NE131609712-237995302	4,693m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/01/2021	Completed Defects	14/01/2021	SB BEFORE DALVEY
NE131609712-237995300	403m	0m	Culvert	Flooding (FLOD)	CAT 1	11/02/2021	Completed Defects	19/01/2021	SB BEFORE CROMDALE
Reactive Defect Recorded 20/01/2021 12:15:34									
D-NE21237996624	0m	0m	TREE	Dead tree (DTRE)	CAT 1	17/02/2021	Completed Defects	25/02/2021	SP DEREST SIGN CROMDALE TO U269 HAUGHS CROMDALE RD 10940/55 1324ch E308383.231936861 N829931.860853086
Safety Inspection of A95.A96 SAFETY INSPECTION on 20 January 2021									
NE131609760-237995908	4,693m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/01/2021	Completed Defects	20/01/2021	NB BEFORE DALVEY FARM

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE131609760-237995905	257m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/01/2021	Completed Defects	20/01/2021	S BEFORE CROMDALE
NE131609760-237995906	256m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/01/2021	Completed Defects	20/01/2021	SB BEFORE CROMDALE
NE131609760-237995907	254m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/01/2021	Completed Defects	20/01/2021	SB BEFORE CROMDALE
Weekly Patrol of A95.A96 SAFETY INSPECTION on 22 January 2021									
NE131609927-237996710	2,990m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/01/2021	Completed Defects	22/01/2021	SB AFTER DALVEY FARM
Safety Inspection of A95.A96 SAFETY INSPECTION on 27 January 2021									
NE131609953-237996708	660m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/02/2021	Completed Defects	10/03/2021	SB AT DALLACHAPPLE
Safety Inspection of A95.A96 SAFETY INSPECTION on 03 February 2021									
NE131610268-237997788	3,667m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/03/2021	Completed Defects	17/02/2021	NB BEFORE DALVEY FARM
NE131610268-237997789	3,652m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/02/2021	Completed Defects	03/02/2021	NB BEFORE DALVEY FARM
Weekly Patrol of A95.A96 SAFETY INSPECTION on 05 February 2021									
NE131610523-237999981	1,911m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BEFORE DALLACHAPPLE
NE131610523-237999982	1,906m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFTER DALLACHAPPLE
NE131610523-237999980	1,906m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BEFORE DALLACHAPPLE
NE131610523-237999983	1,945m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFTER DALLACHAPPLE
NE131610523-237999984	1,979m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFTER DALLACHAPPLE
Safety Inspection of A95.A96 SAFETY INSPECTION on 10 February 2021									
NE131610550-238001645	1,379m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/02/2021	Completed Defects	10/02/2021	NB AFTER DALLACHAPPLE

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE131610550-238001646	1,390m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/02/2021	Completed Defects	10/02/2021	NB AFTER DALLACHAPPLE
NE131610550-238001647	3,655m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/02/2021	Completed Defects	10/02/2021	SB AFTER DALVEY FARM
NE131610550-238001648	3,651m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/02/2021	Completed Defects	10/02/2021	SB AFTER DALVEY FARM
NE131610550-238001649	3,652m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/02/2021	Completed Defects	10/02/2021	SB AFTER DALVEY FARM
NE131610550-238001650	3,680m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/02/2021	Completed Defects	10/02/2021	NB BEFORE DALVEY FARM
Safety Inspection of A95.A96 SAFETY INSPECTION on 03 March 2021									
NE131616403-238008231	647m	0m	CARRIAGEWAY	Patch - adjacent cracking (PACK)	CAT 2		Cat 2 Awaiting Action		SB AT DALLACHAPPEL
NE131616403-238008230	669m	0m	CARRIAGEWAY	Patch - adjacent cracking (PACK)	CAT 2		Cat 2 Awaiting Action		SB AT DALLACHAPPEL
NE131616403-238008229	661m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2		Cat 2 Awaiting Action		SB AT DALLACHAPPEL
NE131616403-238008228	667m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/03/2021	Completed Defects	03/03/2021	SB AT DALLACHAPPEL
Safety Inspection of A95.A96 SAFETY INSPECTION on 10 March 2021									
NE131619294-238010567	1,182m	0m	MANHOLE	Rocking under load (IRLD)	3RD PTY	07/04/2021	Completed Defects	10/03/2021	SB BEFORE DALLACHAPPLE
Safety Inspection of A95.A96 SAFETY INSPECTION on 17 March 2021									
NE131622178-238018742	4,032m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE131622178-238018741	4,029m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/03/2021	Completed Defects	17/03/2021	SB AFTER DALVEY FARM
Safety Inspection of A95.A96 SAFETY INSPECTION on 31 March 2021									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE131627774-238037307	1,795m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	3RD PTY	28/04/2021	Awaiting CCMS Permanent Date	01/01/9999	SB BEFORE DALLACHAPPLE
NE131627774-238037308	1,792m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	28/04/2021	Completed Defects	27/04/2021	SB BEFORE DALLACHAPPLE
Safety Inspection of A95.A96 SAFETY INSPECTION on 07 April 2021									
NE11630658-238046370	3,591m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/05/2021	Completed Defects	28/04/2021	NB TULLCHAN ESTATE
NE11630658-238046371	3,678m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/05/2021	Completed Defects	28/04/2021	NB TULLCHAN ESTATE
NE11630658-238046372	3,655m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/05/2021	Completed Defects	28/04/2021	NB TULLCHAN ESTATE
NE11630658-238046373	3,655m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB TULLCHAN ESTATE
NE11630658-238046369	2,204m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/04/2021	Completed Defects	07/04/2021	NB AFT CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 14 April 2021									
NE131633516-238047076	3,389m	0m	BOLLARDS	Missing (MISS)	CAT 1	12/05/2021	Completed Defects	11/05/2021	NB BEFORE DALVEY FARM
NE131633516-238047075	3,330m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/05/2021	Completed Defects	11/05/2021	SB AFTER DALVEY FARM
NE131633516-238047077	2,936m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
Safety Inspection of A95.A96 SAFETY INSPECTION on 28 April 2021									
NE131639531-238063087	4,239m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/04/2021	Completed Defects	28/04/2021	SB AFTER DALVEY FARM
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 May 2021									
NE131643068-238102211	647m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	02/06/2021	Completed Defects	18/05/2021	SB BEFORE CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 May 2021									
NE131646971-238111791	4,238m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/05/2021	Completed Defects	12/05/2021	SB AFTER DALVEY FARM
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 May 2021									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE131650817-238120920	217m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE131650817-238120918	258m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE131650817-238120923	1,904m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/06/2021	Completed Defects	08/06/2021	SB BEFORE CROMDALE
NE131650817-238120919	263m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE131650817-238120924	1,917m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/05/2021	Completed Defects	19/05/2021	SB BEFORE CROMDALE
NE131650817-238120921	1,382m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/05/2021	Completed Defects	19/05/2021	NB AFTER CROMDALE
NE131650817-238120916	254m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/05/2021	Completed Defects	19/05/2021	SB BEFORE CROMDALE
NE131650817-238120917	254m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/05/2021	Completed Defects	19/05/2021	SB BEFORE CROMDALE
NE131650817-238120922	1,910m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/05/2021	Completed Defects	19/05/2021	SB BEFORE CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 May 2021									
NE11654501-238131676	1,367m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	23/06/2021	Completed Defects	09/06/2021	NB AFT DALLACHAPPLE
NE11654501-238131682	3,178m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/06/2021	Completed Defects	14/06/2021	NB BEF DALVEY FARM
NE11654501-238131678	1,910m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/06/2021	Completed Defects	09/06/2021	SB BEF DALLACHAPPLE
NE11654501-238131679	1,899m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/06/2021	Completed Defects	09/06/2021	SB BEF DALLACHAPPLE
NE11654501-238131684	3,709m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/06/2021	Completed Defects	26/05/2021	NB BEF DALVEY FARM
NE11654501-238131685	3,708m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/06/2021	Completed Defects	26/05/2021	NB BEF DALVEY FARM

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE11654501-238131687	4,700m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/06/2021	Completed Defects	26/05/2021	NB BEF DALVEY FARM
NE11654501-238131689	4,687m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEF DALVEY FARM
NE11654501-238131690	4,694m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEF DALVEY FARM
NE11654501-238131686	3,702m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEF DALVEY FARM
NE11654501-238131677	1,368m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFT DALLACHAPPLE
NE11654501-238131683	3,178m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEF DALVEY FARM
NE11654501-238131680	1,897m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	27/05/2021	Completed Defects	26/05/2021	NB AFT DALLACHAPPLE
NE11654501-238131688	4,687m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	27/05/2021	Completed Defects	26/05/2021	NB BEF DALVEY FARM
NE11654501-238131681	1,903m	0m	CARRIAGEWAY	Miscellaneous surface Defects (MSRF)	CAT 2		Cat 2 Awaiting Action		NB AFT & SB BEF DALLACHAPPLE
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 June 2021									
NE11658327-238147236	2,984m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/06/2021	Completed Defects	08/06/2021	SB BCR CROMDALE
NE11658327-238147235	2,938m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		CETR .LNE NB AFT CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 June 2021									
NE131662464-238158792	561m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/06/2021	Completed Defects	09/06/2021	SB AFTER DALLACHAPPLE
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 June 2021									
NE11673825-238193835	3,456m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVY FARM

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE11673825-238193834	3,451m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/07/2021	Completed Defects	30/06/2021	SB AFTER DALVY FARM
Detailed Inspection TEMPLATE of A95.A96 DETAIL JULY on 02 July 2021									
NE11671019-535	3,715m	0m	BOLLARDS	Physical condition of fittings (COFT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-495	4,168m	0m	BOLLARDS	Physical condition of fittings (COFT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-513	3,716m	0m	BOLLARDS	Dirty sign (DIRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-496	4,168m	0m	BOLLARDS	Dirty sign (DIRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-538	4,131m	0m	BOLLARDS	Dirty sign (DIRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-500	4,168m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-506	4,686m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-512	3,783m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-540	2,980m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-547	2,457m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-556	2,457m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-558	2,515m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-553	2,457m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE11671019-497	4,168m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-587	1,798m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-608	430m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-609	313m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-610	287m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-611	270m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-602	600m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-605	506m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-607	458m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-588	1,722m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-596	362m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-590	1,664m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-613	237m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-614	223m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE11671019-582	1,943m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-530	3,568m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-520	3,514m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-531	3,583m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-503	4,168m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-516	3,683m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-526	3,306m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-583	1,924m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-576	2,045m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-569	1,800m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-570	1,896m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-571	1,925m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-572	1,939m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE11671019-533	3,647m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-534	3,705m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-502	4,168m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-491	4,154m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-492	4,168m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-575	2,052m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-493	4,168m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-574	2,072m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-511	4,041m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-499	4,168m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-501	4,168m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-517	3,667m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-518	3,661m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-510	4,041m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE11671019-515	3,685m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-514	3,715m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-543	3,165m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-560	2,809m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-549	2,457m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-550	2,457m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-551	2,457m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-552	2,457m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-537	4,017m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-505	4,168m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-542	3,165m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-539	2,933m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-528	3,426m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-545	2,460m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE11671019-521	3,508m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-522	3,502m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-523	3,405m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-524	3,344m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-525	3,325m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-507	4,646m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-584	1,898m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-585	1,898m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-599	560m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-579	2,018m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-580	1,997m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-581	1,972m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-603	610m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-621	277m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE11671019-622	302m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-618	216m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-619	218m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-592	1,649m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-593	1,648m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-594	1,409m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-577	2,037m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-595	1,383m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-589	1,698m	0m	CARRIAGEWAY	Shallow spalling at joints / cracks (SSPL)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-563	1,389m	0m	CARRIAGEWAY	Shallow spalling at joints / cracks (SSPL)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-567	1,723m	0m	Culvert	Free flow impeded (FRFL)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-565	1,519m	0m	Culvert	Free flow impeded (FRFL)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-564	1,479m	0m	Culvert	Free flow impeded (FRFL)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE11671019-529	3,428m	0m	Culvert	Free flow impeded (FRFL)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-519	3,653m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-527	3,408m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-546	2,457m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-532	3,584m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-498	4,168m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-604	617m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-606	507m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-612	248m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-600	560m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-601	562m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE11671019-586	1,858m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-623	311m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-620	221m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-578	2,023m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-597	419m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-598	451m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-591	1,664m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-615	17m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE11671019-616	17m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-617	123m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE11671019-561	2,809m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-562	1,267m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-544	2,594m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-494	4,168m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-554	2,457m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-536	3,834m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-541	3,092m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-548	2,457m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-559	2,653m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-557	2,351m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE11671019-566	1,642m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-573	2,011m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-504	4,168m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
NE11671019-568	1,801m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB BEFORE CROMDALE
NE11671019-488	0m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		NB CROMALE
NE11671019-508	4,293m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-509	4,069m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		NB BEFORE DALVEY FARM
NE11671019-555	2,457m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY FARM
Weekly Patrol of A95.A96 SAFETY INSPECTION on 14 July 2021									
NE131556489-237330475	1,932m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFT CROMDALE
NE131556489-237330474	1,927m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/07/2021	Completed Defects	14/07/2021	SB BFR CROMDALE
NE131556489-237330473	1,936m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/07/2021	Completed Defects	14/07/2021	NB AFTT CROMDALE

Safety Inspection of A95.A96 SAFETY INSPECTION on 28 July 2021



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE131691237-238225364	1,903m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/08/2021	Completed Defects	16/08/2021	NB AFT CROMDALE
NE131691237-238225363	1,877m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/08/2021	Completed Defects	16/08/2021	NB AFT CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 08 September 2021									
NE131717454-238329722	3,713m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	09/09/2021	Completed Defects	08/09/2021	NB BF DALVEY FARM
NE131717454-238329723	3,697m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	09/09/2021	Completed Defects	08/09/2021	NB BEFORE DALVEYVFARM
Safety Inspection of A95.A96 SAFETY INSPECTION on 22 September 2021									
NE131725918-238369135	607m	0m	CARRIAGEWAY	Failed repair (RFAL)	3RD PTY	20/10/2021	Awaiting CCMS Permanent Date	01/01/9999	SB BFR CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 29 September 2021									
NE11730084-238378897	3,583m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/09/2021	Completed Defects	29/09/2021	NB BFR CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 20 October 2021									
NE72-742185-238426773	612m	0m	CARRIAGEWAY	Failed repair (RFAL)	3RD PTY	17/11/2021	Awaiting CCMS Permanent Date	01/01/9999	SB BFR CROMDALE GARBH ATH MHOR BT REF NS9BAT39
Safety Inspection of A95.A96 SAFETY INSPECTION on 03 November 2021									
NE72-750054-238445700	3,304m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2		Cat 2 Awaiting Action		NB AFTER CROMDALE
NE72-750054-238445699	3,301m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/11/2021	Completed Defects	03/11/2021	NB AFTER CROMDALE
NE72-750054-238445698	3,300m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/11/2021	Completed Defects	03/11/2021	NB AFTER CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 10 November 2021									
NE72-753859-238459481	1,903m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/12/2021	Completed Defects	08/12/2021	NB BFR CROMDALE
NE72-753859-238459482	1,909m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/12/2021	Completed Defects	08/12/2021	NB BFR CROMDALE
NE72-753859-238459483	1,923m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/12/2021	Completed Defects	08/12/2021	NB BFR CROMDALE

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE72-753859-238459484	1,680m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/12/2021	Completed Defects	08/12/2021	SB AFT CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 24 November 2021									
NE72-761380-238464724	1,789m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2		Cat 2 Awaiting Action		SB BEFORE ADVIE
NE72-761380-238464723	1,779m	0m	EARTHWORKS	Other (OTHR)	CAT 1	22/12/2021	Completed Defects	22/12/2021	SB BEFORE ADVIE
Safety Inspection of A95.A96 SAFETY INSPECTION on 01 December 2021									
NE72-765059-238467514	397m	0m	CARRIAGEWAY	Flooding (FLOD)	CAT 1	29/12/2021	Completed Defects	22/12/2021	BALNAFETTACH ESTATE, NB AFTER CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 08 December 2021									
NE72-768624-238480569	607m	0m	CARRIAGEWAY	Flooding (FLOD)	CAT 1	05/01/2022	Completed Defects	22/12/2021	NB BFR CROMDALE GARBH ATH MHOR
NE72-768624-238480566	1,878m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/01/2022	Completed Defects	08/12/2021	NB BFR CROMDALE
NE72-768624-238480567	1,838m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/01/2022	Completed Defects	08/12/2021	NB BFR CROMDALE
NE72-768624-238480568	1,268m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	09/12/2021	Completed Defects	08/12/2021	SB AFT CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 15 December 2021									
NE72-772319-238488004	2,201m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/12/2021	Completed Defects	15/12/2021	NB AFTER CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 22 December 2021									
NE72-776066-238490421	2,927m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/12/2021	Completed Defects	22/12/2021	SB AFT CROMDALE
NE72-776066-238490420	1,803m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/12/2021	Completed Defects	22/12/2021	SB AFT CROMDALE
NE72-776066-238490419	1,428m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/12/2021	Completed Defects	22/12/2021	SB AFT CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 January 2022									
NE72-784166-238492210	2,476m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/01/2022	Completed Defects	05/01/2022	SB AFT CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 January 2022									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE72-788245-238501931	2,201m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFT CROMDALE
NE72-788245-238501929	3,341m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/01/2022	Completed Defects	12/01/2022	NB AFT CROMDALE
NE72-788245-238501930	2,199m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/01/2022	Completed Defects	12/01/2022	NB AFT CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 January 2022									
NE72-795843-238547470	3,167m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFT CROMDALE
NE72-795843-238547471	3,161m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	23/02/2022	Completed Defects	14/02/2022	SB AFT CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 February 2022									
NE72-806900-238557295	2,188m	0m	CARRIAGEWAY	Patch - difference in level (PDLV)	CAT 2		Cat 2 Awaiting Action		NB AFT CROMDALE
NE72-806900-238557294	2,196m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	17/02/2022	Completed Defects	16/02/2022	NB AFT CROMDALE
NE72-806900-238557296	2,454m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	17/02/2022	Completed Defects	16/02/2022	NB AFT CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 March 2022									
NE72-814379-238592797	3,514m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	03/03/2022	Completed Defects	02/03/2022	NB AFT CROMDALE
NE72-814379-238592794	317m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BFR CROMDALE
NE72-814379-238592792	329m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BFR CROMDALE
NE72-814379-238592791	349m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BFR CROMDALE
NE72-814379-238592795	330m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/03/2022	Completed Defects	02/03/2022	SB BFR CROMDALE
NE72-814379-238592796	562m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/03/2022	Completed Defects	02/03/2022	SB ON BRIDGE BFR CROMDALE

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE72-814379-238592793	333m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/03/2022	Completed Defects	02/03/2022	SB BFR CROMDALE
NE72-814379-238592798	3,506m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/03/2022	Completed Defects	02/03/2022	NB AFT CROMDALE
NE72-814379-238592799	3,502m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/03/2022	Completed Defects	02/03/2022	NB AFT CROMDALE
NE72-814379-238592800	3,502m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/03/2022	Completed Defects	02/03/2022	NB CENTRE LINE AFT CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 April 2022									
NE72-835942-238642299	400m	0m	Culvert	Other (OTHR)	CAT 1	11/05/2022	Completed Defects	20/04/2022	NB AFT CROMDALE
NE72-835942-238642300	464m	0m	VERGE	Other (OTHR)	CAT 1	11/05/2022	Completed Defects	20/05/2022	NB AFT CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 27 April 2022									
NE72-843048-238656535	1,327m	0m	MANHOLE	Rocking under load (IRLD)	3RD PTY	25/05/2022	Completed Defects	27/04/2022	SB BFR CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 18 May 2022									
NE72-855764-238765594	3,790m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFT CROMDALE
Safety Inspection of A95.A96 SAFETY INSPECTION on 15 June 2022									
NE72-875146-238812621	737m	0m	TRAFFIC_SIGNS	Other (OTHR)	CAT 1	13/07/2022	Completed Defects	06/07/2022	NB AFT DALLACHAPPLE
Safety Inspection of A95.A96 SAFETY INSPECTION on 22 June 2022									
NE72-878666-238815914	2,370m	0m	CARRIAGEWAY	Flooding (FLOD)	CAT 1	20/07/2022	Completed Defects	06/07/2022	SB BEFORE CROMDALE
Detailed Inspection TEMPLATE of A95.A96 DETAIL JULY on 07 July 2022									
NE131880483-750	4,189m	0m	BOLLARDS	Physical condition of fittings (COFT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY
NE131880483-749	4,487m	0m	BOLLARDS	Dirty sign (DIRT)	CAT 2		Cat 2 Awaiting Action		SB AFTER DALVEY
NE131880483-751	4,174m	0m	LAYBY	Localised edge deterioration (LODT)	CAT 2		Cat 2 Awaiting Action		SB LAYBY AFTER DALVEY

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE74-880483-119	392m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD
NE122-880483-261	1,275m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE122-880483-288	2,560m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE122-880483-292	3,004m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE122-880483-287	2,398m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE74-880483-116	2m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD
NE74-880483-120	518m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD
NE74-880483-121	520m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD
NE122-880483-289	2,585m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE122-880483-290	2,604m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		
NE122-880483-291	2,914m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE122-880483-262	1,287m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE122-880483-263	1,280m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE122-880483-264	1,269m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD
NE122-880483-278	523m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE122-880483-286	2,436m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD SB
NE122-880483-285	1,434m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD SB
NE122-880483-296	3,729m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE122-880483-279	524m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE122-880483-268	15m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE122-880483-269	5m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD
NE122-880483-270	13m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD SB
NE122-880483-282	932m	0m	ROAD_STUDS	Missing "catseye" (MISC)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE74-880483-118	104m	0m	ROAD_STUDS	Missing "catseye" (MISC)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD
NE122-880483-284	1,411m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE122-880483-274	198m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE122-880483-275	204m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD SB

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE122-880483-276	290m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD SB
NE122-880483-280	528m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD SB
NE122-880483-281	916m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE122-880483-283	1,420m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE74-880483-114	20m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMADALE RD
NE74-880483-115	41m	0m	ROAD_STUDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMADALE RD
NE74-880483-122	914m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMADALE RD
NE122-880483-273	139m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE122-880483-267	4m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD SB
NE74-880483-124	3,713m	0m	TRAFFIC_SIGNS	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMADALE RD
NE122-880483-271	21m	0m	TRAFFIC_SIGNS	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE122-880483-272	41m	0m	TRAFFIC_SIGNS	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD NB
NE74-880483-125	3,730m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMADALE RD
NE122-880483-265	1,318m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD SB
NE122-880483-266	6m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD SB

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE122-880483-277	516m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMDALE RD SB
NE74-880483-123	1,419m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMADALE RD
NE74-880483-117	189m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		SPEED DEREST SIGN TO HAUGHS CROMADALE RD