

A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	763337 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 20/07/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	763338 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 20/07/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	763339 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 20/07/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	763340 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 20/07/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	763341 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 20/07/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	763394 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 20/07/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	763775 NSW M898_A898 Paisley Safety Patrol Route (R) - Safety Patrol on 20/07/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	763797 NSW M898_A898 Paisley Safety Patrol Route (R) - Safety Patrol on 20/07/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	763766 NSW M898_A898 Paisley Safety Patrol Route (R) - Safety Patrol on 20/07/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	912767 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 01/08/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	763774 NSW M898_A898 Paisley Safety Patrol Route (R) - Safety Patrol on 04/08/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	912876 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 08/08/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	952444 NSW M898_A898 Paisley Safety Patrol Route (R) - Safety Patrol on 11/08/2022	A82 N/B offslip onto the A898 S/B - Asset : 18515/91 - 162 Carriageway - Defect Ref : D-22-SW-02719	1 Temporary, 11/08/2022 Deferred - Permanent
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	942253 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 15/08/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	952461 NSW M898_A898 Paisley Safety Patrol Route (R) - Safety Patrol on 18/08/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	942284 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 22/08/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1140693 NSW M898_A898 Paisley Safety Patrol Route (R) - Safety Patrol on 25/08/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	951885 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 29/08/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	763767 NSW M898_A898 Paisley Safety Patrol Route (R) - Safety Patrol on 02/09/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	952016 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 05/09/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1163308 NSW M898_A898 Paisley Safety Patrol Route (R) - Safety Patrol on 08/09/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	952158 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 12/09/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1163425 NSW M898_A898 Paisley Safety Patrol Route (R) - Safety Patrol on 15/09/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	952437 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 19/09/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1205016 NSW M898_A898 Paisley Safety Patrol Route (R) - Safety Patrol on 22/09/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	952442 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 26/09/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	952448 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 03/10/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	952449 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 10/10/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	952452 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 17/10/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1205681 NSW M898_A898 Paisley Safety Patrol Route (R) - Safety Patrol on 13/10/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1206569 M898/A898 Safety Patrol - Safety Patrol on 21/10/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1206516 (Ad-Hoc) A898/M898 Safety Inspection. - Safety Inspection on 25/10/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	763912 NSW M898_A898 Paisley Safety Inspection Route (R) - Safety Inspection on 27/10/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	763768 NSW M898_A898 Paisley Safety Patrol Route (R) - Safety Patrol on 28/10/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1206518 (Ad-Hoc) M898/A898 Safety Patrol. - Safety Patrol on 28/10/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1161492 NSW M898_A898 Paisley Safety Inspection Route (Tue) - Safety Inspection on 01/11/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1206528 A898/M898, Safety Patrol, Nov 4 - Safety Patrol on 05/11/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1163110 NSW M898_A898 Paisley Safety Inspection Route (Tue) - Safety Inspection on 08/11/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1206530 A898/M898, Safety Patrol, Nov 11 - Safety Patrol on 11/11/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1163356 NSW M898_A898 Paisley Safety Inspection Route (Tue) - Safety Inspection on 15/11/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1206532 A898/M898, Safety Patrol, Nov 18 - Safety Patrol on 18/11/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1204965 NSW M898_A898 Paisley Safety Inspection Route (Tue) - Safety Inspection on 24/11/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1206533 A898/M898, Safety Patrol, Nov 25 - Safety Patrol on 25/11/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1205053 NSW M898_A898 Paisley Safety Inspection Route (Tue) - Safety Inspection on 29/11/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1207118 A898 Erskine Bridge - Footway category C & Other - Visual Condition on 29/11/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1318306 A898 Erskine Bridge AGAIN!! - Cycle Facility category C & Other - Visual Condition on 30/11/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1337499 A898/M898 Safety Patrol, Dec 2 - Safety Patrol on 02/12/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1318306 A898 Erskine Bridge AGAIN!! - Footway category C & Other - Visual Condition on 05/12/2022	No Defects Recorded	0
A898 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND	1318306 A898 Erskine Bridge AGAIN!! - Footway category C & Other - Visual Condition on 08/12/2022	No Defects Recorded	0

Applied filters:

Road is A898

Section/Slicer is 18515/25 - WITH: START OF CYCLE WAY TO START OF BRIDGE, 18515/50 - WITH: START OF BRIDGE TO END OF BRIDGE, or 18515/91 - WITH: A898 NORTHBOUND TO A82 NORTHBOUND

Inspection Activity is Cycle Facility category C & Other - Visual Condition,

Footway category C & Other - Visual Condition, Safety Inspection, or Safety Patrol

Date is on or after 01/04/2022 00:00:00 and is before 06/12/2022 00:00:00