

Defect Source	Defect Date	Road Section	Chainage	XSP	Location	Defect Category	Asset Type	Defect Type	Defect Reference	Element
Safety Inspection	11/09/2024	A84	16225/14	173	CL1 North of Strathyre Log Cabins jct n/b	CAT1	Carriageway	Failed Patch/Trench	D-24-NW-25721	E-24-NW-11493-C
Safety Inspection	11/09/2024	A84	16225/14	168	CL1 North of Strathyre Log Cabins jct n/b	CAT1	Carriageway	Cracking	D-24-NW-25719	E-24-NW-11491-C
Safety Inspection	28/08/2024	A84	16225/14	2224	CL1 South of The Cabin Vistor Centre n/b	CAT1	Carriageway	Pothole	D-24-NW-24427	E-24-NW-10808-C
Safety Inspection	22/03/2024	A84	16225/14	1213	CL1 South of loch lubnaig South carpark n/b	CAT1	Carriageway	Bituminous surfacing fretting	D-23-NW-73611	E-24-NW-03588-C
Safety Inspection	22/03/2024	A84	16225/14	1210	CL1 South of loch lubnaig South carpark n/b	CAT1	Carriageway	Bituminous surfacing fretting	D-23-NW-73610	E-24-NW-03587-C
Safety Inspection	22/03/2024	A84	16225/14	943	CL1 South of loch lubnaig South carpark n/b	CAT1	Carriageway	Bituminous surfacing fretting	D-23-NW-73607	E-24-NW-03598-C
Safety Inspection	22/03/2024	A84	16225/14	942	CL1 South of loch lubnaig South carpark n/b	CAT1	Carriageway	Bituminous surfacing fretting	D-23-NW-73605	E-24-NW-03597-C
Safety Inspection	22/03/2024	A84	16225/14	938	CL1 South of loch lubnaig South carpark n/b	CAT1	Carriageway	Bituminous surfacing fretting	D-23-NW-73604	E-24-NW-03589-C
Safety Inspection	26/01/2024	A84	16225/14	180	CL1 South of St. Brides Church n/b	CAT1	Carriageway	Failed Patch/Trench	D-23-NW-69645	E-23-NW-20194-C
Safety Inspection	15/12/2023	A84	16225/14	217	CL1 South of St Brides Church	CAT1	Carriageway	Cracking	D-23-NW-68156	E-23-NW-17951-C
Safety Inspection	15/12/2023	A84	16225/14	206	CL1 South of St Brides Church	CAT1	Carriageway	Failed Patch/Trench	D-23-NW-68155	E-23-NW-17949-C
Safety Inspection	21/11/2023	A84	16225/14	252	CC south of st brides Church	CAT1	Carriageway	Surfacing joints	D-23-NW-66668	E-23-NW-16451-C
Safety Inspection	21/11/2023	A84	16225/14	259	CC south of st brides Church	CAT1	Carriageway	Surfacing joints	D-23-NW-66666	E-23-NW-16449-C
Safety Inspection	21/11/2023	A84	16225/14	281	CC south of st brides Church	CAT1	Carriageway	Surfacing joints	D-23-NW-66665	E-23-NW-16447-C
Safety Inspection	21/11/2023	A84	16225/14	293	CC south of st brides Church	CAT1	Carriageway	Surfacing joints	D-23-NW-66664	E-23-NW-16445-C
Safety Inspection	17/11/2023	A84	16225/14	331	CR1 South of St Brides Chapel	CAT1	Carriageway	Bituminous surfacing fretting	D-23-NW-66432	E-23-NW-16200-C
Safety Inspection	06/10/2023	A84	16225/14	1216	CL1 South of Loch Lubnaig Car Park n/b	CAT1	Carriageway	Bituminous surfacing fretting	D-23-NW-62671	E-23-NW-13525-C
Safety Inspection	06/10/2023	A84	16225/14	1216	CL1 South of Loch Lubnaig Car Park n/b	CAT1	Carriageway	Bituminous surfacing fretting	D-23-NW-62670	E-23-NW-13523-C
Safety Inspection	03/10/2023	A84	16225/14	179	CL1 North of Strathyre forest cabins n/b	CAT1	Carriageway	Bituminous surfacing fretting	D-23-NW-59007	E-23-NW-13302-C
Safety Inspection	27/04/2023	A84	16225/14	940	CL1 South of Loch Lubnaig picnic area n/b	CAT1	Carriageway	Bituminous surfacing fretting	D-23-NW-04484	E-23-NW-04242-C