

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/08/2017 and 13/02/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'Holmston Rbt to start of 3 lane',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
11641/07 : Holmston Rbt to start of 3 lane									
Detailed Inspection TEMPLATE of A77 Ayr N Det on 15 September 2017									
SW82256027-72	726m	806m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	0 HOLMSTON RBT TO WHITLETTS RBT
SW82256027-70	285m	365m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	0 HOLMSTON RBT TO WHITLETTS RBT
SW82256027-71	314m	394m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	0 HOLMSTON RBT TO WHITLETTS RBT
SW82256027-77	1,548m	1,628m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	0 HOLMSTON RBT TO WHITLETTS RBT
SW82256027-79	1,840m	1,920m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	0 HOLMSTON RBT TO WHITLETTS RBT
SW82256027-73	903m	983m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	0 HOLMSTON RBT TO WHITLETTS RBT
SW82256027-75	1,244m	1,324m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	0 HOLMSTON RBT TO WHITLETTS RBT
SW82256027-76	1,408m	1,488m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	0 HOLMSTON RBT TO WHITLETTS RBT
SW82256027-78	1,682m	1,762m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	0 HOLMSTON RBT TO WHITLETTS RBT
SW82256027-68	40m	80m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	0 HOLMSTON RBT TO WHITLETTS RBT
SW82256027-69	87m	167m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	0 HOLMSTON RBT TO WHITLETTS RBT
SW82256027-67	20m	120m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	0 HOLMSTON RBT TO WHITLETTS RBT
SW82256027-74	1,088m	1,168m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	0 HOLMSTON RBT TO WHITLETTS RBT

Detailed Inspection - All other Footways of A77 Ayr N Det
No defects recorded

