

STSV Incident Report

General Details	
Incident ID	00044124
Contract	STSW
Issued	10/07/2016 19:14:08
Status	O
BeCogent Ref:	
Weather	Fine no high winds
Other Cause	

Incident Details	
Incident Cat	SPIL
Incident Type	Diesel
O/I Ref	
Defect Ref	
Police Inc. No:	
Incident Description	
Diesel spillage on slip	

Organisation	Contacts	Contact Phone	Contact Mobile	Contact Email
Police Scotland	Police Scotland			

Location Details				
Region	Route	Junction	Marker Post	
	A898			
Location Description: A898 n/b slip to A82				
Easting	247052	Northing	672896	Link/Section: 18515/91

Vehicle Response				
ISURef	Time Called	Time Allocated	Time Arrived	Time Departed
PAPA 1	10/07/2016 19:00:00	10/07/2016 19:00:00	10/07/2016 19:10:00	10/07/2016 19:30:00

No Trace	False
----------	-------

Vehicles Involved							
Make/Model	Vehicle Registration	Colour	Driver	Foreign Vehicle	Slight Injuries	Serious Injuries	Fatal Injuries

Damage

Action Date	Actions Taken
10/07/2016 19:00:00	Papa 1 attending a report of a diesel spillage on slip at locus.
10/07/2016 19:26:00	ISU Report no trace however 5 Litres of fuel safe used as precaution.

STSV Incident Report

General Details	
Incident ID	00045593
Contract	STSW
Issued	28/08/2016 08:00:21
Status	O
BeCogent Ref:	
Weather	
Other Cause	

Incident Details	
Incident Cat	DEB
Incident Type	Carriageway
O/I Ref	16SW04891
Defect Ref	D-SW162175186
Police Inc. No:	
Incident Description	
Mudguard in lane 1	

Organisation	Contacts	Contact Phone	Contact Mobile	Contact Email
Scotland Transerv	Tango 2			

Location Details				
Region	Route	Junction	Marker Post	
	A898			
Location Description	IMDB A898 N/B - A82 N/B D-SW162175186			
Easting	246982	Northing	672776	Link/Section 18515/91

Vehicle Response				
ISURef	Time Called	Time Allocated	Time Arrived	Time Departed
TANGO 2	28/08/2016 08:00:00	28/08/2016 08:00:00	28/08/2016 08:00:00	28/08/2016 08:05:00
No Trace	False			

Vehicles Involved							
Make/Model	Vehicle Registration	Colour	Driver	Foreign Vehicle	Slight Injuries	Serious Injuries	Fatal Injuries

Damage

Action Date	Actions Taken
28/08/2016 08:04:00	Debris uplifted

STSV Incident Report

General Details	
Incident ID	00046225
Contract	STSW
Issued	18/09/2016 09:00:34
Status	O
BeCogent Ref:	
Weather	
Other Cause	

Incident Details	
Incident Cat	BDAM
Incident Type	Verge Barrier
O/I Ref	
Defect Ref	D-SW162215553
Police Inc. No:	
Incident Description	
Damaged Nearside Barrier	

Organisation	Contacts	Contact Phone	Contact Mobile	Contact Email
Scotland Transerv	Tango 2			

Location Details				
Region	Route	Junction	Marker Post	
	A898			
Location Description: MOI-SW1633129 - A898 N/B slip to A82 S/B (Clydebank), D-SW162215553				
Easting	247152	Northing	672966	Link/Section: 18515/93

Vehicle Response				
ISURef	Time Called	Time Allocated	Time Arrived	Time Departed
TANGO 2	18/09/2016 09:00:00	18/09/2016 09:00:00	18/09/2016 09:00:00	18/09/2016 09:15:00

No Trace	False
----------	-------

Vehicles Involved							
Make/Model	Vehicle Registration	Colour	Driver	Foreign Vehicle	Slight Injuries	Serious Injuries	Fatal Injuries

Damage	
Single Sided Box Beam (OBB)	1 x 4.8m length of OBB
Post	2 x Posts

Action Date	Actions Taken
18/09/2016 09:15:00	From Tango 2 - nearside barrier damaged taped, marked and photographed.
18/09/2016 09:15:00	E-mailed to [REDACTED]