

SE Trunk Roads - Incident Report**ASE214765-2016****Incident Details**

Incident Logged	12/08/2016 13:50:00	Category	Minor
Incident Type	Road Traffic Collision	Junction	-
Route / Direction	A1 Southbound	Section	10147/17
Loc Description	Haddington Abbotsview	Co-ordinates	362385, 677437

Incident Details **OCR notified of vehicle striking central reserve on A1 EB Haddington Abbotsview****Resources Deployed**

Resource	Issued	Arrived	Departed	Response
SE1 (TRISS)	12/08/2016 13:50:00	12/08/2016 14:07:00	12/08/2016 14:39:00	00:17

Communications Log**12/08/2016 13:50:00 - Police Scotland to Amey OCR (Telephone)**

OCR notified of vehicle striking central reserve on A1 EB Haddington Abbotsview (BBOU)

12/08/2016 14:11:00 - SE1 to Amey OCR (Airwave)

A1 EB Oaktree lane 2 closed due to RTC. Vehicle struck centre reservation. Police and recovery on site to remove vehicle. SE1 providing assistance (BBOU)

12/08/2016 14:39:00 - SE1 to Amey OCR (Airwave)

A1 SB Oaktree/Haddington all cleared from RTC on lane 2. Vehicle recovered and uplifted from hard shoulder. Triss and police off site (BBOU)

Network Damage

Asset Type	Quantity	Description
Barrier: Post for TCB/OBB	5.00	5 POST
Barrier: TCB (Tension Corrugated Beam))	4.00	4 tcb Beams

Vehicles Involved

VRM	Manufacturer and Model	Description
SL57 ZVN	Fiat Punto	Blue Car

Roadkill

Close-out

Damage to Crown Property

- Damage identified
- Debris removed
- Spillage treated

Other Responders

- Police attended the Incident
- Ambulance Service / Medics attended the Incident
- Scottish Fire & Rescue attended the Incident

Network Disruption

Type

Lanes Affected

Duration (mins)

- Fuel supplied to allow vehicle to move on