



Incident Type	Road Name	SECTION CODE	XSP	Direction of Travel	Disruption Caused	Weather Conditions	Road Condition	Initial Response Date	Secondary Response	Description	Incident log
Flooding	M9	10308/23	CL1	Southbound	N	UNKNOWN	WET OR DAMP	04/02/2017 13:50:00	01/01/9999 00:00:00	Police reported a drainage issue to the OCR	04/02/2017 13:30:00 - Police Scotland to Amey OCR (Telephone) Police reported a drainage issue to the OCR (JHIG) 04/02/2017 14:25:00 - SE2 to Amey OCR (Airwave) Triss cleared 9 gullies of debris (leaves and mud) and water slowly cleared (JHIG)
Flooding	M9	10309/76	LH	Southbound	N	UNKNOWN	WET OR DAMP	22/07/2017 16:50:00	01/01/9999 00:00:00	Se2 reported flooding to the OCR	22/07/2017 16:50:00 - SE2 to Amey OCR (Airwave) Se2 reported flooding to the OCR (JHIG) 22/07/2017 17:00:00 - SE2 to Amey OCR (Airwave) there is a lot of water running from the verge on to the H/S and heading for lane 1, Triss is going to clear the gullies in the area to allow the water to disperse (JHIG)
Flooding	M9	10309/76	CL1	Southbound	N	UNKNOWN ?		31/12/2017 08:30:00	01/01/9999 00:00:00	SE3 reported a drainage issue to the OCR	31/12/2017 08:30:00 - SE3 to Amey OCR (Airwave) SE3 reported a drainage issue to the OCR (JHIG) 31/12/2017 08:40:00 - SE3 to Amey OCR (Airwave) Cleared 3 gullies of debris, water has been cleared from lane 1 and 2 (JHIG)
Flooding	M9	10309/65	LH	Northbound	N	RAINING NO HIGH WINDS	WET OR DAMP	16/06/2018 15:15:00	01/01/9999 00:00:00	Blocked gullies reported by SE2	16/06/2018 15:15:00 - SE2 to Amey OCR (Telephone) SE2 reported 6 gullies blocked. They will clear and report back. (GTHO) 16/06/2018 16:02:00 - SE2 to Amey OCR (Telephone) SE2 reported the 6 gullies cleared (GTHO)
Flooding	M9	10330/87	LH	Westbound	N	FINE NO HIGH WINDS	DRY	05/06/2019 07:00:00	01/01/9999 00:00:00	SE2, Drainage	05/06/2019 06:50:00 - Trunk Roads Cust Care to Amey OCR (Telephone) TRCC passed report to OCR of reported Drainage issues at the Junction 5 offslip and on the centre Res between 4 & 5. OCR confirms details. (AKER) 05/06/2019 06:54:00 - Amey OCR to Amey OCR (Telephone) OCR Contacted SE2 for assist. SE2 Confirms. (AKER) 05/06/2019 07:05:00 - Amey OCR to Amey OCR (Telephone) SE2 Onsite. Confirm Large area of water over Lane 1, 2 and encroaching Lane 3. SE2 attending scene. (AKER) 05/06/2019 07:35:00 - SE2 to Amey OCR (Telephone) SE2 Confirm Cleared 4 x gullies. Water has receded to Lane 1. Route Engineer (Anne Pearsons) and Drainage Crew Notified. SE2 Confirms. On and Off times confirmed. (AKER)
Flooding	M9	10309/55	LH	Northbound	N	FINE NO HIGH WINDS	WET OR DAMP	27/07/2019 12:50:00	01/01/9999 00:00:00	SE2, Gully Check/Clear	27/07/2019 12:50:00 - SE2 to Amey OCR (Telephone) SE2 Reports Checking and clearing Gullies on M9. OCR Copys. SE2 Will Report after checking section. (AKER) 27/07/2019 13:35:00 - Amey OCR to SE2 (Airwave) OCR Request Assist for RTC Reported at Hermiston Gait. SE2 Confirms enroute. Will report section results ASAP. OCR Confirms. (AKER)
Flooding	M9	10309/38	CL1	Southbound	N	FINE NO HIGH WINDS	DRY	29/07/2018 20:30:00	01/01/9999 00:00:00	PS reported Standing Water to OCR. Cleared @ 20:50	29/07/2018 20:14:00 - Police Scotland to Amey OCR (Telephone) Reported Standing Water, M9 SB J4-3 (Lane 1). OCR confirmed will issue team tpo clear gullies to assist water clearing. (PS No. 3492). (KRID) 29/07/2018 20:15:00 - Amey OCR to Amey ISU (Telephone) Requested B/Muir ISU attend and clear gllies relating to standing water. ISU confirmed on route. (KRID) 29/07/2018 20:50:00 - Amey ISU to Amey OCR (Telephone) B/Muir ISU confirmed 3x Gullies cleared. Provided on/offsite times. (KRID)
Flooding	M9	10308/73	LH	?	N	UNKNOWN ?		01/01/2018 15:45:00	01/01/9999 00:00:00	Drainage issue reported by Amey Route Inspector	01/01/2018 15:13:00 - Amey Office Employee to Amey OCR (Telephone) Drainage issue reported by Amey Route Inspector. ISU tasked to put out Flood Warning signs. (GTHO) 01/01/2018 16:00:00 - Amey ISU to Amey OCR (Telephone) ISU reported signage in place. (GTHO)