

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 27/06/2018 and 05/07/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'THE MOORINGS TO GOGO ST JUNCTION',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
14015/72 : THE MOORINGS TO GOGO ST JUNCTION									
Safety Inspection of A78 Ayr V1 on 27 June 2018									
SW82370027-235867563	340m	341m	MANHOLE	Rocking under load (IRLD)	3RD PTY	25/07/2018	Completed Defects	14/11/2018	A78 NB CW OPPOSITE SUZUKI GARAGE MAIN ST LARGS

Safety Inspection of A78 Ayr V1 on 04 July 2018
No defects recorded

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 28/06/2018 and 15/10/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'NELSON STREET JUNCTION TO THE MOORINGS',) Or

(Section is 'ACCESS TO SERVICE ROAD TO NELSON STREET JUNCTION',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
14015/18 : ACCESS TO SERVICE ROAD TO NELSON STREET JUNCTION									
Safety Inspection of A78 Ayr V1 on 04 July 2018									
SW82373742-235888493	2,448m	2,449m	FOOTWAY	Bituminous surfacing - potholes (BPOT)	CAT 1	01/08/2018	Completed Defects	04/07/2018	A78 LEFT OFF NB CW OUTSIDE BRISBANE HOUSE LARGS
Safety Inspection of A78 Ayr V1 on 11 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 18 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 25 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 01 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 08 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 15 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 22 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 29 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 05 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 12 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 19 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 26 September 2018									
SW82413151-236081877	0m	200m	SHRUB	Overhanging/o vergrown (OVER)	3RD PTY	24/10/2018	Completed Defects	14/11/2018	A78 NB EDGE, PRIOR TO LARGS NTH GATEWAY
SW82413151-236081878	2,297m	2,298m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/10/2018	Completed Defects	26/09/2018	A78 ON CL SOUTH OF VIKINGAR LARGS
SW82413151-236081879	2,408m	2,409m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/10/2018	Completed Defects	26/09/2018	A78 NB CW, OPP NHS BUILDING LARGS
Safety Inspection of A78 Ayr V1 on 03 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 10 October 2018									
SW82419745-236112427	2,429m	2,430m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/10/2018	Completed Defects	10/10/2018	A78 SB CW OUTSIDE BRISBANE HOUSE HOUSE LARGS
Safety Inspection of A78 Ayr V1 on 17 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 24 October 2018									
SW82425913-236154327	2,060m	2,061m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/10/2018	Completed Defects	24/10/2018	A78 SB CW 10M VEFORÉ ENTRANCE TO VIKINGAR LARGS
Safety Inspection of A78 Ayr V1 on 31 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 07 November 2018									

No defects recorded

Safety Inspection of A78 Ayr V1 on 14 November 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 21 November 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 28 November 2018

SW82426873-236234298 2,151m 2,152m CARRIAGEWAY Pothole VIAFIX (POTV) CAT 1 29/11/2018 Completed Defects 28/11/2018 A78 SB CW AT VIKINGAR EXIT

SW82426873-236234299 2,148m 2,149m CARRIAGEWAY Pothole VIAFIX (POTV) CAT 1 29/11/2018 Completed Defects 28/11/2018 A78 NB CW OUTSIDE RNLI LARGS

Safety Inspection of A78 Ayr V1 on 05 December 2018

SW82427166-236238942 43m 142m SHRUB Overhanging/o vergrown (OVER) CAT 1 02/01/2019 Completed Defects 05/12/2018 A78 SB CW 50M NORTH OF LARGS NORTH GATEWAY

Safety Inspection of A78 Ayr V1 on 12 December 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 19 December 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 26 December 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 02 January 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 09 January 2019

SW82428018-236271236 1,705m 1,705m GULLY Other (OTHR) CAT 1 10/01/2019 Completed Defects 09/01/2019 A78 S/B C/W OPOSITE AUBERY VIEW LARGS

Safety Inspection of A78 Ayr V1 on 16 January 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 23 January 2019

SW82428334-236284132 631m 632m GULLY Blockage (BLOK) CAT 1 20/02/2019 Completed Defects 23/01/2019 A78 NB CW 20M NORTH OF DANEFIELD AVENUE JCT LARGS

SW82428334-236284133 32m 33m GULLY Blockage (BLOK) CAT 1 20/02/2019 Completed Defects 23/01/2019 A78 LARGS NORTH GATEWAY

Safety Inspection of A78 Ayr V1 on 30 January 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 06 February 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 13 February 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 20 February 2019

SW82432750-236330362 2,351m 2,351m CARRIAGEWAY Pothole VIAFIX (POTV) CAT 1 21/02/2019 Completed Defects 20/02/2019 A78 S/B 100MTRS PASS HUNTERSTON R/A

Safety Inspection of A78 Ayr V1 on 27 February 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 06 March 2019

SW82440812-236343634 1,715m 1,715m GULLY Blockage (BLOK) CAT 1 03/04/2019 Completed Defects 06/03/2019 A78 N/B OUTSIDE AUBREY FLAT GREENOCK ROAD @ BARR CRES

Safety Inspection of A78 Ayr V1 on 13 March 2019

SW82446497-236433951 1,739m 1,740m GULLY Blockage (BLOK) CAT 1 10/04/2019 Completed Defects 21/03/2019 A78 N/B OPP AUBERY VIEW LARGS

SW82446497-236433952 1,706m 1,707m GULLY Blockage (BLOK) CAT 1 10/04/2019 Completed Defects 21/03/2019 A78 N/B POO AUBERY VIEW LARGS

Safety Inspection of A78 Ayr V1 on 20 March 2019

SW82452163-236463782 1,089m 1,089m TRAFFIC_SIGNS Obscured sign (OBSG) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999 A78 @ROUTENBURN

Safety Inspection of A78 Ayr V1 on 27 March 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 03 April 2019

SW82466422-236493263 1,135m 1,135m MANHOLE Rocking under load (IRLD) 3RD PTY 04/04/2019 Completed Defects 03/04/2019 A78 N/B @ TRAFFIC LIGHTS @ PEARSON GARAGE LARGS

SW82466422-236493264	1,505m	1,505m	GULLY	Blockage (BLOK)	CAT 1	04/04/2019	Completed Defects	03/04/2019	A78 N/B @ ENTRY TO NO 23 GREENOCK RD HOUSE NAME IS LAURISTON @ WILLOWBANK HOTEL
Safety Inspection of A78 Ayr V1 on 08 April 2019									
No defects recorded									
Safety Inspection of A78 Ayr V1 on 10 April 2019									
SW82475940-236554158	1,665m	1,666m	CATCHPIT	Blockage (BLOK)	CAT 1	08/05/2019	Completed Defects	01/05/2019	A78 N/B OPPOSITE NO 84 GREENOCK RD LARGS
SW82475940-236554159	680m	681m	CATCHPIT	Blockage (BLOK)	CAT 1	08/05/2019	Completed Defects	25/04/2019	A78 N/B 30M AFTER DANEFIELD AVE LARGS
SW82475940-236554160	793m	794m	CATCHPIT	Blockage (BLOK)	CAT 1	08/05/2019	Completed Defects	25/04/2019	A78 N/B 80M PRIOR TO DANEFIELD AVE LARGS
SW82475940-236554161	44m	45m	CATCHPIT	Blockage (BLOK)	CAT 1	08/05/2019	Completed Defects	25/04/2019	A78 N/B AT LARGS GATEWAY SIGN
SW82475940-236554165	2,066m	2,100m	CATCHPIT	Blockage (BLOK)	CAT 1	08/05/2019	Completed Defects	01/05/2019	A78 S/B BUS STOP AT VTKINGAR LARGS
Safety Inspection of A78 Ayr V1 on 17 April 2019									
No defects recorded									
Safety Inspection of A78 Ayr V1 on 24 April 2019									
No defects recorded									
Safety Inspection of A78 Ayr V1 on 01 May 2019									
No defects recorded									
Safety Inspection of A78 Ayr V1 on 08 May 2019									
No defects recorded									
Safety Inspection of A78 Ayr V1 on 15 May 2019									
No defects recorded									
Safety Inspection of A78 Ayr V1 on 22 May 2019									
No defects recorded									
Safety Inspection of A78 Ayr V1 on 29 May 2019									
No defects recorded									
Safety Inspection of A78 Ayr V1 on 05 June 2019									
SW82519941-236809385	1,961m	1,962m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/06/2019	Completed Defects	05/06/2019	A78 N/B C/W 150M SOUTH OF TRAFFIC LIGHTS FAIRLY
Detailed Inspection TEMPLATE of A78 Ayr V1 on 12 April 2019									
SW82459961-855	101m	161m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW82459961-856	189m	269m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW82459961-857	193m	293m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW82459961-858	250m	270m	FOOTWAY	Overgrown by vegetation (OVGV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW82459961-893	1,965m	1,965m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW82459961-894	2,018m	218m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW82459961-895	2,055m	2,135m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW82459961-896	2,091m	2,171m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW82459961-898	2,134m	2,174m	FOOTWAY	Bituminous	CAT 2	01/01/9999	Cat 2 Awaiting	01/01/9999	

				surfacing - local cracking (BLCK)			Action	
SW82459961-899	2,210m	2,210m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-900	2,228m	2,308m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-901	2,281m	2,281m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-902	2,304m	2,384m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-903	2,342m	2,342m	FOOTWAY	Bituminous surfacing - potholes (BPOT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-904	2,409m	2,489m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-905	2,434m	2,434m	FOOTWAY	Bituminous surfacing - potholes (BPOT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-906	2,475m	2,555m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-859	319m	399m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-860	320m	400m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-861	341m	421m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-862	428m	468m	FOOTWAY	Overgrown by vegetation (OVGV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-863	477m	497m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-864	585m	585m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-865	656m	656m	FOOTWAY	Overgrown by vegetation (OVGV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-866	675m	675m	GULLY	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-867	675m	755m	FOOTWAY	Overgrown by vegetation (OVGV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-897	2,116m	2,116m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-868	716m	796m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-869	750m	800m	FOOTWAY	Bituminous surfacing -	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999

				<i>local cracking (BLCK)</i>				
SW82459961-870	799m	849m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-871	890m	990m	FOOTWAY	Overgrown by vegetation (OVGV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-872	997m	1,077m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-873	1,057m	1,107m	FOOTWAY	Overgrown by vegetation (OVGV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-874	1,094m	1,094m	FOOTWAY	Bituminous surfacing - potholes (BPOT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-875	1,156m	1,156m	FOOTWAY	Overgrown by vegetation (OVGV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-876	1,209m	1,259m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-877	1,232m	1,242m	CHANNEL	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-878	1,304m	1,344m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-879	1,364m	1,444m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-880	1,457m	1,537m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-881	1,495m	1,525m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-882	1,513m	1,543m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-883	1,543m	1,543m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-884	1,606m	1,636m	FOOTWAY	Overgrown by vegetation (OVGV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-885	1,626m	1,626m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-886	1,671m	1,711m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-887	1,705m	1,755m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-888	1,762m	1,802m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-889	1,772m	1,802m	TRAFFIC_SIGNS	Physical condition of	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999

SW82459961-890	1,863m	1,943m	CARRIAGEWAY	post (COPT) Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW82459961-891	1,917m	1,967m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW82459961-892	1,937m	1,937m	FOOTWAY	Bituminous surfacing - potholes (BPOT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	

Detailed Inspection - All other Footways of A78 Ayr V1

No defects recorded

Detailed Inspection TEMPLATE of A78 Ayr V1 on 10 June 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 12 June 2019

SW82526027-236809387	76m	76m	TREE	Overhanging/o vergrown (OVER)	3RD PTY	13/06/2019	Awaiting CCMS Permanent	01/01/9999	A78 N/B AT LAST BUS STOP GREENOCK RD LARGS
----------------------	-----	-----	------	-------------------------------------	---------	------------	----------------------------	------------	---

Safety Inspection of A78 Ayr V1 on 19 June 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 26 June 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 03 July 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 10 July 2019

SW82531023-236899381	160m	168m	PEDESTRIAN_GU ARDRAIL	Accident damage (ACCD)	CAT 1	07/08/2019	Completed Defects	16/08/2019	A78 N/B APPROX 150M SOUTH OF LARGS GUARD RAIL
SW82531023-236899382	818m	818m	GULLY	Blockage (BLOK)	CAT 1	07/08/2019	Completed Defects	03/08/2019	A78 S/B 148 GREENOCK RD, LARGS

Safety Inspection of A78 Ayr V1 on 17 July 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 24 July 2019

SW82531505-236912391	2,112m	2,112m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/07/2019	Completed Defects	24/07/2019	a78 s/b c/w at traffic lights opposite mli shop, largs
----------------------	--------	--------	-------------	--------------------------	-------	------------	----------------------	------------	---

Safety Inspection of A78 Ayr V1 on 31 July 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 07 August 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 14 August 2019

SW82532384-236939494	91m	216m	FOOTWAY	Overgrown by vegetation (OVGV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	a78 n/b at last bus stop prior to largs north gateway
----------------------	-----	------	---------	--------------------------------------	-------	------------	--------------------------	------------	--

Safety Inspection of A78 Ayr V1 on 21 August 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 28 August 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 04 September 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 11 September 2019

SW82533936-237014750	259m	259m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		a78 197 greenock road largs
----------------------	------	------	-------------	--	-------	--	--------------------------	--	-----------------------------

Safety Inspection of A78 Ayr V1 on 18 September 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 25 September 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 02 October 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 09 October 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 04 July 2018*No defects recorded***Safety Inspection of A78 Ayr V1 on 11 July 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 18 July 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 25 July 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 01 August 2018***No defects recorded***Detailed Inspections - Category B Footways of A78 Largs Footways V1 on 01 August 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 08 August 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 15 August 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 22 August 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 29 August 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 05 September 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 12 September 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 19 September 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 26 September 2018**

SW82413151-236081880	229m	230m	GULLY	Missing (MISS)	3RD PTY	24/10/2018	Completed Defects	14/11/2018	A78 LARGS, PEDESTRIAN CROSSING AT FERRY
----------------------	------	------	-------	----------------	---------	------------	-------------------	------------	---

SW82413151-236081881	233m	234m	FOOTWAY	Slab profile - uneven/trips (SLPF)	CAT 1	24/10/2018	Completed Defects	26/09/2018	A78 SB FW, PED CROSSING AT LARGS FERRY POINT
----------------------	------	------	---------	------------------------------------	-------	------------	-------------------	------------	--

Safety Inspection of A78 Ayr V1 on 03 October 2018*No defects recorded***Safety Inspection of A78 Ayr V1 on 10 October 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 17 October 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 24 October 2018**

SW82425913-236154328	34m	35m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	25/10/2018	Completed Defects	24/10/2018	A78 SB CW OUTSIDE CHURCH AT NARDINIS JCT LARGS
----------------------	-----	-----	---------------	---------------------------	-------	------------	-------------------	------------	--

Safety Inspection of A78 Ayr V1 on 31 October 2018*No defects recorded***Detailed Inspections - Category B Footways of A78 Largs Footways V1 on 31 October 2018**

SW80-426214-5	241m	245m	FOOTWAY	Slab profile - uneven/trips (SLPF)	CAT 1	28/11/2018	Completed Defects	31/10/2018	A78 SB CW AT TRAFFIC LIGHTS OUTSIDE LADBROKES LARGS
---------------	------	------	---------	------------------------------------	-------	------------	-------------------	------------	---

Safety Inspection of A78 Ayr V1 on 07 November 2018*No defects recorded***Safety Inspection of A78 Ayr V1 on 14 November 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 21 November 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 28 November 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 05 December 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 12 December 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 19 December 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 26 December 2018***No defects recorded***Safety Inspection of A78 Ayr V1 on 02 January 2019**

No defects recorded

Safety Inspection of A78 Ayr V1 on 09 January 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 16 January 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 23 January 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 30 January 2019

SW82428608-236291955	191m	191m	FOOTWAY	Slab profile - uneven/trips (SLPF)	CAT 2	27/02/2019	Awaiting CCMS Permanent	01/01/9999	A78 FOOTWAY OUTSIDE PADDLESTEAMER LARGS
----------------------	------	------	---------	------------------------------------	-------	------------	-------------------------	------------	---

Safety Inspection of A78 Ayr V1 on 06 February 2019

No defects recorded

Detailed Inspections - Category B Footways of A78 Largs Footways V1 on 08 February 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 13 February 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 20 February 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 27 February 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 06 March 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 13 March 2019

SW82446497-236433950	220m	226m	CARRIAGEWAY	Miscellaneous surface Defects	CAT 1	10/04/2019	Completed Defects	03/04/2019	A78 N/B OUTSIDE COOP
----------------------	------	------	-------------	-------------------------------	-------	------------	-------------------	------------	----------------------

Safety Inspection of A78 Ayr V1 on 20 March 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 27 March 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 03 April 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 08 April 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 10 April 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 17 April 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 24 April 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 01 May 2019

No defects recorded

Detailed Inspections - Category B Footways of A78 Largs Footways V1 on 08 May 2019

SW82504689-1	23m	24m	FOOTWAY	Bituminous surfacing - potholes (BPOT)	CAT 1	09/05/2019	Completed Defects	08/05/2019	A78 LARGS OPP ST COLUMBA CHURCH
--------------	-----	-----	---------	--	-------	------------	-------------------	------------	---------------------------------

Safety Inspection of A78 Ayr V1 on 08 May 2019

SW82505835-236636343	23m	24m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	09/05/2019	Completed Defects	08/05/2019	A78 AFTER NARDINIES
----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	---------------------

SW82505835-236636344	26m	27m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	09/05/2019	Completed Defects	08/05/2019	A78 LARGS AFTER NARDINIES
----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	---------------------------

SW82505835-236636345	77m	78m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	09/05/2019	Completed Defects	08/05/2019	A78 LARGS OPP ANAYAS RESTURANT
----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------------

SW82505835-236636346	130m	131m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	09/05/2019	Completed Defects	08/05/2019	A78 LARGS OPPCAFE GUZZI
----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	-------------------------

SW82505835-236636347	158m	159m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	09/05/2019	Completed Defects	08/05/2019	A78 LARGS OPP ANCHOR INN
----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------

SW82505835-236636348	166m	167m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	09/05/2019	Completed Defects	08/05/2019	A78 LARGS OPP ANCHOR INN
----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------

Safety Inspection of A78 Ayr V1 on 15 May 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 22 May 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 29 May 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 05 June 2019

No defects recorded

Detailed Inspection TEMPLATE of A78 Ayr V1 on 10 June 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 12 June 2019

No defects recorded

Detailed Inspection TEMPLATE of A78 Ayr V1 on 12 April 2019

SW82459961-907	24m	104m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-908	50m	110m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-909	132m	212m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-910	181m	241m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-911	244m	324m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-923	145m	200m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-924	213m	213m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW82459961-925	249m	329m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999

Detailed Inspection - All other Footways of A78 Ayr V1

No defects recorded

Safety Inspection of A78 Ayr V1 on 19 June 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 26 June 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 03 July 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 10 July 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 17 July 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 24 July 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 31 July 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 07 August 2019

No defects recorded

Detailed Inspections - Category B Footways of A78 Largs Footways V1 on 12 August 2019

SW82531836-1	12m	12m	FOOTWAY	Other (OTHR)	CAT 1	13/08/2019	Completed Defects	12/08/2019	a76 largs opposite church of scotland
SW82531836-2	19m	19m	FOOTWAY	Other (OTHR)	CAT 1	13/08/2019	Completed Defects	12/08/2019	a76 largs opposite church of scotland
SW82531836-3	118m	118m	FOOTWAY	Other (OTHR)	CAT 1	13/08/2019	Completed Defects	12/08/2019	a78 outside cafe guzzi, largs

Safety Inspection of A78 Ayr V1 on 14 August 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 21 August 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 28 August 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 04 September 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 11 September 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 18 September 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 25 September 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 02 October 2019

No defects recorded

Safety Inspection of A78 Ayr V1 on 09 October 2019

No defects recorded