

# Inspection Defect Summary Report



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>14830/50 : WITH: RIVER ORE BR TO MANHOLE NR REDUCE SPEED SIGN</b>									
<b>Safety Inspection of M90 &amp; A92 Safety on 15 March 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 14 day - Signs and lighting of ELEC NE R16A on 15 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 18 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 22 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 25 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 29 March 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 29 March 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 30 March 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 30 March 2022</b>									
<i>No defects recorded</i>									
<b>Weekly Patrol of M90 &amp; A92 Safety on 30 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 01 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 05 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 08 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 12 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 15 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 19 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 22 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 26 April 2022</b>									
<i>No defects recorded</i>									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 26 April 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 27 April 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 27 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 29 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 03 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 06 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 10 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 13 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 17 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 20 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 24 May 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 24 May 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 25 May 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 25 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 27 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 31 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 03 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 07 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 10 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 14 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 17 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 21 June 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 21 June 2022</b>									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 22 June 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 22 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 24 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 28 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 01 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 05 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 08 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 12 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 15 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 19 July 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 19 July 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 20 July 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 20 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 22 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 26 July 2022</b>									
<i>No defects recorded</i>									
<b>Visual Inspection During Daylight - Road Studs of M90 &amp; A92 Safety on 29 July 2022</b>									
<i>No defects recorded</i>									
<b>Visual Inspection During Daylight - Road Markings of M90 &amp; A92 Safety on 29 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 29 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 02 August 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 05 August 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 08 August 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 10 August 2022</b>									
<i>No defects recorded</i>									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

**Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 11 August 2022**

*No defects recorded*

**Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 11 August 2022**

*No defects recorded*

**Safety Patrol of M90 & A92 Safety on 12 August 2022**

*No defects recorded*



# Inspection Defect Summary Report



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>14830/86 : WITH: MANHOLE NR REDUCE SPEED SIGN TO BANKHEAD RBT</b>									
<b>Safety Inspection of M90 &amp; A92 Safety on 15 March 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 14 day - Signs and lighting of ELEC NE R16A on 15 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 18 March 2022</b>									
<i>No defects recorded</i>									
<b>Reactive Defect Recorded 21/03/2022 11:26:07</b>									
D-NE22238613791	0m	0m	LIGHTING_POINT	Lamp failure (LAMP)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A92, Bankhead, Glenrothes
<b>Safety Inspection of M90 &amp; A92 Safety on 22 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 25 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 29 March 2022</b>									
NE7-829000-238616663	407m	0m	ROAD_MARKINGS _LONG	Missing (MISS)	CAT 1	26/04/2022	Completed Defects	01/04/2022	APPR BANKHEAD RBT NB
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 29 March 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 30 March 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 30 March 2022</b>									
<i>No defects recorded</i>									
<b>Weekly Patrol of M90 &amp; A92 Safety on 30 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 01 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 05 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 08 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 12 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 15 April 2022</b>									
<i>No defects recorded</i>									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>Safety Inspection of M90 &amp; A92 Safety on 19 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 22 April 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 26 April 2022</b>									
NE137-839594-238649428	578m	0m	LIGHTING_POINT	Lamp failure (LAMP)	CAT 2		Cat 2 Awaiting Action		
<b>Safety Inspection of M90 &amp; A92 Safety on 26 April 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 27 April 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 27 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 29 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 03 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 06 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 10 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 13 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 17 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 20 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 24 May 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 24 May 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 25 May 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 25 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 27 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 31 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 03 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 07 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 10 June 2022</b>									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 14 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 17 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 21 June 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 21 June 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 22 June 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 22 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 24 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 28 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 01 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 05 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 08 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 12 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 15 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 19 July 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 19 July 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 20 July 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 20 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 22 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 26 July 2022</b>									
<i>No defects recorded</i>									
<b>Visual Inspection During Daylight - Road Studs of M90 &amp; A92 Safety on 29 July 2022</b>									
<i>No defects recorded</i>									
<b>Visual Inspection During Daylight - Road Markings of M90 &amp; A92 Safety on 29 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 29 July 2022</b>									
<i>No defects recorded</i>									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>Safety Inspection of M90 &amp; A92 Safety on 02 August 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 05 August 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 08 August 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 10 August 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 11 August 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 11 August 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 12 August 2022</b>									
<i>No defects recorded</i>									



# Inspection Defect Summary Report



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>14830/87 : AGAINST: BANKHEAD RBT TO M/HOLE 500M S BANKHEAD RB</b>									
<b>Safety Inspection of M90 &amp; A92 Safety on 15 March 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 14 day - Signs and lighting of ELEC NE R16A on 15 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 18 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 22 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 25 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 29 March 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 29 March 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 30 March 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 30 March 2022</b>									
<i>No defects recorded</i>									
<b>Weekly Patrol of M90 &amp; A92 Safety on 30 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 01 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 05 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 08 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 12 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 15 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 19 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 22 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 26 April 2022</b>									
<i>No defects recorded</i>									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 26 April 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 27 April 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 27 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 29 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 03 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 06 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 10 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 13 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 17 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 20 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 24 May 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 24 May 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 25 May 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 25 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 27 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 31 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 03 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 07 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 10 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 14 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 17 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 21 June 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 21 June 2022</b>									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 22 June 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 22 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 24 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 28 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 01 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 05 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 08 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 12 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 15 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 19 July 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 19 July 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 20 July 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 20 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 22 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 26 July 2022</b>									
<i>No defects recorded</i>									
<b>Visual Inspection During Daylight - Road Studs of M90 &amp; A92 Safety on 29 July 2022</b>									
<i>No defects recorded</i>									
<b>Visual Inspection During Daylight - Road Markings of M90 &amp; A92 Safety on 29 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 29 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 02 August 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 05 August 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 08 August 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 10 August 2022</b>									
<i>No defects recorded</i>									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

**Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 11 August 2022**

*No defects recorded*

**Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 11 August 2022**

*No defects recorded*

**Safety Patrol of M90 & A92 Safety on 12 August 2022**

*No defects recorded*



# Inspection Defect Summary Report



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>14830/51 : AGAINST: M/HOLE 500M STH BANKHEAD RBT TO R ORE BR</b>									
<b>Safety Inspection of M90 &amp; A92 Safety on 15 March 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 14 day - Signs and lighting of ELEC NE R16A on 15 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 18 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 22 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 25 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 29 March 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 29 March 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 30 March 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 30 March 2022</b>									
<i>No defects recorded</i>									
<b>Weekly Patrol of M90 &amp; A92 Safety on 30 March 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 01 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 05 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 08 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 12 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 15 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 19 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 22 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 26 April 2022</b>									
<i>No defects recorded</i>									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 26 April 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 27 April 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 27 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 29 April 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 03 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 06 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 10 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 13 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 17 May 2022</b>									
NE7-855765-238761732	698m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2		Cat 2 Awaiting Action		@ LAYBY AFTER BANKHEAD RBT S/B
<b>Safety Patrol of M90 &amp; A92 Safety on 20 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 24 May 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 24 May 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 25 May 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 25 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 27 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 31 May 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 03 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 07 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 10 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 14 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 17 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 21 June 2022</b>									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 21 June 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 22 June 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 22 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 24 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 28 June 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 01 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 05 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 08 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 12 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 15 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 19 July 2022</b>									
<i>No defects recorded</i>									
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 19 July 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 20 July 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 20 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 22 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 26 July 2022</b>									
<i>No defects recorded</i>									
<b>Visual Inspection During Daylight - Road Studs of M90 &amp; A92 Safety on 29 July 2022</b>									
<i>No defects recorded</i>									
<b>Visual Inspection During Daylight - Road Markings of M90 &amp; A92 Safety on 29 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 29 July 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 02 August 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 05 August 2022</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of M90 &amp; A92 Safety on 08 August 2022</b>									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>Night Safety Inspection 28 day - Signs and lighting of ELEC NE R16A on 10 August 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspections (labelling) - Traffic Signals of ELEC NE R16A on 11 August 2022</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection Items 1-12 - Traffic Signals of ELEC NE R16A on 11 August 2022</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of M90 &amp; A92 Safety on 12 August 2022</b>									
<i>No defects recorded</i>									