

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/08/2016 and 04/07/2017, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'M8'.)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>11310/14 : WITH: ALMOND BRIDGE TO CANAL CULVERT</b>									
Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017									
No defects recorded									
<b>11310/25 : WITH: CANAL CULVERT TO DRUMSHORELAND BRIDGE</b>									
Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017									
No defects recorded									
<b>11310/33 : WITH: DRUMSHORELAND BR TO UPHALL STATION BR</b>									
Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017									
No defects recorded									
<b>11310/77 : WITH: UPHALL STAT. BR TO LIVINGSTON INTER EAST</b>									
Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017									
No defects recorded									
<b>11310/84 : WITH: LIVINGSTON INTERCHANGE EAST TO WEST</b>									
Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017									
No defects recorded									
<b>11311/00 : WITH: LIVINGSTON INTER (W) TO NELLBURN PATH F'BR.</b>									
Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017									
SE47242923-1	1,025m	0m	ROAD_STUDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8
<b>11311/15 : WITH: NELLBURN PATH FBR TO LIVINGSTON STATION BR</b>									
Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017									
No defects recorded									
<b>11311/26 : WITH: LIVINGSTON STATION BR TO STARLAW BRIDGE</b>									
Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017									
No defects recorded									
<b>11315/05 : WITH: STARLAW BRIDGE TO EASTER INCH FOOTBRIDGE</b>									
Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017									
SE47242923-2	229m	0m	ROAD_STUDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8
<b>11315/20 : WITH: EASTER INCH FOOTBRIDGE TO B792 BRIDGE</b>									
Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017									
No defects recorded									
<b>11315/50 : WITH: B792 BRIDGE TO RIDDOCH HILL FOOTBRIDGE</b>									
Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017									
No defects recorded									
<b>11315/65 : WITH: RIDDOCH HILL FBR TO EAST WHITBURN JCT(EAST)</b>									
Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017									
No defects recorded									
<b>11315/80 : WITH: E. WHITBURN JCT (E) TO E. WHITBURN JCT (W)</b>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017

No defects recorded

**11319/00 : WITH: EAST WHITBURN JUNCTION (WEST) TO A706 BRIDGE**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017

No defects recorded

**11319/26 : WITH: A706 BRIDGE TO COUNCIL BOUNDARY**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017

SE47242923-3	1,889m	0m	ROAD_STUDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8
--------------	--------	----	------------	----------------	-------	------------	-----------------------	------------	----

**11351/05 : WITH: COUNCIL BOUNDARY TO UBRIDGE SHOTTS RD B7057**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017

SE47242923-4	3,223m	0m	ROAD_STUDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8
--------------	--------	----	------------	----------------	-------	------------	-----------------------	------------	----

**11355/05 : WITH: UBRIDGE B7057 SHOTTS RD TO DUNTILLAND ROAD**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017

No defects recorded

**13713/00 : WITH: MID POINT H.INT BRIDGES TO SLIP RD ENTRY**

Reflective Conspicuity Inspection - Road Studs of M8 W Detail SW on 30 October 2016

SW80182687-7	6m	360m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
--------------	----	------	------------	---	-------	------------	-----------------------	------------	--

**13713/10 : WITH: SLIP FRM HGTN INTR -SLIP TO ARKLESTON**

Reflective Conspicuity Inspection - Road Studs of M8 W Detail SW on 30 October 2016

No defects recorded

**13717/04 : WITH: M8 WB FROM A737 INT TO CRAIGTON INT**

Reflective Conspicuity Inspection - Road Studs of M8 W Detail SW on 30 October 2016

No defects recorded

**13719/06 : WITH: SLIP FROM M898 - WEST FERRY INTERCHANGE**

Reflective Conspicuity Inspection - Road Studs of M8 W Detail SW on 30 October 2016

No defects recorded

**13719/95 : AGAINST: SLIP OFF TO A8 TO ENTRY SLIP M8 EB**

Reflective Conspicuity Inspection - Road Studs of M8 W Detail SW on 30 October 2016

No defects recorded

**13719/03 : AGAINST: SLIP TO M898 TO CRAIGTON INT UPASS**

Reflective Conspicuity Inspection - Road Studs of M8 W Detail SW on 30 October 2016

No defects recorded

**13717/50 : AGAINST:SLIP ON FROM CRAIGTON INT TO MID POINT BR**

Reflective Conspicuity Inspection - Road Studs of M8 W Detail SW on 30 October 2016

SW80182687-8	4m	4,930m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
--------------	----	--------	------------	---	-------	------------	-----------------------	------------	---------------

**13716/56 : AGAINST:MID POINT A737 BRIDGE TO SLIP FROM A737**

Reflective Conspicuity Inspection - Road Studs of M8 W Detail SW on 30 October 2016

No defects recorded

**13716/06 : AGAINST: SLIP FROM A737 INT TO SLIP OFF M8 EB**

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

Reflective Conspicuity Inspection - Road Studs of M8 W Detail SW on 30 October 2016  
No defects recorded

**13713/52 : AGAINST: FROM ARKLESTON ON TO HGTON SLIP OFF**

Reflective Conspicuity Inspection - Road Studs of M8 W Detail SW on 30 October 2016  
No defects recorded

**11355/06 : AGAINST: DUNTILLAND RD C73 TO SHOTTS RD B7057**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11351/06 : AGAINST: UBRIDGE B7057 SHOTTS RD TO COUNCIL BDY**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11319/63 : AGAINST: COUNCIL BOUNDARY TO A706 BRIDGE**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11319/13 : AGAINST: A706 BRIDGE TO EAST WHITBURN JUNCT (W)**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11315/90 : AGAINST: E WHITBURN JCT (W) TO E WHITBURN JCT (E)**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11315/70 : AGAINST: EAST WHITBURN JUNC (E) TO RIDDHILL FOOTB**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11315/55 : AGAINST: RIDDOCH HILL FOOTBRIDGE TO B792 BRIDGE**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11315/25 : AGAINST: B792 BRIDGE TO EASTER INCH FOOTBRIDGE**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11315/06 : AGAINST: EASTER INCH FOOTBRIDGE TO STARLAW BRIDGE**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11311/80 : AGAINST: STARLAW BRIDGE TO END OF SLIP ROAD**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11311/40 : AGAINST: END OF SLIP ROAD TO LIVINGSTON STAT. BR**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11311/20 : AGAINST: LIVSTON STATION BR TO NELLBURN PATH FBR**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11311/08 : AGAINST: NELLBURN PATH FBR TO LIVINGSTON INT WEST**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

**11310/92 : AGAINST: LIVINGSTON INTERCHANGE WEST TO EAST**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11310/80 : AGAINST: LIVINGSTON INTER. E TO UPHALL STATION BR**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11310/34 : AGAINST: UPHALL STATION BR TO DRUMSHORELAND BR**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11310/26 : AGAINST: DRUMSHORELAND BRIDGE TO CANAL CULVERT**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11310/15 : AGAINST: CANAL CULVERT TO ALMOND BRIDGE**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11310/85 : WITH: WESTBOUND SLIP FROM A899 (LIVINGSTON JUNCT)**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11310/93 : AGAINST: EASTBOUND SLIP TO A899**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11311/86 : AGAINST: STARLAW JUNCT EASTBOUND SLIP ON TO M8**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11311/90 : AGAINST: STARLAW JUNCT EASTBOUND SLIP OFF M8**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11315/10 : WITH: STARLAW JUNCT WESTBOUND SLIP OFF M8**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11315/13 : WITH: STARLAW JUNCT WESTBOUND SLIP ON TO M8**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11315/83 : WITH: EAST WHITBURN JUNC WESTBOUND SLIP TO A801**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11315/85 : WITH: EAST WHITBURN JUNC WESTBOUND SLIP FROM A801**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11315/91 : AGAINST: EAST WHITBURN JUNC EBOUND SLIP FROM A801**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11315/93 : AGAINST: EAST WHITBURN JUNC EASTBOUND SLIP TO A801**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

**11351/04 : WITH: WESTBOUND SLIP OFF TO SHOTTS ROAD B7057**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11355/04 : WITH: WESTBOUND ON SLIP FROM SHOTTS ROAD B7057**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11355/07 : AGAINST: JN AGAINST: OFF SLIP TO B7057 SHOTTS RD**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11355/08 : AGAINST: B7057 OFF SLIP TO ON SLIP M8 EB**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**13713/74 : AGAINST: ARKLESTON RD TO ON M8 EASTBOUND**

SW80182687-1	6m	303m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
--------------	----	------	------------	---	-------	------------	--------------------------	------------	---------------

**13717/03 : WITH: SLIP ON TO M8 WB A737 INTERCHANGE**

Reflective Conspicuity Inspection - Road Studs of M8 W Detail SW on 30 October 2016  
*No defects recorded*

**13717/96 : WITH: SLIP OFF M8 WB TO GREENOCK RD OBRIDGE**

Reflective Conspicuity Inspection - Road Studs of M8 W Detail SW on 30 October 2016  
*No defects recorded*

**14210/16 : AGAINST: EB OFF SLIP JUNCTION 10**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
*No defects recorded*

**14210/29 : WITH: WB ON SLIP JCT 10 TO WB OFF SLIP JCT 11**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
*No defects recorded*

**14215/05 : WITH: WB OFF SLIP JCT 11 TO WB ON SLIP JCT 11**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
*No defects recorded*

**14215/06 : AGAINST: JCT 11 EB OFF SLIP TO ENTRY SLIP**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
*No defects recorded*

**14215/10 : WITH: WB OFF SLIP JUNCTION 11**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
*No defects recorded*

**14215/11 : AGAINST: EB ENTRY SLIP AT JCT 11**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
*No defects recorded*

**14215/15 : WITH: WB ON SLIP JUNCTION 11**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
*No defects recorded*



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

**14215/16 : AGAINST: SLIP RD OFF M8 EB AT JCT 11**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
 No defects recorded

**14215/39 : WITH: WB JCT 11 ON SLIP TO JCT 12 OFF SLIP**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
 No defects recorded

**14215/40 : AGAINST: EB M8 JCT 12 OFF SLIP TO JCT 11 ON SLIP**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
 No defects recorded

**14220/05 : WITH: M8 WB JCT 12 OFF SLIP TO ENTRY SLIP**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
 No defects recorded

**14220/06 : AGAINST: EB JCT 12 OFF SLIP TO ENTRY SLIP**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
 No defects recorded

**14220/10 : AGAINST: JCT 12 GARTLOCH RD TO SLIP RD ENTRY**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
 No defects recorded

**14220/11 : WITH: WB JCT 12 OFF SLIP TO CUMBANAULD RD**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
 No defects recorded

**14220/15 : WITH: 2 WAY SLIP TO CUMBANAULD RD**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
 No defects recorded

**14220/16 : WITH: 2 WAY SLIP TO CUMBANAULD RD**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
 No defects recorded

**14220/20 : WITH: CUMBANAULD RD TO 2 WAY SLIP**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016

SW80182688-40	1m	32m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
---------------	----	-----	------------	---	-------	------------	-----------------------	------------	---------------

**14220/21 : WITH: CUMBANAULD RD TO 2 WAY SLIP**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
 No defects recorded

**14220/25 : WITH: JCT 12 WB SLIP ONTO M8**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016

SW80182688-41	9m	253m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
---------------	----	------	------------	---	-------	------------	-----------------------	------------	---------------

**14220/26 : AGAINST: JCT 12 EB SLIP OFF TO CUMBANAULD RD**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016

SW80182688-38	4m	275m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
---------------	----	------	------------	---	-------	------------	-----------------------	------------	---------------

SW80182688-39	18m	275m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
---------------	-----	------	------------	---	-------	------------	-----------------------	------------	---------------

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>14220/50 : WITH: JC T 12 ENTRY SLIP TO OFF SLIP AT JCT 13</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-1	8m	496m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14220/51 : AGAINST: JCT 13 ENTRY FROM M80 TO JCT 12 OFF SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-37	3m	252m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14225/05 : WITH: WB OFF SLIP TO M80 TO SLIP ON FROM M80</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-2	5m	1,000m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14225/06 : AGAINST: EB OFF SLIP TO M80 TO ENTRY FROM M80</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-36	13m	1,017m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14225/10 : WITH: SLIP OFF M8 WB TO M80 INT</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14225/11 : WITH: M80 INTERCHANGE SLIP WB</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14225/16 : WITH: M80 INT SLIP WB</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14225/20 : AGAINST: PROVAN RD UNDERPASS</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14225/55 : WITH: ON SLIP FROM M80 TO OFF SLIP JCT 14</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-3	22m	812m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14225/56 : AGAINST: EB JCT 14 OFF SLIP TO OFF SLIP TO M80</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-35	4m	988m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14225/60 : WITH: SLIP RD ON TO M8 WB</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-45	10m	548m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14225/61 : AGAINST: EB JCT 14 SLIP OFF TO VIEWPARK AVE</b>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016</b>									
SW80182688-44	1m	364m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14230/05 : WITH: WB M8 JCT 14 ON SLIP TO JCT 15 OFF SLIP</b>									
<b>Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016</b>									
SW80182688-4	25m	616m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14230/06 : AGAINST: EB M8 JCT 15 ENTRY TO JCT 14 OFF SLIP</b>									
<b>Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016</b>									
SW80182688-34	8m	494m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14235/05 : WITH: JCT 15 OFF SLIP TO M8 OBRIDGE</b>									
<b>Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016</b>									
SW80182688-5	10m	464m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14235/06 : AGAINST: EB JCT 15 OFF SLIP TO ENTRY SLIP</b>									
<b>Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016</b>									
No defects recorded									
<b>14235/10 : WITH: JCT 15 SLIP OFF M8 TO CASTLE ST</b>									
<b>Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016</b>									
SW80182688-42	19m	346m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14235/11 : WITH: JCT 15 SLIP OFF M8 T STIRLING RD JCT</b>									
<b>Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016</b>									
SW80182688-46	27m	645m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14235/15 : AGAINST: CASTLE ST JCT TO M8 EB JCT 15</b>									
<b>Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016</b>									
SW80182688-43	14m	372m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14235/16 : AGAINST: A803 TO ENTRY M8 EB</b>									
<b>Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016</b>									
No defects recorded									
<b>14235/26 : WITH: A803 TO ENTRY WB M8</b>									
<b>Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016</b>									
SW80182688-47	12m	515m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14235/35 : AGAINST: SLIP OFF EB M8 TO A803 JCT 15</b>									
<b>Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016</b>									
SW80182688-50	30m	217m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>14235/39 : WITH: M8 OBRIDGE TO SLIP ON TO M8 WB</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-6	28m	420m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14235/40 : AGAINST: JCT 15 OFF SLIP TO M8 INT</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-33	21m	209m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14235/81 : WITH: ENTRY M8 WB TO JCT 16 OFF SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-7	17m	201m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14235/82 : AGAINST: JCT 16 ON SLIP TO JCT 15 OFF SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-32	26m	332m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14240/05 : WITH: JCT 16 OFF SLIP TO CRAIGHALL RD</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-8	6m	524m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14240/06 : AGAINST: JCT 16 CRAIGHALL RD TO ENTRY M8 EB</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-31	0m	356m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14240/10 : WITH: JCT 16 M8 OFF SLIP TO CANAL RD</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-51	7m	197m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14240/11 : WITH: M8 SLIP CANAL ST TO CRAIGHALL RD</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-52	26m	195m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14240/12 : WITH: M8 OFF SLIP SPLIT</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14240/15 : AGAINST: CRAIGHALL RD UPASS TO SLIP ON M8 EB</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14240/44 : WITH: WB M8 OFF SLIP TO A81 UPASS</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
SW80182688-9	12m	466m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14240/45 : AGAINST: JCT 17 A81 UPASS TO CRAIGHALL RD UPASS</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-30	13m	493m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14240/83 : WITH: A81 UPASS TO JCT 18 OFF SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-10	4m	188m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14240/84 : AGAINST: EB JCT 18 ENTRY TO A81 UPASS</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-29	4m	244m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14245/05 : WITH: WB M8 JCT 18 OFF SLIP TO ENTRY SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-11	7m	336m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
SW80182688-53	27m	336m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14245/06 : AGAINST: M8 JCT 18 EB ON SLIP TO SLIP FROM A82</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-28	11m	383m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14245/10 : WITH: SLIP TO M8 WB</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-48	6m	490m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14245/11 : WITH: SLIP OFF M8 WB TO A82</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14245/15 : AGAINST: EXIT A82 TO ENTRY M8 EB</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14245/25 : WITH: M8 WB ON SLIP TO JCT 18 INT OBR</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14245/26 : AGAINST: WOODLANDS RD OBR TO ON SLIP EB M8</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-49	12m	206m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>14245/30 : WITH: JCT 18 TO JCT 19</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-12	9m	779m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14245/33 : AGAINST: SAUCHIEHALL ST TO ENTRY M8 EB</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-27	15m	332m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14245/55 : AGAINST: JCT 18 OFF SLIP TO A82</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14245/56 : AGAINST: JCT 18 OFF SLIP TO ST GEORGES RD</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14245/57 : AGAINST: SAUCHIEHALL ST TO M8 SPLIT</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14245/61 : AGAINST: EB JCT 19 TO JCT 18</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14250/05 : WITH: JCT 19 WB OFF SLIP TO ON SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-13	10m	318m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14250/06 : AGAINST: JCT 19 EB OFF SLIP TO ON SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14250/10 : WITH: JCT 19 WB OFF SLIP TO STOBCROSS ST</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-54	2m	217m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14250/11 : AGAINST: M8 EB JCT 19 ON SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-55	26m	202m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14250/50 : WITH: OFF SLIP TO STOBCROSS ST</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14250/51 : WITH: SLIP ENTRY FROM BISHOP LANE JCT 19</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14250/52 : AGAINST: STOBCROSS ST TO START SLIP TO M8</b>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016 <i>No defects recorded</i>									
<b>14250/53 : AGAINST: SLIP OFF M8 EB TO BOTHWELL ST</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016 <i>No defects recorded</i>									
<b>14250/57 : WITH: JCT 19 ON SLIP TO M8 EB Entry</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-14	6m	235m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14250/58 : AGAINST: SLIP OFF TO A814 TOJCT 19 OFF SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-26	7m	274m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14250/90 : AGAINST: SLIP OFF M8 EB TO A814</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016 <i>No defects recorded</i>									
<b>14250/91 : WITH: A814 TO ENTRY M8 WB</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016 <i>No defects recorded</i>									
<b>14255/05 : WITH: ENTRY M8 WB TO JCT 20 OFF SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-15	14m	447m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14255/06 : AGAINST: EB JCT 20 ON SLIP TO JCT 19 OFF SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-25	9m	331m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14255/90 : WITH: JCT 20 OFF SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016 <i>No defects recorded</i>									
<b>14255/91 : WITH: J20 Off Slip to West Street</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016 <i>No defects recorded</i>									
<b>14255/95 : AGAINST: JCT 20 SLIP RD ON TO M8 EB</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016 <i>No defects recorded</i>									
<b>14255/96 : AGAINST: JCT GLOUCESTER/WEST RD TO ST ELEV SECT</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016 <i>No defects recorded</i>									
<b>14260/05 : WITH: JCT 20 SLIP OFF WB M8 TO JCT 22 M77 INT</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-16	19m	1,389m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>14260/06 : AGAINST: JCT 22 M77 INT TO JCT 20</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-24	6m	1,465m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14265/05 : WITH: JCT 22 WB OFF SLIP TO ON SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-17	11m	733m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14265/06 : AGAINST: JCT 22 EB OFF SLIP TO ON SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-23	11m	713m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14265/73 : WITH: WB JCT 22 ON SLIP TO JCT 23 OFF SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-18	15m	270m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14265/74 : AGAINST: EB JCT 23 ON SLIP TO JCT 22 OFF SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14270/05 : WITH: JCT 23 OFF SLIP TO A8 OBRIDGE</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-19	0m	570m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14270/06 : AGAINST: A8 OBRIDGE TO JCT 23 SLIP RD ENTRY</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-22	14m	565m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14270/10 : WITH: JCT 23 OFF SLIP TO B768 DUMBREK RD</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14270/11 : AGAINST: JCT 23 ON SLIP FROM B768 DUMBREK RD</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
No defects recorded									
<b>14275/05 : WITH: WB JCT 24 OFF SLIP TO ON SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-20	22m	617m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
<b>14275/06 : AGAINST: EB JCT 24 OFF SLIP TO ON SLIP</b>									
Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016									
SW80182688-21	4m	587m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

**14275/10 : WITH: WB JCT 24 TO HELEN ST**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
 No defects recorded

**14275/11 : AGAINST: HELEN ST TO ENTRY M8 EB**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
 No defects recorded

**14275/40 : WITH: HELEN ST TO M8 WB**

SW80182687-13	4m	281m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
---------------	----	------	------------	---	-------	------------	-----------------------	------------	---------------

**14275/47 : WITH: WB JCT 24 SLIP RD ENTRY TO JCT 25**

Reflective Conspicuity Inspection - Road Studs of M8 W Detail SW on 30 October 2016  
 No defects recorded

**14280/05 : WITH: WB JCT 25 OFF SLIP TO ON SLIP**

Reflective Conspicuity Inspection - Road Studs of M8 W Detail SW on 30 October 2016  
 No defects recorded

**14280/46 : WITH: WB JCT 25 ON SLIP TO JCT 26 OFF SLIP**

SW80182687-5	4m	1,336m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
--------------	----	--------	------------	---	-------	------------	-----------------------	------------	---------------

**11302/02 : HERMISTON ROUNDABOUT**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
 No defects recorded

**11302/05 : WITH:HERMISTON ROUNDABOUT TO SIGHTHILL SLIP ROAD**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
 No defects recorded

**11302/06 : AGAINST:GOGAR SLIP ROAD TO HERMISTON ROUNDABOUT**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
 No defects recorded

**11302/10 : WITH: WESTBOUND SLIP FROM SIGHTHILL**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
 No defects recorded

**11302/11 : AGAINST: E/B SLIP ROAD TO GOGAR SLIP ROAD**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
 No defects recorded

**11302/15 : WITH: SIGHTHILL SLIP ROAD TO RANSFIELD ROAD BRIDGE**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
 No defects recorded

**11302/16 : AGAINST: RANSFIELD ROAD BRIDGE TO GOGAR SLIP ROAD**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
 No defects recorded

**11302/26 : WITH: RANSFIELD ROAD BRIDGE TO FREELANDS ROAD BR.**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

No defects recorded

**11302/27 : AGAINST: FREELANDS ROAD BR. TO RANSFIELD ROAD BR.**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11302/50 : WITH: FREELANDS RD BR. TO EAST OF CLAYLANDS JUNCT**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11302/51 : AGAINST: EAST OF CLAYLANDS JCT TO FREELANDS RD BR.**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11307/05 : WITH: E OF CLAYLANDS JCT TO W OF CLAYLANDS JCT**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11307/10 : AGAINST: W OF CLAYLANDS JCT TO E OF CLAYLANDS JCT**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11306/06 : AGAINST: WESTBOUND SLIP FROM NEWBRIDGE**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11310/07 : WITH: WEST OF CLAYLANDS TO ALMOND BRIDGE**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11306/52 : WITH: END OF M8 EB SLIP TO NEWBRIDGE NB OFF SLIP**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11310/08 : AGAINST:ALMOND BRIDGE TO WEST OF CLAYLANDS JCT**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11306/05 : WITH: WESTBOUND SLIP TO NEWBRIDGE**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11306/07 : AGAINST: EASTBOUND SLIP FROM NEWBRIDGE**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11306/08 : WITH: EASTBOUND SLIP TO NEWBRIDGE**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**11306/53 : AGAINST:END NEWBRIDGE SB ON SLIP TO M8 EB OFF SLIP**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
No defects recorded

**14280/40 : WITH: W/B OFF SLIP TO BRAEHEAD**

Reflective Conspicuity Inspection - Road Studs of M8 W Detail SW on 30 October 2016

SW80182687-16	0m	1,387m	ROAD_STUDS	Conspicuity catseye test failure (REFF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHOLE SECTION
---------------	----	--------	------------	---	-------	------------	-----------------------	------------	---------------

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

**11310/79 : WITH: WESTBOUND OFF SLIP TO LIVINGSTON EAST RBT**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11310/82 : WITH: WESTBOUND OFF SLIP TO A899**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11319/30 : With: WB off Slip from M8**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11319/32 : Against: EB on Slip from RBT**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11319/34 : With: WB On Slip to M8**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11319/36 : Against: EB Off Slip to Rbt**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11355/42 : With: Duntilland Rd to M8 PPP Responsibility**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11355/45 : Against: SE Boundary to Duntilland Rd (C73)**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**14210/32 : Against: EB on Slip Jct 11 to Jct 10 Off Slip**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
*No defects recorded*

**14210/34 : Against: Jct 10 Off Slip to Jct 10 On Slip**

Reflective Conspicuity Inspection - Road Studs of M8E Detail SW on 18 October 2016  
*No defects recorded*

**11310/90 : Against: Eastbound Slip from A899 With HS**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11310/89 : Against: Eastbound Slip from A899 No HS**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*

**11310/87 : Against: Eastbound Access to M8 with HS**

Reflective Conspicuity Inspection - Road Studs of Amey M8 Safety Inspection on 06 February 2017  
*No defects recorded*