

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 15/04/2016 and 15/04/2017, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A92',)
(Section Code is 14855/10) Or

(Section Code is 14855/20) Or

(Section Code is 14855/30)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

14855/10 : PRESTON ROUNDABOUT TO TULLUS ROUNDABOUT

Safety Patrol of M90 & A92 Safety on 15 April 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 19 April 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 22 April 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 26 April 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 29 April 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 03 May 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 06 May 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 10 May 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 13 May 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 17 May 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 20 May 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 24 May 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 27 May 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 31 May 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 03 June 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 22 May 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 10 June 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 14 June 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 17 June 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 21 June 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 24 June 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 28 June 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 01 July 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 05 July 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 08 July 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 12 July 2016

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE11173879-2082182	464m	0m	GULLY	Blockage (BLOK)	CAT 1	09/08/2016	Completed Defects	04/08/2016	BETWEEN PRESTON RBT AND TULLIS RUSSELL RBT
NE11173879-2082180	439m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	09/08/2016	Completed Defects	04/08/2016	BETWEEN PRESTON RBT AND TULLIS RUSSELL RBT NB
NE11173879-2082181	463m	0m	STRUCTURE	Damaged Parapets (DAMP)	CAT 1	09/08/2016	Completed Defects	18/07/2016	BETWEEN PRESTON RBT AND TULLIS RUSSELL RBT
NE11173879-2082183	501m	0m	GULLY	Cracked or broken (IBCK)	CAT 1	09/08/2016	Completed Defects	04/08/2016	Between Preston Rbt to Tullis Russel rbt NB

Safety Patrol of M90 & A92 Safety on 15 July 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 19 July 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 22 July 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 26 July 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 29 July 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 02 August 2016

No defects recorded

Annual Detailed Inspection - Carriageways of a92 detail 1 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 05 August 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 09 August 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 12 August 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 16 August 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 19 August 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 23 August 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 26 August 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 30 August 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 02 September 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 06 September 2016

NE11-183333-2199821	421m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	04/10/2016	Completed Defects	04/11/2016	APP TO PRESTON RBT. 200M AFTER 40MPH ZONE SB
---------------------	------	----	-------------	---------------------------------	-------	------------	-------------------	------------	--

Safety Patrol of M90 & A92 Safety on 09 September 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 13 September 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 16 September 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 20 September 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 23 September 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 27 September 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 30 September 2016

No defects recorded

Safety Inspection of M90 & A92 Safety on 04 October 2016

No defects recorded

Safety Patrol of M90 & A92 Safety on 07 October 2016

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 11 October 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 14 October 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 18 October 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 21 October 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 25 October 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 28 October 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 01 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 04 November 2016									
NE11-205186-2325776	468m	0m	GULLY	Rocking under load (IRLD)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	Approx 450m before Preston rbt SB
NE11-205186-2325775	643m	0m	MANHOLE	Rocking under load (IRLD)	3RD PTY	02/12/2016	Awaiting CCMS Permanent Date	01/01/9999	Approx 200m after Tullis Russell Rbt SB
Safety Inspection of M90 & A92 Safety on 08 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 11 November 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 15 November 2016									
NE11-210021-2350378	826m	0m	LIGHTING_POINT	Accident damage (ACCD)	CAT 1	13/12/2016	Completed Defects	05/12/2016	EXIT FROM TULLIS RUSSEL RBT SIB
NE11-210021-2350379	537m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	13/12/2016	Completed Defects	12/12/2016	JUST AFTER TULLIS RUSSEL RBT SIB
NE11-210021-2350377	836m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	13/12/2016	Completed Defects	06/12/2016	EXIT FROM TULLIS RUSSEL RBT SIB
Safety Patrol of M90 & A92 Safety on 18 November 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 22 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 25 November 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 29 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 02 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 06 December 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 09 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 13 December 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 16 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 20 December 2016									
NE13-224079-2390195	840m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	APPROACH TO TULLIS RUSSEL RBT N/B
NE13-224079-2390208	78m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/01/2017	Completed Defects	16/01/2017	APPROACH TO PRESTON RBT SIB
Safety Patrol of M90 & A92 Safety on 23 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 27 December 2016									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE13-226935-235030314	824m	0m	LIGHTING_POINT	Accident damage (ACCD)	CAT 1	24/01/2017	Completed Defects	27/12/2016	Tullis Russell Rbt SB
Safety Patrol of M90 & A92 Safety on 30 December 2016									
No defects recorded									
Safety Inspection of M90 & A92 Safety on 03 January 2017									
No defects recorded									
Safety Patrol of M90 & A92 Safety on 06 January 2017									
No defects recorded									
Safety Inspection of M90 & A92 Safety on 10 January 2017									
No defects recorded									
Safety Patrol of M90 & A92 Safety on 13 January 2017									
No defects recorded									
Safety Inspection of M90 & A92 Safety on 17 January 2017									
No defects recorded									
Safety Patrol of M90 & A92 Safety on 20 January 2017									
No defects recorded									
Safety Inspection of M90 & A92 Safety on 24 January 2017									
No defects recorded									
Safety Patrol of M90 & A92 Safety on 27 January 2017									
No defects recorded									
Safety Inspection of M90 & A92 Safety on 31 January 2017									
No defects recorded									
Safety Patrol of M90 & A92 Safety on 03 February 2017									
No defects recorded									
Safety Inspection of M90 & A92 Safety on 07 February 2017									
No defects recorded									
Safety Patrol of M90 & A92 Safety on 08 February 2017									
No defects recorded									
Safety Patrol of M90 & A92 Safety on 10 February 2017									
No defects recorded									
Safety Inspection of M90 & A92 Safety on 14 February 2017									
No defects recorded									
Safety Patrol of M90 & A92 Safety on 17 February 2017									
No defects recorded									
Safety Inspection of M90 & A92 Safety on 21 February 2017									
No defects recorded									
Safety Patrol of M90 & A92 Safety on 24 February 2017									
NE13-246224-235060435	17m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	24/03/2017	Completed Defects	30/04/2017	JUST NTH OF PRESTON RDBT NB CWAY
NE13-246224-235060437	21m	0m	GULLY	Difference in level with road (IDLV)	CAT 1	24/03/2017	Completed Defects	30/04/2017	JUST NTH OF PRESTON RDBT NB CWAY
NE13-246224-235060436	4m	0m	GULLY	Difference in level with road (IDLV)	CAT 1	24/03/2017	Completed Defects	30/04/2017	JUST NTH OF PRESTON RDBT NB CWAY
Safety Inspection of M90 & A92 Safety on 28 February 2017									
No defects recorded									
Safety Patrol of M90 & A92 Safety on 03 March 2017									
No defects recorded									
Safety Inspection of M90 & A92 Safety on 07 March 2017									
NE13-249792-235067210	699m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	04/04/2017	Completed Defects	04/04/2017	JUST PRIOR TOO TULLIS RUSSELL RBT NB
Safety Patrol of M90 & A92 Safety on 10 March 2017									
No defects recorded									
Safety Inspection of M90 & A92 Safety on 14 March 2017									
No defects recorded									
Safety Patrol of M90 & A92 Safety on 17 March 2017									
No defects recorded									
Safety Inspection of M90 & A92 Safety on 21 March 2017									
No defects recorded									
Safety Patrol of M90 & A92 Safety on 24 March 2017									
No defects recorded									
Safety Inspection of M90 & A92 Safety on 28 March 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 31 March 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 04 April 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 07 April 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 11 April 2017									
NE13-260471-235087282	830m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	SB EXIT FROM TULLIS RUSSELL RDBT
NE13-260471-235087281	816m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	SB EXIT FROM TULLIS RUSSELL RDBT
Safety Patrol of M90 & A92 Safety on 14 April 2017									
<i>No defects recorded</i>									
14855/20 : TULLUS ROUNDABOUT									
Safety Patrol of M90 & A92 Safety on 15 April 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 19 April 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 22 April 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 26 April 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 29 April 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 03 May 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 06 May 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 10 May 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 13 May 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 17 May 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 20 May 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 24 May 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 27 May 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 31 May 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 03 June 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 22 May 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 10 June 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 14 June 2016									
NE11164619-2021458	118m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	TULLUS RUSSELL RBT
Safety Patrol of M90 & A92 Safety on 17 June 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 21 June 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 24 June 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 28 June 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 01 July 2016									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 05 July 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 08 July 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 12 July 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 15 July 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 19 July 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 22 July 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 26 July 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 29 July 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 02 August 2016									
<i>No defects recorded</i>									
Annual Detailed Inspection - Carriageways of a92 detail 1 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 05 August 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 09 August 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 12 August 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 16 August 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 19 August 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 23 August 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 26 August 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 30 August 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 02 September 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 06 September 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 09 September 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 13 September 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 16 September 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 20 September 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 23 September 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 27 September 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 30 September 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 04 October 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 07 October 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 11 October 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 14 October 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 18 October 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 21 October 2016									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of M90 & A92 Safety on 25 October 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 28 October 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 01 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 04 November 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 08 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 11 November 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 15 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 18 November 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 22 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 25 November 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 29 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 02 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 06 December 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 09 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 13 December 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 16 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 20 December 2016									
NE13-224079-2390207	128m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	TULLIS RUSSEL RBT
Safety Patrol of M90 & A92 Safety on 23 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 27 December 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 30 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 03 January 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 06 January 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 10 January 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 13 January 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 17 January 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 20 January 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 24 January 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 27 January 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 31 January 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 03 February 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 07 February 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 08 February 2017									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of M90 & A92 Safety on 10 February 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 14 February 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 17 February 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 21 February 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 24 February 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 28 February 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 03 March 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 07 March 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 10 March 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 14 March 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 17 March 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 21 March 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 24 March 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 28 March 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 31 March 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 04 April 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 07 April 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 11 April 2017									
NE13-260471-235087279	133m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	SB EXIT FROM TULLIS RUSSELL RDBT
NE13-260471-235087280	137m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	SB EXIT FROM TULLIS RUSSELL RDBT
Safety Patrol of M90 & A92 Safety on 14 April 2017									
<i>No defects recorded</i>									
14855/30 : TULLUS ROUNDABOUT TO JL C131 CADHAM ROAFIFE									
Safety Patrol of M90 & A92 Safety on 15 April 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 19 April 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 22 April 2016									
NE14146066-1862133	14m	0m	ROAD_MARKINGS_HATCHED	Wear (for example erosion) (WEAR)	CAT 1	20/05/2016	Completed Defects	03/05/2016	app to tullis russell rbt SB
NE14146066-1862132	4m	0m	ROAD_MARKINGS_HATCHED	Wear (for example erosion) (WEAR)	CAT 1	20/05/2016	Completed Defects	03/05/2016	app too tullis russell rbt SB
Safety Inspection of M90 & A92 Safety on 26 April 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 29 April 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 03 May 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 06 May 2016									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of M90 & A92 Safety on 10 May 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 13 May 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 17 May 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 20 May 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 24 May 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 27 May 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 31 May 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 03 June 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 22 May 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 10 June 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 14 June 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 17 June 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 21 June 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 24 June 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 28 June 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 01 July 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 05 July 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 08 July 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 12 July 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 15 July 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 19 July 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 22 July 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 26 July 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 29 July 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 02 August 2016									
<i>No defects recorded</i>									
Annual Detailed Inspection - Carriageways of a92 detail 1 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 05 August 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 09 August 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 12 August 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 16 August 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 19 August 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 23 August 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 26 August 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 30 August 2016									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 02 September 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 06 September 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 09 September 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 13 September 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 16 September 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 20 September 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 23 September 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 27 September 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 30 September 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 04 October 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 07 October 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 11 October 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 14 October 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 18 October 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 21 October 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 25 October 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 28 October 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 01 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 04 November 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 08 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 11 November 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 15 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 18 November 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 22 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 25 November 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 29 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 02 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 06 December 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 09 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 13 December 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 16 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 20 December 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 23 December 2016									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of M90 & A92 Safety on 27 December 2016									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 30 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 03 January 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 06 January 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 10 January 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 13 January 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 17 January 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 20 January 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 24 January 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 27 January 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 31 January 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 03 February 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 07 February 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 08 February 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 10 February 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 14 February 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 17 February 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 21 February 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 24 February 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 28 February 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 03 March 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 07 March 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 10 March 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 14 March 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 17 March 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 21 March 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 24 March 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 28 March 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 31 March 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 04 April 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 07 April 2017									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 11 April 2017									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 14 April 2017									
<i>No defects recorded</i>									

