

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2017 and 06/11/2017, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A83',)
(Section Code is 16512/19)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
16512/19 : ARDGARTEN CARAVAN PARK TO JCT B828 GLENMORE R									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 04 January 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 11 January 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 18 January 2017									
NWG5234566-235032232	5,130m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/01/2017	Completed Defects	18/01/2017	REST&BETHANKFUL, E/B C/WAY
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 25 January 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 01 February 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 08 February 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 15 February 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 22 February 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 01 March 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 08 March 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 15 March 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 22 March 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 29 March 2017									
NWG21254940-235074269	3,857m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	26/04/2017	Completed Defects	14/04/2017	WEST SIDE OF GLEN CROE ACCESS, W/B VERGE. (REST&BETHANKFUL)
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 05 April 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 12 April 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 19 April 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 26 April 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 03 May 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 10 May 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 17 May 2017									
NWG7271899-235158897	2,555m	0m	FOOTWAY	Bituminous surfacing - potholes (BPOT)	CAT 1	14/06/2017	Completed Defects	17/05/2017	JUST WEST OF HONEYMOON BRIDGE, REST&BETHANKFUL. (W/B C/WAY)
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 24 May 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 31 May 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 07 June 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 14 June 2017									
No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 21 June 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 30 August 2017									
NW31283874-235350861	6,155m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	27/09/2017	Awaiting CCMS Temp Date	01/01/9999	TOP OF RESTANDBETHANKFUL, W/B C/WAY.
NW31283874-235350858	2,589m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	27/09/2017	Completed Defects	18/09/2017	NEAR HONEYMOON BRIDGE, RESTANDBETHANKFUL, W/B C/WAY.
NW31283874-235350859	6,000m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	31/08/2017	Completed Defects	30/08/2017	RESTANDBETHANKFUL, W/B C/WAY.
NW31283874-235350860	6,107m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	27/09/2017	Completed Defects	18/09/2017	TOP OF RESTANDBETHANKFUL, W/B C/WAY.
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 13 September 2017									
NWG8295173-235372300	3,342m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	14/09/2017	Completed Defects	13/09/2017	RESTANDBETHANKFUL
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 01 November 2017									
<i>No defects recorded</i>									