


Document: Form 149	Incident Response Report NW 1752519	
Issue: 5		
Related to: All Contracts		
Page No. 1 of 2		

Unit	NW	Route	A87	Link/Section	17404/00	Incident Reference	32310	
Date	[REDACTED]	Latitude	N/A	Longitude		Chainage (ILO enters)		
Type of incident (refer guidance)	12 LGV OFF ROAD							
XSP (refer guidance)	R1	Direction of travel (refer guidance)					WESTBOUND.	
Exact location details (refer guidance)	1/2 MILE WEST OF BUNLOINE JCT					Photos of incident		
						Yes	No	
Disruption type (refer guidance)	3 LANE CLOSED			Diversion used (refer guidance)	3 NONE			
Weather conditions (refer guidance)	1 FINE			Road conditions (refer guidance)	2 DAMP			
ISU / TRISS called out by	CONTROL			Mol Reference No. (ILO enters)				
ISU or TRISS	ISU / TRISS vehicle reg.	A, Incident start time	B, Time arrived at site	C, Response time (B-A)	Response on time?	Time off site		
ISU	[REDACTED]	13:35	14:10	35m	Yes	No	1500	
D, Reason for failure to meet response time if C is more than 1 hour (7am to 7pm) or 1.5 hours (7pm to 7am) for ISU or 20 minutes for TRISS								
E, Operations Manager or depute confirmation of reason for failure to meet response time at D				Signature		Date		
Flood Reports	ISU / TRISS completes Flood Report where; flood is over 3cms deep or water lying represents a hazard to road users / may interrupt the free flow of traffic or b) may cause damage to other Structures or the carriageway or c) may cause damage to adjacent property or land. ILO populates in IRIS and enters RMMf defect reference					Yes	No	
Response details	CLEARED MD FROM 50m OF CARRIAGEWAY					Photos of work		
						Yes	No	
Further works required on site - OI(s) to be raised	advise on further work, eg permanent patch 2.0m x 1.0m required, new sign plate and 2 posts required etc			VERGE REPAIR				
Damage to Crown Property details	eg damage to verge / fencing / signs / carriageway / lighting units / bollards) - or enter "NO DCP"			50m VERGE				
Car registration number / names details of persons involved								
[REDACTED]								
SEPA notified	Dead animal details		including red, roe or fallow deer, otter, badger, red squirrel, raptor species					
No	Yes							
Emergency Services in attendance	Police	Ambulance	Fire	Police Incident Number	[REDACTED]			
Initial resources attended incident								
Name	On site	Off site	Vehicle/ Plant	On site	Off site	Comments		
[REDACTED]	14:10	15:00	[REDACTED]	14:10	15:00			
[REDACTED]	14:15	15:00	[REDACTED]	14:15	15:00			
Secondary or Contingency resources attended incident								
Time Called Out	Name	On site	Off site	Vehicle/ Plant	On site	Off site	Comments	
I hereby certify that the details and resources stated above accurately represent the incident and the subsequent ISU/ TRISS response.								
Sign/ Print name/ Date Incident Liaison on site				Sign/ Print name/ Date Manager/ Supervisor				
Signature	[REDACTED]			Signature	[REDACTED]			
Print Name/ Date	[REDACTED]			Print Name/ Date	[REDACTED]			

