

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 19/09/2016 and 18/12/2017, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A85',)
(Section Code is 11940/82) Or
(Section Code is 11940/89) Or
(Section Code is 11940/93) Or
(Section Code is 11940/94)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

11940/89 : SOUTH STAFFORD ST TO SLIPWAY

Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 September 2016									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 September 2016									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 October 2016									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 October 2016									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 October 2016									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 October 2016									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 01 November 2016									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 08 November 2016									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 15 November 2016									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 November 2016									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 29 November 2016									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 06 December 2016									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 13 December 2016									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 December 2016									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 December 2016									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 03 January 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 10 January 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 17 January 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 24 January 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 31 January 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 February 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 14 February 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 February 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 February 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 March 2017									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 02 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 09 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 16 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 23 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 30 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 13 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 01 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 08 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 15 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 29 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 05 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 12 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 19 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 26 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 03 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 10 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 17 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 24 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 31 October 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 14 November 2017									
NWG23-316160-235470924	30m	0m	GULLY	Blockage (BLOK)	CAT 1	12/12/2017	Completed Defects	07/12/2017	ACROSS FROM N/WIDE BANK
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 05 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 12 December 2017									
<i>No defects recorded</i>									
11940/93 : SLIPWAY TO JCT QUEENS PARK PLACE									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 September 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 September 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 01 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 08 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 15 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 29 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 06 December 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 13 December 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 December 2016									
NWG10222854-2379232	88m	0m	MANHOLE	Difference in level with road (IDLV)	3RD PTY	17/01/2017	Awaiting CCMS Temp Date	01/01/9999	GEORGE ST, OBAN. OUTSIDE WATERSTONES
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 December 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 03 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 10 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 17 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 24 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 31 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 14 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 February 2017									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 March 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 March 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 March 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 March 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 April 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 April 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 April 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 April 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 02 May 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 09 May 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 16 May 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 23 May 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 30 May 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 June 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 13 June 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 June 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 June 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 July 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 July 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 July 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 July 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 01 August 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 08 August 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 15 August 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 August 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 29 August 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 05 September 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 12 September 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 19 September 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 26 September 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 03 October 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 10 October 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 17 October 2017 <i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 24 October 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 31 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 14 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 05 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 12 December 2017									
<i>No defects recorded</i>									
11940/94 : JCT QUEENS PARK PLACE TO JCT A816									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 September 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 September 2016									
NWG10189564-2226021	68m	0m	GULLY	Blockage (BLOK)	CAT 1	25/10/2016	Completed Defects	21/10/2016	JACKSON BUTCHERS OBAN
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 01 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 08 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 15 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 29 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 06 December 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 13 December 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 December 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 December 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 03 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 10 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 17 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 24 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 31 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 14 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 February 2017									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 02 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 09 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 16 May 2017									
<i>No defects recorded</i>									
NWG23-274908-235154338	309m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/05/2017	Completed Defects	23/05/2017	BLACK MOUNT
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 30 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 13 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 01 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 08 August 2017									
<i>No defects recorded</i>									
NWG23-283434-235305441	66m	0m	GULLY	Blockage (BLOK)	CAT 1	12/09/2017	Completed Defects	05/09/2017	REAR OF PERLE HOTEL, A85, OBAN
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 29 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 05 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 12 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 19 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 26 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 03 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 10 October 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 17 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 24 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 31 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 November 2017									
NWG23-316031-235456754	73m	0m	LIGHTING_POINT	Other (OTHR)	CAT 1	05/12/2017	Awaiting CCMS Temp Date	01/01/9999	OPTOMETIST (OBAN TOWN CENTRE)
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 14 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 05 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 12 December 2017									
<i>No defects recorded</i>									
11940/82 : With: JCT WILLIAM ST TO SOUTH STAFFORD ST									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 September 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 September 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 01 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 08 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 15 November 2016									
NWG10208805-2349850	90m	90m	BOLLARDS	Damaged (DAMG)	CAT 1	01/01/9999	Completed Defects	01/12/2016	KEBABISH RESTAURANT
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 29 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 06 December 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 13 December 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 December 2016									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 December 2016									
NWG10225742-2391061	206m	0m	MANHOLE	Rocking under load (IRLD)	3RD PTY	24/01/2017	Awaiting CCMS Temp Date	01/01/9999	DOLCE VITA. OBAN
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 03 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 10 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 17 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 24 January 2017									
NWG10237462-235040681	137m	0m	GULLY	Blockage (BLOK)	CAT 1	21/02/2017	Completed Defects	14/02/2017	TIMPSON SHOP

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG10237462-235040679	21m	0m	GULLY	Blockage (BLOK)	CAT 1	21/02/2017	Completed Defects	14/02/2017	WEBSTERS CAMAERA SHOP
NWG10237462-235040680	127m	0m	FOOTWAY	Slab rocking (SROK)	CAT 1	21/02/2017	Completed Defects	14/02/2017	NORIES CHIP SHOP
NWG10237462-235040684	201m	0m	MANHOLE	Missing (MISS)	CAT 1	21/02/2017	Completed Defects	24/01/2017	OPP DOLCE VITA,, GEORGE ST, OBAN
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 31 January 2017									
NWG23-240350-235047999	200m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/02/2017	Completed Defects	31/01/2017	DOLCE VITA, OBAN
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 February 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 14 February 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 February 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 February 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 March 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 March 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 March 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 March 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 April 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 April 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 April 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 April 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 02 May 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 09 May 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 16 May 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 23 May 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 30 May 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 June 2017									
NWG7278720-235188135	89m	0m	FOOTWAY	Other (OTHR)	CAT 1	05/07/2017	Awaiting CCMS Permanent Date	09/06/2017	OUTSIDE NORIES FISH & CHIP SHOP, OBAN HIGH STREET. (W/B FOOTWAY)
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 13 June 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 June 2017									
No defects recorded									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 June 2017									
NWG23-281573-235232343	39m	0m	FOOTWAY	Slab profile - uneven/trips (SLPF)	CAT 1	25/07/2017	Completed Defects	17/07/2017	ALL OCCASIONS
NWG23-281573-235232342	47m	0m	FOOTWAY	Slab rocking (SROK)	CAT 1	25/07/2017	Completed Defects	17/07/2017	ANGLERS CORNER
NWG23-281573-235232340	104m	0m	KERB	Loose / rocking (ELRK)	CAT 1	25/07/2017	Completed Defects	25/07/2017	KEBABISH
NWG23-281573-235232341	179m	0m	FOOTWAY	Slab rocking (SROK)	CAT 1	25/07/2017	Completed Defects	17/07/2017	SPECSAVERS

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 01 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 08 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 15 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 29 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 05 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 12 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 19 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 26 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 03 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 10 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 17 October 2017									
NWG23-315435-235430860	195m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	14/11/2017	Awaiting CCMS Temp Date	01/01/9999	START OF ESPLANNADE (OBAN)
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 24 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 31 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 14 November 2017									
NWG23-316160-235470927	80m	0m	GULLY	Blockage (BLOK)	CAT 1	12/12/2017	Completed Defects	07/12/2017	OXFAN + B.H.F SHOPS
NWG23-316160-235470926	150m	0m	GULLY	Blockage (BLOK)	CAT 1	12/12/2017	Completed Defects	07/12/2017	TRESPASS SHOP
NWG23-316160-235470928	24m	0m	GULLY	Blockage (BLOK)	CAT 1	12/12/2017	Completed Defects	07/12/2017	OBAN PHOTO CENTRE
NWG23-316160-235470925	169m	0m	GULLY	Blockage (BLOK)	CAT 1	12/12/2017	Completed Defects	07/12/2017	WHISKY SHOP
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 05 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 12 December 2017									
<i>No defects recorded</i>									