

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2017 and 03/02/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section Code is 16301/07)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
16301/07 : DERESTRICTION SIGN TO STONE CULVERT									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 03 January 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 10 January 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 17 January 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 24 January 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 31 January 2017									
No defects recorded									
NWG5242662-235051609	1,930m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/02/2017	Completed Defects	07/02/2017	GLENOGLE, E/B C/WAY
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 14 February 2017									
NWG5243205-235056795	2,221m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/03/2017	Completed Defects	13/03/2017	800M EAST OF GLENOGLE STONE CULVERT, W/B C/WAY
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 21 February 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 28 February 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 07 March 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 14 March 2017									
NWG21250919-235067534	1,251m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/03/2017	Completed Defects	14/03/2017	JUST WEST OF GLENOGLE FARM ACCESS, E/B C/WAY
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 21 March 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 28 March 2017									
NWG21254914-235073900	1,921m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/03/2017	Completed Defects	28/03/2017	GLENOGLE, E/B C/WAY
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 04 April 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 11 April 2017									
NWG21259585-235078124	2,853m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/04/2017	Completed Defects	11/04/2017	GLENOGLE, W/B C/WAY
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 18 April 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 25 April 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 02 May 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 09 May 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 16 May 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 23 May 2017									
NWG7274890-235161626	2,120m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	12/07/2017	JUST WEST OF QUEEN VICTORIA SEAT ACCESS, GLENOGLE. (E/B C/WAY)
NWG7274890-235161627	2,123m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	12/07/2017	JUST WEST OF QUEEN VICTORIA SEAT ACCESS, GLENOGLE. (E/B C/WAY)
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 30 May 2017									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 06 June 2017									
NWG7278711-235173659	1,175m	0m	MANHOLE	Difference in level with road (IDLV)	3RD PTY	04/07/2017	Awaiting CCMS Temp Date	01/01/9999	SOUTH GLEN OGLE N/B C/WAY
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 13 June 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 20 June 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 27 June 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 04 July 2017									
NW31281785-235231128	1,847m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/07/2017	Completed Defects	04/07/2017	QUEEN VICTORIAS SEAT GLENOGLE
NW31281785-235231127	1,862m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/07/2017	Completed Defects	04/07/2017	QUEEN VICTORIAS SEAT GLENOGLE
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 11 July 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 18 July 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 25 July 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 01 August 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 08 August 2017									
NW31283099-235298252	1,926m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	09/08/2017	Completed Defects	08/08/2017	GLENOGLE SB
NW31283099-235298253	1,929m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	09/08/2017	Completed Defects	08/08/2017	GLENOGLE SB
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 15 August 2017									
NW31283425-235305425	663m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/08/2017	Completed Defects	15/08/2017	TOLL HOUSE GLENOGLE SB
NW31283425-235305432	677m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	TOLL HOUSE GLENOGLE SB
NW31283425-235305428	669m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/08/2017	Completed Defects	15/08/2017	TOLL HOUSE GLENOGLE NB
NW31283425-235305429	657m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF TARBERT CO-OP TOLL HOUSE GLENOGLE NB
NW31283425-235305424	681m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/08/2017	Completed Defects	15/08/2017	TOLL HOUSE GLENOGLE SB
NW31283425-235305426	677m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/08/2017	Completed Defects	15/08/2017	TOLL HOUSE GLENOGLE SB
NW31283425-235305427	669m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/08/2017	Completed Defects	15/08/2017	TOLL HOUSE GLENOGLE NB
NW31283425-235305430	668m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	TOLL HOUSE GLENOGLE NB
NW31283425-235305431	687m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	TOLL HOUSE GLENOGLE SB
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 22 August 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 29 August 2017									
NW31283859-235335325	974m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	18/10/2017	JUST SOUTH OF GLENOGLE FARM ACCESS, N/B C/WAY.
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 05 September 2017									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 12 September 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 19 September 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 26 September 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 03 October 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 10 October 2017									
NWG8315296-235426310	1,553m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/10/2017	Completed Defects	10/10/2017	GLEN OGLE NB
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 17 October 2017									
NWG8315430-235430927	192m	0m	CHANNEL	Impeded water flow (detritus) (IMWF)	CAT 1	18/10/2017	Completed Defects	23/10/2017	200M NTH OF LOCHEARNHEAD SB
NWG8315430-235430926	193m	0m	GULLY	Blockage (BLOK)	CAT 1	14/11/2017	Completed Defects	23/10/2017	200M NTH OF LOCHEARNHEAD SB
NWG8315430-235430928	163m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/10/2017	Completed Defects	17/10/2017	200M NTH OF LOCHEARNHEAD SB
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 24 October 2017									
NWG8315577-235434462	1,929m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/10/2017	Completed Defects	24/10/2017	VICTORIAS SEAT GLENOGLE SB
NWG8315577-235434461	2,886m	0m	GULLY	Cracked or broken (IBCK)	CAT 1	21/11/2017	Completed Defects	24/11/2017	100M STH OF STONE CULVERT SB
NWG8315577-235434463	1,175m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/10/2017	Completed Defects	24/10/2017	GLENOGLE FARM SB
NWG8315577-235434452	197m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/10/2017	Completed Defects	24/10/2017	JUST NTH OF LOCHEARNHEAD NB
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 31 October 2017									
NWG8315720-235445776	1,929m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/11/2017	Completed Defects	31/10/2017	GLEN OGLE S/B C/WAY
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 07 November 2017									
NWG11316026-235456712	1,557m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/11/2017	Completed Defects	07/11/2017	GLENOGLE, N/B C/WAY.
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 14 November 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 21 November 2017									
No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 28 November 2017									
NWG8316419-235479027	1,929m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/11/2017	Completed Defects	28/11/2017	QUEEN VICTORIAS SEAT GLENOGLE
NWG8316419-235479028	1,923m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/11/2017	Completed Defects	28/11/2017	QUEEN VICTORIAS SEAT GLENOGLE
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 05 December 2017									
NWG11316593-235486692	1,964m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/12/2017	Completed Defects	05/12/2017	GLENOGLE, S/B C/WAY
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 12 December 2017									
NW122316773-235495328	1,927m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	09/01/2018	Completed Defects	19/12/2017	JUST NTH OF VICTORIAS SEAT GLENOGLE SB
NW122316773-235495327	1,931m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	09/01/2018	Completed Defects	19/12/2017	JUST NTH OF VICTORIAS SEAT GLENOGLE SB
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 19 December 2017									
No defects recorded									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 22 December 2017 No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 29 December 2017 No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 05 January 2018 No defects recorded									
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 09 January 2018 No defects recorded									
NW122317568-235518583	1,562m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	17/01/2018	Completed Defects	16/01/2018	GLENOGLE, W/B C/WAY.
Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 23 January 2018 No defects recorded									
NW122318005-235529557	1,372m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/02/2018	Awaiting CCMS Permanent Date	01/01/9999	NTH OF GLENOGLE FARM SB
NW122318005-235529558	967m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	27/02/2018	Awaiting CCMS Permanent Date	01/01/9999	GLENOGLE FARM
NW122318005-235529559	966m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	27/02/2018	Awaiting CCMS Permanent Date	01/01/9999	GLENOGLE FARM