Defect ID	Date Raised	Date Complete	Status		Location	Item	Item Type
	30/03/2015 13:42:00					CARRIAGEWAY CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)
	30/03/2015 13:54:00					CARRIAGEWAY	Pothole (POTH)
	31/03/2015 14:03:00						Pothole (POTH)
	26/05/2015 15:13:02					GULLY	Rocking under load (IRLD)
	01/06/2015 13:54:00					CARRIAGEWAY	Pothole (POTH)
	04/06/2015 15:13:00					CARRIAGEWAY	Pothole (POTH)
M8-215429-3929	15/06/2015 14:01:00					GULLY	Rocking under load (IRLD)
	06/07/2015 14:37:00					CARRIAGEWAY	Pothole (POTH)
	13/07/2015 14:10:00					CARRIAGEWAY	Pothole (POTH)
M8-223062-3986						CARRIAGEWAY	Pothole (POTH)
	16/07/2015 14:26:00					CARRIAGEWAY	Pothole (POTH)
	27/07/2015 14:08:00					CARRIAGEWAY	Pothole (POTH)
	30/07/2015 14:24:00					CARRIAGEWAY	Pothole (POTH)
	03/08/2015 14:52:00					CARRIAGEWAY	Pothole (POTH)
	06/08/2015 14:28:00					CARRIAGEWAY	Pothole (POTH)
	17/08/2015 14:11:00					CARRIAGEWAY	Pothole (POTH)
	24/08/2015 14:17:00					CARRIAGEWAY	Pothole (POTH)
M8DBFO154355	26/08/2015 15:30:26	11/09/2015 20:30:00	Completed Work	CATEGORY 1	A725 N/B ORBISTON OFF SLIP @ CENTRE SEAM	CARRIAGEWAY	Pothole (POTH)
M8DBFO154373	04/09/2015 10:24:41	17/09/2015 05:00:00	Completed Work	CATEGORY 1	A725 Various Locations	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)
M8-246066-4608	01/10/2015 14:41:00	23/10/2015 00:00:00	Completed Work	CATEGORY 1	?	GULLY	Difference in level with road (IDLV)
M8-253281-10966	26/10/2015 14:19:00	28/10/2015 09:59:00	Completed Work	CATEGORY 1	A725 RAITH INT BETWEEN S/B ON + N/B OFF SLIPS	CARRIAGEWAY	Pothole (POTH)
M8-256070-10966	05/11/2015 13:56:00	02/12/2015 04:00:00	Completed Work	CATEGORY 1	A725 N/B @ ORBISTON OFF SLIP	CARRIAGEWAY	Pothole (POTH)
M8-256080-59403	16/11/2015 13:55:00	16/11/2015 22:30:00	Completed Work	CATEGORY 1	A725 S/B ORBISTON TO RAITH N/S GULLY	GULLY	Rocking under load (IRLD)
M8-256080-59404	16/11/2015 14:08:00	17/11/2015 02:30:00	Completed Work	CATEGORY 1	A725 RAITH R/A/B BETWEEN N/B ON SLIP & S/B OFF SLIP IN LANES 1,2	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)
M8-256082-59421	19/11/2015 13:26:00	10/12/2015 06:00:00	Completed Work	CATEGORY 1	A8 W/B SLIP TO A725 N/S/L N/S/W/TRACK JUST PRIOR TO OLD GASS STATION	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)
M8-256082-59422	19/11/2015 13:43:00	12/12/2015 02:30:00	Completed Work	CATEGORY 1	A725 N/B NORTH ROAD T/LIGHTS+20MTRS O/S/W/T IN LANE2	CARRIAGEWAY	Pothole (POTH)
M8-256082-59423	19/11/2015 13:47:00	10/12/2015 04:30:00	Completed Work	CATEGORY 1	A725 N/B ADJACENT TO BELLZIEHILL ON SLIP N/S/L O/S/W/TRACK	CARRIAGEWAY	Pothole (POTH)
M8-256082-59424	19/11/2015 13:50:00	20/11/2015 00:30:00	Completed Work	CATEGORY 1	A725 N/B WHISTLEBERRY TO RAITH JUST AT ENTRY TO R/A/B	CARRIAGEWAY	Pothole (POTH)
	23/11/2015 13:33:00				A725 S/B ORBISTON OFF-ON N/S/L N/S/W/TRACK	CARRIAGEWAY	Pothole (POTH)
M8-256084-59422	23/11/2015 13:36:00	10/12/2015 20:30:00	Completed Work	CATEGORY 1	A725 S/B ORBISTON TO RAITH JUST AT START OF 3 LANE SECTION GULLY IN L2&POTHOLE IN L3 N/S/W/TRACK	CARRIAGEWAY	Pothole (POTH)
	23/11/2015 13:47:00				A725 N/B SHAWHEAD OVERBRIDGE TO R/A/B LAST N/S GULLY	CARRIAGEWAY	Pothole (POTH)
	23/11/2015 13:50:00					CARRIAGEWAY	Pothole (POTH)
	23/11/2015 14:02:00					CARRIAGEWAY	Pothole (POTH)
	26/11/2015 14:01:00					CARRIAGEWAY	Pothole (POTH)
	30/11/2015 13:57:00					CARRIAGEWAY	Pothole (POTH)
	10/12/2015 14:14:00					CARRIAGEWAY	Pothole (POTH)
	10/12/2015 14:25:00					CARRIAGEWAY	Pothole (POTH)
	11/12/2015 13:40:31					CARRIAGEWAY	Bituminous surfacing fretting (BFRT)
	14/01/2016 13:07:00					GULLY	Rocking under load (IRLD)
	15/01/2016 09:38:20					TREE	Unstable (UNST)
	18/01/2016 14:43:00					GULLY	Rocking under load (IRLD)
						GULLY	Cracked or broken (IBCK)
	21/01/2016 13:50:00					CARRIAGEWAY	Pothole (POTH)
	25/01/2016 14:29:00					CARRIAGEWAY	Pothole (POTH)
	28/01/2016 13:53:00					CARRIAGEWAY	Pothole (POTH)
	28/01/2016 13:59:00					CARRIAGEWAY	Pothole (POTH)
	01/02/2016 13:48:00					CARRIAGEWAY	Pothole (POTH)
	01/02/2016 13:48:00					CARRIAGEWAY	Pothole (POTH)
							,
	08/02/2016 14:52:00					CARRIAGEWAY	Pothole (POTI)
	11/02/2016 13:22:00					CARRIAGEWAY CARRIAGEWAY	Pothole (POTH)
	15/02/2016 13:48:00						Pothole (POTH)
	15/02/2016 13:52:00					GULLY	Rocking under load (IRLD)
	18/02/2016 14:03:00					CARRIAGEWAY	Pothole (POTI)
	22/02/2016 14:46:00					CARRIAGEWAY	Pothole (POTH)
	03/03/2016 14:21:00					CARRIAGEWAY	Pothole (POTH)
	17/03/2016 13:06:00					GULLY	Rocking under load (IRLD)
	17/03/2016 14:06:00					CARRIAGEWAY	Pothole (POTH)
M8-256165-69469	21/03/2016 13:34:00	21/03/2016 21:30:00	Completed Work	CATEGORY 1	A725 S/B NORTH ROAD TO DIAMOND JUST THROUGH X/OVER ONTO OLD A725 AT CENTRR SEEM.	CARRIAGEWAY	Pothole (POTH)