

Inspection Defect Summary Report

This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 10/01/2018 and 14/02/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section Code is 10890/05) Or

(Section Code is 10890/40) Or

(Section Code is 10890/70) Or

(Section Code is 10892/05) Or

(Section Code is 10890/20) Or

(Section Code is 10890/90)



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
10890/05 : A831 DRUMNADROCHIT BRIDGE TO 12ML MILESTONE									
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 10 January 2018									
No defects recorded									
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 17 January 2018									
No defects recorded									
NWG15317571-235519551	1,993m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/01/2018	Completed Defects	17/01/2018	SB AT TEMPLE PIER
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 24 January 2018									
No defects recorded									
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 31 January 2018									
No defects recorded									
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 07 February 2018									
No defects recorded									
NWG15318664-235534274	642m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/02/2018	Completed Defects	07/02/2018	SB BFR DRUMNADROCHIT
NWG15318664-235534282	1,475m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR) Pothole VIAFIX (POTV)	CAT 1	07/03/2018	Completed Defects	19/02/2018	NB AFTER DRUM
NWG15318664-235534273	369m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/02/2018	Completed Defects	07/02/2018	NB AFER DRUMNADROCHIT
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 14 February 2018									
No defects recorded									
NWG15319223-2355641750	325m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/02/2018	Completed Defects	14/02/2018	SB DRUM
10890/20 : 12ML MILESTONE TO CLANSMAN HOTEL									
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 10 January 2018									
No defects recorded									
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 17 January 2018									
No defects recorded									
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 24 January 2018									
No defects recorded									
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 31 January 2018									
No defects recorded									
NWG15318009-235530357	1,616m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	28/02/2018	Completed Defects	15/02/2018	NB BFR CLANSMAN
NWG15318008-235530358	1,648m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/02/2018	Completed Defects	22/02/2018	NB BFR CLANSMAN
NWG15318008-235530359	1,739m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/02/2018	Completed Defects	22/02/2018	SB BFR TYCHAT
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 07 February 2018									
No defects recorded									
NWG15318664-235534269	151m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/03/2018	Completed Defects	15/02/2018	NB BFR TYCHAT

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG15318664-235534271	1,504m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/02/2018	Completed Defects	07/02/2018	SB AFTER CLANSMAN HOTEL
NWG15318664-235534270	142m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/03/2018	Completed Defects	15/02/2018	NB BFR TYCHAT
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 14 February 2018 No defects recorded									
1089040 : CLANSMAN HOTEL TO ROSE COTTAGE									
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 10 January 2018 No defects recorded									
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 17 January 2018 No defects recorded									
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 24 January 2018 No defects recorded									
NWG15317726-235528572	2,239m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2018	Completed Defects	15/02/2018	SB AFT ABREACHAN JNC
NWG15317726-235528571	2,009m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2018	Completed Defects	15/02/2018	NB BFR ABREACHAN JUNC
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 31 January 2018 No defects recorded									
NWG15318008-235530366	353m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/02/2018	Completed Defects	31/01/2018	SB BFR CLANSMAN HOTEL
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 07 February 2018 No defects recorded									
NWG15318664-235534272	1,866m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/03/2018	Completed Defects	07/03/2018	OUTSIDE ABRIACHEN
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 14 February 2018 No defects recorded									
NWG15319223-235541749	6,289m	0m	TRAFFIC_SIGNS	Painting wrong way (RWAY)	CAT 1	15/02/2018	Completed Defects	14/02/2018	SB LOCHEND
1089070 : ROSE COTTAGE TO 1ST LAYBY DUNAIN STR									
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 10 January 2018 No defects recorded									
NWG15317388-235514120	2,087m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	31/01/2018	DOCHFOUR HOUSE
NWG15317388-235514116	2,132m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	31/01/2018	NB AFTR DOCHFOUR HOUSE
NWG15317388-235514117	2,125m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	31/01/2018	NB DOCHFOUR HOUSE
NWG15317388-235514119	2,103m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	31/01/2018	DOCHFOUR HOUSE
NWG15317388-235514114	1,601m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	31/01/2018	SB BFR DOCHFOUR HOUSE
NWG15317388-235514115	1,598m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	31/01/2018	NB AFTR DOCHFOUR HOUSE
NWG15317388-235514118	2,102m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	31/01/2018	DOCHFOUR HOUSE
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 17 January 2018 No defects recorded									
NWG15317571-235519550	4,869m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/01/2018	Completed Defects	17/01/2018	BFR DUNAIN MAINS
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 24 January 2018 No defects recorded									
NWG15317726-235528569	1,926m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2018	Completed Defects	21/02/2018	SB AFT DOCHFOR HOUSE
NWG15317726-235528567	1,967m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/01/2018	Completed Defects	24/01/2018	SB AFT DOCHFOR HOUSE

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG15317726-235528563	2,549m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/01/2018	Completed Defects	24/01/2018	SB AFT OAKWOOD
NWG15317726-235528570	1,603m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2018	Completed Defects	21/02/2018	SB AFT DOCHFORD HOUSE
NWG15317726-235528564	2,122m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/01/2018	Completed Defects	24/01/2018	SB AFT DOCHFORD HOUSE
NWG15317726-235528568	1,950m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/01/2018	Completed Defects	24/01/2018	SB AFT DOCHFORD HOUSE
NWG15317726-235528566	2,032m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 2	25/01/2018	Cat 2 Awaiting Action	24/01/2018	NB NB BFR DOCHFORD HOUSE
NWG15317726-235528561	4,877m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2018	Completed Defects	12/02/2018	SB DUNAIN STRAGT
NWG15317726-235528562	2,536m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2018	Completed Defects	12/02/2018	SB AFT OAKWOOD
NWG15317726-235528565	2,030m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2018	Completed Defects	21/02/2018	SB AFT DOCHFORD HOUSE
Safety Inspection of A9 Safety Daiwhinnie & A82 Invermoriston on 31 January 2018									
NWG15318008-235530353	2,030m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/02/2018	Completed Defects	31/01/2018	SB LOCHEND
NWG15318008-235530355	1,606m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	28/02/2018	Completed Defects	21/02/2018	SB LOCHEND
NWG15318008-235530354	1,847m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/02/2018	Completed Defects	31/01/2018	SB LOCHEND
NWG15318008-235530352	2,195m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/02/2018	Completed Defects	31/01/2018	SB LOCHEND
Safety Inspection of A9 Safety Daiwhinnie & A82 Invermoriston on 07 February 2018									
NWG15318664-235534268	1,920m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/02/2018	Completed Defects	07/02/2018	SB LCH DAUCH HOUSE
Safety Inspection of A9 Safety Daiwhinnie & A82 Invermoriston on 14 February 2018									
NWG15319223-235541746	4,144m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/02/2018	Completed Defects	14/02/2018	SB LACKFOR
NWG15319223-235541747	3,424m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	21/02/2018	NB OAKWOOD
NWG15319223-235541745	4,249m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/02/2018	Completed Defects	14/02/2018	SB BLACKFOLD JUN
NWG15319223-235541748	2,125m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	21/02/2018	NB ROSE COTTAG
1089090 : 1ST LAYBY DUNAIN STR TO TOMNACHURICH BR									
Safety Inspection of A9 Safety Daiwhinnie & A82 Invermoriston on 10 January 2018									
NWG15317368-235514113	573m	0m	MANHOLE	Missing (MISS)	CAT 1	07/02/2018	Completed Defects	07/02/2018	SB LOCHNESS HOUSE
Safety Inspection of A9 Safety Daiwhinnie & A82 Invermoriston on 17 January 2018									
No defects recorded									
Safety Inspection of A9 Safety Daiwhinnie & A82 Invermoriston on 24 January 2018									
No defects recorded									
Safety Inspection of A9 Safety Daiwhinnie & A82 Invermoriston on 31 January 2018									
No defects recorded									
Safety Inspection of A9 Safety Daiwhinnie & A82 Invermoriston on 07 February 2018									

Defect Reference	Start	End	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG15318664-235534267	1,243m	0m	CARRIAGEWAY	Pothole V/AFIX (POTV)	CAT 1	08/02/2018	Awaiting CCMS Permanent Date	07/02/2018	SB BFR CREMATORIUM JUNT
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 14 February 2018 No defects recorded									
10892/05 : TOMNAHURICH BRIDGE TO B862 KENNETH STREET									
NWG15317388-235514112	733m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	29/01/2018	NB BALIFAIRY LANE
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 17 January 2018 No defects recorded									
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 24 January 2018 No defects recorded									
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 31 January 2018 No defects recorded									
NWG15318664-235534283	511m	0m	CARRIAGEWAY	Pothole V/AFIX (POTV)	CAT 1	08/02/2018	Completed Defects	07/02/2018	NB AFTER CEMARET
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 07 February 2018 No defects recorded									
Safety Inspection of A9 Safety Dalwhinnie & A82 Invermoriston on 14 February 2018 No defects recorded									