

2015/16	Scheme Name
Carriageway	A77 - Wee Ireland Jct - B742
	A77 Bonnybraes
	A77 Rhins of Galloway
	A77 Beoch junction
	A77 South of Beoch
Drainage	A77 Maybole Drainage
Lighting	A77 COLUMN INSPECTIONS (Column Replacements 18/12/15 DRB)
	A77 LIGHTING DEFECTS FROM NIGHT INSPECTIONS A77 23/10/2015
Signage	A77 Bogend to Hansel Speed Limit Review
Earthworks	A77 Marchburn Slip Remedial Works Only
Bridges	A77 380 Inchgottrick - Parapet Replacement
	A77 Clune Culvert - Scour Protection Works
	A77 140 W83 Ardmillan Sea Wall - Scour Protection Works
	A77 90 C90 Smyrton

2016/17	Scheme Name
Carriageway	A77 Cairnryan South Gateway
	A77 Bridgemill Roundabout to Girvan Mains
	A77 North of Stena Ferry Terminal
	A77 Littlehill to Burnside Farm
	A77 Whiteside Overbridge to Adamton SB
	A77 Minnybae
	A77 Stena Terminal
	A77 Lendalfoot Nth Gateway
	A77 Bennane Road Girvan s/b
	A77 Kirkoswald Nth Gateway
	A77 Auchendraine
	A77 Sth of Kirkoswald, Anti-skid
	A77 Bogend Toll S/B Off Slip
	A77 Auchairne
	A77 Auchairne
	A77 Turnberry
	A77 Carlock Hill
	A77 North Bridgehouse
	A77 Littlehill to Burnside Farm
	A77 Maybole
	A77 KIRKOSWALD
	A77 Carcluie Toll, North of B7034 traffic loop replacement
	A77 Ardwell replacement of defective traffic loop detector.
	A77 Auchenblaine
	A77 Littlehill to Burnside Farm
	A77 South of Kirkoswald Kerbing Works
	Signage
A77 Dowhill Country Fayre sign	
A77 WHATRIGGS N/B TOURIST SIGN	
A77 North of Bankfield Tourist Sign	
A77 Ballantrae - Pole and Countdown Sign	
A77 Girvan School speed limit VMS signs.	
Drainage	A77 Auchairne
	A77 Maybole
	A77 Carlockhill North
	A77 Auchincrosh
	A77 South of Ballantrae
A77 Kirkoswald Rd Maybole	
Landscaping	A77 Lendalfoot footway vegetation cut back
	A77 Bennane Hill Coastal Path RM Vegetation Cut Back

Lighting	CAT2 LIGHTING DEFECTS A77
	CAIRNRYAN COLUMN TESTING
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTIONS 23/08/2016
	A77 CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTIONS 23/08/2016
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTIONS 21/09/2016 A77
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTIONS A77 21/09/2015
	CAT2 LIGHTING DEFECT FROM NIGHT INSPECTIONS 21/09/2016 A77
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTIONS 21/09/2016 A77
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTIONS 21/09/2016 A77
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTIONS 23/09/2016 A77
	CAT2 LIGHTING DEFECT FROM NIGHT 23/09/2016 A77
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTIONS 23/09/2016 A77
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTIONS A77 23/09/2016
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTIONS A77 23/09/2016
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTION A7729/09/2016
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTIONS A77 23/09/2016
	CAT2 LIGHTING LIGHTING DEFECTS FROM NIGHT INSPECTIONS A77 23/09/2016
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTIONS A77 23/09/2016
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTIONS 23/09/2016 A77
Earthworks	A77 Straid Pass - Landslip 04/02/17
	A77 - North of Stena Terminal, Landslip and tension cracking. (Previously 15/SW/0901/003)
	A77 Carlock Hill 2 Minor Slip
	A77 500 Assloss
	A77 Carlock Wall Rock Face
Road Safety	A75/A76/A77 Roundabout Approaches
	A77 Girvan pedestrian crossing
	A77 Bellfield Roundabout Queuing Vehicles
	A77 Inchgottrick passive safety
	A77 Brocket Farm passive safety
	A77 Kirkoswald speed survey
Bridges	A77 70 Burnfoot - Waterproofing & Patch Repairs
	A77 200 Bridgemill Rail Emergency Inspection to remove loose panels
Operations	A77 Glen App weather station theft.

2017/18	Scheme Name
Carriageway	A77 Layby to Inchgottrick SB
	A77 Drumellan Farm to Smithston
	A77 Shallochpark RBT to Young St
	A77 Auchenblane Reinstated
	A77 Beoch to Drummockloch
	A77 Raith Burn to Shawhill Farm SB
	HD28 Retexturing Site 2 - A77 South of Holmston Roundabout
	HD28 Retexturing Site 7 - A77 Kilphin to Auchairne
	North End of Carlock Hill
	North of Auchencrosh
	A77 south of Carlock house
	A77 Kennedy's pass
	A77 Straid Pass
	A77 South of Carlock Hill
	A77 Drumbo Kennels
	A77 Kilphin farm
	A77 Kirkoswald village
	A77 Girvan Kirkpatrick St -Henrietta St
	A77 Kirkoswald Road Maybole
	A77 Croftengee Cottage
	A77 Dalquhatt Farm
	A77 Dowhill

	A77 North of Girvan
	A77 Sth of Kennedys Pass
	A77 Ballantrae Village
	A77 44 Cassillis Road Maybole
Signage	A77 Dippol Factory Signage scheme
	A77 Whattriggs Tourist Sign Removal
Drainage	A77 Overmills Road Drainage
Earthworks	A77 Straid Pass - Landslip 04/02/17
	A77 Auchincrosh to Ballantrae Vegetation and Woodland Management Scheme
	A77 Treeswood Road northbound
	A77 Kennedys Pass
Lighting	CAT2 LIGHTING DEFECTS FROM NIGHTING SCOUNTS A77
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTIONS A77
	CAT2 LIGHTING DEFECTS FROM INSPECTIONS A77
	CAT2 LIGHTING DEFECTS ON NIGHT INSPECTIONS A77
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTIONS A77
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTONS A77
	CAT2 LIGHTING DEFECTS FROM NIGHT INSPECTION A77
	CAT2 A77 MINISHANT PANNEL RE-NEW
	CAT2 LIGHTING DEFECT FROM NIGHT SCOUTS A77 SHALLOCHPARK RBT
	CAT1 defect in excess of £10k VRS for A77 Kennedys Pass NB
Operations	A77 Turnberry - Weather Station Upgrade
	A77 Storm Dylan - Provision of Transport Scotland Unimog
Bridges	A77 Smithston Bridge Junction
	Lendalfoot traffic management
	110 Ballantrae Deck Refurbishment
	80 W89 Drumbo & A77 82 W25 Finnarts Access Improvements
	180 Bridgemill River Joint Replacement
	150 W8 Craigs Kelly Sea Wall Repairs & VRS Replacement
	70 Burnfoot New - Waterproofing & Surfacing Repairs
	Call Out 60030 - A77 Holmston to Smithston Bridge