

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/12/2017 and 12/02/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'END OF EXIT FROM AUCHINLECK RBT TO B713 JUNCTION',) Or

(Section is 'B713 JUNCTION TO 50M NTH JCT HIGHCLEWS',) Or

(Section is '50M NTH OF JCT HIGHCLEWS TO B705 CATRINE RD',) Or

(Section is 'B705 CATRINE RD JUNCTION TO B743 MANSEFIELD RD JCT',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
13270/09 : END OF EXIT FROM AUCHINLECK RBT TO B713 JUNCTION									
Safety Inspection of A76 & A77 Ayr North V1 on 05 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 12 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 19 December 2017									
SW82316989-235510276	2,927m	2,928m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/01/2018	Completed Defects	25/01/2018	A76 N/B C/W OPPOSITE B713 JCT CATRINE SOUTH OF MAUCLINE
Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018									
SW82317274-235513672	2,652m	2,653m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/01/2018	Completed Defects	25/01/2018	A76 N/B C/W KENSTY JCT SOUTH OF MAUCLINE
SW82317274-235513673	2,963m	2,964m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/01/2018	Completed Defects	25/01/2018	A76 N/B C/W ON BRIDGE 300M SOUTH OF CATRINE JCT SOUTH OF MAUCLINE
Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018									
SW82317767-235529078	2,795m	2,798m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/02/2018	Completed Defects	13/02/2018	A76 NB CW, 300M STH OF CATRINE JCT, STH OF MAUCLINE
SW82317767-235529079	3,287m	3,288m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/02/2018	Completed Defects	13/02/2018	A76 NB CW, AT CATRINE JCT, STH OF MAUCLINE
Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018									
SW82318894-235534940	3,305m	3,306m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	06/02/2018	A76 NB CW, OPPOSITE CATRINE JCT, STH OF MAUCLINE
13270/54 : B713 JUNCTION TO 50M NTH JCT HIGHCLEWS									
Safety Inspection of A76 & A77 Ayr North V1 on 05 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 12 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 19 December 2017									
SW82316989-235510277	981m	981m	GULLY	Blockage (BLOK)	CAT 1	20/12/2017	Completed Defects	19/12/2017	A76 AT HOWFORD BRIDGE
Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017									
SW82317095-235513356	750m	751m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/01/2018	Completed Defects	23/01/2018	A76 NB CW, AT STH BRIDGE JOINT ONHOWFORD BRIDGE

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018**

SW82317767-235529080	1,373m	1,375m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/02/2018	Completed Defects	13/02/2018	A76 SB CW, 400M STH OF BALLOCHMYLE JCT STH OF MAUCLINE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018***No defects recorded***13270/75 : 50M NTH OF JCT HIGHCLEWS TO B705 CATRINE RD****Safety Inspection of A76 & A77 Ayr North V1 on 05 December 2017***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 12 December 2017***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 19 December 2017**

SW82316989-235510278	815m	816m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/01/2018	Completed Defects	24/01/2017	A76 S/B C/W 800M SOUTH OF MAUCLINE NORTH OF GRASMALISE COTAGE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

SW82317095-235513357	865m	866m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/01/2018	Awaiting CCMS Permanent	01/01/9999	A76 SB CW, BETWEEN SOUTH MFIELD KENELS AND GRASSMILLS COTTAGE
----------------------	------	------	-------------	----------------	-------	------------	-------------------------	------------	---

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

SW82317274-235513674	1,237m	1,238m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/01/2018	Completed Defects	25/01/2018	A76 S/B C/W 350M SOUTH OF MAUCLINE PRIOR TO SOUTHFIELD BOARDING KENNELS
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018**

SW82318894-235534941	908m	918m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	07/02/2018	A76 ON CL, 100M STH OF SOUTHFIELD KENNELS, STH OF MAUCLINE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

13274/05 : B705 CATRINE RD JUNCTION TO B743 MANSEFIELD RD JCT**Safety Inspection of A76 & A77 Ayr North V1 on 05 December 2017**

SW82316680-235487339	224m	225m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/01/2018	Completed Defects	20/12/2017	A76 NB CW, 100M STH OF PETROL STATION, MAUCLINE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A76 & A77 Ayr North V1 on 12 December 2017*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 19 December 2017***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018***No defects recorded*

