

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 25/12/2017 and 27/03/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST: M8 SLIP RD TO B768 DUMBRECK RD INT (N)',) Or

(Section is 'AGAINST:B768 DUMBRECK RD INT TO B762 B HEAD RD INT',) Or

(Section is 'AGAINST:B762 B HEAD RD INT(S)TO NITSHILL INT (N)',) Or

(Section is 'AGAINST: SLIP OFF TO NITSHILL ROAD S/B',) Or

(Section is 'AGAINST: NITSHILL RD INT NORTH TO SOUTH SLIP',) Or

(Section is 'AGAINST: NITSHILL INT (S) TO CROOKFUR INT.',) Or

(Section is 'WITH:B768 DUMBRECK RD INT (N) TO M8 SLIP RD',) Or

(Section is 'WITH: B768 DUMBRECK RD INT SOUTH TO NORTH SLIP',) Or

(Section is 'WITH:B762 BARRHEAD RD INT TO B768 DUMBRECK RD INT',) Or

(Section is 'WITH: NITSHILL RD INT TO B762 BARRHEAD RD INT',) Or

(Section is 'WITH: NITSHILL RD INT SOUTH TO NORTH SLIP',) Or

(Section is 'WITH: CROOKFUR INT TO NITSHILL INT (S)',) Or

(Section is 'WITH: A77 OVERBRIDGE TO CROOKFUR INT',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

11455/05 : WITH: CROOKFUR INT TO NITSHILL INT (S)

Safety Inspection of M77 Inspection on 28 December 2017

No defects recorded

Safety Patrol of M77 Inspection on 31 December 2017

No defects recorded

Safety Inspection of M77 Inspection on 04 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 11 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 14 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 18 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 25 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 28 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 01 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 02 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 March 2018

No defects recorded

11455/06 : AGAINST: NITSHILL INT (S) TO CROOKFUR INT.

Safety Inspection of M77 Inspection on 28 December 2017

No defects recorded

Safety Patrol of M77 Inspection on 31 December 2017

No defects recorded

Safety Inspection of M77 Inspection on 04 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 11 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 14 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 18 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 25 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 28 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 01 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 02 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 March 2018

No defects recorded

11460/05 : WITH: NITSHILL RD INT SOUTH TO NORTH SLIP

Safety Inspection of M77 Inspection on 28 December 2017

No defects recorded

Safety Patrol of M77 Inspection on 31 December 2017

No defects recorded

Safety Inspection of M77 Inspection on 04 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 11 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 14 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 18 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 25 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 28 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 01 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 02 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 March 2018

No defects recorded

11460/06 : AGAINST: NITSHILL RD INT NORTH TO SOUTH SLIP

Safety Inspection of M77 Inspection on 28 December 2017

No defects recorded

Safety Patrol of M77 Inspection on 31 December 2017

No defects recorded

Safety Inspection of M77 Inspection on 04 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 11 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 14 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 18 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 25 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 28 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 01 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 02 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 March 2018

No defects recorded

11460/25 : WITH: NITSHILL RD INT TO B762 BARRHEAD RD INT

Safety Inspection of M77 Inspection on 28 December 2017

No defects recorded

Safety Patrol of M77 Inspection on 31 December 2017

No defects recorded

Safety Inspection of M77 Inspection on 04 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 11 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 14 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 18 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 25 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 28 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 01 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 February 2018

SW85-320276-235537149	352m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/03/2018	Completed Defects	22/02/2018	L1 N/S WHEEL TRACK
-----------------------	------	----	-------------	-------------------	-------	------------	----------------------	------------	--------------------

Safety Inspection of M77 Inspection on 22 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 02 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 March 2018

No defects recorded

11460/26 : AGAINST:B762 B HEAD RD INT(S)TO NITSHILL INT (N)

Safety Inspection of M77 Inspection on 28 December 2017

No defects recorded

Safety Patrol of M77 Inspection on 31 December 2017

No defects recorded

Safety Inspection of M77 Inspection on 04 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 11 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 14 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 18 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 25 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 28 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 01 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 02 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 March 2018

No defects recorded

11465/22 : WITH:B762 BARRHEAD RD INT TO B768 DUMBRECK RD INT

Safety Inspection of M77 Inspection on 28 December 2017

No defects recorded

Safety Patrol of M77 Inspection on 31 December 2017

No defects recorded

Safety Inspection of M77 Inspection on 04 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 11 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 14 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 18 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 25 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 28 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 01 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 02 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 March 2018

No defects recorded

11465/23 : AGAINST:B768 DUMBRECK RD INT TO B762 B HEAD RD INT

Safety Inspection of M77 Inspection on 28 December 2017

No defects recorded

Safety Patrol of M77 Inspection on 31 December 2017

No defects recorded

Safety Inspection of M77 Inspection on 04 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 11 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 14 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 18 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 25 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 28 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 01 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 02 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 March 2018

No defects recorded

11470/07 : WITH: B768 DUMBRECK RD INT SOUTH TO NORTH SLIP

Safety Inspection of M77 Inspection on 28 December 2017

No defects recorded

Safety Patrol of M77 Inspection on 31 December 2017

No defects recorded

Safety Inspection of M77 Inspection on 04 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 11 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 14 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 18 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 25 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 28 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 01 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 02 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 March 2018

No defects recorded

11470/42 : WITH:B768 DUMBRECK RD INT (N) TO M8 SLIP RD

Safety Inspection of M77 Inspection on 28 December 2017

No defects recorded

Safety Patrol of M77 Inspection on 31 December 2017

No defects recorded

Safety Inspection of M77 Inspection on 04 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 11 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 14 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 18 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 25 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 28 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 01 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 02 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 March 2018

No defects recorded

11470/43 : AGAINST: M8 SLIP RD TO B768 DUMBRECK RD INT (N)

Safety Inspection of M77 Inspection on 28 December 2017

No defects recorded

Safety Patrol of M77 Inspection on 31 December 2017

No defects recorded

Safety Inspection of M77 Inspection on 04 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 11 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 14 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 18 January 2018

SW85-317680-235521030	313m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	15/02/2018	M77 SB JCT 1 50M PRIOR TO NITHSDALE RD OVERBRIDGE LANE 2 OS WT
-----------------------	------	----	-------------	-------------------	-------	------------	----------------------	------------	--

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 25 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 28 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 01 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 02 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 March 2018

No defects recorded

11450/07 : WITH: A77 OVERBRIDGE TO CROOKFUR INT

Safety Inspection of M77 Inspection on 28 December 2017

No defects recorded

Safety Patrol of M77 Inspection on 31 December 2017

No defects recorded

Safety Inspection of M77 Inspection on 04 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 11 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 14 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 18 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 25 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 28 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 01 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 02 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 March 2018

No defects recorded

11460/16 : AGAINST: SLIP OFF TO NITSHILL ROAD S/B

Safety Inspection of M77 Inspection on 28 December 2017

No defects recorded

Safety Patrol of M77 Inspection on 31 December 2017

No defects recorded

Safety Inspection of M77 Inspection on 04 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 11 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 14 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 18 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 21 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 25 January 2018

No defects recorded

Safety Patrol of M77 Inspection on 28 January 2018

No defects recorded

Safety Inspection of M77 Inspection on 01 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 February 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 February 2018

No defects recorded

Safety Inspection of M77 Inspection on 02 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 04 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 08 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 11 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 15 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 18 March 2018

No defects recorded

Safety Inspection of M77 Inspection on 22 March 2018

No defects recorded

Safety Patrol of M77 Inspection on 25 March 2018

No defects recorded

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 25/12/2017 and 27/03/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST: C46 JUNCTION TO END OF DUAL C'WAY','WITH: START DUAL CARRIAGEWAY TO C46 JUNCTION','AGAINST: ON SLIP FROM NEWTON MEARN'S SB','WITH: OFF SLIP TO NEWTON MEARN'S NB','PILMUIR ROAD TO START DUAL CARRIAGEWAY','AGAINST: MALLET INT. ON SLIP TO END OF DUAL SB','C1 MEARN'S ROAD TO PILMUIR ROAD/B','C1 MEARN'S ROAD TO PILMUIR ROAD/A','C1 MEARN'S ROAD TO PILMUIR ROAD','C1 MEARN'S ROAD TO MALLETSHEUGH INT OFF SLIP','CAIRN ROAD TO C1 MEARN'S RD','EAST RENFREWSHIRE BOUNDARY TO CAIRN ROAD','AGAINST: E RENFREW BDY TO START DUAL NORTH OF B764','WITH: END DUAL N OF B764 TO EAST RENFREWHIRE BDY','AGAINST:START DUAL N OF B764 TO END DUAL S OF B764','WITH:START DUAL S OF B764 TO END DUAL N OF B764','AGAINST: END DUAL S OF B764 TO START DUAL C'WAY','WITH: END OF DUAL C'WAY TO START DUAL S OF B764','AGAINST: START DUAL C'WAY TO A719 JUNCTION','WITH: A719 JUNCTION TO END OF DUAL CARRIAGEWAY','AGAINST: A719 JUNCTION TO END OF DUAL CARRIAGEWAY','WITH: START OF DUAL CARRIAGEWAY TO A719 JUNCTION','AGAINST: END DUAL C'WAY TO B7061 JUNCTION NORTH','WITH: B7061 JCT NORTH TO START DUAL CARRIAGEWAY','AGAINST: B7061 JUNCTION NORTH TO START DUAL C'WAY','WITH: N/B SL.RD EXIT-JCT WITH N/B TRUNK RD','WITH: N/B SL.RD EXIT-JCT WITH B778 NR FENWICK','WITH: END DUAL CARRIAGEWAY TO B7061 JCT NORTH','AGAINST: START DUAL C'WAY TO B7061 JUNCTION SOUTH','WITH: B7061 JUNCTION SOUTH TO END DUAL CARRIAGEWAY','AGAINST: B7061 JUNCTION SOUTH TO OFF SLIP TO B7038','AGAINST: END OF MWAY TO B7061 JCT','WITH: OFF SLIP TO B7038 TO START OF MOTORWAY','WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH','WITH: SL/RD OFF B7038 N/BND-JCT N/BND TR/RD','AGAINST: OFF SLIP TO B7038 TO ON SLIP FROM B7038','WITH: S BND SL/RD OFF B7038-JCT S BND TR/RD','WITH: OFF SLIP TO B7038 TO ON SLIP FROM B7038','WITH: SLIP RD EXIT NTH BOUND-JNCT B7038','AGAINST: ON SLIP FROM B7038 TO M77 DBFO BOUNDARY','WITH: M77 DBFO BOUNDARY TO OFF SLIP TO B7038 NB','AGAINST: ON SLIP FROM B7038 TO OFF SLIP TO A76/A71','AGAINST: S/B SLIP RD EXIT TO HURLFORD INTERCHANGE','AGAINST: SB OFF SLIP TO NEW FARM LOCH B7082','WITH: NB ON SLIP FROM NEW FARM LOCH B7082','AGAINST: SB ON SLIP FROM NEW FARM LOCH B7082','WITH: NB OFF SLIP TO NEW FARM LOCH B7082','AGAINST: M77 DBFO BDY TO OFF SLIP TO A76/A71 SB','WITH: ON SLIP FROM A76/A71 TO M77 DBFO BOUNDARY','HURLFORD INTERCHANGE ROUNDABOUT','WITH: ON SLIP FROM A76/A71 TO OFF SLIP TO B7038','WITH: HURLFORD INTERCHANGE-JCT OF N/B TR.ROAD','AGAINST: OFF SLIP A76/A71 TO 300M N WHATRIGGS BRID','AGAINST: HURLFORD INTERCHANGE-JCT OF S/B TR.ROAD','WITH: OFF SLIP TO A76/A71 TO ON SLIP FROM A76/A71','WITH: N/B SLIP RD EXIT-HURLFORD INTERCHANGE','WITH: 300M N WHATRIGGS BR TO OFF SLIP TO A76/A71','*','AGAINST: 300M N OF WHATRIGGS BR TO E. AYRSHIRE BDY','WITH: EAST AYRSHIRE BDY TO 300M N OF WHATRIGGS BR','AGAINST: EAST AYRSHIRE BDY TO SPITALHILL SLIP ROAD','WITH: SPITALHILL SLIP RD TO EAST AYRSHIRE BOUNDARY','AGAINST: K&C DIST BDY STH BND-95M S OF SLIP ROAD','WITH: SPITTALHILL SL.RD N/BD-K&L DIST BDY','AGAINST: SPITALHILL SLIP ROAD TO EAST LODGE','WITH: EAST LODGE TO SPITTALHILL SLIP ROAD','AGAINST: EAST LODGE TO SYMINGTON SB','WITH: SYMINGTON NB TO EAST LODGE','AGAINST: SYMINGTON SB TO DUTCH HOUSE RBT','WITH: DUTCH HOUSE ROUNDABOUT TO SYMINGTON NB','DUTCH HOUSE ROUNDABOUT','AGAINST: DUTCH HOUSE RBT TO SANDYFORD TOLL RBT','AGAINST: DUTCH HOUSE RBT TO A719 JCT SANDYFORD TOL','WITH: SANDYFORD TOLL R/BOUT to Dutch House Rbt','WITH: A719 JCT SANDYFORD TOLL TO DUTCH HOUSE RBT','SANDYFORD TOLL ROUNDABOUT','Against: Start of 4 lane to Whitletts Rbt','Against: Sandyford Toll Rbt to start of 4 lane','AGAINST: SANDYFORD TOLL R/BOUT TO WHITLETTS R/BOUT','AGAINST: A719 JCT SANDYFORD TOLL TO WHITLETTS RBT','WITH: WHITLETTS ROUNDABOUT TO SANDYFORD TOLL RBT','WITH: WHITLETTS RBT TO A719 JCT SANDYFORD TOLL','Whitletts Roundabout','WHITLETTS ROUNDABOUT','AGAINST: WHITLETTS RBT TO END EXIT WHITLETTS RBT','WITH: START ENTRY WHITLETTS RBT TO WHITLETTS RBT','Against: SB Exit from Whitletts Rbt','With: NB Entry to Whitletts Rbt','Start of 3 Lane to Rbt approach','HOLMSTON ROUNDABOUT TO START ENTRY WHITLETTS RBT','Holmston Rbt to start of 3 lane','HOLMSTON ROUNDABOUT','Start of Single 4-Lane to Holmston Roundabout','End of Climbing Lane to Start of 4 Lane Single','Bankhead Rbt to End of Climbing Lane','BANKHEAD ROUNDABOUT TO HOLMSTON ROUNDABOUT','BANKHEAD ROUNDABOUT','A79 JUNCTION MAYBOLE RD AYR TO BANKHEAD RBT','B7034 JUNCTION TO JUNCTION A79 MAYBOLE ROAD AYR','CULROY BURN BRIDGE TO B7034 JUNCTION','JUNCTION KEWNSTON TO CULROY BURN BRIDGE','SMITHSTON BRIDGE TO JUNCTION KEWNSTON','JUNCTION DRUMELLAN TO SMITHSTON BRIDGE','LYONSTON FARM TO JUNCTION DRUMELLAN','JUNCTION B7023 CULZEAN ROAD TO LYONSTON FARM','JCT JOHN KNOX ST TO JCT B7023 CULZEAN RD','JUNCTION LADYLAND ROAD TO JUNCTION JOHN KNOX ST','30MPH SIGN MAYBOLE TO JUNCTION LADYLAND ROAD','JCT BROOMKNOWES FM TO 30 MPH SIGN MAYBOLE','JCT BLANEFIELD TO JUNCTION BROOMKNOWES FARM','OLD TOLL COTTAGE TO JUNCTION BLANEFIELD','JUNCTION KIRK BRAE KIRKOSWALD TO OLD TOLL COTTAGE','HIGH PARK TO JUNCTION KIRK BRAE KIRKOSWALD','NTH END TURNBERRY CLIMBING LANE TO HIGH PARK','TURNBERRY CLIMBING LANE','A719 JUNCTION TO HIGH PARK','A719 JCT TO STH END TURNBERRY CLIMBING LANE','DIPPLE,FACTORY ENTRANCE TO A719 JUNCTION','BRIDGEMILL ROUNDABOUT TO DIPPLE,FACTORY ENTRANCE','BRIDGEMILL ROUNDABOUT','RAILWAY BRIDGE TO BRIDGEMILL ROUNDABOUT','JUNCTION MONTGOMERIE STREET TO RAILWAY BRIDGE','END OF GRAVEYARD TO JUNCTION MONTGOMERIE STREET','SHALLOCHPARK ROUNDABOUT TO JUNCTION KIRKPATRICK ST','STUMPY CORNER JUNCTION TO END OF GRAVEYARD','DUFF STREET TO KIRKPATRICK STREET RBT','WESLEY ROAD TO DUFF STREET','Against: STUMPY CORNER TO WESLEY ROAD','HENRIETTA STREET RBT TO STUMPY CORNER','HENRIETTA STREET ROUNDABOUT','DUNCAN STREET TO HENRIETTA STREET RBT','JUNCTION KIRKPATRICK ST TO JUNCTION DUFF STREET','YOUNG STREET TO DUNCAN STREET','B734 KIRKPATRICK STREET RBT TO YOUNG STREET','B734 KIRKPATRICK STREET ROUNDABOUT','A714 SHALLOCHPARK RBT TO B734 KIRKPATRICK ST RBT','A714 SHALLOCHPARK ROUNDABOUT','ARDMILLAN CASTLE TO A714 SHALLOCHPARK ROUNDABOUT','ARDMILLAN LODGE TO SHALLOCHPARK ROUNDABOUT/B','ARDMILLAN LODGE TO SHALLOCHPARK ROUNDABOUT','ARDMILLAN LODGE TO SHALLOCHPARK ROUNDABOUT/A','ARDMILLAN LODGE TO SHALLOCHPARK ROUNDABOUT','LENDALFOOT BRIDGE TO ARDMILLAN CASTLE','CARLETON FISHERIES TO LENDALFOOT BRIDGE','*','*','JUNCTION LITTLE BENNANE TO CARLETON FISHERIES','Bennane Jct to Little Bennane Jct','*','End of SB climbing lane to Bennane Jct','B734 JUNCTION TO JUNCTION LITTLE BENNANE','B734 Jct to end of SB climbing lane','End of NB climbing lane to B734 Jct','Start to End of NB climbing lane','BALANTRAE BAY JCT TO B734 JCT','B7044 Jct to Start of climbing lane','B7044 JCT TO BALANTRAE BAY JCT','OLD SMYRTON TO B7044 JUNCTION','JCT BALLOCHDOWAN TO OLD SMYRTON','JCT AT CARLOCK HOUSE TO JCT AT BALLOCHDOWAN','JCT AT CARLOCK HOUSE TO JCT AT BALLOCHDOWAN','NORTH MARK BRIDGE TO JUNCTION AT CARLOCK HOUSE','HAGGSTONE CL NORTH END TO NORTH MARK BRIDGE','HAGGSTONE CLIMBING LANE','JUNCTION FINNARTS FARM TO NORTH MARK BRIDGE','SOUTH AYRSHIRE BOUNDARY TO HAGGSTONE CL SOUTH END','SOUTH AYRSHIRE BOUNDARY TO JUNCTION FINNARTS FARM','JUNCTION BONNY BRAES TO SOUTH AYRSHIRE BOUNDARY','DERESTRICTION SIGN CAIRNRYAN TO JCT BONNY BRAES','DRUMMUCKLOCH FARM TO DERESTRICTION SIGN CAIRNRYAN','JUNCTION BEOCH TO DRUMMUCKLOCH FARM','A751 DUMFRIES JUNCTION TO JUNCTION BEOCH','MCMASTERS ROAD TO A751 DUMFRIES JUNCTION','A718 JUNCTION TO MCMASTERS ROAD','STAIR DRIVE A75 JUNCTION TO A718 JUNCTION','WITH: START OF M77 TO MALLETSHEUGH INT. OFF SLIP',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

11601/05 : STAIR DRIVE A75 JUNCTION TO A718 JUNCTION**Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 27 December 2017***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 03 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 10 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 17 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 24 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 31 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 February 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 February 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 February 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 28 February 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 March 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 March 2018**

SW81-327800-235583896	100m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	14/03/2018	A77 STAIR DRIVE
SW81-327800-235583897	165m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	14/03/2018	A77 STAIR DRIVE
SW81-327800-235583893	12m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	14/03/2018	A75 @ STAIR DRIVE JCT
SW81-327800-235583895	90m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	14/03/2018	A77 STAIR DRIVE
SW81-327800-235583898	162m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	14/03/2018	A77 STAIR DRIVE
SW81-327800-235583892	29m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	14/03/2018	A75 @ STAIR DRIVE JCT
SW81-327800-235583894	33m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	14/03/2018	A75 @ STAIR DRIVE JCT

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 March 2018*No defects recorded***11601/25 : A718 JUNCTION TO MCMASTERS ROAD****Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 27 December 2017***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 03 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 10 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 17 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 24 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 31 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 February 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 February 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 February 2018**

SW81-321674-235545621	524m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	21/02/2018	A77 LONDON RD
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	---------------

SW81-321674-235545622	208m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	21/02/2018	A77 LONDON RD
SW81-321674-235545620	528m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	21/02/2018	A77 LONDON RD

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 28 February 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 March 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 March 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 March 2018

No defects recorded

11605/05 : MCMASTERS ROAD TO A751 DUMFRIES JUNCTION

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 27 December 2017

SW81-317125-235512850	2,518m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/01/2018	Completed Defects	26/01/2018	A77 N/B C/WAY 70M S OF A751 JCT
SW81-317125-235512849	2,481m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/01/2018	Completed Defects	26/01/2018	A77 N/B C/WAY 100M S OF A751 JCT

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 03 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 10 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 17 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 24 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 31 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 February 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 February 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 February 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 28 February 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 March 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 March 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 March 2018

No defects recorded

11610/05 : A751 DUMFRIES JUNCTION TO JUNCTION BEOCH

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 27 December 2017

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 03 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 10 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 17 January 2018

SW81-317651-235519579	697m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/02/2018	Completed Defects	03/02/2018	A77 N/B C/WAY 1KM NORTH OF A751 JCT
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	-------------------------------------

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 24 January 2018

SW81-317782-235528545	754m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2018	Completed Defects	03/02/2018	A77 S/B C/WAY 600M NORTH OF A751 JCT
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	--------------------------------------

SW81-317782-235528544	462m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2018	Completed Defects	03/02/2018	A77 N/B C/WAY 400M NORTH OF THE A751 JCT
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 31 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 February 2018*No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 February 2018**

SW81-319705-235542985	102m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 S/B C/WAY @ A751 JCT
SW81-319705-235542981	103m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 S/B C/WAY @ A751 JCT
SW81-319705-235542983	107m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 S/B C/WAY @ A751 JCT
SW81-319705-235542977	103m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 S/B C/WAY @ A751 JCT
SW81-319705-235542984	107m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 S/B C/WAY @ A751 JCT
SW81-319705-235542974	105m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 S/B C/WAY @ A751 JCT
SW81-319705-235542975	104m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 S/B C/WAY @ A751 JCT
SW81-319705-235542979	103m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 S/B C/WAY @ A751 JCT
SW81-319705-235542980	103m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 N/B C/WAY AT A751 JCT
SW81-319705-235542982	106m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 S/B C/WAY @ A751 JCT
SW81-319705-235542976	102m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 S/B C/WAY @ A751 JCT
SW81-319705-235542978	106m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 S/B C/WAY @ A751 JCT

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 February 2018*No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 28 February 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 March 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 March 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 March 2018***No defects recorded***11610/18 : JUNCTION BEOCH TO DRUMMUCKLOCH FARM****Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 27 December 2017***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 03 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 10 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 17 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 24 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 31 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 February 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 February 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 February 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 28 February 2018**

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 March 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 March 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 March 2018

SW81-329803-235583957	86m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	18/04/2018	Awaiting CCMS Permanent	01/01/9999	A77 S/B VERGE 100M SOUTH OF BEOCH
-----------------------	-----	----	---------------	------------------------	-------	------------	-------------------------	------------	-----------------------------------

11610/36 : DRUMMUCKLOCH FARM TO DERESTRICTION SIGN CAIRNRYAN

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 27 December 2017

SW81-317125-235512851	574m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/01/2018	Completed Defects	26/01/2018	A77 N/B C/WAY 50M S OF CAIRNRYAN
SW81-317125-235512852	593m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/01/2018	Completed Defects	26/01/2018	A77 S/B C/WAY 50M S OF CAIRNRYAN

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 03 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 10 January 2018

SW81-317457-235518240	740m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	10/01/2018	A77 S/B C/WAY 50M N OF S G/WAY
SW81-317457-235518239	722m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	10/01/2018	A77 S/B C/WAY 50M NORTH OF S G/WAY
SW81-317457-235518245	612m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	05/02/2018	A77 S/B C/WAY 50M S OF CAIRNRYAN S G/WAY
SW81-317457-235518249	362m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	05/02/2018	A77 S/B C/WAY @ ROSEBANK COTTAGE
SW81-317457-235518241	723m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	10/01/2018	A77 N/B C/WAY 50M N OF S G/WAY
SW81-317457-235518247	610m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	05/02/2018	A77 S/B C/WAY 50M S OF CAIRNRYAN S G/WAY
SW81-317457-235518248	514m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	05/02/2018	A77 S/B C/WAY 200M S OF CAIRNRYAN
SW81-317457-235518246	610m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	05/02/2018	A77 S/B C/WAY 50M S OF CAIRNRYAN S G/WAY

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 17 January 2018

SW81-317651-235519585	2,376m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/02/2018	Completed Defects	05/02/2018	A77 S/B C/WAY 500M SOUTH OF BARRS YARD
-----------------------	--------	----	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 24 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 31 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 February 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 February 2018

SW81-319705-235542973	388m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 S/B C/WAY AT ROSEBANK COTTAGE
SW81-319705-235542972	665m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/03/2018	Awaiting CCMS Temp Date	01/01/9999	A77 N/B C/WAY CAIRNRYAN S G/WAY
SW81-319705-235542971	844m	0m	CARRIAGEWAY	Flooding (FLOD)	CAT 1	14/03/2018	Completed Defects	16/02/2018	A77 S/B C/WAY 300M N OF S G/WAY

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 February 2018

SW81-321674-235545623	506m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	21/02/2018	A77 CAIRNRYAN
SW81-321674-235545625	473m	0m	CARRIAGEWAY	Pothole	CAT 1	22/02/2018	Completed	21/02/2018	A77 CAIRNRYAN

							Defects		
SW81-321674-235545627	322m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	21/02/2018	A77 CAIRNRYAN
SW81-321674-235545624	475m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	21/02/2018	A77 CAIRNRYAN
SW81-321674-235545626	322m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	21/02/2018	A77 CAIRNRYAN

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 28 February 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 March 2018

SW81-325796-235550015	248m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	07/03/2018	A77 CAIRNRYAN
SW81-325796-235550016	236m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	07/03/2018	A77 CAIRNRYAN

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 March 2018

SW81-327800-235583899	629m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	14/03/2018	A77 CAIRNRYAN
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	---------------

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 March 2018

SW81-329803-235583956	2,278m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	21/03/2018	A77 CAIRNRYAN
-----------------------	--------	----	-------------	----------------	-------	------------	-------------------	------------	---------------

11610/66 : DERESTRICTION SIGN CAIRNRYAN TO JCT BONNY BRAES

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 27 December 2017

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 03 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 10 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 17 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 24 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 31 January 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 February 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 February 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 February 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 28 February 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 March 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 March 2018

No defects recorded

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 March 2018

SW81-329803-235583954	644m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	21/03/2018	A77 CAIRNRYAN
SW81-329803-235583955	163m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	21/03/2018	A77 CAIRNRYAN

11610/75 : JUNCTION BONNY BRAES TO SOUTH AYRSHIRE BOUNDARY

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 27 December 2017

SW81-317125-235512853	1,322m	0m	GULLY	Blockage (BLOK)	CAT 1	24/01/2018	Completed Defects	27/12/2017	A77 S/B C/WAY 300M N OF STENA
SW81-317125-235512854	1,685m	0m	GULLY	Blockage (BLOK)	CAT 1	24/01/2018	Completed Defects	27/12/2017	A77 S/B C/WAY 700M N OF STENA

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 03 January 2018*No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 10 January 2018**

SW81-317457-235518243	1,994m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	10/01/2018	A77 S/B C/WAY 100M S OF AYRSHIRE BORDER
SW81-317457-235518242	1,988m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	10/01/2018	A77 S/B C/WAY 100M S OF AYRSHIRE BORDER
SW81-317457-235518244	1,872m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	10/01/2018	A77 S/B C/WAY 200M S OF AYRSHIRE BORDER

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 17 January 2018

SW81-317651-235519584	2,026m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/02/2018	Completed Defects	05/02/2018	A77 S/B C/WAY 100M SOUTH OF MARCHBURN COTTAGE
SW81-317651-235519580	2,150m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/02/2018	Completed Defects	05/02/2018	A77 N/B C/WAY @ MARCHBURN COTTAGE
SW81-317651-235519582	2,035m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/02/2018	Completed Defects	05/02/2018	A77 N/B C/WAY 100M SOUTH OF MARCHBURN COTTAGE
SW81-317651-235519583	2,037m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/02/2018	Completed Defects	05/02/2018	A77 N/B C/WAY 100M SOUTH OF MARCHBURN COTTAGE
SW81-317651-235519581	2,054m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/02/2018	Completed Defects	05/02/2018	A77 N/B C/WAY 100M SOUTH OF MARCHBURN COTTAGE

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 24 January 2018*No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 31 January 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 February 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 February 2018**

SW81-319705-235542964	2,171m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 N/B @ MARCHBURN
SW81-319705-235542966	2,179m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 N/B @ MARCHBURN
SW81-319705-235542970	2,037m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 N/B @ MARCHBURN
SW81-319705-235542968	2,179m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 N/B @ MARCHBURN
SW81-319705-235542965	2,176m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 N/B @ MARCHBURN
SW81-319705-235542967	2,179m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 N/B @ MARCHBURN
SW81-319705-235542969	2,002m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	14/02/2018	A77 N/B @ MARCHBURN

Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 February 2018*No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 28 February 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 07 March 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 14 March 2018***No defects recorded***Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 21 March 2018***No defects recorded***11611/31 : NORTH MARK BRIDGE TO JUNCTION AT CARLOCK HOUSE****Safety Inspection of A77 Ayr South V1 on 28 December 2017***No defects recorded*

Safety Inspection of A77 Ayr South V1 on 04 January 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 11 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 18 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 25 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 15 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 February 2018**

SW82321955-235548237	1,538m	0m	VERGE	Litter Grade C (LITC)	3RD PTY	23/02/2018	Awaiting CCMS Permanent	01/01/9999	layby northbound south of the bottom of carlck hill
----------------------	--------	----	-------	-----------------------	---------	------------	-------------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 01 March 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 March 2018**

SW82326075-235554318	556m	756m	CARRIAGEWAY	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
----------------------	------	------	-------------	--------------	-------	------------	-----------------------	------------	--

SW82326075-235554317	817m	1,017m	CARRIAGEWAY	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
----------------------	------	--------	-------------	--------------	-------	------------	-----------------------	------------	--

SW82326075-235554321	1,105m	1,106m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 SB CW, AT FARM JCT, NTH OF GLENAPP CHURCH
----------------------	--------	--------	-------------	-----------------------	-------	------------	-------------------	------------	---

SW82326075-235554319	399m	599m	CARRIAGEWAY	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
----------------------	------	------	-------------	--------------	-------	------------	-----------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 15 March 2018

SW82328086-235590008	1,509m	1,510m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	16/03/2018	A77 NB CW, AT LAYBY STH OF CARLOCH HILL
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82328086-235590009	2,974m	2,976m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Awaiting CCMS Temp Date	01/01/9999	A77 BOTH CW, 300M STH OF CARLOCH HOUSE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 22 March 2018*No defects recorded***11611/68 : JCT BALLOCHDOWAN TO OLD SMYRTON****Safety Inspection of A77 Ayr South V1 on 28 December 2017***No defects recorded***Safety Inspection of A77 Ayr South V1 on 04 January 2018**

SW82317326-235513697	447m	448m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	26/01/2018	600 metes norh of minor jct. sb cw 150meters prior to deer sign
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 11 January 2018

SW82317471-235518216	291m	292m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	08/02/2018	A77 ON CL, 300M STH OF OLD SMRYTON, STH OF BALLANTRAE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 18 January 2018

SW82317666-235521313	973m	975m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	06/03/2018	A77 ON CL, OPPOSITE AUCHENCROSH FARM, STH OF BALLANTRAE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

SW82317666-235521314	262m	263m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	15/02/2018	A77 SB CW, 700M STH OF AUCHENCROSH FARM, STH OF BALLANTRAE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 25 January 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 February 2018**

SW82319037-235539795	481m	485m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 SB CW, 400M STH OF AUCHENCROSH, STH OF BALLANTRAE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 15 February 2018									
SW82319984-235544948	968m	969m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/03/2018	Completed Defects	15/02/2018	A77 SB CW, 10M STH OF AUCHENCROSH FARM
SW82319984-235544949	1,026m	1,028m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/03/2018	Completed Defects	15/02/2018	A77 SB CW AND CL, 50M NTH OF AUCHENCROSH FARM
Safety Inspection of A77 Ayr South V1 on 22 February 2018									
SW82321955-235548243	695m	696m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	23/02/2018	A77 SIB CIW SOUTH OF AUCHINCROSH KENNELS
SW82321955-235548245	0m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	A77 BETWEEN SMYRTON AND AUCHINCROSH FARM NIB CIW
SW82321955-235548239	292m	293m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	23/02/2018	A77 SOUTBOUND CARRIAGEWAY BETWEEN AUCHINCROSH AND SMYRTON SIB CIW
SW82321955-235548238	252m	253m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	23/02/2018	SOUTHBOUND CIW BETWEEN AUCHINCROSH AND MINOR JUNCTION SOUTH OF SMYRTON
SW82321955-235548241	394m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	23/02/2018	A77 BETWEEN AUCHINCROSH AND MINOR SIB CIW
SW82321955-235548244	866m	867m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	23/02/2018	A77 BETWEEN AUCHINCROSH FARM AND K4NNELS NIB CIW
SW82321955-235548240	274m	275m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	23/02/2018	A77 BEY3EEN AUCHINCROSH AND MINOR JUNCTION SIB CIW
SW82321955-235548242	703m	704m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	23/02/2018	A77 SOUTH OF AUCHINCROSH KENNELS NIB CIW NOS 25, 26, 27
Safety Inspection of A77 Ayr South V1 on 01 March 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 08 March 2018									
SW82326075-235554315	1,131m	1,132m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, 100M STH OF AUCHENCROSH FARM
SW82326075-235554313	843m	845m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, 300M NTH OF AUCHENCROSH FARM
SW82326075-235554316	1,159m	1,160m	CARRIAGEWAY	Pothole (POTH)	3RD PTY	05/04/2018	Awaiting CCMS Temp Date	01/01/9999	A77 NB CW, 120M STH OF AUCHENCROSH
SW82326075-235554314	1,083m	1,084m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, 50M STH AUCHENCROSH FARM
SW82326075-235554312	983m	984m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, 400M NTH OF AUCHENCROSH FARM
Safety Inspection of A77 Ayr South V1 on 15 March 2018									
SW82328086-235590018	407m	408m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 SB CW, 400M NTH OF JCT BALLOCHDOWAN
SW82328086-235590020	933m	934m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 NB CW, OUTSIDE AUCHENCROSH FARM
SW82328086-235590017	469m	470m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 SB CW, 450M NTH OF JCT BALLOCHDOWAN
SW82328086-235590021	1,596m	1,597m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 SB CW, OUTSIDE OLD SMRYTON
SW82328086-235590015	277m	278m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 SB CW, 300M NTH OF JCT BALLOCH DOWAN
SW82328086-235590016	522m	526m	CARRIAGEWAY	Pothole	CAT 1	12/04/2018	Completed	15/03/2018	A77 SB CW, 500M NTH OF JCT

				(POTH)			Defects		BALLOCH DOWAN
SW82328086-235590019	219m	220m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 NB CW, 200M NTH OF JCT BALLOCHDOWAN

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11611/79 : OLD SMYRTON TO B7044 JUNCTION

Safety Inspection of A77 Ayr South V1 on 28 December 2017

SW82317141-235513268	126m	127m	BOLLARDS	Dirty sign (DIRT)	CAT 1	25/01/2018	Completed Defects	17/01/2018	A77 NB CW, OUTSIDE NEW SMRYTON
----------------------	------	------	----------	-------------------	-------	------------	-------------------	------------	--------------------------------

SW82317141-235513267	11m	12m	MANHOLE	Other (OTHR)	3RD PTY	25/01/2018	Awaiting CCMS Temp Date	01/01/9999	A77 SB CW, OUTSIDE OLD SMRYTON BUS STOP
----------------------	-----	-----	---------	--------------	---------	------------	-------------------------	------------	---

SW82317141-235513269	2,025m	2,026m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/01/2018	Completed Defects	25/01/2018	A77 SB CW, 100M NTH OF WATERTANKS STH OF BALLANTRAE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 04 January 2018

SW82317326-235513696	3,344m	3,464m	GULLY	Flooding (FLOD)	CAT 1	01/02/2018	Awaiting CCMS Permanent	01/01/9999	SOUTH OF STINCHER BRIDG3
----------------------	--------	--------	-------	-----------------	-------	------------	-------------------------	------------	--------------------------

Safety Inspection of A77 Ayr South V1 on 11 January 2018

SW82317471-235518217	3,488m	3,789m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	25/01/2018	A77 SB CW, BRIDGE AT BALLANTRAE STH GATEWAY
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

SW82318129-235532270	2,202m	2,203m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/03/2018	Completed Defects	01/02/2018	A77 SB CW, PRIOR TO WATER TANKS, AT SLOW SIGN
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 08 February 2018

SW82319037-235539794	2,204m	2,206m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 SB CW, 150M NTH OF WATERTANKS, STH OF BALLANTRAE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

SW82319037-235539793	1,308m	1,318m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A77 AT WATERTANKS STH OF BALLANTRAE
----------------------	--------	--------	-------------	----------------	-------	------------	-----------------------	------------	-------------------------------------

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

SW82326075-235554311	3,554m	6,555m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, ON BRIDGE DECK, BALLANTRAE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---------------------------------------

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11614/35 : JUNCTION LITTLE BENNANE TO CARLETON FISHERIES

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

SW82317326-235513695	3,215m	3,216m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	26/01/2018	200 METRES SOUTH OF THE LAY Y SOUTH OF LENDALFOOT SIB CIW
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

SW82317666-235521316	2,187m	2,190m	CARRIAGEWAY	Pothole	CAT 1	15/02/2018	Completed	16/02/2018	A77 SB CW, AT BENANNE
----------------------	--------	--------	-------------	---------	-------	------------	-----------	------------	-----------------------

(POTH)

Defects

SPA, STH OF LENDALFOOT

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

SW82319984-235544952	2,201m	2,202m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	16/02/2018	A77 SB CW, OPP BENNANE SPA
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	----------------------------

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

SW82328086-235590025	3,368m	3,372m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 BOTH CW, 300M STH OF LENDALFOOT
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	-------------------------------------

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11614/85 : CARLETON FISHERIES TO LENDALFOOT BRIDGE

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

SW82317326-235513694	89m	0m	GULLY	Flooding (FLOD)	CAT 1	01/02/2018	Completed Defects	21/02/2018	LENDALFOOT VILLAGE
----------------------	-----	----	-------	-----------------	-------	------------	-------------------	------------	--------------------

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11617/05 : LENDALFOOT BRIDGE TO ARDMILLAN CASTLE

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

SW82317471-235518219	1,624m	1,625m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	09/02/2018	A77 NB CW, AT STH END OF STRAIDS PASS BENDS
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82317471-235518221	1,788m	1,789m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	09/02/2018	A77 ON CL, 200M NTH OF END OF STRAIDS PASS BENDS
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

SW82317471-235518220	1,754m	1,760m	CARRIAGEWAY	Pothole	CAT 1	08/02/2018	Completed	09/02/2018	A77 NB CW, 150M NTH OF STH
----------------------	--------	--------	-------------	---------	-------	------------	-----------	------------	----------------------------

				(POTH)			Defects		END OF STRAIDS PASS BENDS
SW82317471-235518222	1,851m	1,853m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	09/02/2018	A77 NB AND SB CW, 200M NTH OF END OF STRAIDS PASS BENDS
Safety Inspection of A77 Ayr South V1 on 18 January 2018									
SW82317666-235521318	5,186m	5,188m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	08/02/2018	A77 SB CW, OUTSIDE ARDWELL FARM, STH OF GIRVAN
SW82317666-235521317	3,097m	3,100m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	09/02/2018	A77 NB CW AND SB CW, STRAIDS PASS STH OF GIRVAN
Safety Inspection of A77 Ayr South V1 on 25 January 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 01 February 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 08 February 2018									
SW82319037-235539792	1,788m	1,744m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 BOTH CW, CLUSTER OF POTHLES OVER 100M STRETCH, 11 HOLES, 250M STH OF NB LAYBY STRAIDS PASS
SW82319037-235539781	2,948m	2,950m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	08/02/2018	A77 SB CW, STRAIDS PASS
SW82319037-235539791	1,798m	1,799m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 SB CW, 230M STH OF NB LAYBY, STRAIDS PASS
SW82319037-235539783	2,291m	2,295m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 SB CW, 100M NTH OF LAYBY AT STRAIDS PASS ON HILL
SW82319037-235539785	2,156m	2,157m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 STRAIDS PASS, STH OF NB LAYBY
SW82319037-235539789	1,883m	1,884m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 NB CW, 200M STH OF NB LAYBY STRAIDS PASS
SW82319037-235539782	2,897m	2,910m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	08/02/2018	A77 BOTH CW, STRAIDS PASS, STH GIRVAN
SW82319037-235539787	2,020m	2,021m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 SB CW, 120M STH OF NB LAYBY STRAIDS PASS
SW82319037-235539790	1,843m	1,845m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 BOTH CW, 220M STH OF NB LAYBY STRAIDS PASS
SW82319037-235539788	1,938m	1,939m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 NB CW, 150M STH OF NB LAYBY, STRAIDS PASS
SW82319037-235539784	2,238m	2,240m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 NB CW, AT NB LAYBY, STRAIDS PASS
SW82319037-235539786	2,096m	2,097m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 STH OF NB LAYBY STRAIDS PASS, 100M
Safety Inspection of A77 Ayr South V1 on 15 February 2018									
SW82319984-235544954	1,643m	1,645m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	16/02/2018	A77 SB CW, AT STH END OF STRAIDS PASS
SW82319984-235544953	1,581m	1,582m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	16/02/2018	A77 NB CW, AT STH END OF STRAIDS PASS
SW82319984-235544955	4,737m	4,738m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	16/02/2018	A77 NB CW, 400M STH OF ARDWELL FARM, STH OF GIRVAN
Safety Inspection of A77 Ayr South V1 on 22 February 2018									
SW82321955-235548228	1,942m	1,944m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	A77 STRAID PASS
SW82321955-235548230	1,899m	1,900m	CARRIAGEWAY	Pothole	CAT 1	22/03/2018	Completed	22/02/2018	A77 STRAID PASS STH OF

				(POTH)			Defects		GIRVAN
SW82321955-235548232	1,730m	1,731m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	NB CW SOUTHSIDE OF STRAID PASS
SW82321955-235548234	1,652m	1,653m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	POTHOLE
SW82321955-235548231	1,795m	1,796m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	AT pedestrian 200yds sign in straid pass sth of girvan sb cw
SW82321955-235548233	1,659m	1,660m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	NB CW AT SOUTHSIDE OF STRAID PASS SOUTH OF GIRVAN
SW82321955-235548227	2,040m	2,041m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	A77 STRAID PASS
SW82321955-235548229	0m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	A77 STRAID PASS STH OF GIRVAN

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

SW82326075-235554325	313m	314m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, 250M NTH OF LENDALFOOT NTH GATEWAY
SW82326075-235554326	2,587m	2,588m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, 500M NTH OF LAYBY BETWEEN STRAIDS PASS AND KENNEDYS PASS, AT OLD LANDSLIP
SW82326075-235554324	275m	276m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, 200M NTH OF LENDALFOOT NTH GATEWAY

Safety Inspection of A77 Ayr South V1 on 15 March 2018

SW82328086-235590027	4,701m	4,702m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 SB CW, 300M STH OF ARDWELL FARM
SW82328086-235590026	1,646m	1,650m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	25/03/2018	A77 BOTH CW, MULTIPLE HOLES FROM STH START OF STRAIDS PASS TO 100M NTH OF LAYBY

Safety Inspection of A77 Ayr South V1 on 22 March 2018

SW82330474-235608109	2,062m	2,063m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 NB CW, 50M STH OF NB LAYBY STRAIDS PASS
SW82330474-235608111	2,238m	2,239m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 ON CL, 30M NTH OF NB LAYBY, STRAIDS PASS
SW82330474-235608105	1,609m	1,610m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 SB CW, START OF STRAIDS PASS BENDS
SW82330474-235608107	1,892m	1,893m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 NB CW, 170M NTH OF STRAIDS PASS BENDS START
SW82330474-235608110	2,224m	2,225m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 NB CW, 20M NTH OF NB LAYBY, STRAIDS PASS
SW82330474-235608112	2,242m	2,243m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 SB CW, 50M TH OF NB LAYBY, STRAIDS PASS
SW82330474-235608108	1,888m	1,889m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 NB CW, 175M NTH OF START OF STRAIDS PASS BENDS
SW82330474-235608106	1,833m	1,834m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 NB CW, 150M NTH OF STRAIDS PASS STAR

11620/05 : A714 SHALLOCHPARK ROUNDABOUT

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11620/07 : A714 SHALLOCHPARK RBT TO B734 KIRKPATRICK ST RBT

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11620/44 : WESLEY ROAD TO DUFF STREET

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11620/59 : STUMPY CORNER JUNCTION TO END OF GRAVEYARD

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

SW82319984-235544956	180m	181m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	15/02/2018	A77 SB CW, GIRVAN 400M NTH OF STUMPY CORNER
----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11620/65 : END OF GRAVEYARD TO JUNCTION MONTGOMERIE STREET

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018									
SW82328086-235590032	123m	126m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 NB CW, OUTSIDE GRAVEYARD GIRVAN

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11620/72 : JUNCTION MONTGOMERIE STREET TO RAILWAY BRIDGE

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11620/90 : RAILWAY BRIDGE TO BRIDGEMILL ROUNDABOUT

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11622/05 : BRIDGEMILL ROUNDABOUT

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 11 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 18 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 25 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 15 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 15 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 March 2018***No defects recorded***11622/07 : BRIDGEMILL ROUNDABOUT TO DIPPLE,FACTORY ENTRANCE****Safety Inspection of A77 Ayr South V1 on 28 December 2017***No defects recorded***Safety Inspection of A77 Ayr South V1 on 04 January 2018**

SW82317326-235513699	2,790m	2,792m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	27/02/2018	northbound carriageay opposite burnside farm north of girvan
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 11 January 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 18 January 2018**

SW82317666-235521320	2,798m	2,800m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	27/02/2018	A77 NB CW, OPPOSITE BURNSIDE COTTAGE, NTH OF GIRVAN
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82317666-235521321	4,060m	4,061m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	26/02/2018	A77 SB CW, OPPOSITE DIPPLE FACTORY NTH OF GIRVAN
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 25 January 2018

SW82317793-235529554	2,423m	2,425m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	26/02/2018	A77 SB CW, 300M STH OF BURNSIDE COTTAGE, NTH OF GIRVAN
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

SW82317793-235529555	2,362m	2,365m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	26/02/2018	A77 SB CW, 400M STH OF BURNSIDE COTTAGE, NTH OF GIRVAN
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 01 February 2018

SW82318129-235532268	2,904m	3,104m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/03/2018	Completed Defects	01/02/2018	A77 AROUND BURNSIDE COTTAGE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	-----------------------------

Safety Inspection of A77 Ayr South V1 on 08 February 2018

SW82319037-235539780	4,217m	4,019m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	08/02/2018	A77 SB CW, ST BUS STOP OPP DIPPLE FACTORY, NTH OF GIRVAN
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 15 February 2018

SW82319984-235544957	3,009m	3,010m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	16/02/2018	A77 SB CW, OUTSIDE BURNSIDE COTTAGE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	-------------------------------------

Safety Inspection of A77 Ayr South V1 on 22 February 2018

SW82321955-235548226	3,010m	3,012m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	26/02/2018	just prior to burnside farm a77 between girvan and dipple
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 01 March 2018

SW82323945-235550797	1,332m	1,334m	CARRIAGEWAY	Debris in traffic Lane (DBTL)	CAT 1	29/03/2018	Completed Defects	01/03/2018	A77 NB CW, 1300M NTH OF BRIDGEMILL RBT, NTH OF
----------------------	--------	--------	-------------	-------------------------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 08 March 2018

SW82326075-235554307	1,566m	1,568m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, 1500M NTH OF BRIDGEMILL RBT, NTH OF GIRVAN
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

SW82330474-235608124	2,891m	2,991m	FOOTWAY	Excessive muck (MUCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A77 NB FOOTWAY, BURNSIDE COTTAGES FOOTPATH
SW82330474-235608113	2,901m	2,903m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 NB CW, OUTSIDE THE CURRAGH, NTH OF GIRVAN

11622/59 : DIPPLE,FACTORY ENTRANCE TO A719 JUNCTION**Safety Inspection of A77 Ayr South V1 on 28 December 2017**

SW82317141-235513271	2,657m	2,658m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/01/2018	Completed Defects	25/01/2018	A77 SB CW, AROUND GULLY, 50M NTH OF TURNBURY STH GATEWAY
SW82317141-235513273	2,440m	2,441m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/01/2018	Completed Defects	25/01/2018	A77 SB CW, 100M STH OF TURNBURY STH GATEWAY
SW82317141-235513272	2,510m	2,511m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/01/2018	Completed Defects	25/01/2018	A77 SB CW, 30M STH OF TURNBURY STH GATEWAY

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

SW82317793-235529558	2,439m	2,440m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	08/02/2018	A77 SB CW, 80M STH OF TURNBURY STH GATEWAY
SW82317793-235529556	2,652m	2,653m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	08/02/2018	A77 SB CW PH OROUND GULLY, 50M NTH OF TURNBURY STH GATEWAY
SW82317793-235529557	2,489m	2,490m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	08/02/2018	A77SB CW, TURNURRY STH GATEWAY
SW82317793-235529559	2,132m	2,134m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	08/02/2018	A77 SB CW, 400M STH OF TURNBURY STH GATEWAY

Safety Inspection of A77 Ayr South V1 on 01 February 2018

SW82318129-235532267	285m	585m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/03/2018	Completed Defects	01/02/2018	A77 BOTH CW, DIPPLE FACTORY
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	-----------------------------

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

SW82319984-235544958	59m	60m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	15/02/2018	A77 SB CW, OPPOSITE DIPPLE FACTORY
----------------------	-----	-----	-------------	----------------	-------	------------	-------------------	------------	------------------------------------

Safety Inspection of A77 Ayr South V1 on 22 February 2018

SW82321955-235548224	1,811m	1,822m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	27/02/2018	AT ENTRANCE TO BALKENNA TEA ROOM N/B CW
SW82321955-235548225	909m	910m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	27/02/2018	200 meters north of Dowhil Farm northbound carriageway

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

SW82326075-235554303	2,333m	2,334m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	09/03/2018	A77 ON CL, 220M STH OF TURNBURY STH GATEWAY
SW82326075-235554304	2,402m	2,403m	CARRIAGEWAY	Pothole	CAT 1	05/04/2018	Completed	09/03/2018	A77 NB CW, 100M STH OF

				(POTH)			Defects		TURNBURRY STH GATEWAY
SW82326075-235554305	2,402m	2,403m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 1	05/04/2018	Awaiting CCMS Permanent	01/01/9999	A77 NB VERGE, 100M STH OF TURNBURRY STH GATEWAY
SW82326075-235554306	906m	907m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, 200M NTH OF TURNBURRY HOLIDAY PARK
SW82326075-235554302	2,281m	2,282m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	09/03/2018	A77 ON CL, 300M STH OF TURNBURRY STH GATEWAY
Safety Inspection of A77 Ayr South V1 on 15 March 2018									
SW82328086-235590034	2,429m	2,432m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	16/03/2018	A77 BOTH CW, TURNBURRY STH GATEWAY, 100M - GATEWAY
SW82328086-235590033	320m	323m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 BOTH CW, DIPPLE FACTORY
Safety Inspection of A77 Ayr South V1 on 22 March 2018									
SW82330474-235608114	2,142m	2,143m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	22/03/2018	A77 SB CW, 400M STH OF TURNBURRY STH GATEWAY

11626/22 : HIGH PARK TO JUNCTION KIRK BRAE KIRKOSWALD

Safety Inspection of A77 Ayr South V1 on 28 December 2017									
SW82317141-235513276	222m	226m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/01/2018	Completed Defects	09/02/2018	A77 NB CW, AT LAYBY NTH OF DALQUAT FARM
SW82317141-235513275	2m	3m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/01/2018	Completed Defects	26/02/2018	A77 SB CW, AT HIGH PARK JCT
Safety Inspection of A77 Ayr South V1 on 04 January 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 11 January 2018									
SW82317471-235518224	354m	355m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	26/02/2018	A77 SB CW, 200M NTH OF LAYBY, DALQUATT, STH OF KIRKOSWALD
Safety Inspection of A77 Ayr South V1 on 18 January 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 25 January 2018									
SW82317793-235529560	2,007m	2,008m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	08/02/2018	A77 B CW, 20M NTH OF KIRKOSWALD STH GATEWAY
Safety Inspection of A77 Ayr South V1 on 01 February 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 08 February 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 15 February 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 22 February 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 01 March 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 08 March 2018									
SW82326075-235554299	687m	689m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, 700M NTH OF DALQUATT FARMS
SW82326075-235554296	1,883m	1,884m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 1	05/04/2018	Awaiting CCMS Permanent	01/01/9999	A77 SB VERGE, 100M STH OF KIRKOSWALD
SW82326075-235554298	1,370m	1,371m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 SB CW, OUTSIDE CROFTENGEE COTTAGE, STH OF KIRKOSWALD
SW82326075-235554297	1,413m	1,414m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 SB CW, 600M STH OF KIRKOSWALD STH GATEWAY
SW82326075-235554300	672m	673m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 BOTH CW, 650M NTH OF DALQUATT FARM

Safety Inspection of A77 Ayr South V1 on 15 March 2018

SW82328086-235590035	280m	281m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	16/03/2018	A77 NB CW, 100M NTH OF DALQUATT LAYBY
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---------------------------------------

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11626/43 : JUNCTION KIRK BRAE KIRKOSWALD TO OLD TOLL COTTAGE

Safety Inspection of A77 Ayr South V1 on 28 December 2017

SW82317141-235513277	282m	286m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/01/2018	Completed Defects	16/02/2018	A77 NB CW, OUTSIDE THE WHISKEY EXPERIENCE, KIRKOSWALD
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

SW82317141-235513278	332m	334m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/01/2018	Completed Defects	16/02/2018	A77 ON CL, 100M NTH OF WHISKEY EXPERIENCE, KIRKOSWALD
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

SW82317471-235518227	410m	411m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	08/02/2018	A77 SB CW, 300M NTH OF WHISKEY EXPERIENCE, KIRKOSWALD
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

SW82317471-235518229	584m	585m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	16/02/2018	A77 NB CW, ON ANTI SKID, KIRKOSWALD NTH GATEWAY
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

SW82317471-235518228	519m	520m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	08/02/2018	A77 NB CW, 200M STH OF KIRKOSWALD NTH GATEWAY
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 18 January 2018

SW82317666-235521322	187m	188m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	16/02/2018	A77 SB CW, OPPOSITE NO.44 MAIN ROAD KIRKOSWALD
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 25 January 2018

SW82317793-235529562	325m	326m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	08/02/2018	
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

SW82317793-235529561	325m	326m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	08/02/2018	A77 NB CW, 50M NTH OF WHISKEY EXPERIENCE, KIRKOSWALD
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 01 February 2018

SW82318129-235532266	192m	193m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/03/2018	Completed Defects	01/02/2018	A77 KIRKOSWALD
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	----------------

Safety Inspection of A77 Ayr South V1 on 08 February 2018

SW82319037-235539779	206m	207m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	08/02/2018	A77 ON CW, OPPOSITE NO.44, KIRKOSWALD
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---------------------------------------

Safety Inspection of A77 Ayr South V1 on 15 February 2018

SW82319984-235544961	223m	225m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	15/02/2018	A77 SB CW, 40M STH OF WHISKEY EXPERIENCE, KIRKOSWALD
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

SW82319984-235544960	255m	256m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	15/02/2018	A77 SB CW, OPP WHISKEY EXPERIENCE, KIRKOSWALD
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 22 February 2018

SW82321955-235548222	233m	236m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	26/02/2018	MAIN STREET KIRKOSWALD JUST NORTH OF WHISKY EXPERIENCE SBCW
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

SW82330474-235608119	127m	128m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 NB CW, KIRKOSWALD, 20M NTH OF SHOP
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

11626/48 : OLD TOLL COTTAGE TO JUNCTION BLANEFIELD

Safety Inspection of A77 Ayr South V1 on 28 December 2017*No defects recorded***Safety Inspection of A77 Ayr South V1 on 04 January 2018**

SW82317326-235513692	885m	887m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	10/01/2018	sb cw at whitegates north of kirkoswald
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 11 January 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 18 January 2018**

SW82317666-235521326	1,287m	1,288m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	23/02/2018	A77 NB CW, 550M NTH OF WHITEGATES, NTH OF KIRKOSWALD
SW82317666-235521324	1,126m	1,128m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	09/02/2018	A77 SB CW, 400M NTH OF WHITEGATES, NTH OF KIRKOSWALD
SW82317666-235521325	948m	950m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	05/03/2018	A77 SB CW, 200M NTH OF WHITEGATES, NTH OF KIRKOSWALD
SW82317666-235521327	1,370m	1,371m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	09/02/2018	A77 NB CW, 600M NTH OF WHITEGATES, NTH OF KIRKOSWALD
SW82317666-235521323	1,445m	1,448m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	09/02/2018	A77 SB CW, 500M NTH OF WHITEGATES, NTH OF KIRKOSWALD

Safety Inspection of A77 Ayr South V1 on 25 January 2018

SW82317793-235529563	32m	34m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	08/02/2018	A77 SB CW, 50M STH OF KIRKOSWALD NTH GATEWAY
----------------------	-----	-----	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 01 February 2018

SW82318129-235532265	2,212m	2,222m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/03/2018	Completed Defects	01/02/2018	A77 MOSSIDE LAYBY
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	-------------------

Safety Inspection of A77 Ayr South V1 on 08 February 2018

SW82319037-235539776	2,069m	2,075m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	08/02/2018	A77 NB CW, OPP SB LAYBY, MOSSIDE
SW82319037-235539777	2,093m	2,099m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	08/02/2018	A77 NB CW, OPP SB LAYBY, MOSSIDE
SW82319037-235539775	2,031m	2,035m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	08/02/2018	A77 NB CW, OPPOSITE SB LAYBY, MOSSIDE
SW82319037-235539778	859m	870m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	08/02/2018	A77 ON CL, OPPOSITE WHITEGATES, NTH OF KIRKOSWALD

Safety Inspection of A77 Ayr South V1 on 15 February 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 February 2018**

SW82321955-235548219	1,244m	1,247m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	23/02/2018	A77 NB CW AT AUCHINBLANE 1300 M NORTH OF KIRKOSWALD
SW82321955-235548220	1,169m	1,179m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	22/03/2018	Completed Defects	23/02/2018	1200 METERS NORTH OF AUCHINBLANE
SW82321955-235548221	925m	926m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	23/02/2018	A77 SB CW JUST NORTH OF WHITEGATES NORTH OF KIRKOSWALD

Safety Inspection of A77 Ayr South V1 on 01 March 2018

SW82323945-235550799	2,078m	2,079m	CARRIAGEWAY	Pothole (POTH)	CAT 1	29/03/2018	Completed Defects	01/03/2018	A77 NB CW, OPPOSITE MOSSIDE LAYBY, NTH OF KIRKOSWALD
SW82323945-235550798	28m	29m	CARRIAGEWAY	Pothole (POTH)	CAT 1	29/03/2018	Completed Defects	01/03/2018	A77 NB CW, AT KIRKOSWALD NTH GATEWAY
SW82323945-235550800	2,611m	2,612m	CARRIAGEWAY	Pothole (POTH)	CAT 1	29/03/2018	Completed Defects	02/03/2018	A77 NB CW, 600M NTH OF MOSSIDE LAYBY, NTH OF KIRKOSWALD

Safety Inspection of A77 Ayr South V1 on 08 March 2018									
SW82326075-235554294	2,689m	2,690m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 SB CW, 100M NTH OF SB MOSSIDE LAYBY
SW82326075-235554295	1,643m	1,645m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 SB CW, 300M STH OF MOSSIDE LAYBY

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

SW82330474-235608120	2,118m	2,119m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 NB CW, AT MOSSIDE LAYBY
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	-----------------------------

11626/79 : JCT BLANEFIELD TO JUNCTION BROOMKNOWES FARM

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

SW82317326-235513691	1,722m	1,723m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	08/02/2018	100meters south of mosside lay by sb cw
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11629/05 : JCT BROOMKNOWES FM TO 30 MPH SIGN MAYBOLE

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

SW82318129-235532264	227m	230m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/03/2018	Completed Defects	01/02/2018	A77 MAYBOLE STH GATEWAY
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	-------------------------

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

SW82323945-235550801	113m	114m	CARRIAGEWAY	Pothole	CAT 1	29/03/2018	Completed	02/03/2018	A77 NB CW, MAYBOLE STH
----------------------	------	------	-------------	---------	-------	------------	-----------	------------	------------------------

(POTH)

Defects

GATEWAY

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

SW82328086-235590036	20m	28m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	16/03/2018	A77 BOTH CW, MAYBOLE STH GATEWAY, 100M STH TO GW
----------------------	-----	-----	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11629/11 : 30MPH SIGN MAYBOLE TO JUNCTION LADYLAND ROAD

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

SW82317326-235513690	188m	190m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	26/01/2018	opposite maybole academy at splitter island sb cw at last bungalow
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

SW82330474-235608121	125m	126m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/04/2018	Completed Defects	22/03/2018	A77 SB CW, OPPOSITE CARRICK ACADEMY, MAYBOLE
----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--

11629/32 : JUNCTION LADYLAND ROAD TO JUNCTION JOHN KNOX ST

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

SW82317666-235521328	142m	152m	CARRIAGEWAY	Failed repair (RFAL)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A77 SB CW, WHITEHALL STREET MAYBOLE
----------------------	------	------	-------------	----------------------	-------	------------	-----------------------	------------	-------------------------------------

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11629/45 : JCT JOHN KNOX ST TO JCT B7023 CULZEAN RD

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

SW82328086-235590037	173m	174m	GULLY	Other (OTHR)	3RD PTY	12/04/2018	Awaiting CCMS Permanent	01/01/9999	A77 SB CW, OUTSIDE SIMPSONS BAKERY MAYBOLE
----------------------	------	------	-------	--------------	---------	------------	----------------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11629/52 : JUNCTION B7023 CULZEAN ROAD TO LYONSTON FARM

Safety Inspection of A77 Ayr South V1 on 28 December 2017

SW82317141-235513279	286m	287m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/01/2018	Completed Defects	08/02/2018	A77 SB CW, OPPOSITE JACKS GAIT JCT, MAYBOLE
----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

SW82317666-235521330	0m	2m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	05/03/2018	A77 NB CW, 250M STH OF LAYBY AT DRUMELLAN FARM, NTH OF MAYBOLE
----------------------	----	----	-------------	-------------------	-------	------------	----------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

SW82319984-235544962	436m	437m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	15/02/2018	A77 SB CW, AT BUS STOP MCDOWELL TERR, MAYBOLE
----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	--

SW82319984-235544963	364m	365m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	15/02/2018	A77 SB CW, OPP REDBRAE JCT, MAYBOLE
----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11629/76 : LYONSTON FARM TO JUNCTION DRUMELLAN

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11632/05 : JUNCTION DRUMELLAN TO SMITHSTON BRIDGE

Safety Inspection of A77 Ayr South V1 on 28 December 2017

SW82317141-235513280	590m	591m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/01/2018	Completed Defects	05/03/2018	A77 NB CW, APPROX 1 MILE NTH MAYBOLE NTH
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 04 January 2018

SW82317326-235513686	1,905m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	09/02/2018	AT JUNCTION WITH HIGH SMITHSTONE FARM AND JUST SOUTH OF FARM ENTRANCE S\B C\
SW82317326-235513689	585m	587m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	04/01/2018	15meters north of myrehill farm nb cw near centre line

SW82317326-235513687	1,220m	1,221m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	22/01/2018	nb cw north of neth culzean farm at one mile reduce speed now sign
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

SW82317326-235513688	642m	644m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	10/02/2018	100meters north of myrehil farm sb cw
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---------------------------------------

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

SW82317666-235521329	583m	584m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	09/02/2018	A77 SB CW, 200M STH OF LAYBY AT DRUMELLAN, NTH OF MAYBOLE
SW82317666-235521331	458m	459m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	05/03/2018	A77 NB CW, 300M STH OF LAYBY AT DRUMELLAN FARM, NTH OF MAYBOLE

Safety Inspection of A77 Ayr South V1 on 25 January 2018

SW82317793-235529564	1,901m	1,911m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	09/02/2018	A77 ON CL, 150M STH OF SMITHTON BRIDGE, NTH OF MAYBOLE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 01 February 2018

SW82318129-235532262	1,896m	1,900m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/03/2018	Completed Defects	09/02/2018	A77 ON CL, 150M STH OF SMITHTON BRIDGE
SW82318129-235532263	519m	520m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/03/2018	Completed Defects	01/02/2018	A77 BOTH CW, DRUMELLAN NTH OF MAYBOLE

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

SW82319984-235544964	1,864m	1,865m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	16/02/2018	A77 SB CW, 150M STH OF SMITHTON BRIDGE
SW82319984-235544965	1,939m	1,940m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	16/02/2018	A77 NB CW, 80M STH OF SMITHTON BRIDGE

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

SW82326075-235554293	1,117m	1,118m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 SB CW, 200M STH OF DALRYMPLE JCT, NTH OF MAYBOLE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

SW82330474-235608122	1,722m	1,723m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	22/03/2018	A77 ON CL, 150M STH OF SMITHTON BRIDGE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

11632/23 : SMITHSTON BRIDGE TO JUNCTION KEWNSTON

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

SW82317793-235529565	275m	276m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Completed Defects	09/02/2018	A77 SB CW, 200M NTH OF SMITHTON BRIDGE, NTH OF MAYBOLE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

SW82326075-235554292	347m	348m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 SB CW, 300M NTH OF SMITHTON BRIDGE, NTH OF MAYBOLE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11632/40 : JUNCTION KEWNSTON TO CULROY BURN BRIDGE

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

SW82317326-235513685	724m	726m	CARRIAGEWAY	Pothole	CAT 1	01/02/2018	Completed	22/01/2018	OUTSIDE 8 MAIN STREET
----------------------	------	------	-------------	---------	-------	------------	-----------	------------	-----------------------

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

SW82318129-235532261	44m	45m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/03/2018	Completed Defects	02/02/2018	A77 SB CW, MINISHANT
----------------------	-----	-----	-------------	----------------	-------	------------	-------------------	------------	----------------------

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

SW82326075-235554289	782m	783m	BOLLARDS	Accident damage (ACCD)	CAT 1	05/04/2018	Awaiting CCMS Permanent	01/01/9999	A77 MINISHANT, ON FIRST CENTER ISLAND HEADING SOUTH
----------------------	------	------	----------	------------------------	-------	------------	-------------------------	------------	---

SW82326075-235554291	247m	248m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 SB CW, 250M NTH OF MINISHANT STH GATEWAY, OPP SCHOOL
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

SW82326075-235554290	145m	146m	BOLLARDS	Accident damage (ACCD)	CAT 1	05/04/2018	Awaiting CCMS Permanent	01/01/9999	A77 ON CL, AT TRAFFIC ISLAND OPPOSITE SCHOOL, SECOND ISLAND NTH OF NTH GATEWAY
----------------------	------	------	----------	------------------------	-------	------------	-------------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11632/49 : CULROY BURN BRIDGE TO B7034 JUNCTION

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

SW82318129-235532259	1,567m	1,568m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/03/2018	Completed Defects	02/02/2018	A77 SB CW, 100M NTH OF RIVER DOON
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	-----------------------------------

SW82318129-235532260	1,263m	1,264m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/03/2018	Completed Defects	02/02/2018	A77 SB CW, ON RIVER DOON BRIDGE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---------------------------------

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11632/72 : B7034 JUNCTION TO JUNCTION A79 MAYBOLE ROAD AYR**Safety Inspection of A77 Ayr South V1 on 28 December 2017***No defects recorded***Safety Inspection of A77 Ayr South V1 on 04 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 11 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 18 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 25 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 February 2018**

SW82318129-235532257	2,417m	2,418m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/03/2018	Completed Defects	02/02/2018	A77 NB CW, OPPOSITE MAYBOLE RD JCT AYR
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

SW82318129-235532258	1,264m	1,266m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/03/2018	Completed Defects	02/02/2018	A77 NB CW, 300M STH OF CORTON RD END
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--------------------------------------

Safety Inspection of A77 Ayr South V1 on 08 February 2018

SW82319037-235539770	2,159m	2,169m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	08/02/2018	A77 NB CW, 200M STH OF MAYBOLE RD JCT AYR, MULTIPLE POTHLES
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82319037-235539774	1,238m	1,258m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A77 SB CW, APPROX 1KM STH OF DOONFOOT JCT AYR
----------------------	--------	--------	-------------	----------------	-------	------------	-----------------------	------------	---

SW82319037-235539771	2,203m	2,204m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	08/02/2018	A77 NB, 100M STH OF MAYBOLE RD JCT, AYR
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 15 February 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 February 2018**

SW82321955-235548218	1,323m	1,325m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	23/02/2018	NORTH OF AUCHINBLANE SOUTH OF MOSSIDE LAY BY S\BCW 1500 M NORTH OF KIRKOSWALD
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 01 March 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 March 2018**

SW82326075-235554327	1,261m	1,266m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 SB CW, 100M NTH OF BROOMBERRY FARM, STH OF AYR
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 15 March 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 March 2018**

SW82330474-235608123	686m	687m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	23/03/2018	A77 SB CW, OUTSIDE FORD COTTAGE, NTH OF DALRYMPLE JCT, NTH MINISHANT
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

11635/05 : A79 JUNCTION MAYBOLE RD AYR TO BANKHEAD RBT**Safety Inspection of A77 Ayr South V1 on 28 December 2017***No defects recorded***Safety Inspection of A77 Ayr South V1 on 04 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 11 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 18 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 25 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 February 2018**

SW82319037-235539772	13m	23m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	08/02/2018	A77 NB CW, BETWEEN ON AND OFF AT MAYBOLE RD JCT AYR
----------------------	-----	-----	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 15 February 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 15 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 March 2018***No defects recorded***11638/05 : BANKHEAD ROUNDABOUT****Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018***No defects recorded***11641/05 : HOLMSTON ROUNDABOUT****Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018***No defects recorded*

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

11650/05 : DUTCH HOUSE ROUNDABOUT

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

SW82317767-235529086	37m	40m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/02/2018	Completed Defects	24/02/2018	A77 ON DUTCH HOUSE RBT, ON CL
----------------------	-----	-----	-------------	-------------------	-------	------------	----------------------	------------	----------------------------------

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

SW82327521-235576661	100m	101m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/04/2018	Completed Defects	14/03/2018	A77 ON RBT, OPPOSITE NB EXIT A77
----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	-------------------------------------

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11650/08 : WITH: DUTCH HOUSE ROUNDABOUT TO SYMINGTON NB

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

SW82317163-235513437	204m	224m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	26/01/2018	Completed Defects	02/02/2018	A77 CENTER RESERVE, 120M NTH OF DUTCH HOUSE RBT, CENTER RESERVE
Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018									
No defects recorded									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018									
No defects recorded									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018									
No defects recorded									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018									
No defects recorded									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018									
SW82318102-235531999	184m	284m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/02/2018	Completed Defects	14/02/2018	A77 NB CW, LANE 1, 200M NTH OF DUTCHHOUSE RBT
SW82318102-235532000	242m	245m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/02/2018	Completed Defects	14/02/2018	A77 NB CW, LANE 1 250M NTH OF DUTCHHOUSE RBT
SW82318102-235532001	288m	290m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/02/2018	Completed Defects	14/02/2018	A77 NB CW, 300M NTH OF DUTCHHOUSE RBT
Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018									
SW82318894-235534932	1,760m	1,780m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	07/02/2018	A77 NB CW, LANE 1, 200M STH OF HANSEL VILLAGE
SW82318894-235534931	1,499m	1,500m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	07/02/2018	A77 NB CW, LANE 1, 400M STH OF HANSEL VILLAGE
Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018									
SW82319390-235542963	98m	99m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/03/2018	Completed Defects	14/02/2018	A77 NB CW, LANE 1, 100M NTH DUTCH HOUSE RBT, TO 300M
Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018									
SW82321390-235546235	1,751m	1,752m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2018	Completed Defects	21/02/2018	A77N/B LANE1 AT FARM JCT SOUTH OF HANSEL VILAGE
SW82321390-235546234	1,491m	1,493m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2018	Completed Defects	20/02/2018	A77 N/B LANE 1 NORH OF AVERAGE SPEED CAMERAS SOUTH OF HANSEL
Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018									
SW82322248-235548888	1,495m	1,496m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/03/2018	Completed Defects	23/02/2018	A77 N/B LANE 1 30M NORTH OF AVERAGE SPEED CAMERA SOUTH OF HANSEL VILLAGE
Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018									
No defects recorded									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018									
SW82325502-235553022	253m	254m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	06/03/2018	A77 NB CW, LANE 1, 253M NTH OF DUTCH HOUSE RBT
SW82325502-235553023	304m	305m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	06/03/2018	A77 NB CW, LANE 1 280M NTH OF DUTCHHOUSE RBT
SW82325502-235553021	198m	199m	CARRIAGEWAY	Pothole	CAT 1	03/04/2018	Completed	06/03/2018	A77 NB CW LANE 1, 190M NTH

				(POTH)			Defects		OF DUTCH HOUSE RBT
SW82325502-235553024	339m	340m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	06/03/2018	A77 NB CW, LANE 1, 290M NTH OF DUTCH HOUSE RBT
SW82325502-235553025	1,708m	1,709m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	07/03/2018	A77 NB CW, LANE 1, 250M STH OF HANSEL VILLAGE
Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018									
SW82326369-235553165	1,803m	1,804m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	09/03/2018	A77 NB CW, LANE 1, AT WEXFORD FARM, 400M STH OF HANSEL VILLAGE OB
Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018									
No defects recorded									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018									
SW82329522-235601241	2,697m	2,699m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/04/2018	Completed Defects	21/03/2018	A77 NB CW, AT SYMINGTON JCT
SW82329522-235601240	201m	202m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/04/2018	Completed Defects	21/03/2018	A77 NB CW, ON CL, 200M NTH OF DUTCH HOUSE RBT
Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018									
SW82330424-235608130	1,484m	1,485m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/04/2018	Completed Defects	23/03/2018	A77 NB CW, LANE 1, 200M STH OF HANSEL OB

11650/40 : WITH: SYMINGTON NB TO EAST LODGE

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017									
No defects recorded									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017									
SW82317163-235513438	1,258m	1,260m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/01/2018	Completed Defects	06/03/2018	A77 NB CW, ON CL, AT END OF BUS STOP OPPOSITE BALBIRS STH OF BOG END TOLL
Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018									
No defects recorded									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018									
SW82317357-235513857	238m	239m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/02/2018	Completed Defects	31/01/2018	A7 N/B ON CENTRE LINE 50M NORTH OF SYMINGTON OVERBRIDGE
SW82317357-235513858	290m	291m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/02/2018	Completed Defects	13/01/2018	A77 N/B LANE 1 10M NORTH OF END OF ONSLIP FROM SYMINGTON
SW82317357-235513860	464m	466m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/02/2018	Completed Defects	31/01/2018	A77 N/B LANE 1 AND LANE2 60M NORTH OF COTAGES NORTH OF ON SLIP FROM SYMINGTON
Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018									
SW82317440-235515650	1,343m	1,345m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/02/2018	Completed Defects	31/01/2018	A77 NB CW, LANE 1, 350M NTH OF HALFWAY HOUSE, NTH OF SYMINGTON
SW82317440-235515662	720m	721m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/02/2018	Completed Defects	31/01/2018	A77 NB CW, LANE 2, OUTSIDE HALFWAY HOUSE
SW82317440-235515649	1,196m	1,197m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/01/2018	Completed Defects	31/01/2018	A77 NB CW LANE 1, 150M NTH OF HALFWAY HOUSE NTH OF SYMINGTON
Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018									
SW82317632-235520465	1,008m	1,018m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	13/02/2018	Completed Defects	31/01/2018	LANE 2 AT THE SLIP ROAD TO OLD HALFWAY HOUSE BETWEEN SYMINGTON AND BOGENDTOLL
SW82317632-235520466	1,629m	1,649m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/02/2018	Completed Defects	09/02/2018	LANE 1 AT ADS PRIOR TO BOGEND N/B OPPOSITE

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018**

SW82318894-235534934	740m	760m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	07/02/2018	A77 NB CW, 600M NTH OF SYMINGTON ONSLIP
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

SW82319109-235534718	661m	665m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, 660M NTH OF SYMINGTON NB ONSLIP
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

SW82319109-235534720	1,071m	1,073m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, LANE 2, OPPOSITE HALFWAY HOUSE NTH OF SYMINGTON OB
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82319109-235534721	1,737m	1,757m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, 150M STH OF BOGEND TOLL TO BOGEND TOLL
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82319109-235534717	417m	418m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, LANE 1, 410M NTH OF SYMINGTON NB ONSLIP
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

SW82319109-235534719	712m	722m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, ON CL, 720M NTH OF SYMINGTON NB ONSLIP
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018**

SW82326369-235553170	800m	801m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, 300M STH OF HALFWAY HOUSE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

SW82326369-235553172	904m	905m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, 200M STH OF HALFWAY HOUSE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

SW82326369-235553175	1,636m	1,637m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, LANE 1, OPPOSITE SPICE ROUTE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82326369-235553176	1,652m	1,653m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, OPPOSITE SPICE ROUTE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

SW82326369-235553171	850m	851m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, 250M STH OF HALFWAY HOUSE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

SW82326369-235553173	942m	943m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, 150M STH OF HALFWAY HOUSE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--------------------------------------

SW82326369-235553174	998m	999m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, 100M STH OF HALFWAY HOUSE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

SW82326369-235553177	1,656m	1,657m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, OPPOSITE SPICE ROUTE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018**

SW82328364-235586131	552m	553m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW ON CL, 550M STH OF HALFWAY HOUSE
SW82328364-235586134	752m	753m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW, ON CL, 400M STH OF HALFWAY HOUSE
SW82328364-235586130	489m	490m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW, 600M STH OF HALFWAY HOUSE ON CL
SW82328364-235586132	613m	614m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW LANE 1, 500M STH OF HALFWAY HOUSE
SW82328364-235586133	678m	679m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW LANE 2, 450M STH OF HALFWAY HOUSE

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018**

SW82330424-235608132	2,483m	2,485m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/04/2018	Completed Defects	24/03/2018	A77 NB CW, ON CL, AT NB END OF 50MPH SPEED RESTRICTION, FOR 150M NTH
SW82330424-235608131	293m	296m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/04/2018	Completed Defects	23/03/2018	A77 NB CW, ON CL, MULTIPLE HOLES, SYMINGTON NB ONSLIP FOR 300M

11650/80 : WITH: EAST LODGE TO SPITTALHILL SLIP ROAD**Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018**

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11650/90 : WITH: SPITALHILL SLIP RD TO EAST AYRSHIRE BOUNDARY

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11653/04 : WITH: EAST AYRSHIRE BDY TO 300M N OF WHATRIGGS BR
Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017
No defects recorded
Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017
No defects recorded
Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018
No defects recorded
Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018
No defects recorded
Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018
No defects recorded
Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018
No defects recorded
Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018
No defects recorded
Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018
No defects recorded
Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018
No defects recorded
Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018
No defects recorded
Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

SW82318102-235531997	2,273m	2,473m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A77 NB CW, TREESWOOD OB
----------------------	--------	--------	-------------	----------------	-------	------------	-----------------------	------------	-------------------------

SW82318102-235531998	2,440m	2,640m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A77 NB CW, NTH OF TREESWOOD OB
----------------------	--------	--------	-------------	----------------	-------	------------	-----------------------	------------	--------------------------------

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

SW82318553-235533631	3,007m	3,010m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/03/2018	Completed Defects	16/02/2018	A77 ON CL, MULTIPLE POTHLES, 300M STH OF WHATRIGGS OB, STH OF BELLFIELD
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82318553-235533635	2,778m	2,780m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/03/2018	Completed Defects	16/02/2018	A77 NB CW, ON CL, AT END OF LAYBY STH OF WHATRIGGS OB
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82318553-235533634	2,733m	2,735m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/03/2018	Completed Defects	16/02/2018	A77 NB CW, ON CL, 50M PRIOR TO LAYBY STH OF BELLFIELD
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018
No defects recorded
Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

SW82319109-235534724	2,584m	2,588m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	16/02/2018	A77 NB CW, 300M STH OF LAYBY PRIOR TO WHATRIGGS OB
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

SW82319109-235534725	2,805m	2,807m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	16/02/2018	A77 NB CW, LANE 1, OPPOSITE LAST LAYBY PRIOR TO WHATRIGGS OB
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

SW82319109-235534722	2,179m	2,181m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	16/02/2018	A77 NB CL, 200M NTH OF TREESWOOD OB
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	-------------------------------------

SW82319109-235534729	1,912m	1,915m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	21/02/2018	A77 NB CW, LANE 2, 300M STH OF TREESWOOD OB
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82319109-235534723	2,546m	2,548m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	16/02/2018	A77 NB CL, 400M NTH OF TREESWOOD OB
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	-------------------------------------

SW82319109-235534726	2,860m	2,870m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	16/02/2018	A77 NB CW, 100M STH OF WHATRIGGS OB
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	-------------------------------------

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018
No defects recorded
Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018
No defects recorded
Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

SW82321390-235546236	2,966m	2,970m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2018	Completed Defects	22/02/2018	A7 N/B ON CENTRE LINE AT NORTH BOUND END OF
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018**

SW82328364-235586135	2,544m	2,545m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW, LANE 2, 200M STH OF NB LAYBY STH WHATRIGGS OB
SW82328364-235586136	3,023m	3,024m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW, ON CL, AT END OF LAYBY STH OF WHATRIGGS
SW82328364-235586137	3,102m	3,103m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW, ON CL, 200M STH OF WHATRIGGS OB

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018**

SW82330424-235608134	3,117m	3,118m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/04/2018	Completed Defects	24/03/2018	A77 NB CW, ON CL, 300M STH OF WHATRIGGS OB
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

11656/03 : WITH: 300M N WHATRIGGS BR TO OFF SLIP TO A76/A71**Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018**

SW82319109-235534727	78m	80m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	22/02/2018	A77 ON CL, 150M STH OF BELLFIELD NB OFFSLIP
SW82319109-235534728	175m	185m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	22/02/2018	A77 NB CW, AT BELLFIELD NB OFFSLIP

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018***No defects recorded*

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11656/05 : WITH: OFF SLIP TO A76/A71 TO ON SLIP FROM A76/A71

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

SW82317357-235513861	657m	658m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/02/2018	Completed Defects	09/02/2018	A77 N/B LANE1 ON BRIDGE DECK BETWEEN OF SLIP AND ON SLIP BELFIELD INTECHANGE
----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	---

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

SW82321390-235546237	654m	656m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2018	Completed Defects	21/02/2018	A77 N/B LANE1 ON BRIDGE DECK BETWEEN OFF AND ON SLIP BELLFIELD INTERCHANGE
----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018									
SW82325502-235553036	665m	666m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	07/03/2018	A77 NB CW, LANE 1, BRIDGE JOINT UNDER BELLFIELD INTERCHANGE
Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018									
SW82327521-235576662	367m	368m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/04/2018	Completed Defects	14/03/2018	A77 NB CW, ON CL, BELLFIELD MAIN DRAG
Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018									
SW82330424-235608135	187m	188m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/04/2018	Completed Defects	24/03/2018	A77 NB CW, AT BELLFIELD NB OFFSLIP, MAIN DRAG

11656/20 : HURLFORD INTERCHANGE ROUNDABOUT

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018									
<i>No defects recorded</i>									

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11656/12 : AGAINST: OFF SLIP A76/A71 TO 300M N WHATRIGGS BRID

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11653/06 : AGAINST: 300M N OF WHATRIGGS BR TO E. AYRSHIRE BDY

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

SW82317632-235520467	2,811m	2,844m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	13/02/2018	Completed Defects	02/02/2018	INCHGOTRICK A77 CENTRE RESERVE
----------------------	--------	--------	--------------	------------------------	-------	------------	-------------------	------------	--------------------------------

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

SW82317695-235522279	1,966m	2,000m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/02/2018	Completed Defects	01/02/2018	A77 SB CW, 4 POTHLES FROM LAYBY STH OF TREESWOOD OB TO 250M STH
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

SW82317767-235529085	847m	850m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/02/2018	Completed Defects	02/02/2018	A77 SB CW, LANE 1, 50M STH OF BELLFIELD INT
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Annual Detailed Inspection - Carriageways of A77 Ayr N Det

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

SW82318894-235534935	1,928m	1,930m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	07/02/2018	A77 NB CW, LANE 1, AT LAYBY PRIOR TO TREESWOOD OB
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82318894-235534936	1,261m	2,261m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A77 NB CW, TREESWOOD TO WHATRIGGS
----------------------	--------	--------	-------------	----------------	-------	------------	-----------------------	------------	-----------------------------------

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

SW82321390-235546244	775m	777m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2018	Completed Defects	21/02/2018	A77 S/B LANE 1 25M SOUTH OF FIRST LAYBY SOUTH OF BELLFIELD INTERCHAGE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

SW82321390-235546243	741m	742m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2018	Completed Defects	21/02/2018	A7 S/B LANE1 5M SOUTH OFENDOF FIRST LAYBY SOUTH OFBELLFIELDINTERCHANGE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

SW82326369-235553179	1,527m	1,528m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 SB CW, LANE 1, 50M NTH OF TREESWOOD SB LAYBY
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

SW82326369-235553183	1,912m	1,913m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 SB CW, 50M STH OF TREESWOOD SB LAYBY
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

SW82326369-235553184	2,128m	2,129m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 SB CW, LANE 1, 200M STH OF TREESWOOD SB LAYBY
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82326369-235553180	1,646m	1,647m	CARRIAGEWAY	Pothole	CAT 1	06/04/2018	Completed	10/03/2018	A77 SB CW, LANE 1,
----------------------	--------	--------	-------------	---------	-------	------------	-----------	------------	--------------------

				(POTH)			Defects		OPPOSITE TREESWOOD SB LAYBY
SW82326369-235553182	1,838m	1,839m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 SB CW, LANE 1, OPPOSITE TREESWOOD SB LAYBY
SW82326369-235553181	1,748m	1,749m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 SB CW, LANE 1, OPPOSITE TREESWOOD SB LAYBY
SW82326369-235553178	1,425m	1,426m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 SB CW, LANE 1, 100M NTH OF TREESWOOD SB LAYBY

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

SW82327521-235576660	1,396m	1,398m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/04/2018	Completed Defects	14/03/2018	A77 SB CW, LANE 1, 100M STH TREESWOOD OB AND AT LAYBY
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

SW82330424-235608133	1,782m	1,784m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/04/2018	Completed Defects	24/03/2018	A77 NB CW, LANE 1, AT LAYBY STH OF TREESWOOD OB
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

11650/91 : AGAINST: EAST AYRSHIRE BDY TO SPITALHILL SLIP ROAD

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Annual Detailed Inspection - Carriageways of A77 Ayr N Det

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11650/81 : AGAINST: SPITALHILL SLIP ROAD TO EAST LODGE

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11650/41 : AGAINST: EAST LODGE TO SYMINGTON SB**Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017**

SW82317163-235513439	582m	584m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/01/2018	Completed Defects	09/02/2018	A77 NB CL, 100M NTH OF BOG END TOLL NB ON SLIP
SW82317163-235513440	348m	350m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/01/2018	Completed Defects	09/02/2018	A77 NB CW, ON CL, 200M NTH OF BOG END TOLL NB ONSLIP

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018**

SW82317357-235513859	2,457m	2,457m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/02/2018	Completed Defects	31/01/2018	A77 N/B LANE1 AND CENTRELIN 40M NORTH OF COTAGESNORTH OF SYMINGTON ON SLIP
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018**

SW82317632-235520464	2,456m	2,457m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/02/2018	Completed Defects	31/01/2018	LANE 1 200meters north of the symington nb on slip at cottages
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018**

SW82317812-235529552	878m	880m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/02/2018	Completed Defects	09/02/2018	A77 NB CW, AT BOG END TOLL NB ON SLIP
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---------------------------------------

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018**

SW82318894-235534933	2,590m	2,590m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	07/02/2018	A77 NB CW, LANE 1, 100M NTH OF SYMINGTON ONSLIP
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

SW82319109-235534716	2,447m	2,450m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, ON CL, 300M NTH OF SYMINGTON NB ONSLIP
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018**

SW82325502-235553035	2,463m	2,863m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	07/03/2018	A77 NB CW, ON CL, 500M NTH OF SYMINGTON ONSLIP, TO 200M STH HALFWAY HOUSE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018**

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11650/09 : AGAINST: SYMINGTON SB TO DUTCH HOUSE RBT

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

SW82317095-235513358	545m	555m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/01/2018	Completed Defects	01/02/2018	A77 NB CW, ON CL, OPPOSITE HANSEL VILLAGE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

SW82317274-235513678	511m	514m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/01/2018	Completed Defects	02/02/2018	A7 S/B ON CENTRE LINE OPPOSITE JCT HANSEL VILLAGE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

SW82317440-235515661	643m	644m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/02/2018	Completed Defects	01/02/2018	A77 SB CW, LANE 2, OUTSIDE HANSEL VILLAGE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

SW82317632-235520463	2,364m	2,365m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/02/2018	Completed Defects	31/01/2018	300 M NORTH OF DUTCHHOUSE RBT LANE 1
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--------------------------------------

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

SW82319390-235542962	2,103m	2,104m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/03/2018	Completed Defects	13/02/2018	A77 SB CW LANE 1, 500M NTH OF DUTCH HOUSE RBT
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

SW82327521-235576666	608m	610m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/04/2018	Completed Defects	14/03/2018	A77 SB CW, AT HANSEL VILLAGE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	------------------------------

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11650/86 : WITH: SPITTALHILL SL.RD N/BD-K&L DIST BDY

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11650/87 : AGAINST: K&C DIST BDY STH BND-95M S OF SLIP ROAD

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

SW82327521-235576665	680m	681m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/04/2018	Completed Defects	14/03/2018	A77 SPITTALHILL SB ONSLIP, 200M NTH JOIN
----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11656/04 : WITH: N/B SLIP RD EXIT-HURLFORD INTERCHANGE

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded
Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018
SW82318553-235533632 11m 12m CARRIAGEWAY Pothole (POTH) CAT 1 02/03/2018 Completed Defects 02/02/2018 A77 NB CW, ON BELLFIELD NB OFFSLIP

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

SW82323374-235550823 7m 3m CARRIAGEWAY Pothole (POTH) CAT 1 27/03/2018 Completed Defects 28/02/2018 A77 NB CW, START OF BELLFIELD OFFSLIP

SW82323374-235550824 16m 17m CARRIAGEWAY Pothole (POTH) CAT 1 27/03/2018 Completed Defects 28/02/2018 A77 NB CW, LANE 1, AT BELLFIELD NB OFFSLIP

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11656/11 : AGAINST: HURLFORD INTERCHANGE-JCT OF S/B TR.ROAD

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11656/17 : WITH: HURLFORD INTERCHANGE-JCT OF N/B TR.ROAD

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

SW82317163-235513442	117m	120m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/01/2018	Completed Defects	27/02/2018	A77 NB ONSLIP, BELLFIELD, BRIDGE JOINT
----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	---

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11656/46 : AGAINST: S/B SLIP RD EXIT TO HURLFORD INTERCHANGE

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

SW82317163-235513441	3m	4m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/01/2018	Completed Defects	12/01/2018	A77 BELLFIELD SB OFFSLIP AT START
----------------------	----	----	-------------	-------------------	-------	------------	----------------------	------------	--------------------------------------

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018									
SW82330424-235608136	17m	18m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/04/2018	Completed Defects	24/03/2018	A77 SB CW, LANE 1, AT START OF BELLFIELD SB OFFSLIP

11620/10 : B734 KIRKPATRICK STREET ROUNDABOUT

Safety Inspection of A77 Ayr South V1 on 28 December 2017									
SW82317141-235513270	19m	20m	FENCES_AND_BARRIERS	Other (OTHR)	CAT 1	25/01/2018	Completed Defects	28/12/2017	A77 KIRKPATRICK STREET MINI RBT

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11620/12 : B734 KIRKPATRICK STREET RBT TO YOUNG STREET

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

SW82328086-235590028	25m	26m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 NB CW, GIRVAN 50M NTH OF MINI RBT
----------------------	-----	-----	-------------	----------------	-------	------------	-------------------	------------	---------------------------------------

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11620/13 : YOUNG STREET TO DUNCAN STREET

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded
Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded
Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded
Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded
Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded
Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded
Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded
Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded
Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded
Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded
Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded
Safety Inspection of A77 Ayr South V1 on 15 March 2018

SW82328086-235590029	149m	152m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 NB CW, AT YOUNG STREET JCT, GIRVAN
SW82328086-235590030	360m	361m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 NB CW, 20M PRIOR PARK GIRVAN BEACH

Safety Inspection of A77 Ayr South V1 on 22 March 2018
No defects recorded

11620/26 : DUNCAN STREET TO HENRIETTA STREET RBT

Safety Inspection of A77 Ayr South V1 on 28 December 2017
No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018
No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018
No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

SW82317666-235521319	365m	366m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	04/02/2018	A77 NB CW, AT CENTER ISLAND PRIOR TO HENRIETTA STREET MINI RBT, GIRVAN
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 25 January 2018
No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018
No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018
No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018
No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018
No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018
No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018
No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018
No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018
No defects recorded

11620/33 : HENRIETTA STREET ROUNDABOUT

Safety Inspection of A77 Ayr South V1 on 28 December 2017
No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018
No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11620/34 : HENRIETTA STREET RBT TO STUMPY CORNER

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

SW82328086-235590031	15m	20m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 NB CW, BETWEEN HENRIETTA MINI RBT AND STUMPY CORNER
----------------------	-----	-----	-------------	-------------------	-------	------------	----------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11620/37 : Against: STUMPY CORNER TO WESLEY ROAD

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11620/49 : DUFF STREET TO KIRKPATRICK STREET RBT

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11617/73 : ARDMILLAN CASTLE TO A714 SHALLOCHPARK ROUNDABOUT

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

SW82323945-235550796 1,647m 1,648m CARRIAGEWAY Pothole (POTH)

CAT 1

29/03/2018

Completed Defects

01/03/2018

A77 SB CW, 1500M STH OF SHALLOWPARK RBT, STH OF GIRVAN

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11656/22 : WITH: ON SLIP FROM A76/A71 TO M77 DBFO BOUNDARY

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

SW82317695-235522277	1,543m	1,544m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/02/2018	Completed Defects	09/02/2018	A77 SB CW, LANE 2 500M STH OF GRASSYARDS ONSLIP SB
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

SW82318553-235533633	264m	266m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/03/2018	Completed Defects	22/02/2018	A77 NB CW, LANE 1, 300M NTH OF BELLFIELD NB ONSLIP
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

SW82326369-235553166	644m	645m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, 1ST LAYBY AFTER BELLFIELD
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--------------------------------------

SW82326369-235553168	648m	649m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB LAYBY, 1ST LAYBY NTH OF BELLFIELD INT
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

SW82326369-235553167	656m	657m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB LAYBY, 1ST LAYBY NTH OF BELLFIELD INT
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

SW82326369-235553169	669m	700m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB LAYBY, 1ST LAYBY NTH OF BELLFIELD INT
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

SW82327521-235576663	1,422m	1,423m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/04/2018	Completed Defects	14/03/2018	A77 NB CW, 500M STH OF GRASSYARDS, LANE 2
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018**

SW82329522-235601242	3,196m	3,197m	GULLY	Other (OTHR)	CAT 1	17/04/2018	Completed Defects	21/03/2018	A77 NB CW, ON CENTER, 500M STH OF MIEKLEWOOD
----------------------	--------	--------	-------	--------------	-------	------------	-------------------	------------	--

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018*No defects recorded***11656/24 : AGAINST: M77 DBFO BDY TO OFF SLIP TO A76/A71 SB****Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017**

SW82317163-235513447	2,775m	2,795m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	26/01/2018	Completed Defects	13/02/2018	A77 CENTR ISLAND, 200M NTH OF FOOTBRIDGE NTH OF BELLFIELD
----------------------	--------	--------	---------------------	------------------------	-------	------------	-------------------	------------	---

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018**

SW82317357-235513862	2,421m	2,422m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/02/2018	Completed Defects	20/02/2018	A77 S/B ON CENTRE LINE 500M SOUTH OF ON SLIP FROM GRASSYARDS
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018**

SW82317695-235522278	2,297m	2,298m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/02/2018	Completed Defects	20/02/2018	A77 SB CW, LANE 2, 550M STH OF GRASSYARDS SB ONSLIP
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82317695-235522276	2,014m	2,015m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/02/2018	Completed Defects	22/02/2018	A77 SB CW LANE 2 GRASSYARDS SB ONSLIP
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---------------------------------------

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018*No defects recorded***Annual Detailed Inspection - Carriageways of A77 Ayr N Det***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018**

SW82317812-235529553	3,329m	3,330m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/02/2018	Completed Defects	01/02/2018	A77 SB CW, 400M NTH OF BELLFIELD INTERCHANGE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018**

SW82320263-235545151	3,896m	3,898m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/03/2018	Completed Defects	22/02/2018	A77 SB CW, BELLFIELD OFFSLIP, AT START OF SLIP
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018**

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

SW82328364-235586141	2,227m	2,228m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	17/03/2018	A77 SB CW, LANE 2, 500M STH OF SB GRASSYARDS ONSLIP
SW82328364-235586143	2,381m	2,383m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	17/03/2018	A77 SB CW, ON CL, 575M STH OF GRASSYARDS SB ONSLIP
SW82328364-235586140	2,127m	2,128m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	17/03/2018	A77 SB CW, LANE 2, 400M STH OF GRASSYARDS SB ONSLIP
SW82328364-235586142	2,280m	2,282m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	17/03/2018	A77 SB CW, LANE 2, 550M STH OF GRASSYARDS
SW82328364-235586144	2,433m	2,434m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	17/03/2018	A77 SB CW, LANE 2, 600M STH OF GRASSYARDS SB ONSLIP

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11656/31 : WITH: NB OFF SLIP TO NEW FARM LOCH B7082

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

SW82322248-235548889	383m	385m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/03/2018	Completed Defects	23/02/2018	A77 N/B OFF SLIP GRASYARDS
----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	-------------------------------

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11656/32 : AGAINST: SB ON SLIP FROM NEW FARM LOCH B7082

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

SW82317163-235513445	70m	72m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/01/2018	Completed Defects	11/01/2018	A77 GRASSYARDS SB ONSLIP, 100M DOWN SLIP
SW82317163-235513446	186m	187m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/01/2018	Completed Defects	01/02/2018	A77 GRASSYARDS SB ONSLIP, 250M NTH OF JOINING A77 MAIN DRAG

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

SW82327521-235576664	39m	42m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/04/2018	Awaiting CCMS Temp Date	01/01/9999	A77 SB GRASSYARDS ONSLIP, 100M DOWN SLIP
----------------------	-----	-----	-------------	-------------------	-------	------------	----------------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018									
SW82328364-235586139	315m	316m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 SB GRASSYARDS ONSLIP
SW82328364-235586138	185m	186m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 SB GRASSYARDS ONSLIP
Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018									
SW82329522-235601243	399m	400m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/04/2018	Completed Defects	21/03/2018	A77 SB CW, GRASSYARDS SB ONSLIP ON MAIN DRAG

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018
No defects recorded

11656/35 : WITH: NB ON SLIP FROM NEW FARM LOCH B7082

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018									
<i>No defects recorded</i>									

11656/36 : AGAINST: SB OFF SLIP TO NEW FARM LOCH B7082**Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017**

SW82317163-235513443	178m	179m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/01/2018	Completed Defects	11/01/2018	A77 SB OFFSLIP GRASSYARDS, 150M NTH OF END OF SLIP
SW82317163-235513444	259m	261m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/01/2018	Completed Defects	11/01/2018	A77 SB OFFSLIP, GRASSYARDS, 50M NTH OF TOP OF SLIP

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018**

SW82321390-235546238	259m	261m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2018	Completed Defects	20/02/2018	A77 S/B OFF SLIP GRASYARDS
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	----------------------------

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

SW82322248-235548891	236m	237m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/03/2018	Completed Defects	23/02/2018	A77 S/B OF SLIP GRASYARDS
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---------------------------

SW82322248-235548890	227m	237m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/03/2018	Completed Defects	24/02/2018	A77 S/B OF SLIP GRASYARDS
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---------------------------

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

SW82323374-235550826	336m	337m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/03/2018	Completed Defects	28/02/2018	A77 SB CW, GRASSYARDS SB OFFSLIP, 20M NTH OF END OF SLIP
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

SW82323374-235550825	164m	164m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/03/2018	Completed Defects	28/02/2018	A77 SB CW, GRASSYARDS OFFSLIP, 50M STH OF START
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018***No defects recorded*

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018*No defects recorded***11626/04 : A719 JCT TO STH END TURNBERRY CLIMBING LANE****Safety Inspection of A77 Ayr South V1 on 28 December 2017***No defects recorded***Safety Inspection of A77 Ayr South V1 on 04 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 11 January 2018**

SW82317471-235518223	523m	524m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	05/03/2018	A77 NB CW, 100M NTH OF TRUMP TURNBERRY ENTRANCE, TURNBERRY
SW82317471-235518225	168m	168m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	05/03/2018	A77 NB CW, 100M STH DALQUATT LAYBY, STH OF KIRKOSWALD
SW82317471-235518226	227m	229m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	05/03/2018	A77 NB CW, OPP DALQUATT LAYBY, STH OF KIRKOSWALD

Safety Inspection of A77 Ayr South V1 on 18 January 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 25 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 15 February 2018**

SW82319984-235544959	461m	462m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	15/02/2018	A77 SB CW, OPP TRUMP TURNBERRY DELIVERY ENTRANCE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 22 February 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 15 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 March 2018**

SW82330474-235608116	309m	310m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	22/03/2018	A77 SB CW, 20M STH OF TURNBERRY LODGE
SW82330474-235608117	264m	265m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	22/03/2018	A77 ON CL, 40M STH OF TURNBERRY LODGE
SW82330474-235608118	389m	390m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/04/2018	Completed Defects	22/03/2018	A77 SB CW, 30M STH OF TRUMP TURNBERRY DELIVERY ENTRANCE
SW82330474-235608115	333m	334m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2018	Completed Defects	22/03/2018	A77 SB CW, 20M NTH OF TURNBERRY LODGE

11626/06 : TURNBERRY CLIMBING LANE**Safety Inspection of A77 Ayr South V1 on 28 December 2017***No defects recorded***Safety Inspection of A77 Ayr South V1 on 04 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 11 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 18 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 25 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 February 2018***No defects recorded*

Safety Inspection of A77 Ayr South V1 on 15 February 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 March 2018**

SW82326075-235554301	725m	728m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 AT LAYBY TOP OF TURNBERRY HILL, ON STH EXIT
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 15 March 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 March 2018***No defects recorded***11626/16 : NTH END TURNBERRY CLIMBING LANE TO HIGH PARK****Safety Inspection of A77 Ayr South V1 on 28 December 2017**

SW82317141-235513274	609m	610m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/01/2018	Completed Defects	26/02/2018	A77 SB CW, OPPOSITE DALQUATT FARM ENTRANCE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 04 January 2018

SW82317326-235513693	613m	616m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	26/02/2018	JST SOUTH ON SIB CW FROM ENTRANCE TO DALQUAT FARM
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 11 January 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 18 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 25 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 15 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 February 2018**

SW82321955-235548223	599m	56m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	26/02/2018	A77 AT BALLOCHNEIL FARM JUST SOUTH OF DALQUAT SIB CW
----------------------	------	-----	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 01 March 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 15 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 March 2018***No defects recorded***11644/07 : WITH: WHITLETTS ROUNDABOUT TO SANDYFORD TOLL RBT****Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018**

SW82317767-235529087	2,196m	2,198m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/02/2018	Completed Defects	23/01/2018	A77 SB CW, 660M STH OF DUTCHHOUSE RBT
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---------------------------------------

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018**

<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018									
SW82329522-235601244	2,193m	2,195m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/04/2018	Awaiting CCMS Temp Date	01/01/9999	A77 SB CW, LANE 1, 500M NTH OF SANDYFORD RBT

11644/90 : SANDYFORD TOLL ROUNDABOUT

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018									
<i>No defects recorded</i>									

11647/07 : WITH: SANDYFORD TOLL R/BOUT to Dutch House Rbt

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018									
SW82317274-235513675	1,165m	1,169m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/01/2018	Completed Defects	09/02/2018	N/B ON CENTRE LINE 400M NORTH OF OVER BRIDGE NORTH OF SANDY FORD RBT
SW82317274-235513677	1,447m	1,449m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/01/2018	Completed Defects	30/01/2018	A77 N/B ON CENTRE LINE 600M NORTH OF OVERBRIDGE NORTH OF SANDYFORD RBT
SW82317274-235513676	1,247m	1,250m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/01/2018	Completed Defects	29/01/2018	A77 N/B 500M NORTH OF OVERBRIDGE NORTH OF SANDYFORD RBT
Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018									
SW82317632-235520462	468m	469m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/02/2018	Completed Defects	29/01/2018	LANE 2 500 M NORTH OF SANDYFORD RBT NORTHBOUND CARRIAGEWAY
Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018									
SW82317767-235529069	3,223m	3,224m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/02/2018	Completed Defects	09/02/2018	A77 NB CW, LANE 2, 150M STH OF DUTCHHOUSE RBT

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018									
SW82318102-235532002	744m	755m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A77 NB CW, LANE 1, 750M NTH SANDYFORD
Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018									
SW82318894-235534930	396m	2,184m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	06/02/2018	A77 NB CW, BETWEEN SANDYFORD AND DUTCH HOUSE RBT
Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018									
SW82319390-235542964	3,342m	3,343m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/03/2018	Completed Defects	13/02/2018	A77 NB CW, LANE 2, 150M STH OF DUTCH HOUSE RBT
Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018									
SW82323374-235550827	2,101m	2,102m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/03/2018	Completed Defects	28/02/2018	A77 NB CW, LANE 1, ON BRIDGE DECK, 2000M NTH OF SANDYFORD RBT
Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018									
SW82329522-235601239	442m	446m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/04/2018	Completed Defects	20/03/2018	A77 NB CW, 100-400M NTH OF SANDYFORD RBT

11647/55 : AGAINST: DUTCH HOUSE RBT TO SANDYFORD TOLL RBT

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018									
<i>No defects recorded</i>									
Annual Detailed Inspection - Carriageways of A77 Ayr N Det									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018									
<i>No defects recorded</i>									

11656/90 : WITH: OFF SLIP TO B7038 TO START OF MOTORWAY

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018									

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11656/92 : AGAINST: END OF MWAY TO B7061 JCT

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

11611/57 : JCT AT CARLOCK HOUSE TO JCT AT BALLOCHDOWAN

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

SW82317326-235513698	203m	205m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/02/2018	Completed Defects	27/01/2018	at top of carlock hill 150 meters north of carlock house onboth the nb and sbcws
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

SW82319037-235539796	384m	390m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 NB CW, AT TOP OF CARLOCH HILL, 100M NTH OF CARLOCH HOUSE
SW82319037-235539797	41m	50m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2018	Completed Defects	09/02/2018	A77 NB CW, OPPOSITE CARLOCH HOUSE, CARLOCH HILL

Safety Inspection of A77 Ayr South V1 on 15 February 2018

SW82319984-235544947	1,708m	1,709m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/03/2018	Completed Defects	15/02/2018	A77 SB CW, 100M STH OF BALLOCHDOWAN JCT
----------------------	--------	--------	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

SW82326075-235554323	324m	325m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 ON CL, 110M NTH CARLOCH HOUSE
SW82326075-235554322	293m	294m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, 100M NTH OF CARLOCH HOUSE

Safety Inspection of A77 Ayr South V1 on 15 March 2018

SW82328086-235590012	1,380m	1,382m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	16/03/2018	A77NB CW, ON STRAIGHTS, 800M NTH OF CARLOCH HOUSE
SW82328086-235590011	486m	488m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	16/03/2018	A77 NB CW, ON STRAIGHT, 600M NTH OF CARLOCH HOUSE
SW82328086-235590013	1,350m	1,352m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	16/03/2018	A77 SB CW, ON STRAIGHT, 800M NTH OF CARLOCH HOUSE
SW82328086-235590010	58m	60m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Awaiting CCMS Temp Date	01/01/9999	A77 BOTH CW, OUTSIDE CARLOCH HOUSE
SW82328086-235590014	950m	955m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	16/03/2018	A77 SB CW, ON STRAIGHT, 700-500M NTH OF CARLOCH HOUSE

Safety Inspection of A77 Ayr South V1 on 22 March 2018*No defects recorded***11611/07 : SOUTH AYRSHIRE BOUNDARY TO HAGGSTONE CL SOUTH END****Safety Inspection of A77 Ayr South V1 on 28 December 2017***No defects recorded***Safety Inspection of A77 Ayr South V1 on 04 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 11 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 18 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 25 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 15 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 15 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 March 2018***No defects recorded***11611/11 : HAGGSTONE CLIMBING LANE****Safety Inspection of A77 Ayr South V1 on 28 December 2017***No defects recorded***Safety Inspection of A77 Ayr South V1 on 04 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 11 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 18 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 25 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 15 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 February 2018***No defects recorded*

Safety Inspection of A77 Ayr South V1 on 01 March 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 15 March 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 March 2018***No defects recorded***11611/18 : HAGGSTONE CL NORTH END TO NORTH MARK BRIDGE****Safety Inspection of A77 Ayr South V1 on 28 December 2017***No defects recorded***Safety Inspection of A77 Ayr South V1 on 04 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 11 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 18 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 25 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 01 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 February 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 15 February 2018**

SW82319984-235544946	878m	879m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/03/2018	Awaiting CCMS Temp Date	01/01/9999	A77 SB CW, 700M NTH OF DRUMBRO KENNELS
----------------------	------	------	-------------	-----------------------	-------	------------	-------------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 22 February 2018

SW82321955-235548236	690m	701m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	23/02/2018	AT ENTRANCE TO NEW WIND FARM NORTH OF DUMBRO KENNELS
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 01 March 2018*No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 March 2018**

SW82326075-235554320	1,641m	1,841m	CARRIAGEWAY	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
----------------------	--------	--------	-------------	--------------	-------	------------	-----------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 15 March 2018

SW82328086-235590004	478m	479m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 NB CW, OUTSIDE DRUMBRO KENNELS
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	------------------------------------

SW82328086-235590006	588m	590m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 SB CW, ON CL, DRUMBRO KENNELS
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	-----------------------------------

SW82328086-235590005	737m	737m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 SB CW, DRUMBRO KENNELS
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	----------------------------

SW82328086-235590007	350m	352m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 SB CW, STH OF DRUMBRO KENNELS
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	-----------------------------------

Safety Inspection of A77 Ayr South V1 on 22 March 2018*No defects recorded***11612/06 : B7044 Jct to Start of climbing lane****Safety Inspection of A77 Ayr South V1 on 28 December 2017***No defects recorded***Safety Inspection of A77 Ayr South V1 on 04 January 2018***No defects recorded***Safety Inspection of A77 Ayr South V1 on 11 January 2018**

SW82317471-235518218	498m	499m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2018	Completed Defects	08/02/2018	A77 SB CW, 50M NTH OF BALLANTRAE MEDICAL PRACTICE, BALLANTRAE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 18 January 2018

SW82317666-235521315	537m	540m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2018	Completed Defects	08/02/2018	A77 SB CW, OUTSIDE NO,16 MAIN ROAD BALLANTRAE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

SW82318129-235532269	742m	942m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/03/2018	Completed Defects	01/02/2018	A77 BALLANTRAE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	----------------

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

SW82319984-235544950	468m	469m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	15/02/2018	A77 SB CW, BALLANTRAE, OPP MEDICAL PRACTICE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

SW82319984-235544951	400m	402m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/03/2018	Completed Defects	15/02/2018	A77 SB CW, OPP SCOTMID, BALLANTRAE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	------------------------------------

Safety Inspection of A77 Ayr South V1 on 22 February 2018

SW82321955-235548235	731m	732m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/03/2018	Completed Defects	22/02/2018	POTHOLE LARGE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---------------

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

SW82326075-235554310	390m	394m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 NB CW, OUTSIDE SCOTMID, BALLANTRAE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

SW82326075-235554309	500m	501m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/04/2018	Completed Defects	08/03/2018	A77 SB CW, JCT SHORE ROAD, BALLANTRAE
----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---------------------------------------

Safety Inspection of A77 Ayr South V1 on 15 March 2018

SW82328086-235590024	467m	470m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 SB CW, OUTSIDE MEDICAL PRACTICE BALLANTRAE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

SW82328086-235590022	598m	600m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 BOTH CW, OUTSIDE GARDEN CENTER BALLANTRAE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

SW82328086-235590023	540m	545m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2018	Completed Defects	15/03/2018	A77 SB CW, OPP SHORE ROAD BALLANTRAE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--------------------------------------

Safety Inspection of A77 Ayr South V1 on 22 March 2018

SW82330474-235608102	468m	469m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/04/2018	Completed Defects	22/03/2018	A77 ON CL, BALLANTRAE, OUTSIDE MEDICAL PRACTICE
----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

SW82330474-235608103	604m	605m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/04/2018	Completed Defects	22/03/2018	A77 NB CW, 100M STH OF GARDEN CENTER BALLANTRAE
----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

SW82330474-235608104	571m	572m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/04/2018	Completed Defects	22/03/2018	A77 NB CW, 90M STH OF GARDEN CENTER, BALLANTRAE
----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

11612/66 : Start to End of NB climbing lane

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11612/80 : End of NB climbing lane to B734 Jct

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11614/05 : B734 Jct to end of SB climbing lane

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11614/08 : End of SB climbing lane to Bennane Jct

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded
Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

SW82326075-235554308	282m	283m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 1	05/04/2018	Awaiting CCMS Permanent	01/01/9999	A77 SB VERGE, 200M FROM END OF CLIMBING LANE BALLANTRAE
----------------------	------	------	---------------	-------------------	-------	------------	----------------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11614/15 : Bennane Jct to Little Bennane Jct

Safety Inspection of A77 Ayr South V1 on 28 December 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 04 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 11 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 18 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 25 January 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 February 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 March 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 March 2018

No defects recorded

11641/94 : Whitletts Roundabout

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

11641/07 : Holmston Rbt to start of 3 lane

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

11641/83 : Start of 3 Lane to Rbt approach

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

11641/88 : With: NB Entry to Whitletts Rbt

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

11641/89 : Against: SB Exit from Whitletts Rbt

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

11644/65 : Against: Sandyford Toll Rbt to start of 4 lane

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

SW82317767-235529088	874m	878m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/02/2018	Completed Defects	23/01/2018	A77 SB CW, LANE 1, AT FARM ENTRY 800M STH OF DUTCHHOUSE RBT
----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	---

Annual Detailed Inspection - Carriageways of A77 Ayr N Det

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

SW82321390-235546245	853m	855m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2018	Completed Defects	21/02/2018	A77 S/B LANE1 AT RAC PHONE BOX SOUTH OF SANDYFORD RBT
----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	---

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

11644/70 : Against: Start of 4 lane to Whitletts Rbt

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Annual Detailed Inspection - Carriageways of A77 Ayr N Det

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

SW82325502-235553037	74m	75m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	07/03/2018	A77 WHITLETTS RBT, SB ENTRANCE TO RBT
----------------------	-----	-----	-------------	-------------------	-------	------------	----------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

11638/20 : Bankhead Rbt to End of Climbing Lane

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

11638/60 : End of Climbing Lane to Start of 4 Lane Single

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

11638/80 : Start of Single 4-Lane to Holmston Roundabout

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded
Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018
No defects recorded
Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018
No defects recorded
Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018
No defects recorded
Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018
No defects recorded
Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018
No defects recorded