

## Annex A – Pothole Claims Received

Route	2013/2014	2014/2015	2015/2016	2016/2017	2017/2018
A1	0	0	2	0	4
A68	0	1	5	0	0
A6091/A7	0	0	0	1	1
A76	5	5	4	4	16
A78	15	10	5	6	28
A701	1	2	3	5	20
A702	0	0	4	1	8
A725	12	12	8	6	9
A726	2	0	2	0	2
A737	1	2	3	5	20
A82	63	71	89	44	315
A83	20	56	32	14	208
A84	16	11	8	4	24
A85	19	25	15	10	59
A86	5	7	7	1	8
A87	21	42	30	13	84
A828	2	3	0	0	39
A830	7	8	15	5	19
A835	1	5	2	3	13
A876	0	0	0	0	0
A887	1	3	6	1	7
A889	2	0	7	0	0
A898	1	1	4	2	0
A9	6	1	32	12	13
A90	37	18	86	31	87
A92	5	1	8	0	5
A972	0	0	0	0	0
A95	3	8	6	2	10
A96	4	4	13	2	12
A977	0	0	0	0	0
A985	0	2	2	4	1
A99	1	1	0	0	3

## Annex B – Unsuccessful Pothole Claims

Route	2013	2014	2015	2016	2017
A1		0	0	1	2
A68		1	2	2	3
A6091/A7		0	6	2	4
A76	3	11	11	13	7
A78	7	12	11	20	5
A701	2	9	20	3	1
A702		0	2	2	0
A725	4	15	3	3	2
A726	0	2	2	2	1
A737	0	3	5	9	5
A738	1	1	4	0	1
A751	1	1	0	0	0
A82	46	66	115	93	64
A83	13	49	73	35	51
A84	7	24	15	9	14
A85	16	40	38	19	19
A86	4	5	10	5	4
A87	12	28	68	26	9
A828	3	2	4	2	2
A830	1	9	17	12	10
A835	2	6	7	4	3
A876	0	0	0	0	0
A887	0	3	9	1	2
A889	2	2	6	2	0
A898	0	2	2	9	0
A9	48	52	77	30	32
A90	78	10	24	93	28
A92	31	2	2	7	1
A972	0	0	0	0	0
A95	3	1	8	9	2
A96	5	2	9	9	3
A977	0	0	0	0	0
A985	0	0	1	5	1
A99	2	0	4	0	0

\*Blank cells in the 2013 column are for the South East Routes where we do not hold this information.