

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/12/2009 and 31/03/2013, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: SLIP RD ON TO M8 WB',) Or

(Section is 'AGAINST: EB JCT 14 OFF SLIP TO OFF SLIP TO M80',) Or

(Section is 'WITH: WB M8 JCT 14 ON SLIP TO JCT 15 OFF SLIP',) Or

(Section is 'WITH: JCT 15 SLIP OFF M8 TO CASTLE ST',) Or

(Section is 'AGAINST: EB JCT 15 OFF SLIP TO ENTRY SLIP',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

14225/56 : AGAINST: EB JCT 14 OFF SLIP TO OFF SLIP TO M80

Safety Patrol of M8 Tannochside V1 on 04 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 July 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 July 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 July 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 July 2011

SW1326623-3478631	371m	371m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/07/2011	30/07/2011	M8 EB J14 TO J13
-------------------	------	------	-------------	-------------------	-------	------------	------------	------------------

Safety Patrol of M8 Tannochside V1 on 05 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 January 2012

SW829693-3984702

420m

420m

CARRIAGEWAY

Pothole
(POTH)

CAT 1

03/02/2012

07/01/2012

M8 E/B JCT14-13 LANE4
N/S/W/T @ BRIDGE JOINT
POTHOLE

Safety Patrol of M8 Tannochside V1 on 13 January 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 January 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 January 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 February 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 February 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 February 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 February 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 March 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 March 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 March 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 March 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 March 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 April 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 April 2012

Safety Patrol of M8 Tannochside V1 on 30 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 March 2013

No defects recorded

14225/60 : WITH: SLIP RD ON TO M8 WB

Safety Patrol of M8 Tannochside V1 on 04 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 December 2009

SW1416351-1253635	109m	109m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/01/2010	08/01/2010	M8 WB JCT 14 ON
-------------------	------	------	-------------	-------------------	-------	------------	------------	-----------------

Safety Patrol of M8 Tannochside V1 on 24 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 January 2010

SW1416684-1256604	121m	121m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/02/2010	16/01/2010	M8 W/B JCT 14 ON SLIP
-------------------	------	------	-------------	-------------------	-------	------------	------------	-----------------------

Safety Patrol of M8 Tannochside V1 on 22 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 April 2010

SW1418041-1407034	33m	33m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/05/2010	23/04/2010	M8 W/B JUNCTION 14 ON SLIP
-------------------	-----	-----	-------------	-------------------	-------	------------	------------	----------------------------

Safety Patrol of M8 Tannochside V1 on 30 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 July 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 July 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 July 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 December 2010

SW1522585-2714134 118m 118m CARRIAGEWAY Pothole
(POTH) CAT 1 07/01/2011 15/12/2010 M8 W/B JUNCTION 14 ON SLIP

Safety Patrol of M8 Tannochside V1 on 17 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 March 2011

SW1524002-2812024 117m 117m CARRIAGEWAY Pothole
(POTH) CAT 1 15/04/2011 19/03/2011 M8 W/B JUNCTION 14 ON SLIP

Safety Patrol of M8 Tannochside V1 on 25 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 April 2011

SW1524351-2855649 109m 109m CARRIAGEWAY Pothole
(POTH) CAT 1 06/05/2011 08/04/2011 M8 W/B JUNCTION 14 ON SLIP

Safety Patrol of M8 Tannochside V1 on 15 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 May 2011

SW1325182-3051338 115m 115m CARRIAGEWAY Pothole
CAT 1 24/06/2011 28/05/2011 M8 W/B JUNCTION 14 ON SLIP

(POTH)

Safety Patrol of M8 Tannochside V1 on 03 June 2011

SW1325336-3080422	99m	99m	CARRIAGEWAY	Pothole (POTH)	CAT 1	04/06/2011	03/06/2011	M8 W/B JUNCTION 14 ON SLIP
SW1325336-3080422	99m	99m	CARRIAGEWAY	Pothole (POTH)	CAT 1	04/06/2011	04/06/2011	M8 W/B JUNCTION 14 ON SLIP

Safety Patrol of M8 Tannochside V1 on 10 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 June 2011

SW1325783-3210432	96m	96m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/06/2011	25/06/2011	M8 W/B JUNCTION 14 ON SLIP
-------------------	-----	-----	-------------	-------------------	-------	------------	------------	----------------------------

Safety Patrol of M8 Tannochside V1 on 01 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 October 2011

SW828351-3751754	13m	13m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	22/10/2011	21/10/2011	M8 W/B ON SLIP FROM JCT14 BLOCHAIRN 1ST O/S GULLY
------------------	-----	-----	-------------	--	-------	------------	------------	--

Safety Patrol of M8 Tannochside V1 on 27 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 January 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 January 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 January 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 January 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 February 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 February 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 February 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 February 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 March 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 March 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 March 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 March 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 March 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 April 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 April 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 April 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 April 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 May 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 May 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 May 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 May 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 June 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 June 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 June 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 June 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 June 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 July 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 July 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 July 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 July 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 August 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 August 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 August 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 August 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 August 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 September 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 September 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 September 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 September 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 March 2013

No defects recorded

14230/05 : WITH: WB M8 JCT 14 ON SLIP TO JCT 15 OFF SLIP

Safety Patrol of M8 Tannochside V1 on 04 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 July 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 July 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 July 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 November 2011

No defects recorded
Safety Patrol of M8 Tannochside V1 on 18 November 2011

No defects recorded
Safety Patrol of M8 Tannochside V1 on 25 November 2011

No defects recorded
Safety Patrol of M8 Tannochside V1 on 02 December 2011

No defects recorded
Safety Patrol of M8 Tannochside V1 on 09 December 2011

No defects recorded
Safety Patrol of M8 Tannochside V1 on 16 December 2011

No defects recorded
Safety Patrol of M8 Tannochside V1 on 23 December 2011

No defects recorded
Safety Patrol of M8 Tannochside V1 on 30 December 2011

No defects recorded
Safety Patrol of M8 Tannochside V1 on 06 January 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 13 January 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 20 January 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 27 January 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 03 February 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 10 February 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 17 February 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 24 February 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 02 March 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 09 March 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 16 March 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 23 March 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 30 March 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 06 April 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 13 April 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 20 April 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 27 April 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 04 May 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 11 May 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 18 May 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 25 May 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 01 June 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 08 June 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 15 June 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 22 June 2012

SW832456-4264507	55m	1,800m	ROAD MARKINGS LONG	Wear (for example erosion) (WEAR)	CAT 1	06/07/2012	30/06/2012	M8 W/B JCT14 TO 16
------------------	-----	--------	-----------------------	--	-------	------------	------------	--------------------

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 June 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 July 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 July 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 July 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 July 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 August 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 August 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 August 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 August 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 August 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 September 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 September 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 September 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 September 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 February 2013

No defects recorded
Safety Patrol of M8 Tannochside V1 on 22 February 2013

No defects recorded
Safety Patrol of M8 Tannochside V1 on 01 March 2013

No defects recorded
Safety Patrol of M8 Tannochside V1 on 08 March 2013

No defects recorded
Safety Patrol of M8 Tannochside V1 on 15 March 2013

No defects recorded
Safety Patrol of M8 Tannochside V1 on 22 March 2013

No defects recorded
Safety Patrol of M8 Tannochside V1 on 28 March 2013

No defects recorded

14235/06 : AGAINST: EB JCT 15 OFF SLIP TO ENTRY SLIP

Safety Patrol of M8 Tannochside V1 on 04 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 December 2009

SW1416197-1192223	232m	232m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/01/2010	16/12/2009	M8 EB J15 KIRKI OFF TO STIRLING ROAD ON
-------------------	------	------	-------------	-------------------	-------	------------	------------	--

Safety Patrol of M8 Tannochside V1 on 18 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 March 2010

SW1417328-1365148	504m	504m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/04/2010	06/03/2010	M8 E/B JCT 15 OFF TO ON
-------------------	------	------	-------------	-------------------	-------	------------	------------	-------------------------

Safety Patrol of M8 Tannochside V1 on 12 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 May 2010

No defects recorded
Safety Patrol of M8 Tannochside V1 on 21 May 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 28 May 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 04 June 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 11 June 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 18 June 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 25 June 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 02 July 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 23 July 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 30 July 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 06 August 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 13 August 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 20 August 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 27 August 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 03 September 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 10 September 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 17 September 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 24 September 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 01 October 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 08 October 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 15 October 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 22 October 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 29 October 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 05 November 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 12 November 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 19 November 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 26 November 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 03 December 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 10 December 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 17 December 2010
SW1522660-2714889 131m 131m CARRIAGEWAY Pothole
(POTH) CAT 1 14/01/2011 12/01/2011 M8 E/B JUNCTION 15 OFF TO
ON

Safety Patrol of M8 Tannochside V1 on 24 December 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 31 December 2010
No defects recorded
Safety Patrol of M8 Tannochside V1 on 07 January 2011
No defects recorded
Safety Patrol of M8 Tannochside V1 on 14 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 January 2011

SW1523092-2718415	226m	226m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/02/2011	25/01/2011	M8 E/B JUNCTION 15 OFF TO ON
-------------------	------	------	-------------	----------------	-------	------------	------------	------------------------------

Safety Patrol of M8 Tannochside V1 on 28 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 February 2011

SW1523303-2743286	144m	144m	CARRIAGEWAY	Pothole (POTH)	CAT 1	04/03/2011	04/02/2011	M8 E/B JUNCTION 15 OFF TO ON
-------------------	------	------	-------------	----------------	-------	------------	------------	------------------------------

Safety Patrol of M8 Tannochside V1 on 11 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 March 2011

SW1523798-2789146	512m	512m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/04/2011	05/03/2011	M8 E/B JUNCTION 15 OFF TO ON
-------------------	------	------	-------------	----------------	-------	------------	------------	------------------------------

Safety Patrol of M8 Tannochside V1 on 11 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 March 2011

SW1524095-2815804	518m	518m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/04/2011	29/03/2011	M8 E/B JUNCTION 15 OFF TO ON
-------------------	------	------	-------------	----------------	-------	------------	------------	------------------------------

Safety Patrol of M8 Tannochside V1 on 01 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 June 2011

SW1325783-3210431	450m	450m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/06/2011	25/06/2011	M8 E/B JUNCTION 15 OFF TO ON
-------------------	------	------	-------------	----------------	-------	------------	------------	------------------------------

Safety Patrol of M8 Tannochside V1 on 01 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 December 2011

SW829381-3954759	50m	50m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	17/12/2011	16/12/2011	M8 E/B JCT15 OFF TO ON POTHOLE @ N/S GULLY ON BEND
------------------	-----	-----	-------------	--	-------	------------	------------	--

Safety Patrol of M8 Tannochside V1 on 23 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 January 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 January 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 January 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 January 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 February 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 February 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 February 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 February 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 March 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 March 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 March 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 March 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 March 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 April 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 April 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 April 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 April 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 May 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 May 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 May 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 May 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 June 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 June 2012

SW832456-4264508	0m	622m	ROAD MARKINGS LONG	Wear (for example erosion) (WEAR)	CAT 1	06/07/2012	25/06/2012	M8 E/B JCT15 TO JCT14
------------------	----	------	-----------------------	--	-------	------------	------------	-----------------------

Safety Patrol of M8 Tannochside V1 on 15 June 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 June 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 June 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 July 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 July 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 July 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 July 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 August 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 August 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 August 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 August 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 August 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 September 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 September 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 September 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 September 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 March 2013

No defects recorded

14235/10 : WITH: JCT 15 SLIP OFF M8 TO CASTLE ST

Safety Patrol of M8 Tannochside V1 on 04 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 December 2009

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 January 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 February 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 March 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 April 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 May 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 June 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 July 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 July 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 July 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 August 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 September 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 October 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 November 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 December 2010

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 January 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 February 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 March 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 April 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 May 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 June 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 July 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 August 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 September 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 October 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 November 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 December 2011

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 January 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 January 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 January 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 January 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 February 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 10 February 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 17 February 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 24 February 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 02 March 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 09 March 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 16 March 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 23 March 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 30 March 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 06 April 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 13 April 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 20 April 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 27 April 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 04 May 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 11 May 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 18 May 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 25 May 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 01 June 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 08 June 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 15 June 2012

SW832581-4278020 50m 50m TRAFFIC SIGNS Missing (MISS) CAT 1 13/07/2012 29/06/2012 M8 W/B JCT 15 OFF SLIP TO CASTLE ST

Safety Patrol of M8 Tannochside V1 on 22 June 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 29 June 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 06 July 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 13 July 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 20 July 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 27 July 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 03 August 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 10 August 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 17 August 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 24 August 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 31 August 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 07 September 2012

No defects recorded
Safety Patrol of M8 Tannochside V1 on 14 September 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 September 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 September 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 October 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 November 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 December 2012

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 January 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 February 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 March 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 March 2013

No defects recorded

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/04/2013 and 23/02/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: SLIP RD ON TO M8 WB',) Or

(Section is 'AGAINST: EB JCT 14 OFF SLIP TO OFF SLIP TO M80',) Or

(Section is 'WITH: WB M8 JCT 14 ON SLIP TO JCT 15 OFF SLIP',) Or

(Section is 'WITH: JCT 15 SLIP OFF M8 TO CASTLE ST',) Or

(Section is 'AGAINST: EB JCT 15 OFF SLIP TO ENTRY SLIP',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

14225/56 : AGAINST: EB JCT 14 OFF SLIP TO OFF SLIP TO M80

Safety Inspection of M8 Tannochside V1 on 09 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 April 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 April 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 April 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 February 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 February 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 February 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 March 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014

SW3815299-348	0m	500m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	lane 1
SW3815299-349	750m	980m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	lane 3
SW3815299-348	0m	500m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Jobs	01/01/9999	lane 1
SW3815299-349	750m	980m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Jobs	01/01/9999	lane 3

Safety Patrol of M8 Tannochside V1 on 28 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 May 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 June 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 June 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 June 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 June 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 June 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 June 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 June 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 June 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 July 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 July 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 July 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 July 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 July 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 July 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 July 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 July 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 July 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 August 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 August 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 August 2014

SW862735-653314	304m	304m	STRUCTURE	Pothole around Expansion Joint (PEXP)	CAT 1	16/09/2014	Completed Defects	21/01/2015	M8 EB J14 TO J13, BRIDGE OVER J14, LANE 4 OF 5 NSWT
-----------------	------	------	-----------	---	-------	------------	----------------------	------------	--

Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 August 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 September 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 09 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 September 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 November 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 November 2014

No defects recorded

Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8370461-124	364m	364m	SAFETY_FENCE	Other (OTHR)	CAT 2	08/01/2015	Cat 2 Awaiting Action	01/01/9999
---------------	------	------	--------------	--------------	-------	------------	-----------------------	------------

Safety Inspection of M8 Tannochside V1 on 11 November 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 November 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 November 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 November 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 November 2014

SW8572073-779572	292m	292m	STRUCTURE	Pothole around Expansion Joint (PEXP)	CAT 1	23/12/2014	Completed Defects	29/04/2015	M8 EB J14 TO J13
SW8572073-779573	318m	320m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/12/2014	Completed Defects	20/12/2014	M8 EB BRIDGE OVER J14

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 November 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 July 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 July 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 July 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 July 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 July 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 July 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 July 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 July 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 August 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 August 2015

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 August 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 August 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 October 2015

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 February 2016

SW77137326-1703916	33m	39m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 1	22/03/2016	Completed Defects	23/03/2016	M8 EB JCT 14 OFF SLIP
--------------------	-----	-----	---------------	-------------------	-------	------------	----------------------	------------	-----------------------

Safety Patrol of M8 Tannochside V1 on 27 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 June 2016*No defects recorded***Safety Patrol of M8 Tannochside V1 on 02 July 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 05 July 2016***No defects recorded***Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016**

SW80143086-199	603m	630m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-195	414m	470m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-196	505m	555m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-190	186m	186m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-193	397m	450m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-189	98m	110m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-203	899m	930m	CARRIAGEWAY	Surface crazing (SRCZ)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-205	964m	988m	CARRIAGEWAY	Surface crazing (SRCZ)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-201	743m	3m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-194	410m	490m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-197	543m	583m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-191	323m	360m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-192	321m	370m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-198	594m	594m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-200	686m	715m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-202	868m	900m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-204	928m	960m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999

Safety Patrol of M8 Tannochside V1 on 09 July 2016*No defects recorded***Safety Inspection of M8 Tannochside V1 on 12 July 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 16 July 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 19 July 2016***No defects recorded*

Safety Patrol of M8 Tannochside V1 on 23 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 July 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 September 2016

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016

SW86182611-11	191m	201m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86182611-9	730m	735m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86182611-10	338m	343m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999

Safety Patrol of M8 Tannochside V1 on 24 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 October 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 October 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 October 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 October 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 November 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 November 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 November 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 November 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 November 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 November 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 November 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 November 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 November 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 December 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 December 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 December 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 December 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 December 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 December 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 December 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 December 2016

No defects recorded

Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016

SW83-143364-84	664m	664m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 14 OFF TO M80 ON
SW83-143364-83	515m	515m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 14 TO M80 @ SOS 699E
SW83-143364-85	689m	689m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB HARD SHOULDER AT OVERBRIDGE BEFORE M80

Safety Inspection of M8 Tannochside V1 on 30 December 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 December 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 January 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 January 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 January 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 January 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 May 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 May 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 May 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 May 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 June 2017

No defects recorded
Safety Inspection of M8 Tannochside V1 on 06 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 June 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 June 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 June 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 August 2017

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017

SW77-257611-66	547m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 E/B JCT 14 TO JCT 13 5 SQ METERS
SW77-257611-65	509m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 E/B JCT 14 TO 13

Safety Patrol of M8 Tannochside V1 on 05 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 September 2017

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017

SW86-284656-8	786m	796m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
---------------	------	------	----------	-------------------------	-------	------------	-----------------------	------------	--

SW86-284656-7

397m

417m

WOODLAND

Invasive
species (INVS)

CAT 2

01/01/9999

Cat 2 Awaiting
Action

01/01/9999

Safety Patrol of M8 Tannochside V1 on 09 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 February 2018

No defects recorded

14225/60 : WITH: SLIP RD ON TO M8 WB

Safety Inspection of M8 Tannochside V1 on 09 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 April 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 April 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 April 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 February 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 February 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 February 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 March 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014

SW3815299-286	0m	50m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	lane 1-2
SW3815299-284	0m	550m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	lane 1
SW3815299-285	0m	550m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	lane 2

Safety Patrol of M8 Tannochside V1 on 28 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 May 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 June 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 June 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 June 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 June 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 June 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 June 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 June 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 June 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 July 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 July 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 July 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 July 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 July 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 July 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 July 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 July 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 July 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 August 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 August 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 August 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 August 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 September 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 November 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 November 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 November 2014

No defects recorded

Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8370461-123	390m	390m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	08/01/2015	Completed Defects	03/08/2015
---------------	------	------	--------------	---	-------	------------	----------------------	------------

Safety Patrol of M8 Tannochside V1 on 14 November 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 November 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 November 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 November 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 November 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 July 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 July 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 July 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 July 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 July 2015*No defects recorded***Safety Inspection of M8 Tannochside V1 on 21 July 2015***No defects recorded***Safety Patrol of M8 Tannochside V1 on 25 July 2015***No defects recorded***Safety Inspection of M8 Tannochside V1 on 28 July 2015***No defects recorded***Safety Patrol of M8 Tannochside V1 on 01 August 2015***No defects recorded***Safety Inspection of M8 Tannochside V1 on 04 August 2015***No defects recorded***Safety Patrol of M8 Tannochside V1 on 08 August 2015***No defects recorded***Safety Inspection of M8 Tannochside V1 on 11 August 2015***No defects recorded***Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015**

SW8585886-41	37m	81m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 14 ONSLIP
SW8585886-39	9m	110m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 14 ONSLIP
SW8585886-43	75m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 14 ONSLIP
SW8585886-45	126m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 14 ONSLIP
SW8585886-46	128m	228m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 14 ONSLIP
SW8085886-35	282m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	@ STEWART PLANT
SW8085886-37	305m	0m	ROAD_STUDS	Damaged "catseye" (DAMC)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	STEWART PLANT
SW8585886-40	13m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 14 ONSLIP
SW8585886-44	104m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 14 ONSLIP
SW8085886-34	102m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	@ START OFF ON SLIP
SW8085886-36	282m	0m	ROAD_STUDS	Damaged "catseye" (DAMC)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	@ STEWART PLANT
SW8585886-42	34m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 14 ONSLIP

Safety Patrol of M8 Tannochside V1 on 15 August 2015*No defects recorded***Safety Inspection of M8 Tannochside V1 on 18 August 2015***No defects recorded***Safety Patrol of M8 Tannochside V1 on 22 August 2015***No defects recorded***Safety Inspection of M8 Tannochside V1 on 25 August 2015***No defects recorded*

Safety Patrol of M8 Tannochside V1 on 29 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 October 2015

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 July 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 July 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 July 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 July 2016

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016

SW80143086-225	24m	74m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-227	480m	530m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999

SW80143086-226 244m 294m CARRIAGEWAY Bituminous surfacing fretting (BFRT) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999

Safety Patrol of M8 Tannochside V1 on 30 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 September 2016

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 October 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 October 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 October 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 October 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 November 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 November 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 November 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 November 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 November 2016*No defects recorded***Safety Patrol of M8 Tannochside V1 on 19 November 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 22 November 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 26 November 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 29 November 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 03 December 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 06 December 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 10 December 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 13 December 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 17 December 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 20 December 2016***No defects recorded***Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016**

SW83-143364-30	77m	77m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 14 ON @ BOTTOM
SW83-143364-28	106m	106m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	23/12/2016	Completed Defects	09/11/2017	M8 WB JCT 14 ON
SW83-143364-26	220m	220m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 14 ON
SW83-143364-142	190m	190m	SAFETY_FENCE	Safety fence - too high (SBTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 14 ON
SW83-143364-29	101m	101m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 14 ON @ OVERBRIDGE
SW83-143364-27	163m	163m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 14 ON
SW83-143364-143	474m	474m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB GANTRY AFTER 14 ON

Safety Inspection of M8 Tannochside V1 on 23 December 2016*No defects recorded***Safety Patrol of M8 Tannochside V1 on 25 December 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 30 December 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 31 December 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 06 January 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 07 January 2017***No defects recorded***Safety Inspection of M8 Tannochside V1 on 10 January 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 14 January 2017***No defects recorded***Safety Inspection of M8 Tannochside V1 on 17 January 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 21 January 2017***No defects recorded***Safety Inspection of M8 Tannochside V1 on 24 January 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 28 January 2017***No defects recorded*

Safety Inspection of M8 Tannochside V1 on 31 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 May 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 May 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 May 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 May 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 June 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 June 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 June 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 June 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 August 2017

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017

SW77-257611-84	83m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 W/B JCT 14 ON SLIP
----------------	-----	----	-------------	--	-------	------------	--------------------------	------------	-----------------------

Safety Patrol of M8 Tannochside V1 on 05 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 September 2017

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017

SW86-284656-32	366m	376m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
----------------	------	------	----------	----------------------------	-------	------------	--------------------------	------------	--

Safety Patrol of M8 Tannochside V1 on 09 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 February 2018

SW85-321388-235545864	27m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2018	Awaiting CCMS Permanent	01/01/9999	M8 WB JCT 14 ONSLIP NS WT
-----------------------	-----	----	-------------	-------------------	-------	------------	----------------------------	------------	---------------------------

14230/05 : WITH: WB M8 JCT 14 ON SLIP TO JCT 15 OFF SLIP

Safety Inspection of M8 Tannochside V1 on 09 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 April 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 April 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 April 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 February 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 February 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 February 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 March 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 May 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 May 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 03 June 2014

No defects recorded
Safety Patrol of M8 Tannochside V1 on 06 June 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 10 June 2014

No defects recorded
Safety Patrol of M8 Tannochside V1 on 13 June 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 17 June 2014

No defects recorded
Safety Patrol of M8 Tannochside V1 on 20 June 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 24 June 2014

No defects recorded
Safety Patrol of M8 Tannochside V1 on 27 June 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 01 July 2014

No defects recorded
Safety Patrol of M8 Tannochside V1 on 04 July 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 08 July 2014

No defects recorded
Safety Patrol of M8 Tannochside V1 on 11 July 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 15 July 2014

No defects recorded
Safety Patrol of M8 Tannochside V1 on 18 July 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 22 July 2014

No defects recorded
Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014

SW5562071-10	0m	0m	INVASIVE_SPECIE	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
--------------	----	----	-----------------	-------------------------	-------	------------	-----------------------	------------

No defects recorded
Safety Patrol of M8 Tannochside V1 on 25 July 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 29 July 2014

No defects recorded
Safety Patrol of M8 Tannochside V1 on 01 August 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 05 August 2014

No defects recorded
Safety Patrol of M8 Tannochside V1 on 08 August 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 12 August 2014

No defects recorded
Safety Patrol of M8 Tannochside V1 on 15 August 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 19 August 2014

No defects recorded
Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014

No defects recorded
Safety Patrol of M8 Tannochside V1 on 22 August 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 26 August 2014

No defects recorded
Safety Patrol of M8 Tannochside V1 on 29 August 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 02 September 2014

No defects recorded
Safety Patrol of M8 Tannochside V1 on 05 September 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 09 September 2014

No defects recorded
Safety Patrol of M8 Tannochside V1 on 12 September 2014

No defects recorded
Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014

No defects recorded
Safety Inspection of M8 Tannochside V1 on 16 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 November 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 November 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 November 2014

No defects recorded

Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8370461-117	555m	555m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTF)	CAT 2	08/01/2015	Cat 2 Awaiting Action	01/01/9999	HOLES IN BEAM CODE RED CORRTION FULL LENGTH OF BEAM
SW8370461-119	359m	359m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	

Safety Patrol of M8 Tannochside V1 on 14 November 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 November 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 November 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 November 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 November 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 July 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 July 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 July 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 July 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 July 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 July 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 July 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 July 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 August 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 August 2015

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015

SW8085886-39	22m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	@ START OF H/S
SW8085886-41	213m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	@ GANTRY FOR 40M
SW8085886-43	0m	0m	GULLY	Silted (SILT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	?
SW8085886-42	367m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	15 PRIOR TO GANTRY
SW8085886-40	113m	0m	ROAD_STUDS	Damaged "catseye" (DAMC)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	@ TELE BOX 704W
SW8085886-38	13m	0m	ROAD_STUDS	Damaged "catseye" (DAMC)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	LANE1

Safety Patrol of M8 Tannochside V1 on 15 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 August 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 August 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 October 2015

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 July 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 July 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 July 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 July 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 July 2016

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 September 2016

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016

SW86182611-33	416m	426m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
---------------	------	------	----------	-------------------------	-------	------------	-----------------------	------------

Safety Patrol of M8 Tannochside V1 on 24 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 October 2016*No defects recorded***Safety Inspection of M8 Tannochside V1 on 04 October 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 08 October 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 11 October 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 15 October 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 18 October 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 22 October 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 25 October 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 29 October 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 01 November 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 05 November 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 08 November 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 12 November 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 15 November 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 19 November 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 22 November 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 26 November 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 29 November 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 03 December 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 06 December 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 10 December 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 13 December 2016**

SW80221192-2378762	479m	479m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	10/01/2017	Awaiting CCMS Permanent	04/01/2017	M8 W/B J14 TO J15 @FOOTBRIDGE SOS BOX 709W
--------------------	------	------	-----------	-----------------------------------	-------	------------	----------------------------	------------	--

Safety Patrol of M8 Tannochside V1 on 17 December 2016*No defects recorded***Safety Inspection of M8 Tannochside V1 on 20 December 2016***No defects recorded***Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016**

SW83-143364-31	521m	521m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB START HIS @ 15 OFF
SW83-143364-145	419m	419m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	02/04/2017	Completed Defects	02/04/2017	M8 WB 14 TO 15 2ND GANTRY TO FOOTBRIDGE
SW83-143364-144	346m	346m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	AT 2ND GANTRY

Safety Inspection of M8 Tannochside V1 on 23 December 2016*No defects recorded***Safety Patrol of M8 Tannochside V1 on 25 December 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 30 December 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 31 December 2016**

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 January 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 January 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 January 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 January 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 May 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 May 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 May 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 May 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 June 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 June 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 June 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 June 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 August 2017

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017

SW77-257611-78	112m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 W/B JCT 14 TO JCT 15
SW85-257611-12	55m	155m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW77-257611-77	93m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 W/ JCT 14 TO JCT 15

SW85-257611-11	56m	156m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 14 OFFSLIP TO 15 OFF
----------------	-----	------	-------------	--------------------------------------	-------	------------	-----------------------	------------	--------------------------------

Safety Patrol of M8 Tannochside V1 on 05 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 September 2017

SW85-289118-235368033	574m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/10/2017	Completed Defects	16/11/2017	M8 WB JCT 14 ONSLIP -JCT 15 OFFSLIP 30M PAST HM 213 LANE 1 OS WT ON CENTRE LINE
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	---

Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017

SW86-284656-33	361m	371m	WOODLAND	Injurious weeds (IWED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
----------------	------	------	----------	------------------------	-------	------------	-----------------------	------------	--

SW86-284656-34	546m	566m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
----------------	------	------	----------	-------------------------	-------	------------	-----------------------	------------	--

Safety Patrol of M8 Tannochside V1 on 09 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 February 2018

No defects recorded

14235/06 : AGAINST: EB JCT 15 OFF SLIP TO ENTRY SLIP

Safety Inspection of M8 Tannochside V1 on 09 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 April 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 April 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 April 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 August 2013

SW222155-104441	217m	217m	GULLY	Rocking under load (IRLD)	CAT 1	28/08/2013	Completed Defects	30/10/2013	M8 E/B JCT15 OFF-ON 6TH N/S GULLY
-----------------	------	------	-------	---------------------------	-------	------------	-------------------	------------	-----------------------------------

Safety Patrol of M8 Tannochside V1 on 30 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 February 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 February 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 February 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 March 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014

SW3815299-341	0m	620m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	lane 3
SW3815299-342	0m	620m	ROAD_MARKINGS	Wear (for	CAT 2	01/01/9999	Cat 2 Awaiting	01/01/9999	lane 1

			<i>_LONG</i>	<i>example erosion (WEAR) (SRJT)</i>				<i>Action</i>		
SW3815299-343	145m	148m	CARRIAGEWAY	Surfacing joints (SRJT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	lane 1-2	

Safety Patrol of M8 Tannochside V1 on 28 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 May 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 May 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 June 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 June 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 June 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 June 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 June 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 June 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 June 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 June 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 July 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 July 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 July 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 July 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 July 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 July 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 July 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 July 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 July 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 August 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 August 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 August 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 August 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 September 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 October 2014*No defects recorded***Safety Patrol of M8 Tannochside V1 on 31 October 2014***No defects recorded***Safety Inspection of M8 Tannochside V1 on 04 November 2014***No defects recorded***Safety Patrol of M8 Tannochside V1 on 07 November 2014***No defects recorded***Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014**

SW8370461-115	620m	620m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW8370461-113	428m	0m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW8370461-112	402m	402m	SAFETY_FENCE	Other (OTHR)	CAT 2	08/01/2015	Cat 2 Awaiting Action	01/01/9999	SURFACE MOUNTS WERE ON SLEAVES
SW8370461-114	558m	558m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	

Safety Inspection of M8 Tannochside V1 on 11 November 2014

SW1571891-760965	56m	56m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/12/2014	Awaiting CCMS Permanent	09/12/2014	M8 EB MAIN C/W, JUNCTION 15 E/B TO SPRINGBURN, LANE 3 O/S NEXT TO KERB, 10M PRIOR TO SOS BOX 715E
------------------	-----	-----	-------------	----------------	-------	------------	-------------------------	------------	---

Safety Patrol of M8 Tannochside V1 on 14 November 2014*No defects recorded***Safety Inspection of M8 Tannochside V1 on 18 November 2014***No defects recorded***Safety Patrol of M8 Tannochside V1 on 21 November 2014***No defects recorded***Safety Inspection of M8 Tannochside V1 on 25 November 2014***No defects recorded***Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014**

SW8062946-1	250m	310m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
-------------	------	------	-------------	--------------------------------------	-------	------------	-----------------------	------------	--

Safety Patrol of M8 Tannochside V1 on 28 November 2014*No defects recorded***Safety Inspection of M8 Tannochside V1 on 02 December 2014***No defects recorded***Safety Patrol of M8 Tannochside V1 on 05 December 2014***No defects recorded***Safety Inspection of M8 Tannochside V1 on 09 December 2014***No defects recorded***Safety Patrol of M8 Tannochside V1 on 12 December 2014***No defects recorded***Safety Inspection of M8 Tannochside V1 on 16 December 2014***No defects recorded***Safety Patrol of M8 Tannochside V1 on 19 December 2014***No defects recorded***Safety Patrol of M8 Tannochside V1 on 20 December 2014***No defects recorded***Safety Inspection of M8 Tannochside V1 on 23 December 2014***No defects recorded***Safety Inspection of M8 Tannochside V1 on 30 December 2014***No defects recorded***Safety Patrol of M8 Tannochside V1 on 03 January 2015***No defects recorded***Safety Inspection of M8 Tannochside V1 on 06 January 2015***No defects recorded***Safety Patrol of M8 Tannochside V1 on 09 January 2015***No defects recorded***Safety Patrol of M8 Tannochside V1 on 09 January 2015***No defects recorded***Safety Patrol of M8 Tannochside V1 on 10 January 2015***No defects recorded*

Safety Inspection of M8 Tannochside V1 on 13 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 February 2015

SW8076910-878702	197m	197m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/03/2015	Completed Defects	24/02/2015	M8 EB JCT 17-15. 1ST POTHOLE - 20M AFTER TELE BOX 730E. 2ND POTHOLE 40M AFTER TELE BOX 730E
------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	--

Safety Patrol of M8 Tannochside V1 on 28 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 March 2015

SW5578554-880682	228m	228m	CARRIAGEWAY	Pothole (POTH)	CAT 1	31/03/2015	Completed Defects	03/03/2015	M8 EB JCT 15-14 N/S LANE N/S/W/T
------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	-------------------------------------

Safety Patrol of M8 Tannochside V1 on 07 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 April 2015

No defects recorded
Safety Inspection of M8 Tannochside V1 on 28 April 2015
No defects recorded
Safety Patrol of M8 Tannochside V1 on 02 May 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 05 May 2015
No defects recorded
Safety Patrol of M8 Tannochside V1 on 09 May 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 11 May 2015
No defects recorded
Safety Patrol of M8 Tannochside V1 on 16 May 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 19 May 2015
No defects recorded
Safety Patrol of M8 Tannochside V1 on 23 May 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 26 May 2015
No defects recorded
Safety Patrol of M8 Tannochside V1 on 30 May 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 06 January 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 02 June 2015
No defects recorded
Safety Patrol of M8 Tannochside V1 on 06 June 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 08 June 2015
No defects recorded
Safety Patrol of M8 Tannochside V1 on 13 June 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 16 June 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 18 June 2015
No defects recorded
Safety Patrol of M8 Tannochside V1 on 20 June 2015
No defects recorded
Safety Patrol of M8 Tannochside V1 on 27 June 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 30 June 2015
No defects recorded
Safety Patrol of M8 Tannochside V1 on 04 July 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 07 July 2015
No defects recorded
Safety Patrol of M8 Tannochside V1 on 11 July 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 14 July 2015
No defects recorded
Safety Patrol of M8 Tannochside V1 on 18 July 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 21 July 2015
No defects recorded
Safety Patrol of M8 Tannochside V1 on 25 July 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 28 July 2015
No defects recorded
Safety Patrol of M8 Tannochside V1 on 01 August 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 04 August 2015
No defects recorded
Safety Patrol of M8 Tannochside V1 on 08 August 2015
No defects recorded
Safety Inspection of M8 Tannochside V1 on 11 August 2015
No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015
SW8085886-26 358m 0m CARRIAGEWAY Pothole CAT 2 01/01/9999 Cat 2 Awaiting 01/01/9999 ON SLIP FROM C/STREET

Safety Patrol of M8 Tannochside V1 on 15 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 August 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 August 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 October 2015

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 March 2016

SW77142266-1740513	13m	13m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2016	Completed Defects	23/07/2016	M8 EB ADJACENT TO JCT 15 OFF SLIP, O/S LANE,RIGHT EDGE
--------------------	-----	-----	-------------	-------------------	-------	------------	----------------------	------------	--

Safety Patrol of M8 Tannochside V1 on 19 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 June 2016

SW77164594-2009111	290m	292m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/07/2016	Completed Defects	13/07/2016	M8 WB JCT 15 ADJACENT TO LOOP, O/S LANE
--------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of M8 Tannochside V1 on 18 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 July 2016

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016

SW80143086-345	94m	114m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW80143086-342	37m	37m	CARRIAGEWAY	Pothole	CAT 2	01/01/9999	Cat 2 Awaiting	01/01/9999	

				(POTH)				Action
SW80143086-343	62m	72m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-346	177m	200m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-344	65m	80m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999

Safety Patrol of M8 Tannochside V1 on 09 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 July 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 July 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 July 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 July 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 August 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 August 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 September 2016

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 October 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 October 2016

<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 15 October 2016									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 18 October 2016									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 22 October 2016									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 25 October 2016									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 29 October 2016									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 01 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 05 November 2016									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 08 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 12 November 2016									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 15 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 19 November 2016									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 22 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 26 November 2016									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 29 November 2016									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 03 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 06 December 2016									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 10 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 13 December 2016									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 17 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 20 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 23 December 2016									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 25 December 2016									
<i>No defects recorded</i>									
Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 30 December 2016									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 31 December 2016									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 06 January 2017									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 07 January 2017									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 10 January 2017									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 14 January 2017									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 17 January 2017									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 21 January 2017									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 24 January 2017									
SW77238668-235040632	142m	142m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/01/2017	Completed Defects	24/01/2017	M8 EB JCT 15 OFF TO 15 ON, LANE 2 O/S/W/T
Safety Patrol of M8 Tannochside V1 on 28 January 2017									

No defects recorded
Safety Inspection of M8 Tannochside V1 on 31 January 2017
No defects recorded
Safety Patrol of M8 Tannochside V1 on 04 February 2017
No defects recorded
Safety Inspection of M8 Tannochside V1 on 07 February 2017
No defects recorded
Safety Patrol of M8 Tannochside V1 on 11 February 2017
No defects recorded
Safety Inspection of M8 Tannochside V1 on 14 February 2017
No defects recorded
Safety Patrol of M8 Tannochside V1 on 18 February 2017
No defects recorded
Safety Inspection of M8 Tannochside V1 on 21 February 2017
No defects recorded
Safety Patrol of M8 Tannochside V1 on 25 February 2017
No defects recorded
Safety Inspection of M8 Tannochside V1 on 28 February 2017
No defects recorded
Safety Patrol of M8 Tannochside V1 on 04 March 2017
No defects recorded
Safety Inspection of M8 Tannochside V1 on 07 March 2017
No defects recorded
Safety Patrol of M8 Tannochside V1 on 11 March 2017
No defects recorded
Safety Inspection of M8 Tannochside V1 on 14 March 2017
No defects recorded
Safety Patrol of M8 Tannochside V1 on 18 March 2017
No defects recorded
Safety Inspection of M8 Tannochside V1 on 21 March 2017
No defects recorded
Safety Patrol of M8 Tannochside V1 on 25 March 2017
No defects recorded
Safety Inspection of M8 Tannochside V1 on 28 March 2017
No defects recorded
Safety Patrol of M8 Tannochside V1 on 01 April 2017
No defects recorded
Safety Inspection of M8 Tannochside V1 on 04 April 2017
No defects recorded
Safety Patrol of M8 Tannochside V1 on 08 April 2017
No defects recorded
Safety Inspection of M8 Tannochside V1 on 11 April 2017
No defects recorded
Safety Patrol of M8 Tannochside V1 on 15 April 2017
No defects recorded
Safety Inspection of M8 Tannochside V1 on 18 April 2017
No defects recorded
Safety Patrol of M8 Tannochside V1 on 22 April 2017
No defects recorded
Safety Inspection of M8 Tannochside V1 on 25 April 2017
No defects recorded
Safety Patrol of M8 Tannochside V1 on 29 April 2017
No defects recorded
Safety Inspection of M8 Tannochside V1 on 02 May 2017
No defects recorded
Safety Patrol of M8 Tannochside V1 on 06 May 2017
No defects recorded
Safety Inspection of M8 Tannochside V1 on 09 May 2017
No defects recorded
Safety Patrol of M8 Tannochside V1 on 13 May 2017
No defects recorded
Safety Inspection of M8 Tannochside V1 on 16 May 2017

SW85-273030-235160275	382m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/06/2017	Completed Defects	10/06/2017	M8 EB JCT 15-14 LANE 3 NS WT
SW85-273030-235160277	436m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/06/2017	Completed Defects	10/06/2017	M8 EB JCT 15-14 LANE 2

Safety Patrol of M8 Tannochside V1 on 20 May 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 May 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 June 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 June 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 June 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 June 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 June 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 July 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 July 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 August 2017

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 September 2017

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017

SW86-284656-5

177m

197m

WOODLAND

Invasive

CAT 2

01/01/9999

Cat 2 Awaiting

01/01/9999

species (INVS)

Action

Safety Patrol of M8 Tannochside V1 on 09 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 February 2018

No defects recorded

14235/10 : WITH: JCT 15 SLIP OFF M8 TO CASTLE ST

Safety Inspection of M8 Tannochside V1 on 09 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 April 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 April 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 April 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 April 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 May 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 May 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 June 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 June 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 July 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 July 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 August 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 August 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 September 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 September 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 October 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 October 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 November 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 November 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 December 2013

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 December 2013

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 January 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 January 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 February 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 February 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 February 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 February 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 March 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 March 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014

SW3815299-279	0m	350m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	lane 1
SW3815299-281	300m	350m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	26/08/2015	lane 1-2
SW3815299-281	300m	350m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	26/08/2015	lane 1-2
SW3815299-280	0m	350m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	lane 2

Safety Patrol of M8 Tannochside V1 on 28 March 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 April 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 April 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 May 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 May 2014

<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 09 May 2014									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 13 May 2014									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 16 May 2014									
<i>No defects recorded</i>									
Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 20 May 2014									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 23 May 2014									
SW861010-539920	191m	191m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/06/2014	Completed Defects	20/06/2014	M8 WB J15 AT TOP OF CASTLE ST OFF SLIP, NS + OS WT
Safety Inspection of M8 Tannochside V1 on 27 May 2014									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 30 May 2014									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 03 June 2014									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 06 June 2014									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 10 June 2014									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 13 June 2014									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 17 June 2014									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 20 June 2014									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 24 June 2014									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 27 June 2014									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 01 July 2014									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 04 July 2014									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 08 July 2014									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 11 July 2014									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 15 July 2014									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 18 July 2014									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 22 July 2014									
<i>No defects recorded</i>									
Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 25 July 2014									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 29 July 2014									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 01 August 2014									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 05 August 2014									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 08 August 2014									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 12 August 2014									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 15 August 2014									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 19 August 2014									
<i>No defects recorded</i>									

Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 August 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 August 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 September 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 September 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 September 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 October 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 October 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 November 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 November 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 November 2014

No defects recorded

Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 November 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 November 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 November 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 November 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 November 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 December 2014

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 December 2014

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 January 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 February 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 February 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 March 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 March 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 April 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 April 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 May 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 January 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 June 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 June 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 July 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 July 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 July 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 July 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 July 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 July 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 July 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 July 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 August 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 August 2015

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 August 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 August 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 August 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 September 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 September 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 October 2015

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 October 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 October 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 November 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 November 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 December 2015

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 December 2015

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 January 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 January 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 February 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 February 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 March 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 March 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 April 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 April 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 May 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 May 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 June 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 June 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 June 2016*No defects recorded***Safety Inspection of M8 Tannochside V1 on 28 June 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 02 July 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 05 July 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 09 July 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 12 July 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 16 July 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 19 July 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 23 July 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 26 July 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 30 July 2016***No defects recorded***Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016**

SW80143086-422	60m	80m	ROAD_MARKINGS _HATCHED	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-425	293m	323m	ROAD_MARKINGS _HATCHED	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-423	178m	200m	ROAD_MARKINGS _HATCHED	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW80143086-424	284m	284m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999

Safety Inspection of M8 Tannochside V1 on 02 August 2016*No defects recorded***Safety Patrol of M8 Tannochside V1 on 06 August 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 09 August 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 13 August 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 16 August 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 20 August 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 23 August 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 27 August 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 30 August 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 03 September 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 06 September 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 10 September 2016***No defects recorded***Safety Inspection of M8 Tannochside V1 on 13 September 2016***No defects recorded***Safety Patrol of M8 Tannochside V1 on 17 September 2016***No defects recorded*

Safety Inspection of M8 Tannochside V1 on 20 September 2016

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 September 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 September 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 October 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 October 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 October 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 October 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 October 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 01 November 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 05 November 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 08 November 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 12 November 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 November 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 November 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 November 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 November 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 November 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 December 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 December 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 December 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 December 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 December 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 December 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 December 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 December 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 December 2016

No defects recorded

Safety Patrol of M8 Tannochside V1 on 31 December 2016

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 07 January 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 14 January 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 January 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 January 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 January 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 February 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 February 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 March 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 March 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 01 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 04 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 08 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 11 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 15 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 18 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 22 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 25 April 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 29 April 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 02 May 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 May 2017

No defects recorded

Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016*No defects recorded***Safety Inspection of M8 Tannochside V1 on 09 May 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 13 May 2017***No defects recorded***Safety Inspection of M8 Tannochside V1 on 16 May 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 20 May 2017***No defects recorded***Safety Inspection of M8 Tannochside V1 on 23 May 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 27 May 2017***No defects recorded***Safety Inspection of M8 Tannochside V1 on 30 May 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 03 June 2017***No defects recorded***Safety Inspection of M8 Tannochside V1 on 06 June 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 10 June 2017***No defects recorded***Safety Inspection of M8 Tannochside V1 on 13 June 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 17 June 2017***No defects recorded***Safety Inspection of M8 Tannochside V1 on 20 June 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 24 June 2017***No defects recorded***Safety Inspection of M8 Tannochside V1 on 27 June 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 01 July 2017***No defects recorded***Safety Inspection of M8 Tannochside V1 on 04 July 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 08 July 2017***No defects recorded***Safety Inspection of M8 Tannochside V1 on 11 July 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 15 July 2017***No defects recorded***Safety Inspection of M8 Tannochside V1 on 18 July 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 22 July 2017***No defects recorded***Safety Inspection of M8 Tannochside V1 on 25 July 2017***No defects recorded***Safety Patrol of M8 Tannochside V1 on 29 July 2017***No defects recorded***Safety Inspection of M8 Tannochside V1 on 01 August 2017***No defects recorded***Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017**

SW77-257611-85	250m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 W/B JCT 15 OFF TO CASTLE ST
SW77-257611-86	291m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 W/B OFF SLIP TO CASTLE ST JCT 15

Safety Patrol of M8 Tannochside V1 on 05 August 2017*No defects recorded***Safety Inspection of M8 Tannochside V1 on 08 August 2017**

SW85-283366-235301859	325m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	09/08/2017	Completed Defects	08/08/2017	M8 WB JCT 15 OFFSLIP TO CASTLE ST
-----------------------	------	----	---------------	----------------------	-------	------------	-------------------	------------	-----------------------------------

Safety Patrol of M8 Tannochside V1 on 12 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 15 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 19 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 22 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 26 August 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 29 August 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 September 2017

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 26 September 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 September 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 10 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 17 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 21 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 24 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 28 October 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 31 October 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 04 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 07 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 11 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 14 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 18 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 21 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 25 November 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 28 November 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 02 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 February 2018

No defects recorded

