

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2018 and 28/02/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: WB M8 OFF SLIP TO A81 UPASS',) Or

(Section is 'WITH: WB M8 OFF SLIP TO A81 UPASS',) Or

(Section is 'WITH: SLIP TO M8 WB',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
14240/44 : WITH: WB M8 OFF SLIP TO A81 UPASS									
Safety Inspection of M8 Tannochside V1 on 03 January 2018									
No defects recorded									
Safety Patrol of M8 Tannochside V1 on 06 January 2018									
No defects recorded									
Safety Inspection of M8 Tannochside V1 on 09 January 2018									
No defects recorded									
Safety Patrol of M8 Tannochside V1 on 13 January 2018									
No defects recorded									
Safety Inspection of M8 Tannochside V1 on 16 January 2018									
No defects recorded									
Safety Patrol of M8 Tannochside V1 on 20 January 2018									
No defects recorded									
Safety Inspection of M8 Tannochside V1 on 23 January 2018									
No defects recorded									
Safety Patrol of M8 Tannochside V1 on 27 January 2018									
No defects recorded									
Safety Inspection of M8 Tannochside V1 on 30 January 2018									
No defects recorded									
Safety Patrol of M8 Tannochside V1 on 03 February 2018									
No defects recorded									
Safety Inspection of M8 Tannochside V1 on 06 February 2018									
No defects recorded									
Safety Patrol of M8 Tannochside V1 on 10 February 2018									
No defects recorded									
Safety Inspection of M8 Tannochside V1 on 13 February 2018									
No defects recorded									
Safety Patrol of M8 Tannochside V1 on 17 February 2018									
No defects recorded									
Safety Inspection of M8 Tannochside V1 on 20 February 2018									
No defects recorded									
Safety Patrol of M8 Tannochside V1 on 24 February 2018									
No defects recorded									
Safety Inspection of M8 Tannochside V1 on 27 February 2018									
SW85-323372-235549083	29m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	28/02/2018	Completed Defects	28/02/2018	M8 WB JCT 16-17 100M PAST SOS BOX 725W LANE 3

14245/10 : WITH: SLIP TO M8 WB

Safety Inspection of M8 Tannochside V1 on 03 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 January 2018
No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 January 2018
No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 January 2018
No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 February 2018
No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 February 2018
No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 February 2018
No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 February 2018
No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 February 2018
No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 February 2018
No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 February 2018
No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 February 2018
No defects recorded