

| Address 1 | L.A.Code | Defect | Description | Date Ordered | Date Originated | Date Completed | Stage | Action | Client Target Due | Originated | Link Id | Section Reference | Location | Order Target Due | Activity | Unit Type | XSP | Action Type Description | Priority |
|---|----------|--------|--|--------------|-----------------|----------------|----------|--------|-------------------|------------------|---------|-------------------|--------------------------|------------------|----------|---------------|-----|-------------------------|-------------|
| 11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A | 11465 | POTH | 2 Large potholes in outside lane At MP 13/7 & 13/7 + 50. carry out repairs with back up of to IPV Vehicles. | 15/02/2018 | 15/02/2018 | 15/02/2018 | APPROVED | P1 | 15/02/2018 | 15/02/2018 11:59 | 11445 | 11445/07 | M77 NB Maidenhill | 15/02/2018 | MC | CARRIAGEWAY | 6 | CAT-1 Permanent | 1 24 HOUR |
| 11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A | 11452 | PLMT | Repairs to Surface Defects at Maidenhill in both Lanes repairs carried out by Raynesway Surfacing, Motorway Closure. | 30/01/2018 | 30/01/2018 | 30/01/2018 | APPROVED | P1 | 30/01/2018 | 30/01/2018 20:00 | 11445 | 11445/07 | M77 NB at Maidenhill. | 30/01/2018 | MC | CARRIAGEWAY | Y | CAT-1 Permanent | 0 IMMEDIATE |
| 11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A | 11415 | DBHS | Metal chain in Hard shoulder at Maidenhill. | 29/01/2018 | 29/01/2018 | 29/01/2018 | APPROVED | P1 | 29/01/2018 | 29/01/2018 19:21 | 11445 | 11445/07 | M77 Nb at Maidenhill O/B | 29/01/2018 | SC | HARD SHOULDER | 4 | CAT-1 Permanent | 0 IMMEDIATE |

