

Address 1	L.A.Code	Defect	Description	Date Originated	Date Completed	Action	Link Id	Section Reference	Location	Order Target Due	Activity	Unit Type	XSP	Action Type	Description	Priority
11435/33 M77 S/B: OFF SLIP TO B778 FENWICK	11309	DBHS	Large piece of wooden door in hard shoulder.	04/12/2017	04/12/2017	P1		11435 11435/33	M77 S/B. OFF RAMP TO B778 STEWARTON ROAD AT FENWICK	04/12/2017	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11440/06 M77 S/B: FLOAK FARM OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11310	DBHS	Car Tyre In Hard sHoulder. at Mp 19/6	04/12/2017	04/12/2017	P1		11440 11440/06		04/12/2017	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11440/35 M77 N/B: FLOAK FARM OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11314	ACCD	Barrier damage found in centre Reserve posts at MP 17/1 M77 North .Bound ISU Called to cone of Damage & make Safe.	04/12/2017	20/12/2017	P1		11440 11440/35	M77 N/B: FLOAK FARM O/B TO CAIRN ROAD U/B	01/01/2018	SC	SAFETY FENCE	8	CAT-1	Permanent	2 28 DAYS
11440/35 M77 N/B: FLOAK FARM OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11313	ACCD	Barrier damage found in centre Reserve 2 posts at MP 17/1 M77 North .Bound ISU Called to cone of Damage & make Safe.	04/12/2017	04/12/2017	I1		11440 11440/35	M77 N/B: FLOAK FARM O/B TO CAIRN ROAD U/B	04/12/2017	SC	SAFETY FENCE	8	CAT-1	Immediate	0 IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11312	ACCD	Barrier Damage Found on M77 Southbound centre reserve at MP 15/0 , ISU called to cone of damaged area and Make Safe.No Culprit found.	04/12/2017	05/12/2017	P1		11440 11440/66	M77 S/B. MAIDENHILL INTERCHNAGE TO CAIRN ROAD U/B	29/12/2017	SC	SAFETY FENCE	8	CAT-1	Permanent	2 28 DAYS
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11311	OTHR	Barrier Damage Found on M77 Southbound centre reserve at MP 15/0 , ISU called to cone of damaged area and Make Safe.No Culprit found.	04/12/2017	04/12/2017	I1		11440 11440/66	M77 S/B. MAIDENHILL INTERCHNAGE TO CAIRN ROAD U/B	01/12/2017	SC	SAFETY FENCE	8	CAT-1	Immediate	0 IMMEDIATE
11435/31 M77 S/B: A719 OVERBRIDGE TO B778 OVERBRIDGE AT FENWICK	11319	POTH	Small pothole in lane 1 Mp 25/0 Repair With Viafix.	05/12/2017	05/12/2017	P1		11435 11435/31	M77 SB MP 25/0	05/12/2017	MC	CARRIAGEWAY	4	CAT-1	Permanent	0 IMMEDIATE
11440/09 M77 S/B: OFF SLIP TO A77 AT KINGSWELL INTERCHANGE	11318	POTH	Various Small Potholes in Both Lane on of Slip, Repair With Viafix RTC M77 NB at Floak Overbridge MP 19/3, Vauxhal Corsa { DV54TAJ} lost Control & Damaged Safety Barrier in Centre Reserve, 1 Anchor Block 3 post + 2 top sections of Box beam. to be replaced , ISU calle	05/12/2017	05/12/2017	P1		11440 11440/09	SB of Slip to Kingswell	05/12/2017	MC	CARRIAGEWAY	4	CAT-1	Permanent	0 IMMEDIATE
11440/35 M77 N/B: FLOAK FARM OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11316	ACCD	RTC M77 NB at Floak Overbridge MP 19/3, Vauxhal Corsa { DV54TAJ} lost Control & Damaged Safety Barrier in Centre Reserve, 1 Anchor Block 3 post + 2 top sections of Box beam. to be replaced , ISU calle	05/12/2017	20/12/2017	P1		11440 11440/35	M77 N/B: FLOAK FARM O/B TO CAIRN ROAD U/B	02/01/2018	SC	SAFETY FENCE	8	CAT-1	Permanent	2 28 DAYS
11440/35 M77 N/B: FLOAK FARM OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11315	OTHR	RTC M77 NB at Floak Overbridge MP 19/3, Vauxhal Corsa { DV54TAJ} lost Control & Damaged Safety Barrier in Centre Reserve, 1 Anchor Block 3 post + 2 top sections of Box beam. to be replaced , ISU calle	05/12/2017	05/12/2017	I1		11440 11440/35	M77 N/B: FLOAK FARM O/B TO CAIRN ROAD U/B	05/12/2017	SC	SAFETY FENCE	8	CAT-1	Immediate	0 IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11317	POTH	Small Pothole in Lane at MP14/6 Repair With Viafix. Debris in hard shoulder. Debris removed. No further action required.PLASTIC CONTAINER IN HARD SHOULDER	05/12/2017	05/12/2017	P1		11440 11440/66	M77 SB Mp 14/6 M77 S/B. ON RAMP FROM B778 STEWARTON ROAD AT FENWICK	05/12/2017	MC	CARRIAGEWAY	4	CAT-1	Permanent	0 IMMEDIATE
11435/28 M77 S/B: ON SLIP FROM B778 FENWICK	11320	DBHS	SHOULDER	07/12/2017	07/12/2017	P1		11435 11435/28		07/12/2017	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11440/36 M77 S/B: CAIRN ROAD UNDERBRIDGE TO FLOAK FARM OVERBRIDGE	11321	DBTL	Debris in traffic Lane (Lane 1), Debris removed. No further action required.LANE RATCHET STRAPS IN TRAFFIC LANE AT CAIRN ROAD	07/12/2017	07/12/2017	P1		11440 11440/36		07/12/2017	SC	CARRIAGEWAY	5	CAT-1	Permanent	0 IMMEDIATE
11435/28 M77 S/B: ON SLIP FROM B778 FENWICK	11325	DBHS	Large Damaged Tyre in Hard Shoulder.	11/12/2017	11/12/2017	P1		11435 11435/28	M77 S/B. ON RAMP FROM B778 STEWARTON ROAD AT FENWICK	11/12/2017	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11445/08 M77 S/B: A77 OVERBRIDGE AT MALLETSHEUGH TO MAIDENHILL	11326	DBHS	Debris in Hard Shoulder.	11/12/2017	11/12/2017	P1		11445 11445/08		11/12/2017	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11440/90 M77 N/B: OFF SLIP TO A726 MAIDENHILL INTERCHANGE	11335	LAMP	40 Mph Sign lamp out/	12/12/2017	12/12/2017	P1		11440 11440/90	M77 N/B. OFF RAMP FROM M77 TO MAIDENHILL ROUNDABOUT AT JUNCTION 5	17/12/2017	SS	SIGNS	3	CAT-1	Permanent	4 5 DAYS
11440/90 M77 N/B: OFF SLIP TO A726 MAIDENHILL INTERCHANGE	11334	LAMP	Lamp # J3/C2 out.	12/12/2017	12/12/2017	P1		11440 11440/90	NB of Ramp Maidenhill. M77 N/B. START OF MOTORWAY TO B778 STEWARTON ROAD OVERBRIDGE	17/12/2017	SLF	LIGHTING POINT	3	CAT-1	Permanent	4 5 DAYS
11435/05 M77 N/B: START OF MOTORWAY TO B778 OVERBRIDGE AT FENWICK	11330	MUCK	Litter Removal of Hard Shoulders & Verges.	13/12/2017	13/12/2017	P1		11435 11435/05		13/11/2017		VERGE	1	CAT-1	Permanent	0 IMMEDIATE
11435/05 M77 N/B: START OF MOTORWAY TO B778 OVERBRIDGE AT FENWICK	11327	MUCK	Litter Removal of Hard Shoulders & Verges. Debris in hard shoulder. Debris removed. No further action required.WOODEN BOARD IN HARD SHOULDER	13/12/2017	13/12/2017	I1		11435 11435/05		09/11/2017				CAT-1	Immediate	0 IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11329	MUCK	SHOULDER Debris in hard shoulder. Debris removed. No further action required.	13/12/2017	13/12/2017	P1		11440 11440/66	M77 SOUTH BOUND At CAIRN ROAD	13/12/2017		HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11328	CYC	Debris in hard shoulder.	13/12/2017	13/12/2017	I1		11440 11440/66	M77 SOUTH BOUND At CAIRN ROAD	13/12/2017		HARD SHOULDER	4	CAT-1	Immediate	0 IMMEDIATE
11435/30 M77 N/B: B778 OVERBRIDGE AT FENWICK TO A719 OVERBRIDGE	11332	DBHS	Wooden Sheet in Hard Shoulder..	14/12/2017	14/12/2017	P1		11435 11435/30	M77 NB Stewarton road.	14/12/2017	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11435/30 M77 N/B: B778 OVERBRIDGE AT FENWICK TO A719 OVERBRIDGE	11348	DBHS	Large Plastic sheet in Hard Shoulder.	18/12/2017	18/12/2017	P1		11435 11435/30	M77 NB at Stewarton Road.	18/12/2017	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	11349	DBHS	Metal Container in Hard Shoulder at Ayr O/B	18/12/2017	18/12/2017	P1		11445 11445/07	M77 NB at Ayr O/B	18/12/2017	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11435/31 M77 S/B: A719 OVERBRIDGE TO B778 OVERBRIDGE AT FENWICK	11355	DBHS	Polythene Sheet in Hard Shoulder	21/12/2017	21/12/2017	P1		11435 11435/31	M77 S/B. A719 GALSTON ROAD TO B778 STEWARTON ROAD OVERBRIDGE	21/12/2017	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11435/30 M77 N/B: B778 OVERBRIDGE AT FENWICK TO A719 OVERBRIDGE	11357	DBTL	Large Piece of wood In Outside Lane.	25/12/2017	25/12/2017	P1		11435 11435/30	M77 NB Stewarton Road	25/12/2017	SC	CARRIAGEWAY	5	CAT-1	Permanent	0 IMMEDIATE
11440/06 M77 S/B: FLOAK FARM OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11358	DBHS	Large blown out Lorry tyre in Hard Shoulder.	25/12/2017	25/12/2017	P1		11440 11440/06	M77 SB Floak M77 N/B. START OF MOTORWAY TO B778 STEWARTON ROAD O'BRIDGE AT FENWICK	25/12/2017	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11435/05 M77 N/B: START OF MOTORWAY TO B778 OVERBRIDGE AT FENWICK	11361	DBHS	Broken Pallet In Hard shoulder.	28/12/2017	28/12/2017	P1		11435 11435/05		28/12/2017	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11435/71 M77 S/B: KINGSWELL INT UNDERBRIDGE TO A719 OVERBRIDGE	11362	DBHS	Large Piece of Polythene sheeting in hard Shoulder,	28/12/2017	28/12/2017	P1		11435 11435/71		28/12/2017	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11435/71 M77 S/B: KINGSWELL INT UNDERBRIDGE TO A719 OVERBRIDGE	11364	DBHS	Large tarpaulin sheet in hard shoulder.	04/01/2018	04/01/2018	P1		11435 11435/71	M77 SB SB Galston.O/B	04/01/2018	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11440/35 M77 N/B: FLOAK FARM OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11365	DBHS	Plastic Container in Hard Shoulder.	04/01/2018	04/01/2018	P1		11440 11440/35		04/01/2018	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11440/09 M77 S/B: OFF SLIP TO A77 AT KINGSWELL INTERCHANGE	11369	DBTL	Dead Fox In Traffic Lane at start of slip road.	08/01/2018	08/01/2018	P1		11440 11440/09		08/01/2018	SC	CARRIAGEWAY	5	CAT-1	Permanent	0 IMMEDIATE
11440/35 M77 N/B: FLOAK FARM OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11371	POTH	1 large pothole1 in lane 1at Mp 17/5 to be repaired under nightshift emergency closure.with Viatec	08/01/2018	08/01/2018	D22		11440 11440/35	M77 NB at Floak	09/01/2018	MC	CARRIAGEWAY	5	CAT-2.2	Permanent	1 24 HOUR
11440/35 M77 N/B: FLOAK FARM OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11370	POTH	2 large potholes in lane 1at Mp 18/6 to be repaired under nightshift emergency closure.with Viatec	08/01/2018	08/01/2018	D22		11440 11440/35	M77 NB at Floak	09/01/2018	MC	CARRIAGEWAY	5	CAT-2.2	Permanent	1 24 HOUR
11440/65 M77 N/B: CAIRN ROAD UNDERBRIDGE TO MAIDENHILL INTERCHANGE	11373	POTH	Large pothole in lane 1at Mp 15/1 to be repaired under nightshft emergency closure.with Viatec	08/01/2018	08/01/2018	D22		11440 11440/65	M77 NB after Cairn road.	09/01/2018	MC	CARRIAGEWAY	5	CAT-2.2	Permanent	1 24 HOUR
11440/65 M77 N/B: CAIRN ROAD UNDERBRIDGE TO MAIDENHILL INTERCHANGE	11372	POTH	Various Small potholes in lane 1at Mp 16/1 to be repaired under nightshift emergency closure.with Viatec	08/01/2018	08/01/2018	D22		11440 11440/65	M77 NB at Cairn road.	09/01/2018	MC	CARRIAGEWAY	5	CAT-2.2	Permanent	1 24 HOUR
11440/65 M77 N/B: CAIRN ROAD UNDERBRIDGE TO MAIDENHILL INTERCHANGE	11368	DBHS	Wooden post in hard shoulder.	08/01/2018	08/01/2018	P1		11440 11440/65	M77 NB cairn Road	08/01/2018	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11440/91 M77 S/B: ON SLIP FROM MAIDENHILL INTERCHANGE	11367	DBHS	large Tyre In Hard shoulder of on ramp RTC M77 SB at MP 22/0 Mercedes { SG67ESF} lost control & damaged 4 posts of wire rope safety fence in centre reserve. ISU called to clean up debris and make safe .Police in attendance Incident # 076	08/01/2018	08/01/2018	P1		11440 11440/91	M77 S/B. ON RAMP TO M77 FROM MAIDENHILL ROUNDABOUT AT JUNCTION 5	08/01/2018	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11435/71 M77 S/B: KINGSWELL INT UNDERBRIDGE TO A719 OVERBRIDGE	11551	ACCD	RTC M77 SB at MP 22/0 Mercedes { SG67ESF} lost control & damaged 4 posts of wire rope safety fence in centre reserve. ISU called to clean up debris and make safe .Police in attendance Incident # 076	09/01/2018	06/02/2018	P1		11435 11435/71	M77 S/B: KINGSWELL INT UNDERBRIDGE TO A719 OVERBRIDGE	06/02/2018	SC	SAFETY FENCE	3	CAT-1	Permanent	2 28 DAYS
11435/71 M77 S/B: KINGSWELL INT UNDERBRIDGE TO A719 OVERBRIDGE	11384	ACCD	RTC M77 SB at MP 22/0 Mercedes { SG67ESF} lost control & damaged 4 posts of wire rope safety fence in centre reserve. ISU called to clean up debris and make safe .Police in attendance Incident # 076	09/01/2018	05/02/2018	P1		11435 11435/71	M77 S/B: KINGSWELL INT UNDERBRIDGE TO A719 OVERBRIDGE	06/02/2018	SC	SAFETY FENCE	8	CAT-1	Permanent	2 28 DAYS
11435/71 M77 S/B: KINGSWELL INT UNDERBRIDGE TO A719 OVERBRIDGE	11383	OTHR	RTC M77 SB at MP 22/0 Mercedes { SG67ESF} lost control & damaged 4 posts of wire rope safety fence in centre reserve. ISU called to clean up debris and make safe .Police in attendance Incident # 076	09/01/2018	09/01/2018	I1		11435 11435/71	M77 S/B: KINGSWELL INT UNDERBRIDGE TO A719 OVERBRIDGE	09/01/2018	SC	SAFETY FENCE	8	CAT-1	Immediate	0 IMMEDIATE
11435/70 M77 N/B: A719 OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11376	DBHS	Debris in hard shoulder. Debris removed. No further action required.BLOWN OUT TYRE IN HARD SHOULDER	11/01/2018	11/01/2018	P1		11435 11435/70		11/01/2018	SC	HARD SHOULDER	4	CAT-1	Permanent	0 IMMEDIATE
11440/65 M77 N/B: CAIRN ROAD UNDERBRIDGE TO MAIDENHILL INTERCHANGE	11375	DBTL	Debris in traffic Lane (Lane 2), Debris removed. No further action required.PLANK OF WOOD IN TRAFFIC LANE	11/01/2018	11/01/2018	P1		11440 11440/65	M77 NORTH BOUND At KINGSWELL	11/01/2018	SC	CARRIAGEWAY	4	CAT-1	Permanent	0 IMMEDIATE

11435/06 M77 S/B: B778 OVERBRIDGE AT FENWICK TO END OF MOTORWAY	11381 DBHS	Debris in hard shoulder. Debris removed. No further action required.PLASTIC CONTAINER IN HARD SHOULDER	15/01/2018	15/01/2018 P1	11435 11435/06	M77 S/B. B778 STEWARTON ROAD OVERBRIDGE TO END OF MOTORWAY	15/01/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11440/35 M77 N/B: FLOAK FARM OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11378 DBTL	Debris in traffic lane (Lane 2). Debris removed. No further action required.Large STRAP IN TRAFFIC LANE	15/01/2018	15/01/2018 P1	11440 11440/35	M77 NORTH BOUND At FLOAK O/B	15/01/2018 SC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11379 DBHS	Debris in hard shoulder. Debris removed. No further action required.WATER CONTAINER IN HARD SHOULDER PRIOR CAIRN ROAD	15/01/2018	15/01/2018 P1	11440 11440/66		15/01/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11435/05 M77 N/B: START OF MOTORWAY TO B778 OVERBRIDGE AT FENWICK	11386 DBHS	Exhaust pipe In Traffic hard shoulder.	18/01/2018	18/01/2018 P1	11435 11435/05		18/01/2018 SC		4 CAT-1 Permanent	NO PRIOR.
11440/90 M77 N/B: OFF SLIP TO A726 MAIDENHILL INTERCHANGE	11385 DBHS	Large Sheet of Plywood in Hard shoulder.	18/01/2018	18/01/2018 P1	11440 11440/90	NB of Slip Maidenhill.	25/01/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11440/65 M77 N/B: CAIRN ROAD UNDERBRIDGE TO MAIDENHILL INTERCHANGE	11391 POTH	Large Pothole in outside lane opposite of ramp at Maidenhill Mp 14/2 Emergency repair carried out after call from Transerve.	20/01/2018	20/01/2018 P1	11440 11440/65	M77 NB Cairn Rd to Maidenhill.	20/01/2018 MC	CENTRAL ISLAND	6 CAT-1 Permanent	0 IMMEDIATE
11435/06 M77 S/B: B778 OVERBRIDGE AT FENWICK TO END OF MOTORWAY	11393 POTH	Varlous potholes In Lane 1 Between Mp 27/1 to 27/2 Emergency repairs carried out to repair Potholes.	22/01/2018	22/01/2018 P1	11435 11435/06	M77 SB at Jcn 8	22/01/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11435/31 M77 S/B: A719 OVERBRIDGE TO B778 OVERBRIDGE AT FENWICK	11394 POTH	Varlous potholes in Lane 1 Between MP 24/9 to 25/0 Emergency repairs carried out to repair Potholes.	22/01/2018	22/01/2018 P1	11435 11435/31	M77 SB MP 24/9	22/01/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11435/70 M77 N/B: A719 OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11412 POTH	Potholes in lane 1 at Mp 23/1 Emergency repairs carried out to repair Potholes.	22/01/2018	22/01/2018 P1	11435 11435/70	M77 NB at MP 23/1	22/01/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11435/70 M77 N/B: A719 OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11389 DBHS	Polythene sheet on hard shoulder.	22/01/2018	22/01/2018 P1	11435 11435/70	M77 NB at Galston O/B	22/01/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11440/09 M77 S/B: OFF SLIP TO A77 AT KINGSWELL INTERCHANGE	11387 OTHR	Large Refuse sack left on Verge.	22/01/2018	22/01/2018 P1	11440 11440/09	SB of Slip to Kingswell	22/01/2018 SC	VERGE	3 CAT-1 Permanent	0 IMMEDIATE
11445/08 M77 S/B: A77 OVERBRIDGE AT MALLETSHEUGH TO MAIDENHILL	11388 DBHS	Large Tyre left on hard shoulder at Ayr O/B.	22/01/2018	22/01/2018 P1	11445 11445/08	M77 South at Ayr O/B.	22/01/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11440/09 M77 S/B: OFF SLIP TO A77 AT KINGSWELL INTERCHANGE	11395 LAMP	No Entry sign Lamp Out.	23/01/2018	23/01/2018 P1	11440 11440/09	SB of Slip Kingswell	28/01/2018 SS	SIGNS	8 CAT-1 Permanent	4 5 DAYS
11440/65 M77 N/B: CAIRN ROAD UNDERBRIDGE TO MAIDENHILL INTERCHANGE	11403 POTH	Various Large Potholes In Lane 2 at Mp 13/8 to 13/6 Carry out Repair under Emergency closure .	24/01/2018	24/01/2018 P1	11440 11440/65	M77 NB at Maidenhill	24/01/2018 MC		6 CAT-1 Permanent	0 IMMEDIATE
11440/65 M77 N/B: CAIRN ROAD UNDERBRIDGE TO MAIDENHILL INTERCHANGE	11402 POTH	Large Pothole in Lane 1 at Mp 13/8 Carry out Repair under Emergency closure .	24/01/2018	24/01/2018 P1	11440 11440/65	M77 NB at Maidenhill	24/01/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11440/36 M77 S/B: CAIRN ROAD UNDERBRIDGE TO FLOAK FARM OVERBRIDGE	11406 DBHS	Large plastic Sheet in hard Shoulder.	25/01/2018	25/01/2018 P1	11440 11440/36		25/01/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11435/15 M77 N/B: OFF SLIP TO B751 KILMAURS ROAD ROUNDABOUT	11405 DBHS	Car Tyre in hard Shoulder.	25/01/2018	25/01/2018 P1	11435 11435/15		25/01/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11435/31 M77 S/B: A719 OVERBRIDGE TO B778 OVERBRIDGE AT FENWICK	11451 PLMT	Repairs to Surface Defects Prior Fenwick in both Lanes repairs carried out by Raynesway Surfacing, Motorway Closure.	29/01/2018	29/01/2018 P1	11435 11435/31	M77 SB	29/01/2018 MC	CARRIAGEWAY	Y CAT-1 Permanent	0 IMMEDIATE
11440/06 M77 S/B: FLOAK FARM OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11450 PLMT	Repairs to Surface Defects Prior Kingswell in both Lanes repairs carried out by Raynesway Surfacing, Motorway Closure.	29/01/2018	29/01/2018 P1	11440 11440/06	M77 SB	29/01/2018 MC	CARRIAGEWAY	Y CAT-1 Permanent	0 IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11449 PLMT	Repairs to Surface Defects Prior Cairn Road in Lane one repairs carried out by Raynesway Surfacing, Motorway Closure.	29/01/2018	29/01/2018 P1	11440 11440/66	M77 SB	29/01/2018 MC	CARRIAGEWAY	Y CAT-1 Permanent	0 IMMEDIATE
11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	11415 DBHS	Metal chain in Hard shoulder at Maidenhill.	29/01/2018	29/01/2018 P1	11445 11445/07	M77 Nb at Maidenhill O/B	29/01/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11445/11 M77 S/B: OFF SLIP TO GSO MAIDENHILL INTERCHANGE	11411 POTH	Various potholes in Lane 1at start of slip Emergency repairs carried out to repair Potholes.	29/01/2018	29/01/2018 P1	11445 11445/11	SB of Ramp Maidenhill .	29/01/2018 MC	CARRIAGEWAY	4 CAT-1 Permanent	0 IMMEDIATE
11435/30 M77 N/B: B778 OVERBRIDGE AT FENWICK TO A719 OVERBRIDGE	11448 ACCD	Vehicle Has Damaged 11 Posts of Wire Rope Safety Barrier In Centre Reserve at MP 25/4, I S U Called to Clean up Damage & Make Safe.	30/01/2018	08/02/2018 P1	11435 11435/30	M77 NB at MP 25/4	21/02/2018 SC	SAFETY FENCE	8 CAT-1 Permanent	2 28 DAYS
11435/30 M77 N/B: B778 OVERBRIDGE AT FENWICK TO A719 OVERBRIDGE	11447 OTHR	Vehicle Has Damaged 11 Posts of Wire Rope Safety Barrier In Centre Reserve at MP 25/4, I S U Called to Clean up Damage & Make Safe.	30/01/2018	30/01/2018 I1	11435 11435/30	M77 NB at MP 25/4	31/01/2018 SC	SAFETY FENCE	8 CAT-1 Immediate	0 IMMEDIATE
11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	11452 PLMT	Repairs to Surface Defects at Maidenhill In both Lanes repairs carried out by Raynesway Surfacing, Motorway Closure.	30/01/2018	30/01/2018 P1	11445 11445/07	M77 NB at Maidenhill.	30/01/2018 MC	CARRIAGEWAY	Y CAT-1 Permanent	0 IMMEDIATE
11435/05 M77 N/B: START OF MOTORWAY TO B778 OVERBRIDGE AT FENWICK	11417 DBHS	Large Piece of polythene in hard shoulder.	01/02/2018	01/02/2018 P1	11435 11435/05	A77 NB	01/02/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11435/06 M77 S/B: B778 OVERBRIDGE AT FENWICK TO END OF MOTORWAY	11446 ACCD	Vehicle Has Damaged 22 Posts of Wire Rope Safety Barrier in Centre Reserve I S U Called to Clean up Damage & Make Safe.	01/02/2018	08/02/2018 P1	11435 11435/06	M77 SB at MP 26/8	01/03/2018 SC	SAFETY FENCE	3 CAT-1 Permanent	2 28 DAYS
11435/06 M77 S/B: B778 OVERBRIDGE AT FENWICK TO END OF MOTORWAY	11445 OTHR	Vehicle Has Damaged 22 Posts of Wire Rope Safety Barrier in Centre Reserve I S U Called to Clean up Damage & Make Safe.	01/02/2018	01/02/2018 I1	11435 11435/06	M77 SB at MP 26/8	01/02/2018 SC	SAFETY FENCE	8 CAT-1 Immediate	0 IMMEDIATE
11435/71 M77 S/B: KINGSWELL INT UNDERBRIDGE TO A719 OVERBRIDGE	11418 DBHS	Car Exhaust pipe in Hard shoulder.	01/02/2018	01/02/2018 P1	11435 11435/71		01/02/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11435/06 M77 S/B: B778 OVERBRIDGE AT FENWICK TO END OF MOTORWAY	11444 OTHR	Repairs to Surface Defects Prior Leigh Fenwick In Lane one repairs carried out by Raynesway Surfacing under Lane Closure.	05/02/2018	05/02/2018 P1	11435 11435/06	M77 SB at Leigh Fenwick.	05/02/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11440/06 M77 S/B: FLOAK FARM OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11421 DBHS	Large Tarpaulin sheet in Hard shoulder,	05/02/2018	05/02/2018 P1	11440 11440/06		05/02/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11440/09 M77 S/B: OFF SLIP TO A77 AT KINGSWELL INTERCHANGE	11439 LAMP	No Entry Sign Lamp out.	06/02/2018	06/02/2018 P1	11440 11440/09	SB of Slip at Kingswell	11/02/2018 SS	SIGNS	8 CAT-1 Permanent	4 5 DAYS
11445/11 M77 S/B: OFF SLIP TO GSO MAIDENHILL INTERCHANGE	11441 POTH	large Pothole on Slip Road 500 x 500 Repair With Viafix	06/02/2018	06/02/2018 P1	11445 11445/11	SB of Slip Maidenhill	06/02/2018 MC	CARRIAGEWAY	4 CAT-1 Permanent	0 IMMEDIATE
11445/11 M77 S/B: OFF SLIP TO GSO MAIDENHILL INTERCHANGE	11429 LAMP	End of Motorway sign lamp out.	06/02/2018	06/02/2018 P1	11445 11445/11	SB of Ramp to Maidenhill.	11/02/2018 SS	SIGNS	1 CAT-1 Permanent	0 IMMEDIATE
11440/65 M77 N/B: CAIRN ROAD UNDERBRIDGE TO MAIDENHILL INTERCHANGE	11428 LAMP	40 MPH sign Lamp out.	06/02/2018	06/02/2018 P1	11445 11445/11	SB of Ramp to Maidenhill.	11/02/2018 SLF	LIGHTING POINT	1 CAT-1 Permanent	4 5 DAYS
11435/70 M77 N/B: A719 OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11442 POTH	Pothole in Lane 1 at MP 15/8 15/9 16/2 14/6 16/0 16/3 Repair With Viafix with IPV Protection.	07/02/2018	07/02/2018 P1	11440 11440/65	M77 SB Prior Cairn road.	07/02/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11440/09 M77 S/B: OFF SLIP TO A77 AT KINGSWELL INTERCHANGE	11423 DBHS	Large Piece of Safety Netting In hard Shoulder.	08/02/2018	08/02/2018 P1	11435 11435/70		08/02/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11435/05 M77 N/B: START OF MOTORWAY TO B778 OVERBRIDGE AT FENWICK	11424 DBTL	Car Tyre in Traffic Lane.	08/02/2018	08/02/2018 P1	11440 11440/09		08/02/2018 SC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11435/05 M77 N/B: START OF MOTORWAY TO B778 OVERBRIDGE AT FENWICK	11475 ACCD	RTC A77 Meiklewood Interchange 4 vehicles involved in accident DY59CZC RN07HXB SC09LNF & SK59UYA 5 post & 5 Beams of TCB Barrier Damaged , Police in Attendance Incident # 11/02/18/4163. ISU Called to	11/02/2018	12/03/2018 P1	11435 11435/05	A77 Meiklewood Interchange .	12/03/2018 SC	SAFETY FENCE	Y CAT-1 Permanent	2 28 DAYS
11435/05 M77 N/B: START OF MOTORWAY TO B778 OVERBRIDGE AT FENWICK	11474 ACCD	RTC A77 Meiklewood Interchange 4 vehicles involved in accident DY59CZC RN07HXB SC09LNF & SK59UYA 5 post & 5 Beams of TCB Barrier Damaged , Police in Attendance Incident # 11/02/18/4163. ISU Called to	11/02/2018	11/02/2018 I1	11435 11435/05	A77 Meiklewood Interchange .	19/02/2018 SC	SAFETY FENCE	Y CAT-1 Immediate	0 IMMEDIATE
11435/06 M77 S/B: B778 OVERBRIDGE AT FENWICK TO END OF MOTORWAY	11473 ACCD	RTC M77 South at MP 26/6 vehicle has lost control White Van Reg NU62 RMV & Damaged 2 post of wire rope safety fence in centre reserve ISU Called to Clean up Damaged Area & Make safe.	12/02/2018		P1 11435 11435/06	M77 SB at MP 26/6	26/03/2018 SC	SAFETY FENCE	8 CAT-1 Permanent	2 28 DAYS
11435/06 M77 S/B: B778 OVERBRIDGE AT FENWICK TO END OF MOTORWAY	11472 ACCD	RTC M77 South at MP 26/6 vehicle has lost control White Van Reg NU62 RMV & Damaged 2 post of wire rope safety fence in centre reserve ISU Called to Clean up Damaged Area & Make safe.	12/02/2018	12/02/2018 I1	11435 11435/06	M77 SB at MP 26/6	12/02/2018 SC	SAFETY FENCE	8 CAT-1 Immediate	0 IMMEDIATE
11435/30 M77 N/B: B778 OVERBRIDGE AT FENWICK TO A719 OVERBRIDGE	11458 POTH	Large Pothole in Lane 2 just at Gardrum Mill . 500 x 350 Repair to pothole with Viafix.	13/02/2018	13/02/2018 P1	11435 11435/30	M77 Nb at Gardrum Mill.	13/02/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11435/31 M77 S/B: A719 OVERBRIDGE TO B778 OVERBRIDGE AT FENWICK	11455 DBHS	Large Piece of Ratchet Strap in hard Shoulder.	13/02/2018	13/02/2018 P1	11435 11435/31	M77 SB Galston O/B	12/02/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE

11440/05 M77 N/B: KINGSWELL INT UNDERBRIDGE TO FLOAK FARM OVERBRIDGE	11456 DBHS	Blown out Tyre in hard shoulder,at Kingswell.	13/02/2018	13/02/2018 P1	11440 11440/05		12/02/2018 SC	HARD SHOULDER	4	CAT-1 Permanent	0	IMMEDIATE
11435/33 M77 S/B: OFF SLIP TO B778 FENWICK	11467 POTH	3 Small potholes on slip Repair with Viafix.	15/02/2018	15/02/2018 P1	11435 11435/33	SB of Slip Fenwick	15/02/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0	IMMEDIATE
11440/35 M77 N/B: FLOAK FARM OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11466 POTH	3 Potholes in Lane 1 between MP 18/6/ to 18/5 Carry out Repairs with Back up of IPV for Protection.	15/02/2018	15/02/2018 P1	11440 11440/35	M77 NB at MP18/6	15/02/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0	IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11464 DBHS	Large piece of chain in hard shoulder.	15/02/2018	15/02/2018 P1	11440 11440/66	M77 SB Cairn road	15/02/2018 SC	HARD SHOULDER	4	CAT-1 Permanent	0	IMMEDIATE
11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	11465 POTH	2 Large potholes in outside lane At MP 13/7 & 13/7 + 50. carry out repairs with back up of IPV Vehicles.	15/02/2018	15/02/2018 P1	11445 11445/07	M77 NB Maidenhill	15/02/2018 MC	CARRIAGEWAY	6	CAT-1 Permanent	1	24 HOUR
11435/71 M77 S/B: KINGSWELL INT UNDERBRIDGE TO A719 OVERBRIDGE	11471 DBHS	Large Tarpaulin Sheet in Hard Shoulder.	19/02/2018	19/02/2018 P1	11435 11435/71	M77 SB Galston O/B	19/02/2018 SC	HARD SHOULDER	4	CAT-1 Permanent	0	IMMEDIATE
11440/06 M77 S/B: FLOAK FARM OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11469 DBHS	large piece of car Bumper in hard Shoulder.	19/02/2018	19/02/2018 P1	11440 11440/06	M77 SB at Cairn Road.	19/02/2018 SC	HARD SHOULDER	4	CAT-1 Permanent	0	IMMEDIATE
11440/35 M77 N/B: FLOAK FARM OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11477 CRCK	Large rut at Centre Joint at Mp 17/4 to 17/3 Carry out repair with Viafix	19/02/2018	19/02/2018 P1	11440 11440/35	M77 NB Floak to Cairn Road	19/02/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0	IMMEDIATE
11440/65 M77 N/B: CAIRN ROAD UNDERBRIDGE TO MAIDENHILL INTERCHANGE	11478 POTH	Various Potholes at Mp 14/1 14/0 10/0 + 50 both lanes carry out repair with Viafix.	19/02/2018	19/02/2018 P1	11440 11440/65	M77 North at Cairn Road	19/02/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0	IMMEDIATE
11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	11479 POTH	Potholes at MP 13/7 & 13/7+ 50 carry out repairs with Viafix.	19/02/2018	19/02/2018 P1	11445 11445/07	M77 North at Maidenhill	19/02/2018 MC	CARRIAGEWAY	6	CAT-1 Permanent	0	IMMEDIATE
11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	11470 DBHS	Large Plastic Sheet in Hard Shoulder.	19/02/2018	19/02/2018 P1	11445 11445/07	M77 NB at Ayr O/B	19/02/2018 SC	HARD SHOULDER	4	CAT-1 Permanent	0	IMMEDIATE
11440/09 M77 S/B: OFF SLIP TO A77 AT KINGSWELL INTERCHANGE	11486 POTH	Various Potholes in Both Lanes of Ramp to Kingswell Carry out Repairs with Viafix with Back up from 2 x IPV vehicles.	20/02/2018	20/02/2018 P1	11440 11440/09	M77 SB of Slip for Kingswell	20/02/2018 MC	CARRIAGEWAY	Y	CAT-1 Permanent	0	IMMEDIATE
11440/90 M77 N/B: OFF SLIP TO A726 MAIDENHILL INTERCHANGE	11502 LAMP	End of M/Way sign lamp out.	20/02/2018	20/02/2018 P1	11440 11440/90	NB of slip Maidenhill	25/02/2018 SS	SIGNS	8	CAT-1 Permanent	4	5 DAYS
11440/08 M77 N/B: ON SLIP FROM A77 AT KINGSWELL INTERCHANGE	11487 POTH	Various Potholes at on Ramp to Kingswell Carry out Repairs with Viafix.	21/02/2018	21/02/2018 P1	11440 11440/08	NB on Slip Kingswell	21/02/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0	IMMEDIATE
11435/06 M77 S/B: B778 OVERBRIDGE AT FENWICK TO END OF MOTORWAY	11497 OTHR	Tarpaulin Sheet in left Verge	22/02/2018	22/02/2018 P1	11435 11435/06	M77 SB at Fenwick	22/02/2018 SC	VERGE	1	CAT-1 Permanent	0	IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11499 DBHS	Car Tyre in Hard Shoulder	22/02/2018	22/02/2018 P1	11440 11440/66	M77 Sb Maidenhill	23/02/2018 SC	HARD SHOULDER	4	CAT-1 Permanent	0	IMMEDIATE
11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	11485 POTH	Various Potholes in Both Lanes Between Mp 14/1 to 13/7 in both lanes Carry out Repairs with Viafix with Back up from 2 x IPV vehicles.	26/02/2018	26/02/2018 P1	11445 11445/07	M77 NB Maidenhill to Ayr O/B	26/03/2018 MC	CARRIAGEWAY	Y	CAT-1 Permanent	0	IMMEDIATE
11435/05 M77 N/B: START OF MOTORWAY TO B778 OVERBRIDGE AT FENWICK	11493 DBHS	Large Wooden Post in Hard Shoulder at Start of Motorway.	27/02/2018	27/02/2018 P1	11435 11435/05	M77 NB	27/02/2018 SC	HARD SHOULDER	4	CAT-1 Permanent	0	IMMEDIATE
11435/70 M77 N/B: A719 OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11494 OTHR	Builders sack on Left Verge.	27/02/2018	27/02/2018 P1	11435 11435/70	M77 NB at Galston O/B	27/02/2018 SC	VERGE	3	CAT-1 Permanent	0	IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11495 DBHS	Plastic Container in Hard Shoulder	27/02/2018	27/02/2018 P1	11440 11440/66	M77 SB at Cairn Road.	27/03/2018 SC	HARD SHOULDER	4	CAT-1 Permanent	0	IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11492 POTH	Large Pothole at 16/6 Carry out repairs with Viafix.	27/02/2018	27/02/2018 P1	11440 11440/66	M77 SB at Cairn Road	27/02/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0	IMMEDIATE
11435/70 M77 N/B: A719 OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11498 DBHS	Plastic Bucket in Hard Shoulder	01/03/2018	01/03/2018 P1	11435 11435/70	M77 NB	01/03/2018 SC	HARD SHOULDER	4	CAT-1 Permanent	0	IMMEDIATE
11435/30 M77 N/B: B778 OVERBRIDGE AT FENWICK TO A719 OVERBRIDGE	11480 DBHS	Debris in hard shoulder. Debris removed. No further action required.METAL CHAIN IN HARD SHOULDER	05/03/2018	05/03/2018 P1	11435 11435/30	M77 N/B: B778 STEWARTON ROAD TO A719 GALSTON ROAD	05/03/2018 SC	HARD SHOULDER	4	CAT-1 Permanent	0	IMMEDIATE
11440/06 M77 S/B: FLOAK FARM OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11481 DBTL	Debris in R/H Verge. Debris removed. No further action requiredLARGE PIECE OF PLASTIC PIPE IN OUTSIDE LANE	05/03/2018	05/03/2018 P1	11440 11440/06		05/03/2018 SC	CARRIAGEWAY	6	CAT-1 Permanent	0	IMMEDIATE
11445/11 M77 S/B: OFF SLIP TO GSO MAIDENHILL INTERCHANGE	11491 POTH	Large Pothole at Start of slip road Carry out repairs with Viafix.	05/03/2018	05/03/2018 P1	11445 11445/11	SB of Slip Maidenhill	05/03/2018 MC	CARRIAGEWAY	4	CAT-1 Permanent	0	IMMEDIATE
11440/08 M77 N/B: ON SLIP FROM A77 AT KINGSWELL INTERCHANGE	11523 LAMP	70 MPH sign lamp out	06/03/2018	06/03/2018 P1	11440 11440/08	NB on Slip Kingswell	11/03/2018 SS	SIGNS	1	CAT-1 Permanent	4	5 DAYS
11440/09 M77 S/B: OFF SLIP TO A77 AT KINGSWELL INTERCHANGE	11522 LAMP	Give Way sign lamp out	06/03/2018	06/03/2018 P1	11440 11440/09	South Bound of Slip Kingswell	11/03/2018 SS	SIGNS	3	CAT-1 Permanent	4	5 DAYS
11435/05 M77 N/B: START OF MOTORWAY TO B778 OVERBRIDGE AT FENWICK	11535 CYC	Litter Removal all Verges & Hard Shoulder Area.	08/03/2018	09/03/2018 CYC	11435 11435/05		13/03/2018	74		Cyclic Maintenance	NO	PRIOR.
11435/06 M77 S/B: B778 OVERBRIDGE AT FENWICK TO END OF MOTORWAY	11536 CYC	Litter Removal all Verges & Hard Shoulder Area. Debris in traffic Lane (Lane 1). Debris removed. No further action required.PLASTIC SHEET IN TRAFFIC LANE At OF SLIP	08/03/2018	08/03/2018 CYC	11435 11435/06		13/03/2018	74		Cyclic Maintenance	NO	PRIOR.
11435/10 M77 S/B: OFF SLIP TO SOUTH END OF FENWICK	11483 DBTL	Debris in hard shoulder. Debris removed. No further action required.Large RATCHET STRAPS in HARD SHOULDER	08/03/2018	08/03/2018 P1	11435 11435/10	M77 S/B. OFF RAMP TO B778 AT FENWICK	08/03/2018 SC	CARRIAGEWAY	4	CAT-1 Permanent	0	IMMEDIATE
11435/30 M77 N/B: B778 OVERBRIDGE AT FENWICK TO A719 OVERBRIDGE	11484 DBHS	Debris in L/H Verge. Debris removed. No further action requiredDebris in L/H Verge. Debris removed.	08/03/2018	08/03/2018 P1	11435 11435/30	M77 N/B: B778 STEWARTON ROAD TO A719 GALSTON ROAD	08/03/2018 SC	HARD SHOULDER	4	CAT-1 Permanent	0	IMMEDIATE
11435/70 M77 N/B: A719 OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11482 DBHS	No further action requiredCAR TYRE IN LEFT HAND VERGE	08/03/2018	08/03/2018 P1	11435 11435/70		08/03/2018 SC	VERGE	3	CAT-1 Permanent	0	IMMEDIATE
11440/91 M77 S/B: ON SLIP FROM MAIDENHILL INTERCHANGE	11537 CYC	Litter Removal all Verges & Hard Shoulder Area.	08/03/2018	09/03/2018 CYC	11440 11440/91		13/03/2018	74		Cyclic Maintenance	NO	PRIOR.
11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	11538 CYC	Litter Removal all Verges & Hard Shoulder Area.	08/03/2018	08/03/2018 CYC	11445 11445/07		13/03/2018	74		Cyclic Maintenance	NO	PRIOR.
11445/10 M77 N/B: ON SLIP FROM A726 MAIDENHILL INTERCHANGE	11539 CYC	Litter Removal all Verges & Hard Shoulder Area.	08/03/2018	08/03/2018 CYC	11445 11445/10		13/03/2018	74		Cyclic Maintenance	NO	PRIOR.
11435/05 M77 N/B: START OF MOTORWAY TO B778 OVERBRIDGE AT FENWICK	11534 CYC	Litter Removal of Hard Shoulders & Verges.	09/03/2018	09/03/2018 CYC	11435 11435/05	M77 N/B. START OF MOTORWAY TO B778 STEWARTON ROAD OVERBRIDGE	09/03/2018	74 VERGE	0	Cyclic Maintenance	0	IMMEDIATE
11435/06 M77 S/B: B778 OVERBRIDGE AT FENWICK TO END OF MOTORWAY	11530 POTH	Pothole in Lane 1 at MP 27/3 carry out repair with Viafix.	12/03/2018	12/03/2018 P1	11435 11435/06	M77 SB MP 27/3	12/03/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0	IMMEDIATE
11435/30 M77 N/B: B778 OVERBRIDGE AT FENWICK TO A719 OVERBRIDGE	11532 POTH	Pothole in Lane 1 at MP 25/0 carry out repair with Viafix.	12/03/2018	12/03/2018 P1	11435 11435/30	M77 NB MP 25/0	12/03/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0	IMMEDIATE
11435/31 M77 S/B: A719 OVERBRIDGE TO B778 OVERBRIDGE AT FENWICK	11529 POTH	Pothole in Lane 1 at MP 24/8 carry out repair with Viafix.	12/03/2018	12/03/2018 P1	11435 11435/31	M77 SB MP 24/8.	12/03/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0	IMMEDIATE
11440/06 M77 S/B: FLOAK FARM OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11525 DBHS	Large Piece of wooden sheet in hard shoulder	12/03/2018	12/03/2018 P1	11440 11440/06	M77 SB at Kingswell	12/03/2018 SC	HARD SHOULDER	4	CAT-1 Permanent	0	IMMEDIATE
11440/65 M77 N/B: CAIRN ROAD UNDERBRIDGE TO MAIDENHILL INTERCHANGE	11528 DBHS	Dead bird in hard shoulder.	12/03/2018	12/03/2018 P1	11440 11440/65	M77 NB at Cairn Rd	12/03/2018 SC	HARD SHOULDER	4	CAT-1 Permanent	0	IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11531 POTH	Pothole in Lane 1 at MP 14/0 carry out repair with Viafix.	12/03/2018	12/03/2018 P1	11440 11440/66	M77 SB MP 14/0	12/03/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0	IMMEDIATE
11445/11 M77 S/B: OFF SLIP TO GSO MAIDENHILL INTERCHANGE	11526 DBTL	Car Tyre at start of slip road	12/03/2018	12/03/2018 P1	11445 11445/11	SB of slip to Jcn 5	12/03/2018 SC	CARRIAGEWAY	4	CAT-1 Permanent	0	IMMEDIATE
11445/08 M77 S/B: A77 OVERBRIDGE AT MALLETSHEUGH TO MAIDENHILL	11541 ACCD	RTC . Transerve Gritter has Lost Control and Damaged 25 mtrs of TCB safety Barrier in centre reserve Just prior Jcn 5 Maldehill. Control Room has called to report Damage and Cleaned up Debris & Made s	13/03/2018	28/03/2018 P1	11445 11445/08	M77 SB Maidenhill.	11/04/2018 SC	SAFETY FENCE	8	CAT-1 Permanent	2	28 DAYS
11445/08 M77 S/B: A77 OVERBRIDGE AT MALLETSHEUGH TO MAIDENHILL	11540 OTHR	RTC . Transerve Gritter has Lost Control and Damaged 25 mtrs of TCB safety Barrier in centre reserve Just prior Jcn 5 Maldehill. Control Room has called to report Damage and Cleaned up Debris & Made s	13/03/2018	13/03/2018 I1	11445 11445/08	M77 SB Maidenhill.	14/03/2018 SC	SAFETY FENCE	8	CAT-1 Immediate	0	IMMEDIATE

11440/05 M77 N/B: KINGSWELL INT UNDERBRIDGE TO FLOAK FARM OVERBRIDGE	11545 DBHS	Large Metal chain in Hard Shoulder.	15/03/2018	15/03/2018 P1	11440 11440/05	M77 NB at Floak	15/03/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11440/65 M77 N/B: CAIRN ROAD UNDERBRIDGE TO MAIDENHILL INTERCHANGE	11544 DBHS	Car Tyre in hard Shoulder.	15/03/2018	15/03/2018 P1	11440 11440/65	M77 NB cairn road	15/03/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11440/91 M77 S/B: ON SLIP FROM MAIDENHILL INTERCHANGE	11542 DBTL	Broken Wooden Pallet in Traffic Lane.	15/03/2018	15/03/2018 P1	11440 11440/91	SB on slip Maidenhill	15/03/2018 SC	CARRIAGEWAY	4 CAT-1 Permanent	0 IMMEDIATE
11435/05 M77 N/B: START OF MOTORWAY TO B778 OVERBRIDGE AT FENWICK	11547 RWAY	TURN Sign to correct position No further action required. Debris in hard shoulder. Debris removed. No further action required.EXHAUST PIPE IN HARD SHOULDER	19/03/2018	19/03/2018 P1	11435 11435/05	M77 NORTH BOUND At FENWICK M77 S/B. OFF RAMP TO B778 STEWARTON ROAD AT FENWICK	19/03/2018 SG	SIGNS	8 CAT-1 Permanent	0 IMMEDIATE
11435/33 M77 S/B: OFF SLIP TO B778 FENWICK	11548 DBHS		19/03/2018	19/03/2018 P1	11435 11435/33		19/03/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11573 POTH	Small Pothole in Lane 1 at MP 14/1 Carry out Repair with Viafix.	19/03/2018	19/03/2018 P1	11440 11440/66	M77 SB at Jcn 5.	19/03/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11440/91 M77 S/B: ON SLIP FROM MAIDENHILL INTERCHANGE	11550 POTH	Various Small potholes on slip road carry out repairs with Viafix	19/03/2018	19/03/2018 P1	11440 11440/91	Maidenhill on slip Jcn 5	20/03/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11445/08 M77 S/B: A77 OVERBRIDGE AT MALLETSHEUGH TO MAIDENHILL	11549 DBHS	Large Piece of Plastic Pipe in hard Shoulder .	19/03/2018	19/03/2018 P1	11445 11445/08	M77 SB Maidenhill	19/03/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11440/09 M77 S/B: OFF SLIP TO A77 AT KINGSWELL INTERCHANGE	11568 LAMP	No Entry Sign Lamp out	20/03/2018	20/03/2018 P1	11440 11440/09	SB of Slip kingswell	25/03/2018 SS	SIGNS	3 CAT-1 Permanent	4 5 DAYS
11440/09 M77 S/B: OFF SLIP TO A77 AT KINGSWELL INTERCHANGE	11567 LAMP	Give way Sign Lamp Out	20/03/2018	20/03/2018 P1	11440 11440/09	SB of Slip kingswell	25/03/2018 SS	SIGNS	3 CAT-1 Permanent	4 5 DAYS
11435/15 M77 N/B: OFF SLIP TO B751 KILMAURS ROAD ROUNDABOUT	11569 LAMP	Keep Left Arrow Sign lamp out	20/03/2018	20/03/2018 P1	11435 11435/15	Nb of slip Fenwick Motors	25/03/2018 SS	SIGNS	8 CAT-1 Permanent	4 5 DAYS
11435/05 M77 N/B: START OF MOTORWAY TO B778 OVERBRIDGE AT FENWICK	11556 DBHS	Large Piece of Polythene Sheeting in Hard Shoulder.	22/03/2018	22/03/2018 P1	11435 11435/05	M77 NB start of Motorway	22/03/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11440/08 M77 N/B: ON SLIP FROM A77 AT KINGSWELL INTERCHANGE	11554 DBHS	Debris in hard shoulder. Debris removed. No further action required.Dead Fox in HARD SHOULDER Debris in traffic Lane (Lane 2). Debris removed. No further action required.Dead BADGER In TRAFFIC LANE AT MAIDENHILL	22/03/2018	22/03/2018 P1	11440 11440/08		22/03/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11555 DBTL		22/03/2018	22/03/2018 P1	11440 11440/66		22/03/2018 SC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11435/05 M77 N/B: START OF MOTORWAY TO B778 OVERBRIDGE AT FENWICK	11578 POTH	Pothole in Traffic Lane at MP 26/4 carry out Repair with Viafix.	23/03/2018	23/03/2018 P1	11435 11435/05	M77 Nb 26/4	23/03/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11435/31 M77 S/B: A719 OVERBRIDGE TO B778 OVERBRIDGE AT FENWICK	11575 POTH	Pothole in Lane 1 at MP 24/7 carry out Repair with Viafix.	23/03/2018	23/03/2018 P1	11435 11435/31	M77 SB MP 24/7	23/03/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11435/31 M77 S/B: A719 OVERBRIDGE TO B778 OVERBRIDGE AT FENWICK	11574 POTH	Pothole in Traffic Lane at MP 24/5 carry out Repair with Viafix.	23/03/2018	23/03/2018 P1	11435 11435/31	M77 SB MP 24/5	23/03/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11435/06 M77 S/B: B778 OVERBRIDGE AT FENWICK TO END OF MOTORWAY	11577 POTH	Various small potholes in both lanes 27/4 to 27/5 carry out Repair with Viafix.	24/03/2018	24/03/2018 P1	11435 11435/06	M77 SB at MP 27/4 to 27/5	24/03/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11435/06 M77 S/B: B778 OVERBRIDGE AT FENWICK TO END OF MOTORWAY	11576 POTH	Pothole in Traffic Lane at MP 26/8 carry out Repair with Viafix.	24/03/2018	24/03/2018 P1	11435 11435/06	M77 SB at MP 26/8	24/03/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11440/05 M77 N/B: KINGSWELL INT UNDERBRIDGE TO FLOAK FARM OVERBRIDGE	11582 POTH	various Small potholes in lane 1 from MP 18/5/ to 18/4 carry out Repairs with Viafix.	24/03/2018	24/03/2018 P1	11440 11440/05	M77 North prior Floak.	24/03/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	NO PRIOR.
11440/65 M77 N/B: CAIRN ROAD UNDERBRIDGE TO MAIDENHILL INTERCHANGE	11583 POTH	Potholes at MP 16/4 carry out Repairs with Viafix Debris in traffic Lane (Lane 1). Debris removed. No further action required.Large polythene sheet in HARD SHOULDER	24/03/2018	24/03/2018 P1	11440 11440/65	M77 NB MP 16/4	24/03/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11435/06 M77 S/B: B778 OVERBRIDGE AT FENWICK TO END OF MOTORWAY	11571 DBHS		26/03/2018	26/03/2018 P1	11435 11435/06	M77 S/B. B778 STEWARTON ROAD OVERBRIDGE TO END OF MOTORWAY	26/03/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11435/30 M77 N/B: B778 OVERBRIDGE AT FENWICK TO A719 OVERBRIDGE	11570 DBHS	Debris in hard shoulder. Debris removed. No further action required.CAR EXHAUST PIPE IN HARD SHOULDER	26/03/2018	26/03/2018 P1	11435 11435/30	M77 N/B: B778 STEWARTON ROAD TO A719 GALSTON ROAD	26/03/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11435/70 M77 N/B: A719 OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11580 ACCD	RTC M77 North at Drumtree Overbridge Vehicle has lost control & damaged 3 posts of wire rope safety barrier in central reserve. ISU Called to clean up debris and Make safe. ER/0039	26/03/2018	P1	11435 11435/70	M77 North at Drumtree Overbridge	23/04/2018 SC	SAFETY FENCE	8 CAT-1 Permanent	2 28 DAYS
11435/70 M77 N/B: A719 OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11579 OTHR	RTC M77 North at Drumtree Overbridge Vehicle has lost control & damaged 3 posts of wire rope safety barrier in central reserve. ISU Called to clean up debris and Make safe. ER/0039	26/03/2018	26/03/2018 I1	11435 11435/70	M77 North at Drumtree Overbridge	26/03/2018 SC	SAFETY FENCE	8 CAT-1 Immediate	0 IMMEDIATE
11440/05 M77 N/B: KINGSWELL INT UNDERBRIDGE TO FLOAK FARM OVERBRIDGE	11572 DBHS	Debris in hard shoulder. Debris removed. No further action required.WHEEL ARCH IN HARD SHOULDER	26/03/2018	26/03/2018 P1	11440 11440/05		26/03/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11440/91 M77 S/B: ON SLIP FROM MAIDENHILL INTERCHANGE	11584 POTH	Various Small potholes on slip road carry out Repairs with Viafix	26/03/2018	26/03/2018 P1	11440 11440/91	SB of slip Maidenhill.	26/03/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11435/31 M77 S/B: A719 OVERBRIDGE TO B778 OVERBRIDGE AT FENWICK	11586 DBHS	Large Wooden Board on Hard Shoulder.	29/03/2018	29/03/2018 P1	11435 11435/31	M77 S/B. A719 GALSTON ROAD TO B778 STEWARTON ROAD OVERBRIDGE	29/03/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11445/08 M77 S/B: A77 OVERBRIDGE AT MALLETSHEUGH TO MAIDENHILL	11587 DBHS	Plastic Cover on Hard Shoulder.	29/03/2018	29/03/2018 P1	11445 11445/08		29/03/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11435/71 M77 S/B: KINGSWELL INT UNDERBRIDGE TO A719 OVERBRIDGE	11593 DBHS	Ratchet Strap in Hard Shoulder	02/04/2018	02/04/2018 P1	11435 11435/71	M77 SB Galston O/B	02/04/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11435/71 M77 S/B: KINGSWELL INT UNDERBRIDGE TO A719 OVERBRIDGE	11592 DBHS	Ratchet Strap in Hard Shoulder	02/04/2018	03/04/2018 I1	11435 11435/71	M77 SB Galston O/B	02/04/2018 SC	HARD SHOULDER	4 CAT-1 Immediate	0 IMMEDIATE
11440/05 M77 N/B: KINGSWELL INT UNDERBRIDGE TO FLOAK FARM OVERBRIDGE	11595 POTH	2 potholes at MP 20/2 in Lane 1 Carry out Repairs with Viafix	02/04/2018	02/04/2018 P1	11440 11440/05	M77 Nb at MP 20/2	02/04/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11440/05 M77 N/B: KINGSWELL INT UNDERBRIDGE TO FLOAK FARM OVERBRIDGE	11594 POTH	3 potholes at MP 21/7 in Lane 1 Carry out Repairs with Viafix	02/04/2018	02/04/2018 P1	11440 11440/05	M77 NB at MP 21/7	02/04/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11440/35 M77 N/B: FLOAK FARM OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11596 POTH	4 x potholes at MP 18/6 to 18/5 Carry out Repairs with Viafix	02/04/2018	02/04/2018 P1	11440 11440/35	M77 NB MP 18/6	02/04/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11440/65 M77 N/B: CAIRN ROAD UNDERBRIDGE TO MAIDENHILL INTERCHANGE	11597 POTH	2 x Large potholes in Lane 1 at MP 14/0 & 14/1 Carry out Repairs With Viafix.	02/04/2018	02/04/2018 P1	11440 11440/65	M77 NB just at Maidenhill	02/04/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11435/10 M77 S/B: OFF SLIP TO SOUTH END OF FENWICK	11612 LAMP	No Entry Sign lamp out	03/04/2018	03/04/2018 P1	11435 11435/10	SB of Slip Laigh Fenwick	08/04/2018 SS	SIGNS	3 CAT-1 Permanent	4 5 DAYS
11435/10 M77 S/B: OFF SLIP TO SOUTH END OF FENWICK	11611 LAMP	D/Reg sign lamp out	03/04/2018	03/04/2018 P1	11435 11435/10	SB of Slip Laigh Fenwick	08/04/2018 SS	SIGNS	3 CAT-1 Permanent	4 5 DAYS
11435/33 M77 S/B: OFF SLIP TO B778 FENWICK	11610 LAMP	All Lamps Out Dark Section	03/04/2018	03/04/2018 P1	11435 11435/33	SB of Slip to Fenwick	03/04/2018 SLF	LIGHTING POINT	3 CAT-1 Permanent	4 5 DAYS
11440/09 M77 S/B: OFF SLIP TO A77 AT KINGSWELL INTERCHANGE	11591 DBHS	Plastic Barrel in hard Shoulder,	03/04/2018	03/04/2018 P1	11440 11440/09	M77 SB of slip Kingswell	02/04/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11440/91 M77 S/B: ON SLIP FROM MAIDENHILL INTERCHANGE	11590 OTHR	Car Tyre on Verge.	03/04/2018	03/04/2018 P1	11440 11440/91	SB on slip Jcn 5	02/04/2018 SC	VERGE	3 CAT-1 Permanent	0 IMMEDIATE
11440/35 M77 N/B: FLOAK FARM OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11600 OTHR	Large Container on Verge.	05/04/2018	05/04/2018 P1	11440 11440/35	M77 NB at Floak	05/04/2018 SC	VERGE	3 CAT-1 Permanent	0 IMMEDIATE
11440/35 M77 N/B: FLOAK FARM OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11599 OTHR	Large Container on Verge.	05/04/2018	05/04/2018 I1	11440 11440/35	M77 NB at Floak	05/04/2018 SC	VERGE	3 CAT-1 Immediate	0 IMMEDIATE
11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	11598 DBTL	Builders Rubble in Hard Shoulder	05/04/2018	05/04/2018 P1	11445 11445/07	M77 NB Maidenhill	05/04/2018 SC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE
11435/05 M77 N/B: START OF MOTORWAY TO B778 OVERBRIDGE AT FENWICK	11613 DBHS	Debris in hard shoulder. Debris removed. No further action required.Large polythene sheet in HARD SHOULDER	09/04/2018	09/04/2018 P1	11435 11435/05	M77 N/B. START OF MOTORWAY TO B778 STEWARTON ROAD O'BRIDGE AT FENWICK	09/04/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11440/36 M77 S/B: CAIRN ROAD UNDERBRIDGE TO FLOAK FARM OVERBRIDGE	11616 DBHS	Large Piece of Chain in hard shoulder.	09/04/2018	09/04/2018 P1	11440 11440/36		09/04/2018 SC	HARD SHOULDER	4 CAT-1 Permanent	0 IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11617 POTH	Large pothole in lane 1 at MP 14/2 on Traffic loops.Repaired with Viafix	09/04/2018	09/04/2018 P1	11440 11440/66	M77 NB at Mp 14/2.	09/04/2018 MC	CARRIAGEWAY	5 CAT-1 Permanent	0 IMMEDIATE

11435/30 M77 N/B: B778 OVERBRIDGE AT FENWICK TO A719 OVERBRIDGE	11622 POTH	Small pothole in Lane 1 at Mp 24/7 Repair with Viafix	11/04/2018	11/04/2018 P1	11435 11435/30	M77 NB MP 24/7	11/04/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0 IMMEDIATE
11440/05 M77 N/B: KINGSWELL INT UNDERBRIDGE TO FLOAK FARM OVERBRIDGE	11620 POTH	Small pothole in Lane 1 at Mp 20/1 Repair with Viafix.	11/04/2018	11/04/2018 P1	11440 11440/05	M77 NB MP 20/1.	11/04/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0 IMMEDIATE
11440/36 M77 S/B: CAIRN ROAD UNDERBRIDGE TO FLOAK FARM OVERBRIDGE	11621 POTH	Small pothole in Lane 1 at Mp 16/2 Repair with Viafix.	11/04/2018	11/04/2018 P1	11440 11440/36	M77 NB MP 16/2	11/04/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0 IMMEDIATE
11445/11 M77 S/B: OFF SLIP TO GSO MAIDENHILL INTERCHANGE	11623 POTH	2 Potholes in outside lane just at 40 MPH signs Repair with Viafix.	11/04/2018	11/04/2018 P1	11445 11445/11	SB of slip to Maidenhill.	11/04/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0 IMMEDIATE
11440/06 M77 S/B: FLOAK FARM OVERBRIDGE TO KINGSWELL INT UNDERBRIDGE	11625 DBHS	Debris in hard shoulder. Debris removed. No further action required.Large polythene sheet in hard shoulder	12/04/2018	12/04/2018 P1	11440 11440/06		12/04/2018 SC	HARD SHOULDER	4	CAT-1 Permanent	0 IMMEDIATE
11440/08 M77 N/B: ON SLIP FROM A77 AT KINGSWELL INTERCHANGE	11624 DBTL	Debris in traffic Lane (Lane 2). Debris removed. No further action required.Large pieces of broken wood in traffic lane	12/04/2018	12/04/2018 P1	11440 11440/08		12/04/2018 SC	CARRIAGEWAY	Y	CAT-1 Permanent	0 IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11626 OTHR	Barrier repairs due toDebris in L/H Verge. Debris removed. No further action required RTC DAMAGE TO Verge	12/04/2018	12/04/2018 P1	11440 11440/66		12/04/2018 SC	VERGE	3	CAT-1 Permanent	NO PRIOR.
11435/30 M77 N/B: B778 OVERBRIDGE AT FENWICK TO A719 OVERBRIDGE	11628 OTHR	Car Tyre on Verge.	16/04/2018	16/04/2018 P1	11435 11435/30	M77 NB at Stewarton Road	16/04/2018 SC	VERGE	1	CAT-1 Permanent	0 IMMEDIATE
11440/08 M77 N/B: ON SLIP FROM A77 AT KINGSWELL INTERCHANGE	11668 SILT	Filter drain silted in centre reserve from Mp 13/6 to 14/2.	16/04/2018	16/04/2018 P1	11440 11440/08		17/04/2018 FD	FILTER DRAIN	8	CAT-1 Permanent	0 IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11669 FMDM	Filter drain silted in centre reserve from Mp 15/5 to 18/2.	16/04/2018	16/04/2018 P1	11440 11440/66		17/04/2018 FD		8	CAT-1 Permanent	0 IMMEDIATE
11440/66 M77 S/B: MAIDENHILL INT OVERBRIDGE TO CAIRN ROAD UNDERBRIDGE	11629 DBHS	Plastic Pole in Hard Shoulder,	16/04/2018	16/04/2018 P1	11440 11440/66	M77 SB Cairn Road.	16/04/2018 SC	HARD SHOULDER	4	CAT-1 Permanent	0 IMMEDIATE
11440/90 M77 N/B: OFF SLIP TO A726 MAIDENHILL INTERCHANGE	11634 POTH	Small pothole in lane 1	16/04/2018	16/04/2018 P1	11440 11440/90	M77 NB of slip to Maidenhill	17/04/2018 MC	CARRIAGEWAY	Y	CAT-1 Permanent	0 IMMEDIATE
11440/90 M77 N/B: OFF SLIP TO A726 MAIDENHILL INTERCHANGE	11631 POTH	Small Pothole at Bottom of slip Road Repair with Viafix	16/04/2018	16/04/2018 P1	11440 11440/90	NB of slip Jcn 5	16/04/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0 IMMEDIATE
11445/11 M77 S/B: OFF SLIP TO GSO MAIDENHILL INTERCHANGE	11635 OTHR	Carrigeway resurfacing work on of slip & Roadmarkings & studs	16/04/2018	16/04/2018 P1	11445 11445/11	SB of slip Maidenhill.	16/04/2018 MC	CARRIAGEWAY	Y	CAT-1 Permanent	0 IMMEDIATE
11445/10 M77 N/B: ON SLIP FROM A726 MAIDENHILL INTERCHANGE	11636 OTHR	Carrigeway resurfacing work on slip road & Roadmarkings & studs.	17/04/2018	17/04/2018 P1	11445 11445/10	NB on Slip from Maidenhill	18/04/2018 MC	CARRIAGEWAY	Y	CAT-1 Permanent	0 IMMEDIATE
11435/30 M77 N/B: B778 OVERBRIDGE AT FENWICK TO A719 OVERBRIDGE	11637 POTH	Small Pothole in Lane 1 at MP 24/6 carry out Repair with Viafix.	18/04/2018	18/04/2018 P1	11435 11435/30	M77 NB MP 24/6	18/04/2018 MC	CARRIAGEWAY	5	CAT-1 Permanent	0 IMMEDIATE