

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/12/2017 and 18/04/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST: ON SLIP FROM B7038 TO M77 DBFO BOUNDARY',) Or

(Section is 'AGAINST: M77 DBFO BDY TO OFF SLIP TO A76/A71 SB',) Or

(Section is 'AGAINST: OFF SLIP A76/A71 TO 300M N WHATRIGGS BRID',) Or

(Section is 'WITH: OFF SLIP TO B7038 TO START OF MOTORWAY',) Or

(Section is 'WITH: OFF SLIP TO B7038 TO ON SLIP FROM B7038',) Or

(Section is 'WITH: ON SLIP FROM A76/A71 TO M77 DBFO BOUNDARY',) Or

(Section is 'WITH: HURLFORD INTERCHANGE-JCT OF N/B TR.ROAD',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

11656/12 : AGAINST: OFF SLIP A76/A71 TO 300M N WHATRIGGS BRID

Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 05 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 12 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 19 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 03 April 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 10 April 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 17 April 2018

No defects recorded

11656/17 : WITH: HURLFORD INTERCHANGE-JCT OF N/B TR.ROAD

Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 05 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 12 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 19 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

SW82317163-235513442	117m	120m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/01/2018	Completed Defects	27/02/2018	A77 NB ONSLIP, BELLFIELD, BRIDGE JOINT
----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	---

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 03 April 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 10 April 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 17 April 2018

No defects recorded

11656/22 : WITH: ON SLIP FROM A76/A71 TO M77 DBFO BOUNDARY

Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 05 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 12 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 19 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

SW82317695-235522277	1,543m	1,544m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/02/2018	Completed Defects	09/02/2018	A77 SB CW, LANE 2 500M STH OF GRASSYARDS ONSLIP SB
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

SW82318553-235533633	264m	266m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/03/2018	Completed Defects	22/02/2018	A77 NB CW, LANE 1, 300M NTH OF BELLFIELD NB ONSLIP
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

SW82326369-235553167	656m	657m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB LAYBY, 1ST LAYBY NTH OF BELLFIELD INT
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

SW82326369-235553169	669m	700m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB LAYBY, 1ST LAYBY NTH OF BELLFIELD INT
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

SW82326369-235553166	644m	645m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, 1ST LAYBY AFTER BELLFIELD
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--------------------------------------

SW82326369-235553168	648m	649m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB LAYBY, 1ST LAYBY NTH OF BELLFIELD INT
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

SW82327521-235576663	1,422m	1,423m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/04/2018	Completed Defects	14/03/2018	A77 NB CW, 500M STH OF GRASSYARDS, LANE 2
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018
 SW82329522-235601242 3,196m 3,197m GULLY Other (OTHR) CAT 1 17/04/2018 Completed Defects 21/03/2018 A77 NB CW, ON CENTER, 500M STH OF MIEKLEWOOD

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 03 April 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018

SW82335189-235618856 446m 0m CARRIAGEWAY Pothole VIAFIX (POTV) CAT 1 07/04/2018 Completed Defects 06/04/2018 A77 S/B 400M PRIOR TO BELLFIELD OFF SLIP

Safety Inspection of A76 & A77 Ayr North V1 on 10 April 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 17 April 2018

No defects recorded

11656/24 : AGAINST: M77 DBFO BDY TO OFF SLIP TO A76/A71 SB

Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 05 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 12 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 December 2017

SW82316898-235497619 2,403m 2,404m CARRIAGEWAY Pothole (POTH) CAT 1 12/01/2018 Completed Defects 24/02/2018 A77 SB CW LANE 1 700M STH OF GRASSYARDS ONSLIP

Safety Inspection of A76 & A77 Ayr North V1 on 19 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 December 2017

SW82317041-235510684 2,769m 2,789m FENCES_AND_BARRIERS Damaged / deformed - fence / barrier (DAMM) CAT 1 19/01/2018 Completed Defects 16/02/2018 A77 NB VERGE, 150M NTH OF RAILBRIDGE, NTH OF BELLFIELD INTERCHANGE

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

SW82317163-235513447 2,775m 2,795m FENCES_AND_BARRIERS Accident damage (ACCD) CAT 1 26/01/2018 Completed Defects 13/02/2018 A77 CENTR ISLAND, 200M NTH OF FOOTBRIDGE NTH OF BELLFIELD

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

SW82317357-235513862 2,421m 2,422m CARRIAGEWAY Pothole (POTH) CAT 1 02/02/2018 Completed Defects 20/02/2018 A77 S/B ON CENTRE LINE 500M SOUTH OF ON SLIP FROM GRASSYARDS

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

SW82317695-235522278 2,297m 2,298m CARRIAGEWAY Pothole (POTH) CAT 1 16/02/2018 Completed Defects 20/02/2018 A77 SB CW, LANE 2, 550M STH OF GRASSYARDS SB ONSLIP

SW82317695-235522276 2,014m 2,015m CARRIAGEWAY Pothole (POTH) CAT 1 16/02/2018 Completed Defects 22/02/2018 A77 SB CW LANE 2 GRASSYARDS SB ONSLIP

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018**

SW82317812-235529553	3,329m	3,330m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/02/2018	Completed Defects	01/02/2018	A77 SB CW, 400M NTH OF BELLFIELD INTERCHANGE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018**

SW82320263-235545151	3,896m	3,898m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/03/2018	Completed Defects	22/02/2018	A77 SB CW, BELLFIELD OFFSLIP, AT START OF SLIP
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018**

SW82328364-235586142	2,280m	2,282m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	17/03/2018	A77 SB CW, LANE 2, 550M STH OF GRASSYARDS
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82328364-235586144	2,433m	2,434m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	17/03/2018	A77 SB CW, LANE 2, 600M STH OF GRASSYARDS SB ONSLIP
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82328364-235586141	2,227m	2,228m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	17/03/2018	A77 SB CW, LANE 2, 500M STH OF SB GRASSYARDS ONSLIP
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

SW82328364-235586143	2,381m	2,383m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	17/03/2018	A77 SB CW, ON CL, 575M STH OF GRASSYARDS SB ONSLIP
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

SW82328364-235586140	2,127m	2,128m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	17/03/2018	A77 SB CW, LANE 2, 400M STH OF GRASSYARDS SB ONSLIP
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018*No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 27 March 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 03 April 2018**

SW82334242-235618381	3,932m	3,942m	CARRIAGEWAY	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A77 S/B AT START OF S/B OF SLIP BELFIELD INTERCHANGE
----------------------	--------	--------	-------------	--------------	-------	------------	-----------------------	------------	--

Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 10 April 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018**

SW82337186-235634094	154m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/05/2018	Completed Defects	13/04/2018	A77 S/B PRIOR TO LAYBY BETWEEN MIEKLEWOOD AND GRASSYARD
----------------------	------	----	-------------	-------------------	-------	------------	----------------------	------------	---

Safety Inspection of A76 & A77 Ayr North V1 on 17 April 2018

No defects recorded

11656/90 : WITH: OFF SLIP TO B7038 TO START OF MOTORWAY

Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 05 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 12 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 19 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018
No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 March 2018
No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 03 April 2018
No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 10 April 2018
No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 17 April 2018
No defects recorded