

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 09/05/2017 and 09/05/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A702',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
13501/13 : BRIDGE OVER WANDEL BURN TO HARTSIDE									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
SE65278190-235178477	425m	0m	SAFETY_FENCE	Other (OTHR)	CAT 1	28/06/2017	Completed Defects	31/05/2017	nb at Wandel Bridge
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
SE65282717-235277903	86m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	23/08/2017	Completed Defects	01/09/2017	nb just before wandel wind farm
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
SE65315778-235449278	17m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	29/11/2017	Completed Defects	17/11/2017	A702 N/B IN LAYBY PRIOR TO WINDFARM NORTH OF WANDEL
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
SE65317775-235528438	810m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2018	Completed Defects	17/02/2018	A702 S/B SOUTH OF HEARTSIDE 1/2 MILE PRIOR TO WINDFARM
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
SE55318109-235529621	1,161m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	28/02/2018	Completed Defects	17/02/2018	A702 Wandel Area.
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
SE57329533-235594423	3m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/04/2018	Completed Defects	17/04/2018	A702 N/B START OF LAYBY 50M PRIOR TO WINDFARM ENTRANCE/WANDEL
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
SE65338306-235650533	780m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/05/2018	Completed Defects	19/04/2018	A702 S/B WANDEL 1/2 MILE PRIOR TO WIND FARM
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
No defects recorded									
13501/31 : HARTSIDE TO JCT OVERBURNS									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
SE65278190-235178478	1,905m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 1	28/06/2017	Completed Defects	18/10/2017	nb prior to lamington gateway
SE65278190-235178479	1,961m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	28/06/2017	Completed Defects	07/06/2017	just be4 lamington phone box
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
SE65281357-235202433	2,919m	0m	EMBANKMENTS_A ND_CUTTINGS	Other (OTHR)	CAT 1	19/07/2017	Completed Defects	29/07/2017	sb 400m prior to lamington at hpuse on bend
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
SE67282331-235263639	1,965m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	09/08/2017	Completed Defects	12/07/2017	STH OF LAMington toll
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
SE67282542-235268415	362m	0m	GULLY	Collapsed (COLP)	CAT 1	16/08/2017	Completed Defects	15/08/2017	nb just after hrtsidecottage
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
SE65315644-235445287	4,066m	0m	EMBANKMENTS_A ND_CUTTINGS	Other (OTHR)	3RD PTY	22/11/2017	Completed Defects	25/10/2017	A702 SB 200m SOUTH OF OVERBURNS COTTAGES LAMINGTON left verge
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
SE65316367-235473915	1,520m	0m	LIGHTING_POINT	Accident damage (ACCD)	CAT 1	20/12/2017	Completed Defects	12/01/2018	A702 N/B AT LAMINGTON SOUTH GATEWAYS
SE65316367-235473914	2,117m	0m	GULLY	Blockage (BLOK)	CAT 1	20/12/2017	Completed Defects	24/11/2017	A702 S/B LAMINGTON CROSSROADS OPPOSITE BUS STOP
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
SE65316467-235483305	2,118m	0m	GULLY	Blockage (BLOK)	CAT 1	27/12/2017	Completed Defects	08/02/2018	A702 S/B AT LAMINGTON CROSSROADS AT BROOKSIDE COTTAGE
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
SE65317306-235511258	1,696m	0m	ROAD_STUDS	Missing (MISS)	CAT 1	31/01/2018	Completed Defects	09/02/2018	A702 SB DOUBLE WHITE LINES AT LAMINGTON KENNELS
SE65317306-235511260	118m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	31/01/2018	Completed Defects	25/01/2018	A702 SB SOUTH OF RIGSIDE JCT OPP WHITE COTTAGE
SE65317306-235511259	27m	0m	ROAD_STUDS	Missing (MISS)	CAT 1	31/01/2018	Completed Defects	09/02/2018	A702 SB DOUBLE WHITE LINES SOUTH OF RIGSIDE JCT TO HARTSIDE FARM
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
SE57318919-235534059	859m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	07/03/2018	Completed Defects	10/04/2018	A702 S/B AT RIGSIDE JUNCTION
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
SE65319457-235541669	3,360m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/03/2018	Completed Defects	22/02/2018	A702 S/B 20M PRIOR TO ENTRANCE FOR LOANHEAD FARM
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
SE55321401-235545072	245m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	21/03/2018	Completed Defects	15/03/2018	A702 SB 1 mile South of Lamington
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
SE65334232-235615524	3,436m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/05/2018	Completed Defects	01/05/2018	A702 N/B 100m NORTH OF LOANHEAD FARM
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									
13501/58 : JCT OVERBURNS TO COULTER									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
SE65276222-235161776	3,473m	0m	STRUCTURE	Damaged Parapets (DAMP)	CAT 1	19/07/2017	Completed Defects	21/07/2017	sb on coulter bridge
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
SE65278989-235189463	2,421m	0m	CARRIAGEWAY	Other (OTHR)	3RD PTY	05/07/2017	Completed Defects	07/06/2017	sb just after john deere
SE65278989-235189462	3,465m	0m	STRUCTURE	Damaged Parapets (DAMP)	CAT 1	02/08/2017	Completed Defects	21/07/2017	sb coulter bridge
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
SE65279796-235193494	1,985m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	12/07/2017	Completed Defects	23/06/2017	nb just prior to unthank farm
SE65279796-235193495	3,465m	0m	STRUCTURE	Damaged Parapets (DAMP)	CAT 1	09/08/2017	Completed Defects	21/07/2017	sb on coulter bridge
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
SE65283548-235305455	3,390m	0m	GULLY	Cracked or broken (IBCK)	CAT 1	13/09/2017	Completed Defects	11/09/2017	sb at the mill inn coulter
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
SE65283771-235326268	2,001m	0m	GRASSED_AREAS	Other (OTHR)	3RD PTY	20/09/2017	Completed Defects	23/08/2017	nb after unthank farm
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
SE65316999-235497883	3,478m	0m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	17/01/2018	Completed Defects	03/01/2018	A702 COULTER BRIDGE SB
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
SE65317306-235511255	3,479m	0m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	31/01/2018	Completed Defects	19/03/2018	A702 NB ON COULTER BRIDGE
SE65317306-235511256	3,482m	0m	ROAD_STUDS	Missing (MISS)	CAT 1	31/01/2018	Completed Defects	09/02/2018	A702 SB DOUBLE WHITE LINES AT COULTERS BRIDGE
SE65317306-235511257	3,201m	0m	ROAD_STUDS	Missing (MISS)	CAT 1	31/01/2018	Completed Defects	09/02/2018	A702 SB DOUBLE WHITE LINES AT COULTER SOUTH GATEWAYS
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									
13501/80 : COULTER TO A72 JNCTN SOUTH OF BIGGAR									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
SE65278190-235178480	495m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	28/06/2017	Completed Defects	23/06/2017	nb COULTER just after side road to bridge
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
SE65316099-235457100	1,903m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	06/12/2017	Completed Defects	25/11/2017	A702 SB SOUTH OF BIGGAR AT EASTFIELD FARM ENTRANCE

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
SE65316099-235457101	1,910m	0m	EMBANKMENTS_AND_CUTTINGS	Other (OTHR)	CAT 1	06/12/2017	Completed Defects	24/11/2017	A702 SB SOUTH OF BIGGAR AT EASTFIELD FARM ENTRANCE
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
SE65316367-235473916	2,235m	0m	CARRIAGEWAY	Flooding (FLOD)	CAT 1	20/12/2017	Completed Defects	22/11/2017	A702 N/B SOUTH OF CAUSEWAYEND
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
SE65316999-235497882	298m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/01/2018	Completed Defects	11/01/2018	A702 S/B COULTER 10m SOUTH OF NEWHOLM OF COULTER
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
SE65319457-235541670	318m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/03/2018	Completed Defects	14/03/2018	A702 S/B 300M PRIOR TO COULTER BRIDGE
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
SE55321401-235545071	1,272m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	21/03/2018	Completed Defects	14/03/2018	A702 NB 1m south of Causewayend
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
No defects recorded									
13511/05 : A72 SOUTH JUNCTION TO A72 NORTH JUNCTION									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
SE65278989-235189464	1,393m	0m	CARRIAGEWAY	Flooding (FLOD)	CAT 1	05/07/2017	Completed Defects	07/06/2017	os sainsburys
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
SE65281357-235202435	2,065m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	3RD PTY	19/07/2017	Completed Defects	21/06/2017	A702 NB OUTSIDE 16 EDINBURGH RD
SE65281357-235202434	1,296m	0m	CARRIAGEWAY	Other (OTHR)	3RD PTY	19/07/2017	Completed Defects	21/06/2017	A702 NB OUTSIDE 43 BIGGAR HIGH ST
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
SE67282542-235268414	1,275m	0m	CARRIAGEWAY	Miscellaneous surface Defects (MSRF)	CAT 1	16/08/2017	Completed Defects	16/08/2017	os 30 high st
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
SE65282717-235277901	1,658m	0m	TRAFFIC_SIGNAL S	Damaged (DAMG)	CAT 1	23/08/2017	Completed Defects	19/07/2017	nb north biggar ped xing
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
SE65316689-235487204	1,349m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/01/2018	Completed Defects	20/12/2017	A702 BIGGAR NB OUTSIDE THE BARONY RESTAURANT
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
SE65316999-235497881	1,720m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/01/2018	Completed Defects	11/01/2018	A702 BIGGAR SB OPPOSITE WILLIAM OVENS BUTCHERS
SE65316999-235497880	1,648m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/01/2018	Completed Defects	11/01/2018	A702 BIGGAR S/B OPPOSITE THE ELPHINSTONE ARMS PUB
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
SE65317306-235511254	1,731m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	31/01/2018	Completed Defects	11/01/2018	A702 S/B OPP WILLIAM OVENS BUTCHERS ON MAIN ST
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
SE57317450-235514035	2,059m	0m	MANHOLE	Rocking under load (IRLD)	3RD PTY	07/02/2018	Completed Defects	10/01/2018	A702 NB OUTSIDE 18 EDINBURGH ROAD BIGGAR
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
SE65319457-235541672	2,187m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/03/2018	Completed Defects	07/03/2018	A702 NB 50m prior to north gateway
SE65319457-235541671	1,742m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/03/2018	Completed Defects	07/03/2018	A702 S/B OUTSIDE TOWNHEAD CHIPPY
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
SE55321401-235545070	1,847m	0m	GULLY	Blockage (BLOK)	CAT 1	21/03/2018	Completed Defects	09/03/2018	A702 NB o/s Police Station in Biggar
SE55321401-235545069	1,849m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	21/03/2018	Completed Defects	21/03/2018	A702 NB o/s police station in Biggar
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
SE57325531-235549209	1,487m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	04/04/2018	Completed Defects	03/04/2018	A702 N/B BIGGAR HIGH ST OPPOSITE HEART AND HOME STORE
SE57325531-235549210	1,662m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	04/04/2018	Completed Defects	03/04/2018	A702 N/B OUTSIDE DIAMOND HAIR AND BEAUTY SALON BIGGAR HIGH ST BEFORE AND AFTER TRAFFIC LIGHTS
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
SE57329533-235594424	2,207m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/04/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 N/B 20M PRIOR TO NORTH GATEWAYS, BIGGAR
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
SE65331518-235607674	1,349m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/04/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 N/B OUTSIDE BARONY RESTAURANT BIGGAR
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
SE65334232-235615525	1,537m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/05/2018	Completed Defects	01/05/2018	A702 BIGGAR N/B OPPOSITE NEW IMAGE SALON
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
No defects recorded									
13520/05 : NORTH BIGGAR TO SOUTH CANDYBANK									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
SE65273048-235158019	308m	0m	MANHOLE	Damaged (DAMG)	CAT 1	14/06/2017	Completed Defects	12/06/2017	nb hillview cottage bigar
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
SE65278190-235178482	2,778m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	28/06/2017	Completed Defects	23/06/2017	sb bapp 400 m after elsrickle
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
SE65282834-235289836	245m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/08/2017	Completed Defects	18/08/2017	A702 N/B 250m NORTH OF SKIRLING JCT
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
SE65299574-235372248	2,237m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/10/2017	Completed Defects	21/09/2017	A702 EB 20m PRIOR TO BACKSHIELDS FARM ENTRANCE NORTH OF BIGGER
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
SE65316099-235457099	900m	0m	EMBANKMENTS_A ND_CUTTINGS	Other (OTHR)	3RD PTY	06/12/2017	Completed Defects	08/11/2017	A702 s/b 100m south of tofcombs farm prior to bigger
SE65316099-235457098	908m	0m	EMBANKMENTS_A ND_CUTTINGS	Other (OTHR)	CAT 1	06/12/2017	Completed Defects	05/12/2017	A702 SB 100m south of tofcombs farm prior to bigger
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
SE57317450-235514037	2,452m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	02/02/2018	A702 S/B 50M PRIOR TO BACKSHIELS FARM PRIOR TO BIGGAR
SE57317450-235514036	2,244m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/02/2018	Completed Defects	02/02/2018	A702 N/B PRIOR TO BACKSHIELS FARM NORTH OF BIGGAR
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
SE65317775-235528439	2,454m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2018	Completed Defects	17/02/2018	A702 S/B SOUTH OF CANDYMILL 200M PRIOR TO BACKSHIELS FARM
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
SE57318919-235534060	2,325m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/03/2018	Completed Defects	17/02/2018	A702 N/B 50M NORTH OF BACKSHIELS FARM
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
SE55327537-235554819	26m	0m	MANHOLE	Cracked or broken (IBCK)	CAT 1	11/04/2018	Completed Defects	15/03/2018	A702 NB footway 1km north biggar
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
SE65331518-235607675	2,370m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/04/2018	Completed Defects	25/04/2018	A702 N/B 300M PAST BACKSHIELDS FARM 1 MILE PRIOR CANDYMILL
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
SE55336331-235619230	3,135m	0m	TRAFFIC_SIGNS	Surface corrosion (SFCO)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A702 NB at Elsrickle jct
SE55336331-235619231	2,474m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	09/05/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 SB 1 milesouth Candymill
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
No defects recorded									
13520/43 : SOUTH CANDYBANK TO A721 JCT AT MELBOURNE									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
SE65278190-235178481	0m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	28/06/2017	Completed Defects	31/05/2017	nb candymill tm
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
SE57325531-235549211	1,774m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 1	04/04/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 N/B AND S/B CANDY MILL BENDS
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									
13525/05 : A721 JCT AT MELBOURNE TO MEADOWHEAD									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
SE65283548-235305456	2,403m	0m	GULLY	Cracked or broken (IBCK)	CAT 1	13/09/2017	Completed Defects	12/09/2017	nb at hillsidegardens
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
SE65299574-235372249	1,986m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	11/10/2017	Completed Defects	26/09/2017	A702 NB 350m PRIOR TO DOLPHINGTON LEFT VERGE
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
SE65315345-235426349	253m	0m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	08/11/2017	Completed Defects	01/11/2017	A720 S/B 200M PRIOR TO MELBOURNE JCT
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
SE65334232-235615527	387m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/05/2018	Completed Defects	01/05/2018	A702 N/B 400M NORTH OF MELBOURNE JCT
SE65334232-235615526	256m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/05/2018	Completed Defects	01/05/2018	A702 S/B 250M PRIOR TO CARLUKE JCT (MELBOURNE JCT
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
SE62343107-235678780	1,645m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/05/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 SB 200M AFTER TOWN FOOT FARM, SOUTH OF DOLPHINGSTON, LEFT EDGE
13525/63 : MEADOWHEAD TO REGIONAL BOUNDARY									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
SE65317644-235519608	951m	0m	MANHOLE	Rocking under load (IRLD)	CAT 1	14/02/2018	Completed Defects	09/03/2018	A702 Dolphington N/B outside BT exchange 300m prior to Carmaben Brae
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
SE55318109-235529623	966m	0m	MANHOLE	Rocking under load (IRLD)	CAT 1	28/02/2018	Completed Defects	28/02/2018	A702 NB in North of Dolphinton

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
SE55321401-235545068	989m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	21/03/2018	Completed Defects	15/03/2018	A702SB in North part of Dolphinton
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
SE62343107-235678777	1,228m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/05/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 NB, AT 40MPH RED SCREED MARKINGS EXITING DOLPHINGTON, LEFT EDGE
SE62343107-235678778	438m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	30/05/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 NB AT MACKENZIE GARDENS JCT, DOLPHINGTON, LEFT EDGE
13531/05 : STRATHCL. BOUND. TO GOLF COURSE RD. W.L.									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
SE65273048-235158020	5,865m	0m	TRAFFIC_SIGNS	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	at gateway sign
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
SE65281666-235235375	1,333m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/07/2017	Completed Defects	14/07/2017	A702 NB NORTH OF THE OLD CREAMERY NORTH OF DOLPHINGTON
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
SE67282331-235263638	273m	0m	GULLY	Other (OTHR)	CAT 1	09/08/2017	Completed Defects	14/07/2017	SB just before entrance to layby
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
SE65283771-235326269	3,499m	0m	CARRIAGEWAY	Patch - difference in level (PDLV)	CAT 1	20/09/2017	Completed Defects	11/09/2017	sb layby dolphinton straight
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
SE65316467-235483304	3,187m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/12/2017	Completed Defects	20/12/2017	A702 S/B AT START OF DOLPHINTON STRAIGHT 200M SOUTH OF LAYBY
SE65316467-235483303	3,430m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/12/2017	Completed Defects	20/12/2017	A702 S/B START OF DOLPHINTON STRAIGHT AFTER LAYBY
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
SE65317644-235519609	3,493m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/02/2018	Completed Defects	25/01/2018	A702 S/B south of west linton 100m prior to and at layby at start of dolphinton straight
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
SE55318109-235529624	237m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	28/02/2018	Completed Defects	21/03/2018	A702 SB north of Dolphinton

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
SE55321401-235545073	3,477m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	21/03/2018	Completed Defects	07/03/2018	A702 SB at layby at start of Dolphinton Straight
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
SE55327537-235554820	121m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/04/2018	Completed Defects	30/03/2018	A702 SB pat Layby prior to Dolphinton
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
SE57329533-235594425	248m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/04/2018	Completed Defects	18/04/2018	A702 N/B 400M NORTH OF DOLPHINTON
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
SE65331518-235607676	3,344m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/04/2018	Completed Defects	25/04/2018	A702 S/B AT START OF DOLPHINTON STRAIGHT END OF LAYBY TO BURNHAM FARM JCT
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									
13534/05 : 30 MPHS WEST LINTON TO JCT. SOUTH MAINS									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
SE65282146-235253428	1,432m	0m	Drainage Ancillary Items	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	nb prior to rutherford junction in layby
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
SE65316823-235495412	138m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/01/2018	Completed Defects	10/01/2018	A702 SB 150M PRIOR TO WEST LINTON
SE65316823-235495413	122m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/01/2018	Completed Defects	10/01/2018	A702 N/B 125M NORTH OF WEST LINTON
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
SE65317775-235528440	2,249m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2018	Completed Defects	10/02/2018	A702 N/B 100M NORTH OF RUTHERFORD CASTLE JCT PRIOR TO CARLOPS
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
SE57318919-235534062	455m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/03/2018	Completed Defects	10/02/2018	A702 S/B 400M PRIOR TO WEST LINTON
SE57318919-235534061	1m	1m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/03/2018	Completed Defects	17/02/2018	A702 S/B 100M PRIOR TO ROBINLAND RBT, WEST LINTON
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
SE55321401-235545066	2,280m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	21/03/2018	Completed Defects	15/03/2018	A702 SB Slip after Carlops, Prior to Rutherford jct.
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
SE55327537-235554823	2,547m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/04/2018	Completed Defects	30/03/2018	A702 NB opp. Rutherford castle jct
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
SE65331518-235607677	143m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/04/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 S/B 150M PRIOR TO WEST LINTON
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
SE55336331-235619232	598m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/05/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 NB 1km north West Linton
SE55336331-235619233	2,746m	0m	TRAFFIC_SIGNS	Surface corrosion (SFCO)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A702 NB 160m south Macbiehill jct
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
SE65340434-235660867	1,434m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/05/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 S/B 500M PRIOR TO ROBINSLAND R/B
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
No defects recorded									
13535/05 : JCT. SOUTH MAINS TO LOTHIAN BOUNDARY									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
SE65282146-235253427	472m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	02/08/2017	Completed Defects	30/08/2017	SB JUST PRIOR TO LAST 30 SIGN
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702				Safety Inspection on 16 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 23 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 30 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 06 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 13 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 20 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 27 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 04 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 11 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 18 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 25 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 01 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 08 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 15 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 22 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 29 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 06 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 13 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 20 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 27 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 03 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 10 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 17 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 24 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 31 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 07 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 14 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 21 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 28 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 07 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 14 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 21 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 28 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 04 April 2018					

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017 SE65316999-235497879	32m	0m	GULLY	Rocking under load (IRLD)	CAT 1	17/01/2018	Completed Defects	10/01/2018	A702 carlops SB 100m from gateway signs
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									
13561/20 : CORNER OF FIELD (E) TO END OF KERB									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 07 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 14 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 21 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 28 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 07 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 14 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 21 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 28 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 04 April 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 11 April 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 18 April 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 25 April 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 02 May 2018					
				<i>No defects recorded</i>					

13561/42 : END OF KERB TO START OF NEW HALL LAYBY

Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 10 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 17 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 24 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 31 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 07 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 14 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 21 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 28 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 05 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 12 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 19 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 26 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 02 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 09 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 16 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 23 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 30 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 06 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 13 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 20 September 2017					

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 27 September 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 04 October 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 11 October 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 18 October 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 25 October 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 01 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 08 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 15 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 22 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 29 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 06 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 13 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 20 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 27 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 03 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 10 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 17 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 24 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 31 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 07 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 14 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 21 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 28 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 07 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 14 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 21 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 28 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 04 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 11 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 18 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 25 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 02 May 2018
No defects recorded

13561/52 : START OF NEW HALL LAYBY TO START OF VERGE

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 10 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 17 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 24 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 31 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 07 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 14 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 21 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 28 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 05 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 12 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 19 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 26 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 02 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 09 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 16 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 23 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 30 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 06 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 13 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 20 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 27 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 04 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 11 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 18 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 25 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 01 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 08 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 15 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 22 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 29 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 06 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 13 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 20 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 27 December 2017					

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 03 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 10 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 17 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 24 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 31 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 07 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 14 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 21 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 28 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 07 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 14 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 21 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 28 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 04 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 11 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 18 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 25 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 02 May 2018
No defects recorded

13561/73 : START OF VERGE TO END OF VERGE

Safety Inspection of Amey A702 Safety Inspection on 10 May 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 17 May 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 24 May 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 31 May 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 07 June 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 14 June 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 21 June 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 28 June 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 05 July 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 12 July 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 19 July 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 26 July 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 02 August 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 09 August 2017
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 16 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 23 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 30 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 06 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 13 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 20 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 27 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 04 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 11 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 18 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 25 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 01 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 08 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 15 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 22 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 29 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 06 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 13 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 20 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 27 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 03 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 10 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 17 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 24 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 31 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 07 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 14 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 21 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 28 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 07 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 14 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 21 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 28 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 04 April 2018					

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018
No defects recorded

13561/85 : END OF VERGE TO A766 PENICUIK

Safety Inspection of Amey A702 Safety Inspection on 10 May 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
SE55318109-235529625	255m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	28/02/2018	Completed Defects	10/02/2018	A702 SB at Nine mile burn advance direction sign.
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
SE65319457-235541673	161m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/03/2018	Completed Defects	10/02/2018	A702 S/B 300M PRIOR TO NINE MILE BURN JCT
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									
13562/07 : A766 PENICUIK TO C57 SILVERBURN ROAD									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
SE65283548-235305453	722m	0m	GULLY	Other (OTHR)	CAT 1	13/09/2017	Completed Defects	12/09/2017	as above
SE65283548-235305454	640m	0m	GULLY	Other (OTHR)	CAT 1	13/09/2017	Completed Defects	12/09/2017	1/2 mile ater penicuik jctn
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
SE65317306-235511253	1,784m	0m	ROAD_STUDS	Missing (MISS)	CAT 1	31/01/2018	Completed Defects	09/02/2018	A702 SB DOUBLE WHITE LINES SOUTH OF SILVERBURN
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
SE55318109-235529626	1,841m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	28/02/2018	Completed Defects	17/02/2018	A702 NB 1 mile prior to Silverburn on bends.
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
SE65331518-235607678	2,018m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/04/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 S/B OPP EAST SIDE FARM SOUTH OF SILVERBURN
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
SE65338306-235650534	1,759m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/05/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 N/B ON BENDS 1/2 MILE PRIOR TO SILVERURN
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									
13563/07 : C57 SILVERBURN RD TO JCT GRANGE DELL									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
SE65270184-235132840	14m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 1	07/06/2017	Completed Defects	07/06/2017	21 silverburnsb
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
SE65276222-235161775	371m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/06/2017	Completed Defects	07/06/2017	opp Silerburn laybyon nth side
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
SE65282146-235253426	91m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/08/2017	Completed Defects	28/07/2017	A702 NB prior to last house silverburn
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
SE65317306-235511252	167m	0m	ROAD_STUDS	Missing (MISS)	CAT 1	31/01/2018	Completed Defects	09/02/2018	A702 SB DOUBLE WHITE LINES AT START OF SILVERBURN
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
SE65319457-235541674	118m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/03/2018	Completed Defects	09/03/2018	A702 N/B SILVERBURN 200M PRIOR TO NORTH GATEWAYS
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
SE55327537-235554824	374m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/04/2018	Completed Defects	03/04/2018	A702 NB exit out of Silverburn
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
SE62343107-235678781	639m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	30/05/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 NB SILVERBURN STRAIGHT 300M AFTER 40MPH SIGNS
13563/69 : JCT GRANGE DELL TO C41 BELLWOOD RD									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 04 October 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 11 October 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 18 October 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 25 October 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 01 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 08 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 15 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 22 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 29 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 06 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 13 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 20 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 27 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 03 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 10 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 17 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 24 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 31 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 07 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 14 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 21 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 28 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 07 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 14 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 21 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 28 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 04 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 11 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 18 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 25 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 02 May 2018
No defects recorded

13564/05 : C41 BELLWOOD RD TO U71 GLENCORSE KIRK RD

Safety Inspection of Amey A702 Safety Inspection on 10 May 2017
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702				Safety Inspection on 17 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 24 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 31 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 07 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 14 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 21 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 28 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 05 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 12 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 19 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 26 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 02 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 09 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 16 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 23 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 30 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 06 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 13 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 20 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 27 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 04 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 11 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 18 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 25 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 01 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 08 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 15 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 22 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 29 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 06 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 13 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 20 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 27 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 03 January 2018					

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
SE65319457-235541675	242m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/03/2018	Completed Defects	14/03/2018	A702 N/B AND S/B 300M NORTH OF MORRISWOOD JCT AND 100M PRIOR TO MORRISWOOD JCT
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									
13564/62 : U71 GLENCORSE KIRK RD TO C40 BUSHLOAN RD									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
SE65317306-235511251	858m	0m	ROAD_STUDS	Missing (MISS)	CAT 1	31/01/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 SB DOUBLE WHITE LINES EASTER HOWGATE PRIOR TO BUSH JCT
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018
 No defects recorded

13565/05 : C40 BUSHLOAN ROAD TO A703 PEEBLES ROAD

Safety Inspection of Amey A702 Safety Inspection on 10 May 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017

SE65281357-235202436	158m	0m	CARRIAGEWAY	Miscellaneous surface Defects (MSRF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	just nth of the bush jctn
----------------------	------	----	-------------	--------------------------------------	-------	------------	-----------------------	------------	---------------------------

Safety Inspection of Amey A702 Safety Inspection on 28 June 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017
 No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
SE65315483-235430959	87m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 1	15/11/2017	Completed Defects	23/10/2017	A702 S/B EASTER HOWGATE ON BEND PRIOR TO BUSH JCT
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
SE65317306-235511249	2,507m	0m	ROAD_STUDS	Missing (MISS)	CAT 1	31/01/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 SB DOUBLE WHITE LINES AT OLD PENTLAND JCT
SE65317306-235511250	1,884m	0m	ROAD_STUDS	Missing (MISS)	CAT 1	31/01/2018	Awaiting CCMS Permanent Date	01/01/9999	A702 SB AT DOUBLE WHITE LINES ADJACENT TO ERRAID COTTAGE SOUTH OF HILLEND
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
13570/00 : A703 PEBBLES ROAD TO LOTHIANBURN CULVERT									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
SE65315644-235445288	315m	0m	MANHOLE	Rocking under load (IRLD)	CAT 1	22/11/2017	Completed Defects	06/11/2017	A702 SB OPPOSITE JCT FOR HILLEND SKI CENTER
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									
13575/05 : LOTHIANBURN CULVERT TO 40MPH SIGNS									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
SE65281357-235202437	74m	0m	BOLLARDS	Damaged (DAMG)	CAT 1	19/07/2017	Completed Defects	28/09/2017	<i>nb just after bus turning circle and entrance for park</i>
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018 <i>No defects recorded</i>									
13575/40 : 40MPH SIGNS TO SOUTH ROUNDABOUT A720									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017 <i>No defects recorded</i>									
SE55309876-235378306	161m	0m	MANHOLE	Rocking under load (IRLD)	CAT 1	18/10/2017	Completed Defects	17/10/2017	A702 S/B +N/B 500 m south of lothianburn roundabouts
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018
No defects recorded

13575/60 : SOUTH ROUNDABOUT A720 TO A720 LOTHIANBURN JCT

Safety Inspection of Amey A702 Safety Inspection on 10 May 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702				Safety Inspection on 14 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 21 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 28 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 05 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 12 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 19 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 26 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 02 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 09 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 16 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 23 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 30 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 06 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 13 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 20 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 27 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 04 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 11 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 18 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 25 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 01 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 08 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 15 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 22 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 29 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 06 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 13 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 20 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 27 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 03 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 10 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 17 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 24 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 31 January 2018					

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									

13575/65 : WITH: SOUTH ROUNDABOUT TO NORTH ROUNDABOUT

Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702			Safety Inspection	on 20 September 2017					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 27 September 2017					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 04 October 2017					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 11 October 2017					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 18 October 2017					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 25 October 2017					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 01 November 2017					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 08 November 2017					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 15 November 2017					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 22 November 2017					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 29 November 2017					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 06 December 2017					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 13 December 2017					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 20 December 2017					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 27 December 2017					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 03 January 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 10 January 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 17 January 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 24 January 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 31 January 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 07 February 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 14 February 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 21 February 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 28 February 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 07 March 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 14 March 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 21 March 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 28 March 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 04 April 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 11 April 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 18 April 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 25 April 2018					
<i>No defects recorded</i>									
Safety Inspection of Amey A702			Safety Inspection	on 02 May 2018					
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
13575/70 : AGAINST: NORTH ROUNDABOUT TO SOUTH ROUNDABOUT									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017 <i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017 <i>No defects recorded</i>									
SE65316689-235487205	137m	0m	GULLY	Difference in level with road (IDLV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A702 SB LOTHIANBURN BRIDGE
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017 <i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
SE65317306-235511248	46m	0m	BOLLARDS	Accident damage (ACCD)	CAT 1	31/01/2018	Completed Defects	24/01/2018	A702 E/B START OF LOTHIANBURN ONSLIP
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									

13575/90 : NORTH ROUNDABOUT TO LOTHIANBURN JUNCTION

Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017 SE65289199-235362521	21m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	04/10/2017	Completed Defects	12/09/2017	nth roundabout lothianburn
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017 SE65316099-235457102	19m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	06/12/2017	Completed Defects	21/11/2017	A702 LOTHIANBURN R/ABOUT OPPOSITE A720 EB LOTHIANBURN OFF-SLIP
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									
13500/15 : WITH: ABINGTON INT SB RBT EXIT TO N END DUAL CWAY									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
SE65283926-235348187	54m	0m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	27/09/2017	Completed Defects	27/09/2017	A702 NB 50m NORTH OF ABBINGTON RBT C/RES
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 11 October 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 18 October 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 25 October 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 01 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 08 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 15 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 22 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 29 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 06 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 13 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 20 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 27 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 03 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 10 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 17 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 24 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 31 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 07 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 14 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 21 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 28 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 07 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 14 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 21 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 28 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 04 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 11 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 18 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 25 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 02 May 2018
No defects recorded

13500/16 : AGAINST: N END OF DUAL CWAY TO ABINGTON INT SB RBT

Safety Inspection of Amey A702 Safety Inspection on 10 May 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 17 May 2017
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 24 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 31 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 07 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 14 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 21 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 28 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 05 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 12 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 19 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 26 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 02 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 09 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 16 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 23 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 30 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 06 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 13 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 20 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 27 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 04 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 11 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 18 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 25 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 01 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 08 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 15 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 22 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 29 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 06 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 13 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 20 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 27 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 03 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 10 January 2018					

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
SE62343107-235678779	138m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A702 SB APPROX. 100M PRIOR TO ABINGTON INT RBT, LEFT VERGE

13500/05 : ABINGTON INT NORTHBOUND ROUNDABOUT

Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
SE65282717-235277902	6m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	23/08/2017	Completed Defects	28/07/2017	on north roundabout abington
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
SE57317450-235514034	65m	65m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	07/02/2018	Completed Defects	06/02/2018	A702 NB ABINGTON R/B OPP JCT FOR CRAWFORDJOHN
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 28 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 04 April 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 11 April 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 18 April 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 25 April 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 02 May 2018					
				<i>No defects recorded</i>					

13500/08 : ABINGTON INT NB RBT EXIT TO ABINGTON INT SB RBT

Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 10 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 17 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 24 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 31 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 07 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 14 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 21 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 28 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 05 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 12 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 19 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 26 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 02 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 09 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 16 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 23 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 30 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 06 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 13 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 20 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 27 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 04 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 11 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 18 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 25 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 01 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 08 November 2017					

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018
No defects recorded

13500/10 : ABINGTON INTERCHANGE SOUTHBOUND ROUNDABOUT

Safety Inspection of Amey A702 Safety Inspection on 10 May 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017
No defects recorded
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702				Safety Inspection on 28 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 05 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 12 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 19 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 26 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 02 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 09 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 16 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 23 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 30 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 06 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 13 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 20 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 27 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 04 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 11 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 18 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 25 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 01 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 08 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 15 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 22 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 29 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 06 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 13 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 20 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 27 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 03 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 10 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 17 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 24 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 31 January 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 07 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 14 February 2018					

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									
13533/07 : GOLF COURSE ROAD TO ROBINS LAND ROUNDABOUT									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
SE67282331-235263637	125m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Completed Defects	31/03/2018	SB south of gordon arms
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
SE65289199-235362522	229m	0m	Drainage Ancillary Items	Other (OTHR)	3RD PTY	04/10/2017	Completed Defects	06/09/2017	nb opp gordon arms

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
SE65289199-235362523	182m	0m	GULLY	Other (OTHR)	CAT 1	04/10/2017	Completed Defects	21/09/2017	nb at manor garage
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
SE55321401-235545067	130m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A702 NB in West Linton opp B7059
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
SE55327537-235554821	178m	0m	GULLY	Blockage (BLOK)	CAT 1	11/04/2018	Completed Defects	04/04/2018	A702 SB o/s Gordon Arms
SE55327537-235554822	180m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/04/2018	Completed Defects	30/03/2018	A702 SB o/s Gordon Arms
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

Safety Inspection of Amey A702 Safety Inspection on 04 April 2018

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 11 April 2018

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 18 April 2018

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 25 April 2018

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 02 May 2018

No defects recorded

13533/79 : ROBINS LAND RBT TO 30MPH NORTH OF WEST LINTON

Safety Inspection of Amey A702 Safety Inspection on 10 May 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 17 May 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 24 May 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 31 May 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 07 June 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 14 June 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 21 June 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 28 June 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 05 July 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 12 July 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 19 July 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 26 July 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 02 August 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 09 August 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 16 August 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 23 August 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 30 August 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 06 September 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 13 September 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 20 September 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 27 September 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 04 October 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 11 October 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 18 October 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 25 October 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 01 November 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 08 November 2017

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 15 November 2017

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
SE65316231-235470535	12m	0m	BOLLARDS	Accident damage (ACCD)	CAT 1	13/12/2017	Completed Defects	12/02/2018	A702 SB ON THE SPLITTER ISLAND AT ROBIN LAND RBT, WEST LINTON
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									

13533/68 : ROBINS LAND ROUNDABOUT

Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
SE65283771-235326267	12m	0m	GRASSED_AREAS	Other (OTHR)	CAT 1	20/09/2017	Completed Defects	01/09/2017	robinsland RBT
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702				Safety Inspection on 07 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 14 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 21 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 28 February 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 07 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 14 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 21 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 28 March 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 04 April 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 11 April 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 18 April 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 25 April 2018					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 02 May 2018					
				<i>No defects recorded</i>					

13500/45 : NORTH END DUAL C/WAY TO MAIDENCOTS RBT

Safety Inspection of Amey A702				Safety Inspection on 10 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 17 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 24 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 31 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 07 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 14 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 21 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 28 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 05 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 12 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 19 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 26 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 02 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 09 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 16 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 23 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 30 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 06 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 13 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702				Safety Inspection on 20 September 2017					

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 27 September 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 04 October 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 11 October 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 18 October 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 25 October 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 01 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 08 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 15 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 22 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 29 November 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 06 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 13 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 20 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 27 December 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 03 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 10 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 17 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 24 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 31 January 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 07 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 14 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 21 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 28 February 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 07 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 14 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 21 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 28 March 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 04 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 11 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 18 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 25 April 2018
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 02 May 2018
No defects recorded

13500/90 : MAIDENCOTS ROUNDABOUT

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 10 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 17 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 24 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 31 May 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 07 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 14 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 21 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 28 June 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 05 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 12 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 19 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 26 July 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 02 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 09 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 16 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 23 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 30 August 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 06 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 13 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 20 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 27 September 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 04 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 11 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 18 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 25 October 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 01 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 08 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 15 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 22 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 29 November 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 06 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 13 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 20 December 2017					
				<i>No defects recorded</i>					
Safety Inspection of Amey A702			Safety Inspection	Safety Inspection on 27 December 2017					

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									

13501/07 : MAIDENCOTS RBT TO BR OVER WANDEL BURN

Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
SE65276222-235161777	936m	0m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	21/06/2017	Completed Defects	07/06/2017	wandel rail bridge
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
SE65317306-235511261	1,631m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	31/01/2018	Completed Defects	25/01/2018	A702 NB 400M PRIOR TO WINDFARM ENTRANCE
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
SE57318919-235534058	1,217m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/03/2018	Completed Defects	17/02/2018	A702 S/B 150M PRIOR TO WANDEL BURN BRIDGE
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
SE65319457-235541668	565m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/03/2018	Completed Defects	14/02/2018	A702 N/B RIVER CLYDE BRIDGE
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									