

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 12/01/2017 and 20/03/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WEST MAINS ROUNDABOUT',) Or

(Section is 'WITH: EB WEST MAINS RBT OT EAGLESHAM RD RBT',) Or

(Section is 'WITH: EB EAGLESHAM RD RBT TO RIGHEAD RBT',) Or

(Section is 'WITH: EB RIGHEAD RBT TO THE MURRAY RBT (QUEENSWAY)',) Or

(Section is 'WEST MAINS ROUNDABOUT',) Or

(Section is 'EAGLESHAM ROAD ROUNDABOUT',) Or

(Section is 'WITH: EB THE MURRAY RBT TO BIRNIEHILL RBT',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
14945/85 : WITH: EB WEST MAINS RBT OT EAGLESHAM RD RBT									
Safety Inspection of A725 & A726 Tannochside V1 on 16 January 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 23 January 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 30 January 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017									
No defects recorded									

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018
No defects recorded

14945/90 : EAGLESHAM ROAD ROUNDABOUT

Safety Inspection of A725 & A726 Tannochside V1 on 16 January 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 January 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 January 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018
No defects recorded

14950/47 : WITH: EB RIGHEAD RBT TO THE MURRAY RBT (QUEENSWAY)

Safety Inspection of A725 & A726 Tannochside V1 on 16 January 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 23 January 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 30 January 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018
No defects recorded

14950/85 : WITH: EB THE MURRAY RBT TO BIRNIEHILL RBT

Safety Inspection of A725 & A726 Tannochside V1 on 16 January 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 January 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 January 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017

Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017

Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017

Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017

Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017

Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017

A726 EB 30M PAST MURRAY
RBT LANE 1 NS WT

Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017

Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017

Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017

Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017

Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017

Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017

Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017

Safety Inspection of A725 & A726 Tannochside V1 on 23 October 2017

Safety Inspection of A725 & A726 Tannochside V1 on 30 October 2017

Safety Inspection of A725 & A726 Tannochside V1 on 06 November 2017

Safety Inspection of A725 & A726 Tannochside V1 on 13 November 2017

Safety Inspection of A725 & A726 Tannochside V1 on 20 November 2017

Safety Inspection of A725 & A726 Tannochside V1 on 26 November 2017

Safety Inspection of A725 & A726 Tannochside V1 on 04 December 2017

Safety Inspection of A725 & A726 Tannochside V1 on 11 December 2017

Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017

Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017

Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017

Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018

Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018

Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018

Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018

Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018

Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018

Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018

Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018

Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018

No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018									
No defects recorded									
Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018									
SW85-327259-235553269	5m	0m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	09/04/2018	Completed Defects	26/03/2018	A726 EB 5M PAST MURRAY RBT
Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018									
No defects recorded									

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2017 and 20/03/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST: WB EAGLESHAM RD RBT TO WEST MAINS RBT',) Or

(Section is 'AGAINST: WB RIGHEAD RBT TO EAGLESHAM ROAD RBT',) Or

(Section is 'AGAINST: WB THE MURRAY RBT TO RIGHEAD RBT',) Or

(Section is 'AGAINST: WB BIRNIEHILL RBT TO THE MURRAY RBT',) On

(Section is 'BIRNIEHILL ROUNDABOUT',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
14945/86 : AGAINST: WB EAGLESHAM RD RBT TO WEST MAINS RBT									
Safety Inspection of A725 & A726 Tannochside V1 on 06 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 09 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 16 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 23 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 30 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017									
<i>No defects recorded</i>									

Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018

Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018

Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018

Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018

Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018

Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018

Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018

Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018

Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018

Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018

Safety Inspection of A725 & A726 Tannochside V1 on 06 January 2017

Safety Inspection of A725 & A726 Tannochside V1 on 09 January 2017

Safety Inspection of A725 & A726 Tannochside V1 on 16 January 2017

Safety Inspection of A725 & A726 Tannochside V1 on 23 January 2017

Safety Inspection of A725 & A726 Tannochside V1 on 30 January 2017

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2011

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2011

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 201

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017

Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017

Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017

Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017

Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017

Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017

Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017

Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017

Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017

Safety Inspection of A725 & A726 Tannochside V1 on 28 August 2017

Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017

Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017

Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017

Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017

Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017

Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017

Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017

Safety Inspection of A725 & A726 Tannochside V1 on 23 October 2017

Safety Inspection of A725 & A726 Tannochside V1 on 30 October 2017

Safety Inspection of A725 & A726 Tannochside V1 on 06 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018

No defects recorded