

Date	Location	Description
12/04/2018	Whole section Calderglen Park to South Road	the whole stretch of road from its dual carriageway start near Calderglen park to the Thorntonhall/Busby/Castlemilk roundabout is in a woeful, parlous state.
04/10/2017	Peel Park Place to Redwood Drive	There are huge deep potholes mainly down the centre line but also many ravaged spots in the centre of all lanes.
22/11/2018	Queensway	<p>There are insufficient safe crossing points across the carriageway for pedestrians. There are a significant number of workers in the Peel Park area and in the HMRC, Holiday Inn etc. There is no safe crossing point near this area.</p> <p>One side of the carriageway has no pavement access. The closest pedestrian bridge is at the retail park where Aldi is located. This means that pedestrians have to walk a significant distance only to then double back to gain access to the industrial park and bus stops at the other side. This results in a number of pedestrians risking their lives trying to run across four lanes of traffic.</p>

