

Done Date/Time	Location	Section Reference	Activity Type Description	Section Description	Road Part	Activity	Observations?	Start	End	L.A.Code?	Link Id	Done Date	Date Due	Frequency	Late?	Composite Act.	Parameter 1 Value	Parameter 2 Value	Parameter 3 Value	Survey
13/02/2017 10:59	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	13/02/2017	13/02/2017	1 Week	N		Fine	Dry		8832
16/02/2017 10:24	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	16/02/2017	16/02/2017	1 Week	N		Rain	Wet		8835
20/02/2017 10:56	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	20/02/2017	20/02/2017	1 Week	N		Rain	Wet		8837
21/02/2017 14:04	11656/88	11656/88	Lamp Scout	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	LPS	N	0	952.1	N	11656	21/02/2017	21/02/2017	14 Days	N		Rain	Wet		8839
21/02/2017 14:04	11656/88	11656/88	Spec: Lamp Col - Lamp Failure	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SLF	N	0	952.1	N	11656	21/02/2017	27/11/2019	4 Weeks	N	LPS				8839
21/02/2017 14:04	11656/88	11656/88	Signs - Lamp Failure	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SS	N	0	952.1	N	11656	21/02/2017	27/11/2019	4 Weeks	N	LPS				8839
23/02/2017 12:57	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	23/02/2017	23/02/2017	1 Week	N		Rain	Wet		8841
27/02/2017 13:05	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	27/02/2017	27/02/2017	1 Week	N		Fine	Dry		8842
02/03/2017 10:49	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	02/03/2017	02/03/2017	1 Week	N		Fine	Dry		8846
06/03/2017 12:19	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	06/03/2017	06/03/2017	1 Week	N		Fine	Dry		8847
07/03/2017 06:00	11656/88	11656/88	Lamp Scout	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	LPS	N	0	952.1	N	11656	07/03/2017	07/03/2017	14 Days	N		Fine	Dry		8848
07/03/2017 06:00	11656/88	11656/88	Spec: Lamp Col - Lamp Failure	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SLF	N	0	952.1	N	11656	07/03/2017	25/12/2019	4 Weeks	N	LPS				8848
07/03/2017 06:00	11656/88	11656/88	Signs - Lamp Failure	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SS	N	0	952.1	N	11656	07/03/2017	25/12/2019	4 Weeks	N	LPS				8848
09/03/2017 12:37	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	09/03/2017	09/03/2017	1 Week	N		Fine	Dry		8851
13/03/2017 11:38	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	13/03/2017	13/03/2017	1 Week	N		Fine	Dry		8853
16/03/2017 10:27	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	Y	0	952.1	Y	11656	16/03/2017	16/03/2017	1 Week	N		Rain	Wet		8855
20/03/2017 11:20	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	20/03/2017	20/03/2017	1 Week	N		Rain	Wet		8856
22/03/2017 07:53	11656/88	11656/88	Lamp Scout	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	LPS	N	0	952.1	N	11656	22/03/2017	21/03/2017	14 Days	Y		Rain	Wet		8861
22/03/2017 07:53	11656/88	11656/88	Spec: Lamp Col - Lamp Failure	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SLF	N	0	952.1	N	11656	22/03/2017	22/01/2020	4 Weeks	N	LPS				8861
22/03/2017 07:53	11656/88	11656/88	Signs - Lamp Failure	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SS	N	0	952.1	N	11656	22/03/2017	22/01/2020	4 Weeks	N	LPS				8861
23/03/2017 11:46	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	23/03/2017	23/03/2017	1 Week	N		Rain	Wet		8863
27/03/2017 08:01	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	27/03/2017	27/03/2017	1 Week	N		Fine	Dry		8864
30/03/2017 11:58	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	30/03/2017	30/03/2017	1 Week	N		Fine	Wet		8869
03/04/2017 10:53	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	03/04/2017	03/04/2017	1 Week	N		Fine	Dry		8873
04/04/2017 05:30	11656/88	11656/88	Lamp Scout	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	LPS	N	0	952.1	N	11656	04/04/2017	04/04/2017	14 Days	N		Fine	Dry		8874
04/04/2017 05:30	11656/88	11656/88	Spec: Lamp Col - Lamp Failure	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SLF	N	0	952.1	N	11656	04/04/2017	19/02/2020	4 Weeks	N	LPS				8874
04/04/2017 05:30	11656/88	11656/88	Signs - Lamp Failure	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SS	N	0	952.1	N	11656	04/04/2017	19/02/2020	4 Weeks	N	LPS				8874
06/04/2017 11:15	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	06/04/2017	06/04/2017	1 Week	N		Fine	Dry		8876
10/04/2017 10:36	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	Y	0	952.1	Y	11656	10/04/2017	10/04/2017	1 Week	N		Fine	Dry		8878
13/04/2017 10:31	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	13/04/2017	13/04/2017	1 Week	N		Fine	Dry		8881
17/04/2017 10:25	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	17/04/2017	17/04/2017	1 Week	N		Fine	Dry		8882
20/04/2017 10:52	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	20/04/2017	20/04/2017	1 Week	N		Fine	Dry		8886
24/04/2017 08:05	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	24/04/2017	24/04/2017	1 Week	N		Fine	Dry		8887
27/04/2017 10:15	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	Y	0	952.1	Y	11656	27/04/2017	27/04/2017	1 Week	N		Fine	Dry		8888
01/05/2017	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	01/05/2017	01/05/2017	1 Week	N		Fine	Dry		8890
02/05/2017	11656/88	11656/88	Lamp Scout	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	LPS	N	0	952.1	N	11656	02/05/2017	02/05/2017	4 Weeks	N		Fine	Dry		8896
02/05/2017	11656/88	11656/88	Spec: Lamp Col - Lamp Failure	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SLF	N	0	952.1	N	11656	02/05/2017	18/03/2020	4 Weeks	N	LPS				8896
02/05/2017	11656/88	11656/88	Signs - Lamp Failure	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SS	N	0	952.1	N	11656	02/05/2017	18/03/2020	4 Weeks	N	LPS				8896
04/05/2017 10:30	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	04/05/2017	04/05/2017	1 Week	N		Fine	Dry		8923
08/05/2017 11:26	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	08/05/2017	08/05/2017	1 Week	N		Fine	Dry		8925
11/05/2017 14:07	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	11/05/2017	11/05/2017	1 Week	N		Fine	Dry		8926
15/05/2017 11:46	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	15/05/2017	15/05/2017	1 Week	N		Rain	Wet		8928
18/05/2017 09:50	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	18/05/2017	18/05/2017	1 Week	N		Fine	Dry		8934
19/05/2017	11656/88	11656/88	Road Studs Conspicuity	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	RC	N	0	952.1	N	11656	19/05/2017	19/05/2017	6 Months	N					8935
22/05/2017	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	22/05/2017	22/05/2017	1 Week	N		Fine	Dry		8936
25/05/2017	11656/88	11656/88	Grassed areas: Svalthe cut	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	68	N	0	952.1	Y	11656	25/05/2017	25/05/2017							
25/05/2017 13:06	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	25/05/2017	25/05/2017	1 Week	N		Fine	Dry		8937
29/05/2017	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	29/05/2017	29/05/2017	1 Week	N		Fine	Dry		8941
30/05/2017 10:21	11656/88	11656/88	Lamp Scout	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	LPS	N	0	952.1	N	11656	30/05/2017	30/05/2017	4 Weeks	N					9001
30/05/2017	11656/88	11656/88	Road Marking Retroreflectivity	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	RR	N	0	952.1	N	11656	30/05/2017	30/05/2017	2 Years	N					8940
01/06/2017 13:13	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	01/06/2017	01/06/2017	1 Week	N		Fine	Dry		9083
01/06/2017 10:21	11656/88	11656/88	Road Marking Retroreflectivity	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	RR	N	0	952.1	N	11656	01/06/2017	30/05							



23/01/2018 15:27	11656/88	11656/88	Signs - Lamp Failure	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SS	N	0	952.1	N	11656	23/01/2018	06/03/2018	4 Weeks	N	LPS				9291
25/01/2018 11:47	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	25/01/2018	25/01/2018	1 Week	N		Fine	Dry		9296
29/01/2018 19:21	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	29/01/2018	29/01/2018	1 Week	N		Fine	Dry		9297
01/02/2018 07:44	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	01/02/2018	01/02/2018	1 Week	N		Fine	Dry		9299
05/02/2018 10:42	11656/88	11656/88	Safety Inspection	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	SAF	N	0	952.1	N	11656	05/02/2018	05/02/2018	1 Week	N		Fine	Dry		9300
06/02/2018 12:25	11656/88	11656/88	Lamp Scout	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	LPS	N	0	952.1	N	11656	06/02/2018	06/02/2018	2 Weeks	N		Fine	Dry		9302
08/02/2018 10:10	11656/88	11656/88	Safety Patrol	11656/88 WITH: ON SLIP FROM B7038 TO B7061 JUNCTION SOUTH	A77	PAT	N	0	952.1	N	11656	08/02/2018	08/02/2018	1 Week	N		Fine	Dry		9304