

Defect Reference	Chainage	Item Type	Item Detail	Defect	Required	Current Status	Completion	Location Description	OI 1	OI 1 Area	OI 2	OI 2 Area
SE67251813-235068185	32m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2017	Completed Defects	06/04/2017	sb just prior to west linton gateway	OI/16SE04513	pothole No 1 - 1m x 3m, pothole No 2 - 1m x 1m	OI/16SE04677	Temporary fill
SE67253795-235071900	741m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2017	Completed Defects	13/04/2017	sb app 1/2 mile prior to west linton	OI/16SE04635	repair pothole around gully - approx 1m x 1m	OI/16SE04679	Temporary fill
SE65316823-235495412	138m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/01/2018	Completed Defects	10/01/2018	A702 SB 150M PRIOR TO WEST LINTON	OI/17SE04097	1M X 3M POTHOLE	OI/17SE04100	Temporary fill
SE65316823-235495413	122m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/01/2018	Completed Defects	10/01/2018	A702 N/B 125M NORTH OF WEST LINTON	OI/17SE04102	1M2 POTHOLE	OI/17SE04104	Temporary fill
SE57318919-235534062	455m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/03/2018	Completed Defects	10/02/2018	A702 S/B 400M PRIOR TO WEST LINTON	OI/17SE04954	1M2 POTHOLE ROUND GULLY FRAME	OI/17SE04955	Temporary fill
SE57318919-235534061	1m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/03/2018	Completed Defects	17/02/2018	A702 S/B 100M PRIOR TO ROBINLAND RBT, WE	OI/17SE04961	4 X POTHLES 2 X 1M2 / 1 X 2M X1M / 1X 4M X 1M	OI/17SE04962	Temporary fill
SE65331518-235607677	143m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/04/2018	Completed Defects	11/05/2018	A702 S/B 150M PRIOR TO WEST LINTON	OI/17SE05839	2 X POTHLES 1= 2M X 1M 2= 2M2	OI/17SE05840	Temporary fill
SE55336331-235619232	598m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/05/2018	Completed Defects	09/05/2018	A702 NB 1km north West Linton	OI/18SE00401	Made safe 1 no. 5m2 pothole.	OI/18SE00403	Temporary fill
SE65340434-235660867	1,434m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/05/2018	Completed Defects	11/05/2018	A702 S/B 500M PRIOR TO ROBINSLAND R/B	OI/18SE00717	1M2 POTHOLE ROUND GULLY	OI/18SE00719	Temporary fill
SE57346108-235731407	1,037m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/06/2018	Completed Defects	16/05/2018	A702 N/B NORTH OF ROBINSWOOD RBT 60M A	OI/18SE01047	Perm Repair - 1m2 POTHOLE AROUND GULLY FRAME	OI/18SE01048	Temporary fill
SE57346108-235731408	867m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/06/2018	Completed Defects	22/05/2018	A702 S/B PRIOR TO WEST LINTON, 40M B4 TOI	OI/18SE01051	Temp Repair - 1m2 POTHOLE AROUND GULLY FRAME	OI/18SE01052	Temporary fill
SE65316231-235470535	12m	BOLLARDS	Accident damage (ACCD)	CAT 1	13/12/2017	Completed Defects	12/02/2018	A702 SB ON THE SPLITTER ISLAND AT ROBIN I	OI/17SE03706	DAMAGED ILLUMINATED KEEP LEFT BOLLARD ASE229719	OI/17SE03707	Cones and make safe