

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/06/2015 and 30/06/2017, and defects raised outside of inspections on the same Section(s) during this period.

(Section Code is 13910/80) Or

(Section Code is 13910/91) Or

(Section Code is 13910/99)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>13910/80 : C473 TO FOWLIS WESTER TO U7 MILTON OF CULTOQUEHY</b>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 02 June 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 09 June 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 16 June 2015</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection TEMPLATE of A85 Detail West of Methven - 30mph E of Crieff on 23 June 2015</b>									
NWG1191244-170	371m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT
NWG1191244-177	1,516m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF ABERCAIRNY
NWG1191244-180	1,869m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF ABERCAIRNY
NWG1191244-173	660m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT
NWG1191244-174	640m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT
NWG1191244-184	2,085m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF ABERCAIRNY
NWG1191244-187	2,103m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF ABERCAIRNY
NWG1191244-181	2,193m	0m	FOOTWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF ABERCAIRNY
NWG1191244-183	2,088m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF ABERCAIRNY
NWG1191244-188	2,105m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF ABERCAIRNY
NWG1191244-179	1,721m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF ABERCAIRNY
NWG1191244-168	143m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT
NWG1191244-175	1,015m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT
NWG1191244-182	2,118m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF ABERCAIRNY
NWG1191244-189	2,103m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF ABERCAIRNY

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG1191244-171	590m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT
NWG1191244-172	878m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT
NWG1191244-185	2,074m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF ABERCAIRNY
NWG1191244-186	2,083m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF ABERCAIRNY
NWG1191244-169	202m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT
NWG1191244-176	1,338m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF ABERCAIRNY
NWG1191244-178	1,678m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF ABERCAIRNY

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 23 June 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 30 June 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 07 July 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 14 July 2015**

NWG11115307-1183437	712m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY
NWG11115307-1183436	703m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	11/08/2015	Completed Defects	27/07/2015	WEST OF FOWLIS WESTER JCT, W/B C/WAY

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 21 July 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 28 July 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 04 August 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 11 August 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 18 August 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 25 August 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 01 September 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 08 September 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 15 September 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 22 September 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 29 September 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 06 October 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 13 October 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 20 October 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 27 October 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 03 November 2015**

No defects recorded

**Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 10 November 2015**

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 17 November 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 24 November 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 01 December 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 08 December 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 15 December 2015</b>									
NWG11132252-1557256	1,295m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/01/2016	Completed Defects	07/01/2016	ABERCAIRNY, W/B C/WAY
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 22 December 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 29 December 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 05 January 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 12 January 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 19 January 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 26 January 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 02 February 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 09 February 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 16 February 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 23 February 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 01 March 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 08 March 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 15 March 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 22 March 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 29 March 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 05 April 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 12 April 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 19 April 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 26 April 2016</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection TEMPLATE of A85 30 SIGN WEST METHVEN TO 30 SIGN EAST CRIEFF on 28 April 2016</b>									
NWG21142421-114	699m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF NEW FOWLIS E/B VERGE
NWG21142421-121	1,930m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF MILTON OF CULTOQUEHY W/B VERGE
NWG21142421-110	300m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF NEW FOWLIS W/B VERGE
NWG21142421-120	1,840m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF MILTON OF CULTOQUEHY E/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG21142421-116	1,101m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF NEW FOWLIS E/B VERGE
NWG21142421-118	1,449m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF MILTON OF CULTOQUEHY W/B VERGE
NWG21142421-112	614m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF NEW FOWLIS W/B VERGE
NWG21142421-119	1,698m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF MILTON OF CULTOQUEHY W/B VERGE
NWG21142421-108	204m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF NEW FOWLIS W/B VERGE
NWG21142421-109	293m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF NEW FOWLIS E/B VERGE
NWG21142421-111	398m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF NEW FOWLIS E/B VERGE
NWG21142421-113	614m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF NEW FOWLIS E/B VERGE
NWG21142421-115	894m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF NEW FOWLIS W/B VERGE
NWG21142421-117	1,376m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF MILTON OF CULTOQUEHY W/B VERGE
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 03 May 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 10 May 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 17 May 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 24 May 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 31 May 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 07 June 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 14 June 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 21 June 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 28 June 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 05 July 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 12 July 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 19 July 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 26 July 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 02 August 2016</b>									
NWG21176745-2095874	431m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/08/2016	Completed Defects	02/08/2016	WEST OF NEW FOWLIS W/B C/WAY
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 09 August 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 16 August 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 23 August 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 30 August 2016</b>									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 06 September 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 13 September 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 20 September 2016</b>									
NWG21186916-2210242	924m	0m	BOLLARDS	Damaged (DAMG)	CAT 1	18/10/2016	Completed Defects	18/10/2016	1KM WEST OF NEW FOWLIS W/B VERGE
NWG21186916-2210244	1,745m	0m	BOLLARDS	Damaged (DAMG)	CAT 1	18/10/2016	Completed Defects	03/10/2016	EAST OF ABERCAIRNEY COTTAGE W/B VERGE
NWG21186916-2210243	1,515m	0m	BOLLARDS	Damaged (DAMG)	CAT 1	18/10/2016	Completed Defects	04/10/2016	1.5KM WEST OF NEW FOWLIS W/B VERGE
NWG21186916-2210245	1,971m	0m	BOLLARDS	Damaged (DAMG)	CAT 1	18/10/2016	Completed Defects	03/10/2016	EAST OF MILTON OF CULTOQUHEY W/B VERGE
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 27 September 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 04 October 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 11 October 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 18 October 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 25 October 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 01 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 08 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 15 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 22 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 29 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 06 December 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 13 December 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 20 December 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 27 December 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 03 January 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 10 January 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 17 January 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 24 January 2017</b>									
NWG5237443-235040659	1,633m	0m	GULLY	Blockage (BLOK)	CAT 1	25/01/2017	Completed Defects	24/01/2017	MILTON OF ABERCAIRNY, W/B VERGE
NWG5237443-235040660	2,256m	0m	DITCH	Flooding (FLOD)	CAT 1	21/02/2017	Completed Defects	07/02/2017	JUST WEST OF MILTON OF CULTOQUHEY JCT, E/B VERGE
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 31 January 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 07 February 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 14 February 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 21 February 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 28 February 2017</b>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 07 March 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 14 March 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 21 March 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 28 March 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 04 April 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 11 April 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 18 April 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 25 April 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 02 May 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 09 May 2017</b>									
NWG7268931-235145508	2,152m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 1	06/06/2017	Completed Defects	18/05/2017	JUST EAST OF MILTON OF ABERCAIRNEY WB VERGE
NWG7268931-235145509	2,124m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 1	06/06/2017	Completed Defects	18/05/2017	JUST EAST OF MILTON OF ABERCAIRNEY WB VERGE
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 16 May 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 23 May 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 30 May 2017</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection TEMPLATE of A85 30 SIGN WEST METHVEN TO 30 SIGN EAST CRIEFF on 05 May 2017</b>									
NWG32253125-333	1,381m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-309	87m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-320	567m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-327	900m	0m	BOLLARDS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B VERGE.
NWG32253125-338	1,429m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-347	1,572m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT.
NWG32253125-354	1,932m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT.
NWG32253125-361	2,083m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-372	2,276m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-313	255m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF FOWLIS WESTER JCT, W/B VERGE.
NWG32253125-316	421m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF FOWLIS WESTER JCT, W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG32253125-330	1,387m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-335	1,389m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-350	1,850m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-351	1,855m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT.
NWG32253125-365	2,158m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B VERGE.
NWG32253125-368	2,219m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-310	93m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-312	210m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-317	434m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-319	537m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-344	1,662m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT.
NWG32253125-346	1,615m	0m	BOLLARDS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B VERGE.
NWG32253125-353	1,914m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-355	1,948m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B VERGE.
NWG32253125-304	2m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	FOWLIS WESTER JCT.
NWG32253125-308	24m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-321	614m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B VERGE.
NWG32253125-323	776m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-340	1,484m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-342	1,487m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG32253125-357	1,956m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-359	2,058m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-374	2,412m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST SIDE OF MILTON OF CULTOQUEHY JCT, E/B VERGE.
NWG32253125-331	1,386m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-311	126m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF FOWLIS WESTER JCT, W/B VERGE.
NWG32253125-318	467m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-325	859m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT.
NWG32253125-302	35m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-345	1,593m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-352	1,894m	0m	GULLY	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	OUTSIDE HOME FARM ACCESS, WEST OF FOWLIS WESTER JCT, E/B VERGE.
NWG32253125-356	1,956m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-363	2,085m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-370	2,251m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-334	1,389m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-314	405m	0m	GULLY	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF FOWLIS WESTER JCT, W/B VERGE.
NWG32253125-315	411m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-329	947m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B VERGE.
NWG32253125-336	1,399m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-337	1,414m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B VERGE.
NWG32253125-348	1,805m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-349	1,805m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG32253125-366	2,190m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-367	2,218m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-332	1,381m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT.
NWG32253125-303	11m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-326	889m	0m	BOLLARDS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B VERGE.
NWG32253125-328	937m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-301	39m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-339	1,483m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-362	2,083m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-364	2,096m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-369	2,239m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-371	2,268m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-305	5m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-307	12m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-322	757m	0m	GULLY	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B VERGE.
NWG32253125-324	789m	0m	GULLY	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B VERGE.
NWG32253125-341	1,487m	0m	BOLLARDS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B VERGE.
NWG32253125-343	1,563m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, W/B C/WAY.
NWG32253125-358	2,017m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-360	2,077m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF FOWLIS WESTER JCT, E/B C/WAY.
NWG32253125-373	2,399m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF MILTON OF CULTOQUEHY JCT, E/B VERGE

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 06 June 2017

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 13 June 2017



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 20 June 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 27 June 2017</b>									
<i>No defects recorded</i>									
<b>13910/91 : U7 MILTON OF CULTOQUEHY TO 30 SIGNS E OF GILMERTON</b>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 02 June 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 09 June 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 16 June 2015</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection TEMPLATE of A85 Detail West of Methven - 30mph E of Crieff on 23 June 2015</b>									
NWG1191244-208	1,354m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-210	1,352m	0m	CARRIAGEWAY	Surfacing joints (SRJT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-199	1,046m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-201	1,133m	0m	ROAD_MARKINGS_LONG	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-220	1,597m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON
NWG1191244-203	1,199m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-205	1,285m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-216	1,431m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-218	1,258m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-195	924m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-192	849m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-207	1,351m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-212	1,374m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-197	958m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-204	1,274m	0m	CARRIAGEWAY	Surfacing joints (SRJT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-215	1,430m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG1191244-209	1,354m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-211	1,373m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-198	1,022m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-200	1,046m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF MILTON OF CULTOQUEHY JCT
NWG1191244-219	1,563m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON
NWG1191244-221	1,595m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON
NWG1191244-190	578m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-193	849m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-196	935m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-206	1,344m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-213	1,377m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-214	1,427m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-191	789m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-194	955m	0m	FILTER_DRAIN	Silted (SILT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-202	1,197m	0m	ROAD_MARKINGS_LONG	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
NWG1191244-217	1,430m	0m	GULLY	Difference in level with road (IDLV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MILTON OF CULTOQUEHY
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 23 June 2015</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 30 June 2015</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 07 July 2015</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 14 July 2015</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 21 July 2015</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 28 July 2015</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 04 August 2015</b>									
NWG5121136-1238995	1,242m	0m	GULLY	Difference in level with road (IDLV)	CAT 2	01/01/9999	Completed Defects	25/01/2016	JUST EAST OF GILMERTON E/B C/WAY

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 11 August 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 18 August 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 25 August 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 01 September 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 08 September 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 15 September 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 22 September 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 29 September 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 06 October 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 13 October 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 20 October 2015</b>									
NWG11130779-1459096	657m	0m	GULLY	Cracked or broken (IBCK)	CAT 1	17/11/2015	Completed Defects	30/10/2015	EAST OF GILMERTON
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 27 October 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 03 November 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 10 November 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 17 November 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 24 November 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 01 December 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 08 December 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 15 December 2015</b>									
NWG11132252-1557257	719m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/01/2016	Completed Defects	07/01/2016	OUTSIDE CULTOQUHEY ACCESS, E/B C/WAY
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 22 December 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 29 December 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 05 January 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 12 January 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 19 January 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 26 January 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 02 February 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 09 February 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 16 February 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 23 February 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 01 March 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 08 March 2016</b>									



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11140384-1738633	1,046m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	25/08/2016	OUTSIDE NORTH LODGE, EAST OF GILMERTON
NWG11140384-1738632	1,048m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	25/08/2016	OUTSIDE NORTH LODGE, EAST OF GILMERTON
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 15 March 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 22 March 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 29 March 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 05 April 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 12 April 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 19 April 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 26 April 2016</b>									
No defects recorded									
<b>Detailed Inspection TEMPLATE of A85 30 SIGN WEST METHVEN TO 30 SIGN EAST CRIEFF on 28 April 2016</b>									
NWG21142421-132	1,569m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON W/B VERGE
NWG21142421-134	1,408m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON E/B VERGE
NWG21142421-123	956m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF MILTON CULTOQUEHY E/B
NWG21142421-126	1,185m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON W/B VERGE
NWG21142421-130	1,597m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON E/B VERGE
NWG21142421-133	1,503m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON E/B VERGE
NWG21142421-135	1,361m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON W/B
NWG21142421-122	835m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF MILTON OF CULTOQUEHY W/B
NWG21142421-127	1,275m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON W/B
NWG21142421-129	1,599m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON W/B VERGE
NWG21142421-131	1,580m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON E/B VERGE
NWG21142421-124	1,030m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON
NWG21142421-125	1,065m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON E/B
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 03 May 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 10 May 2016</b>									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 17 May 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 24 May 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 31 May 2016</b>									
NWG21157692-1965372	1,573m	0m	BOLLARDS	Damaged (DAMG)	CAT 1	28/06/2016	Completed Defects	23/06/2016	EAST SIDE OF GILMERTON E/B VERGE
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 07 June 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 14 June 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 21 June 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 28 June 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 05 July 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 12 July 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 19 July 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 26 July 2016</b>									
NWG21175598-2088232	570m	0m	GULLY	Blockage (BLOK)	CAT 1	23/08/2016	Completed Defects	10/08/2016	SMITHY COTTAGE EAST OF GILMERTON W/B C/WAY
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 02 August 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 09 August 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 16 August 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 23 August 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 30 August 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 06 September 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 13 September 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 20 September 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 27 September 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 04 October 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 11 October 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 18 October 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 25 October 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 01 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 08 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 15 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 22 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 29 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 06 December 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 13 December 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 20 December 2016</b>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG5222835-2389466	882m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/12/2016	Completed Defects	20/12/2016	JUST EAST OF GILMERTON, E/B C/WAY
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 27 December 2016</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 03 January 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 10 January 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 17 January 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 24 January 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 31 January 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 07 February 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 14 February 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 21 February 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 28 February 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 07 March 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 14 March 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 21 March 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 28 March 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 04 April 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 11 April 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 18 April 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 25 April 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 02 May 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 09 May 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 16 May 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 23 May 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 30 May 2017</b>									
No defects recorded									
<b>Detailed Inspection TEMPLATE of A85 30 SIGN WEST METHVEN TO 30 SIGN EAST CRIEFF on 05 May 2017</b>									
NWG32253125-375	720m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF MILTON OF CULTOQUEHY JCT.
NWG32253125-377	1,029m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF MILTON OF CULTOQUEHY JCT, W/B C/WAY.
NWG32253125-376	708m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF MILTON OF CULTOQUEHY JCT, E/B C/WAY.
NWG32253125-378	1,024m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF MILTON OF CULTOQUEHY JCT, E/B C/WAY.
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 06 June 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 13 June 2017</b>									
No defects recorded									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 20 June 2017</b>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 27 June 2017

No defects recorded

**13910/99 : 30 SIGNS E OF GILMERTON TO A822 JUNCT**

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 02 June 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 09 June 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 16 June 2015

No defects recorded

Detailed Inspection TEMPLATE of A85 Detail West of Methven - 30mph E of Crieff on 23 June 2015

NWG1191244-223	230m	0m	MANHOLE	Difference in level with road (IDLV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF GILMERTON
----------------	------	----	---------	--------------------------------------	-------	------------	-----------------------	------------	-------------------

NWG1191244-222	128m	0m	GULLY	Difference in level with road (IDLV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON
----------------	------	----	-------	--------------------------------------	-------	------------	-----------------------	------------	-------------------

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 23 June 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 30 June 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 07 July 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 14 July 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 21 July 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 28 July 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 04 August 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 11 August 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 18 August 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 25 August 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 01 September 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 08 September 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 15 September 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 22 September 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 29 September 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 06 October 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 13 October 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 20 October 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 27 October 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 03 November 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 10 November 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 17 November 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 24 November 2015

No defects recorded

Safety Inspection of A85 Safety Perth-Crianlarich&A84Lochearnhead-Stir on 01 December 2015

No defects recorded



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 08 December 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 15 December 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 22 December 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 29 December 2015</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 05 January 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 12 January 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 19 January 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 26 January 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 02 February 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 09 February 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 16 February 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 23 February 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 01 March 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 08 March 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 15 March 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 22 March 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 29 March 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 05 April 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 12 April 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 19 April 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 26 April 2016</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection TEMPLATE of A85 30 SIGN WEST METHVEN TO 30 SIGN EAST CRIEFF on 28 April 2016</b>									
NWG21142421-128	52m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GILMERTON E/B VERGE
NWG21142421-137	222m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GILMERTON E/B
NWG21142421-136	53m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GILMERTON W/B VERGE
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 03 May 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 10 May 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 17 May 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 24 May 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 31 May 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 07 June 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 14 June 2016</b>									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 21 June 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 28 June 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 05 July 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 12 July 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 19 July 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 26 July 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 02 August 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 09 August 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 16 August 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 23 August 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 30 August 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 06 September 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 13 September 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 20 September 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 27 September 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 04 October 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 11 October 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 18 October 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 25 October 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 01 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 08 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 15 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 22 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 29 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 06 December 2016</b>									
NWG5217081-2372565	206m	0m	MANHOLE	Rocking under load (IRLD)	3RD PTY	03/01/2017	Awaiting CCMS Temp Date	01/01/9999	OUTSIDE SOUTHWICK HOUSE EAST COTTAGE, GILMERTON
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 13 December 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 20 December 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 27 December 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 03 January 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 10 January 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 17 January 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 24 January 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 31 January 2017</b>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 07 February 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 14 February 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 21 February 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 28 February 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 07 March 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 14 March 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 21 March 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 28 March 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 04 April 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 11 April 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 18 April 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 25 April 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 02 May 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 09 May 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 16 May 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 23 May 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 30 May 2017</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection TEMPLATE of A85 30 SIGN WEST METHVEN TO 30 SIGN EAST CRIEFF on 05 May 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 06 June 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 13 June 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 20 June 2017</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of A85 Safety Perth-Crianlarich&amp;A84Lochearnhead-Stir on 27 June 2017</b>									
<i>No defects recorded</i>									