

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 16/12/2017 and 16/03/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST: EAST LODGE TO SYMINGTON SB',) Or

(Section is 'AGAINST: SYMINGTON SB TO DUTCH HOUSE RBT',) Or

(Section is 'WITH: DUTCH HOUSE ROUNDABOUT TO SYMINGTON NB',) Or

(Section is 'WITH: SYMINGTON NB TO EAST LODGE',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
11650/08 : WITH: DUTCH HOUSE ROUNDABOUT TO SYMINGTON NB									
Safety Inspection of A76 & A77 Ayr North V1 on 19 December 2017									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 December 2017									
SW82317041-235510681	2,657m	2,677m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/01/2018	Completed Defects	31/01/2018	A77 NB CW, CL, AT SYMINGTON NB OFFSLIP
Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017									
SW82317163-235513437	204m	224m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	26/01/2018	Completed Defects	02/02/2018	A77 CENTER RESERVE, 120M NTH OF DUTCH HOUSE RBT, CENTER RESERVE
Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018									
<i>No defects recorded</i>									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018									
SW82318102-235532001	288m	290m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/02/2018	Completed Defects	14/02/2018	A77 NB CW, 300M NTH OF DUTCHHOUSE RBT
SW82318102-235531999	184m	284m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/02/2018	Completed Defects	14/02/2018	A77 NB CW, LANE 1, 200M NTH OF DUTCHHOUSE RBT
SW82318102-235532000	242m	245m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/02/2018	Completed Defects	14/02/2018	A77 NB CW, LANE 1 250M NTH OF DUTCHHOUSE RBT
Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018									
SW82318894-235534931	1,499m	1,500m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	07/02/2018	A77 NB CW, LANE 1, 400M STH OF HANSEL VILLAGE
SW82318894-235534932	1,760m	1,780m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	07/02/2018	A77 NB CW, LANE 1, 200M STH OF HANSEL VILLAGE
Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018									
<i>No defects recorded</i>									

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018
SW82319390-235542963 98m 99m CARRIAGEWAY Pothole (POTH) CAT 1 13/03/2018 Completed Defects 14/02/2018 A77 NB CW, LANE 1, 100M NTH DUTCH HOUSE RBT, TO 300M

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

SW82321390-235546234 1,491m 1,493m CARRIAGEWAY Pothole (POTH) CAT 1 20/03/2018 Completed Defects 20/02/2018 A77 N/B LANE 1 NORH OF AVERAGE SPEED CAMERAS SOUTH OF HANSEL

SW82321390-235546235 1,751m 1,752m CARRIAGEWAY Pothole (POTH) CAT 1 20/03/2018 Completed Defects 21/02/2018 A77N/B LANE1 AT FARM JCT SOUTH OF HANSEL VILAGE

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

SW82322248-235548888 1,495m 1,496m CARRIAGEWAY Pothole (POTH) CAT 1 23/03/2018 Completed Defects 23/02/2018 A77 N/B LANE 1 30M NORTH OF AVERAGE SPEED CAMERA SOUTH OF HANSEL VILLAGE

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

SW82325502-235553021 198m 199m CARRIAGEWAY Pothole (POTH) CAT 1 03/04/2018 Completed Defects 06/03/2018 A77 NB CW LANE 1, 190M NTH OF DUTCH HOUSE RBT

SW82325502-235553024 339m 340m CARRIAGEWAY Pothole (POTH) CAT 1 03/04/2018 Completed Defects 06/03/2018 A77 NB CW, LANE 1, 290M NTH OF DUTCH HOUSE RBT

SW82325502-235553025 1,708m 1,709m CARRIAGEWAY Pothole (POTH) CAT 1 03/04/2018 Completed Defects 07/03/2018 A77 NB CW, LANE 1, 250M STH OF HANSEL VILLAGE

SW82325502-235553022 253m 254m CARRIAGEWAY Pothole (POTH) CAT 1 03/04/2018 Completed Defects 06/03/2018 A77 NB CW, LANE 1, 253M NTH OF DUTCH HOUSE RBT

SW82325502-235553023 304m 305m CARRIAGEWAY Pothole (POTH) CAT 1 03/04/2018 Completed Defects 06/03/2018 A77 NB CW, LANE 1 280M NTH OF DUTCHHOUSE RBT

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

SW82326369-235553165 1,803m 1,804m CARRIAGEWAY Pothole (POTH) CAT 1 06/04/2018 Completed Defects 09/03/2018 A77 NB CW, LANE 1, AT WEXFORD FARM, 400M STH OF HANSEL VILLAGE OB

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

11650/40 : WITH: SYMINGTON NB TO EAST LODGE

Safety Inspection of A76 & A77 Ayr North V1 on 19 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 December 2017

SW82317041-235510682 493m 494m CARRIAGEWAY Pothole (POTH) CAT 1 19/01/2018 Completed Defects 09/01/2018 A77 NB CW, LANE 1, 200M NTH OF SYMINGTON OB

SW82317041-235510683 1,142m 1,145m CARRIAGEWAY Pothole (POTH) CAT 1 19/01/2018 Completed Defects 08/01/2018 A77 NB CW, LANE 2, 150M NTH OF HALFWAY HOUSE

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

SW82317163-235513438 1,258m 1,260m CARRIAGEWAY Pothole (POTH) CAT 1 26/01/2018 Completed Defects 06/03/2018 A77 NB CW, ON CL, AT END OF BUS STOP OPPOSITE BALBIRS STH OF BOG END TOLL

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

SW82317357-235513858 290m 291m CARRIAGEWAY Pothole (POTH) CAT 1 02/02/2018 Completed Defects 13/01/2018 A77 N/B LANE 1 10M NORTH OF END OF ONSLIP FROM

SW82317357-235513860	464m	466m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/02/2018	Completed Defects	31/01/2018	SYMINGTON A77 N/B LANE 1 AND LANE2 60M NORTH OF COTAGES NORTH OF ON SLIP FROM SYMINGTON
SW82317357-235513857	238m	239m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/02/2018	Completed Defects	31/01/2018	A7 N/B ON CENTRE LINE 50M NORTH OF SYMINGTON OVERBRIDGE
Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018									
SW82317440-235515662	720m	721m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/02/2018	Completed Defects	31/01/2018	A77 NB CW, LANE 2, OUTSIDE HALFWAY HOUSE
SW82317440-235515649	1,196m	1,197m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/01/2018	Completed Defects	31/01/2018	A77 NB CW LANE 1, 150M NTH OF HALFWAY HOUSE NTH OF SYMINGTON
SW82317440-235515650	1,343m	1,345m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/02/2018	Completed Defects	31/01/2018	A77 NB CW, LANE 1, 350M NTH OF HALFWAY HOUSE, NTH OF SYMINGTON
Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018									
SW82317632-235520466	1,629m	1,649m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/02/2018	Completed Defects	09/02/2018	LANE 1 AT ADS PRIOR TO BOGEND NB OPPOSITE WHITELEES COTTAGES
SW82317632-235520465	1,008m	1,018m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	13/02/2018	Completed Defects	31/01/2018	LANE 2 AT THE SLIP ROAD TO OLD HALFWAY HOUSE BETWEEN SYMINGTON AND BOGENDTOLL
Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018									
No defects recorded									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018									
No defects recorded									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018									
SW82318894-235534934	740m	760m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	07/02/2018	A77 NB CW, 600M NTH OF SYMINGTON ONSLIP
Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018									
SW82319109-235534717	417m	418m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, LANE 1, 410M NTH OF SYMINGTON NB ONSLIP
SW82319109-235534719	712m	722m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, ON CL, 720M NTH OF SYMINGTON NB ONSLIP
SW82319109-235534718	661m	665m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, 660M NTH OF SYMINGTON NB ONSLIP
SW82319109-235534720	1,071m	1,073m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, LANE 2, OPPOSITE HALFWAY HOUSE NTH OF SYMINGTON OB
SW82319109-235534721	1,737m	1,757m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, 150M STH OF BOGEND TOLL TO BOGEND TOLL
Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018									
No defects recorded									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018									
No defects recorded									
Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018									

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

SW82326369-235553171	850m	851m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, 250M STH OF HALFWAY HOUSE
SW82326369-235553173	942m	943m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, 150M STH OF HALFWAY HOUSE
SW82326369-235553177	1,656m	1,657m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, OPPOSITE SPICE ROUTE
SW82326369-235553174	998m	999m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, 100M STH OF HALFWAY HOUSE
SW82326369-235553170	800m	801m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, 300M STH OF HALFWAY HOUSE
SW82326369-235553175	1,636m	1,637m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, LANE 1, OPPOSITE SPICE ROUTE
SW82326369-235553176	1,652m	1,653m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, OPPOSITE SPICE ROUTE
SW82326369-235553172	904m	905m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/04/2018	Completed Defects	10/03/2018	A77 NB CW, ON CL, 200M STH OF HALFWAY HOUSE

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

SW82328364-235586130	489m	490m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW, 600M STH OF HALFWAY HOUSE ON CL
SW82328364-235586132	613m	614m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW LANE 1, 500M STH OF HALFWAY HOUSE
SW82328364-235586133	678m	679m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW LANE 2, 450M STH OF HALFWAY HOUSE
SW82328364-235586134	752m	753m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW, ON CL, 400M STH OF HALFWAY HOUSE
SW82328364-235586131	552m	553m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2018	Completed Defects	16/03/2018	A77 NB CW ON CL, 550M STH OF HALFWAY HOUSE

11650/41 : AGAINST: EAST LODGE TO SYMINGTON SB

Safety Inspection of A76 & A77 Ayr North V1 on 19 December 2017

SW82316989-235510270	2,457m	2,458m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/01/2018	Completed Defects	31/01/2018	A77N/B ON CENTRE LINE OPPOSITE FIRST COTAGES 150M NORTH OF SYMINGTON N/B ON SLIP
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

SW82317163-235513439	582m	584m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/01/2018	Completed Defects	09/02/2018	A77 NB CL, 100M NTH OF BOG END TOLL NB ON SLIP
SW82317163-235513440	348m	350m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/01/2018	Completed Defects	09/02/2018	A77 NB CW, ON CL, 200M NTH OF BOG END TOLL NB ONSLIP

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

SW82317357-235513859	2,457m	2,457m	CARRIAGEWAY	Pothole	CAT 1	02/02/2018	Completed	31/01/2018	A77 N/B LANE1 AND
----------------------	--------	--------	-------------	---------	-------	------------	-----------	------------	-------------------

(POTH)

Defects

CENTRELINE 40M NORTH OF
COTAGESNORTH
OFSYMRINGTON ON SLIP

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

SW82317632-235520464	2,456m	2,457m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/02/2018	Completed Defects	31/01/2018	LANE 1 200meters north of the symington nb on slip at cottages
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

SW82317812-235529552	878m	880m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/02/2018	Completed Defects	09/02/2018	A77 NB CW, AT BOG END TOLL NB ON SLIP
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---------------------------------------

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

SW82318894-235534933	2,590m	2,590m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2018	Completed Defects	07/02/2018	A77 NB CW, LANE 1, 100M NTH OF SYMRINGTON ONSLIP
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

SW82319109-235534716	2,447m	2,450m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	09/02/2018	A77 NB CW, ON CL, 300M NTH OF SYMRINGTON NB ONSLIP
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

SW82325502-235553035	2,463m	2,863m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	07/03/2018	A77 NB CW, ON CL, 500M NTH OF SYMRINGTON ONSLIP, TO 200M STH HALFWAY HOUSE
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

11650/09 : AGAINST: SYMRINGTON SB TO DUTCH HOUSE RBT

Safety Inspection of A76 & A77 Ayr North V1 on 19 December 2017

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 26 December 2017

SW82317095-235513358	545m	555m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/01/2018	Completed Defects	01/02/2018	A77 NB CW, ON CL, OPPOSITE HANSEL VILLAGE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 December 2017

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

SW82317274-235513678	511m	514m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/01/2018	Completed Defects	02/02/2018	A7 S/B ON CENTRE LINE OPPOSITE JCT HANSEL
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018**

SW82317440-235515661	643m	644m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/02/2018	Completed Defects	01/02/2018	A77 SB CW, LANE 2, OUTSIDE HANSEL VILLAGE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018**

SW82317632-235520463	2,364m	2,365m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/02/2018	Completed Defects	31/01/2018	300 M NORTH OF DUTCHHOUSE RBT LANE 1
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--------------------------------------

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018**

SW82319390-235542962	2,103m	2,104m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/03/2018	Completed Defects	13/02/2018	A77 SB CW LANE 1, 500M NTH OF DUTCH HOUSE RBT
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018*No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018***No defects recorded***Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018***No defects recorded***Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018**

SW82327521-235576666	608m	610m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/04/2018	Completed Defects	14/03/2018	A77 SB CW, AT HANSEL VILLAGE
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	------------------------------

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018*No defects recorded*