


Personal Injury Accident Details – 1 Jan 2015 to present

Reviewed area based on A83 chart section 16520/05 only and includes all accidents in that search area in the period detailed above.



Accident, Vehicle and Casualty Details

Accident Reference: LB01308

Road/Link/Section/Chainage: A83 16520/05 (1,351m)

Weather Conditions: Rain

Vehicle Details

Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overtaken	Hit Object in Cway	Hit Object off Cway
1	CAR	S N	ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	NOT AT, OR WITHIN 20 METRES OF, JUNCTION	GOING AHEAD RIGHT HAND BEND	SKIDDED	NONE	TREE

Date/Time: [REDACTED] 1542

Junction Road Code: ?

Road Surface Conditions: Wet

Severity: SERIOUS

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Lighting Conditions: Light

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER	[REDACTED]	[REDACTED]	SERIOUS

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)
SLIPPERY ROAD (DUE TO WEATHER) (POSSIBLE)

Accident Reference: LB03010

Road/Link/Section/Chainage: A83 16520/05 (1,098m)

Weather Conditions: Rain

Vehicle Details

Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overtaken	Hit Object in Cway	Hit Object off Cway
1	CAR	S N	ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	NOT AT, OR WITHIN 20 METRES OF, JUNCTION	GOING AHEAD RIGHT HAND BEND	SKIDDED	NONE	NONE

Date/Time: [REDACTED] 2016 080

Junction Road Code: ?

Road Surface Conditions: Wet

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Lighting Conditions: Dark

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER	[REDACTED]	[REDACTED]	SLIGHT

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)
CARELESS/RECKLESS/IN A HURRY (POSSIBLE)

Accident Reference: LB01903

Date/Time: [REDACTED] 2018 0811

Severity: SLIGHT

Road/Link/Section/Chainage: A83 16520/05 (1,220m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
1	CAR	S N	ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	NOT AT, OR WITHIN 20 METRES OF, JUNCTION	GOING AHEAD RIGHT HAND BEND	SKIDDED	BOLLARD / REFUGE	NEARSIDE OR OFFSIDE CRASH BARRIER

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	VEHICLE OR PILLION PASSENGER	[REDACTED]	[REDACTED]	SLIGHT

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY) ROAD LAYOUT (EG. BEND, HILL, NARROW CARRIAGEWAY) (VERY LIKELY) SWERVED (VERY LIKELY)
